July 26, 2019

Jaclyn Lee
City of Camarillo
Department of Community Development
601 Carmen Drive
Camarillo, CA 93010
ilee@cityofcamarillo.org

SCH # 2019070514

Project Title: Camarillo Springs GPA 2017-2 Project Lead Agency: City of Camarillo

Dear Ms. Jaclyn Lee:

Governor's Office of Planning & Research

JULY 29 2019

STATE CLEARINGHOUSE

The Division of Oil, Gas, and Geothermal Resources (Division) authority is set forth in Division 3 of the Public Resources Code (PRC), and Title 14 of the California Code of Regulations (CCR). PRC § 3208.1 establishes well reabandonment responsibility when a previously plugged and abandoned well may be impacted by planned property development or construction activities. Local permitting agencies, property owners, and/or developers should be aware of, and fully understand, that significant and potentially dangerous issues may be associated with development near oil, gas, or geothermal wells.

The Division has received and reviewed the Notice of Preparation for the above referenced project dated July 11, 2019. To assist local permitting agencies, property owners, and developers in making wise land use decisions regarding potential development near oil, gas, or geothermal wells, the Division provides the following well evaluations.

The project is located in Ventura County, within the abandoned Conejo field. Our records indicate 15 known oil, gas, or geothermal wells located within the project boundary as identified in the application. Of those wells, three are located within or adjacent to the Development Area, one is within the Recreation Area, and 11 are within the Parking area (Figure 1). Of the 11 wells in the Parking area 8 appear to already have structures or pavement over them.

The wells listed below are not abandoned to current Division requirements as prescribed by law. It is the opinion of the Division that these wells require abandonment or reabandonment if they will be built over or have future access impeded. Wells that have existing structures over them do not require abandonment unless they will be re-developed over.

Well	Status
Conejo Syndicate Well No. 1 API 0411100552	The record review process shows that the abandonment status of this well is not abandoned to current Division standards as of July 26, 2019.
Inside development area	Based on well records: 1. Zone plug is insufficient (CCR § 1723.1) 2. There is no record of a casing shoe plug (CCR § 1723.3) 3. There is no record of a surface plug (CCR § 1723.5)
Trinitas Oil Co. Well No. 1 API 0411121695	The record review process shows that the abandonment status of this well is not abandoned to current Division standards as of July 26, 2019.
Inside development area	Based on well records: 1. There is no record of a zone plug (CCR § 1723.1) 2. There is no record of a casing shoe plug (CCR § 1723.3) 3. There is no record of a surface plug (CCR § 1723.5)
National Oil Co. Well No. 62 API 0411121677	The record review process shows that the abandonment status of this well is not abandoned to current Division standards as of July 26, 2019.
Near the development area	Based on well records: 1. There is no record of a zone plug (CCR § 1723.1) 2. There is no record of a casing shoe plug (CCR § 1723.3) 3. There is no record of a surface plug (CCR § 1723.5)
National Oil Co. Well No. 68 API 0411121681	The record review process shows that the abandonment status of this well is not abandoned to current Division standards as of July 26, 2019.
In recreation area	Based on well records: 1. There is no record of a zone plug (CCR § 1723.1) 2. There is no record of a casing shoe plug (CCR § 1723.3) 3. There is no record of a surface plug (CCR § 1723.5)
National Oil Co. Well No. 69 API 0411121682	The record review process shows that the abandonment status of this well is not abandoned to current Division standards as of July 26, 2019.
Inside parking area	Based on well records: 1. There is no record of a zone plug (CCR § 1723.1) 2. There is no record of a casing shoe plug (CCR § 1723.3) 3. There is no record of a surface plug (CCR § 1723.5)

DocuSign Envelope ID: DACF6249-E5DA-4110-9781-A7E774D5EC10
Ms. Jaclyn Lee
July 26, 2019
Page 3

Logsdon & Sloan Syndicate No 1 Well No. 4 API 0411121688	The record review process shows that the abandonment status of this well is not abandoned to current Division standards as of July 26, 2019.
Inside parking area	Based on well records: 1. There is no record of a zone plug (CCR § 1723.1) 2. There is no record of a casing shoe plug (CCR § 1723.3) 3. There is no record of a surface plug (CCR § 1723.5)
Logsdon & Sloan Syndicate No 1 Well No. 1 API 0411121685	The record review process shows that the abandonment status of this well is not abandoned to current Division standards as of July 26, 2019.
Inside parking area – already built over (?)	Based on well records: 1. There is no record of a zone plug (CCR § 1723.1) 2. There is no record of a casing shoe plug (CCR § 1723.3) 3. There is no record of a surface plug (CCR § 1723.5)
Logsdon & Sloan Syndicate No 1 Well No. 3 API 0411121687	The record review process shows that the abandonment status of this well is not abandoned to current Division standards as of July 26, 2019.
Inside parking area – already built over	Based on well records: 1. There is no record of a zone plug (CCR § 1723.1) 2. There is no record of a casing shoe plug (CCR § 1723.3) 3. There is no record of a surface plug (CCR § 1723.5)
Equity Petro. Co. Equity 3 API 0411121665	The record review process shows that the abandonment status of this well is not abandoned to current Division standards as of July 26, 2019.
Inside parking area	Based on well records: 1. There is no record of a zone plug (CCR § 1723.1) 2. There is no record of a casing shoe plug (CCR § 1723.3) 3. There is no record of a surface plug (CCR § 1723.5)
Equity Petro. Co. Equity 4 API 0411121666	The record review process shows that the abandonment status of this well is not abandoned to current Division standards as of July 26, 2019.
Inside parking area – already built over	Based on well records: 1. There is no record of a zone plug (CCR § 1723.1) 2. There is no record of a casing shoe plug (CCR § 1723.3) 3. There is no record of a surface plug (CCR § 1723.5)

DocuSign Envelope ID: DACF6249-E5DA-4110-9781-A7E774D5EC10
Ms. Jaclyn Lee
July 26, 2019
Page 4

Dr. J. Von Gal-Scale Well No. 7 API 0411121702 Inside parking area – already built over	The record review process shows that the abandonment status of this well is not abandoned to current Division standards as of July 26, 2019. Based on well records: 1. There is no record of a zone plug (CCR § 1723.1) 2. There is no record of a casing shoe plug (CCR § 1723.3) 3. There is no record of a surface plug (CCR § 1723.5)
International Oil Devel Inc. Lt Well No. 18 API 0411102251	The record review process shows that the abandonment status of this well is not abandoned to current Division standards as of July 26, 2019.
Inside parking area – <u>already built over</u>	Based on well records: 1. There is no record of a zone plug (CCR § 1723.1) 2. There is no record of a casing shoe plug (CCR § 1723.3) 3. There is no record of a surface plug (CCR § 1723.5)
B & B Oil Co. Well No. 1 API 0411100523	The record review process shows that the abandonment status of this well is not abandoned to current Division standards as of July 26, 2019.
Inside parking area – already built over	Based on well records: 1. There is no record of a zone plug (CCR § 1723.1) 2. There is no record of a casing shoe plug (CCR § 1723.3) 3. There is no record of a surface plug (CCR § 1723.5)
Charles E. Clinton Well No. 1 API 0411100554	The record review process shows that the abandonment status of this well is not abandoned to current Division standards as of July 26, 2019.
Inside parking area – already built over	Based on well records: 1. There is no record of a zone plug (CCR § 1723.1) 2. There is no record of a casing shoe plug (CCR § 1723.3) 3. There is no record of a surface plug (CCR § 1723.5)
B & B Oil Co. Well No. 3 API 0411100525	The record review process shows that the abandonment status of this well is not abandoned to current Division standards as of July 26, 2019.
Inside parking area – already built over	Based on well records: 1. There is no record of a zone plug (CCR § 1723.1) 2. There is no record of a casing shoe plug (CCR § 1723.3) 3. There is no record of a surface plug (CCR § 1723.5)

Ms. Jaclyn Lee July 26, 2019 Page 5



Figure 1. Map of known oil and gas wells in the vicinity of the proposed project. A map view of DOGGR wells is available at https://maps.conservation.ca.gov/doggr/wellfinder.

The Division categorically advises against building over, or in any way impeding access to, oil, gas, or geothermal wells. Access is considered the ability for a well servicing unit and associated necessary equipment to reach a well from a public street or access way, solely over the parcel on which the well is located. A well servicing unit, and any necessary equipment, should be able to pass unimpeded along and over the route, and should be able to access the well without disturbing the integrity of surrounding infrastructure. Items that can affect well access include, but are not limited to, buildings, housing, fencing, hardscape, landscape, trees, pools, patios, sidewalks, roadways, parking lots, waterways or channels, and decking. Impeding access to a well could result in the need to remove any structure or obstacle that prevents or impedes access.

There are no guarantees a well abandoned in compliance with current Division requirements will not start leaking in the future. It always remains a possibility that any well may start to leak oil, gas, and/or water after abandonment, no matter how thoroughly the well was plugged and abandoned. The Division acknowledges wells plugged and abandoned to the most current standards have a lower probability of leaking in the future, however there is no guarantee that such abandonments will not leak.

The Division advises that all wells identified on the development parcel prior to, or during, development activities be tested for liquid and gas leakage. Surveyed locations should be provided to the Division in Latitude and Longitude, NAD 83 decimal format. The Division expects any wells found leaking to be reported to it immediately.

Failure to plug and reabandon a well may result in enforcement action, including an order to perform reabandonment well work, pursuant to PRC § 3208.1, and 3224.

PRC § 3208.1 gives the Division the authority to order or permit the re-abandonment of any well where it has reason to question the integrity of the previous abandonment, or if the well is not

DocuSign Envelope ID: DACF6249-E5DA-4110-9781-A7E774D5EC10

Ms. Jaclyn Lee July 26, 2019 Page 6

accessible or visible. Responsibility for re-abandonment costs may be affected by the choices made by the local permitting agency, property owner, and/or developer in considering the general advice set forth in this letter. The PRC continues to define the person or entity responsible for reabandonment as:

- 1. The property owner If the well was plugged and abandoned in conformance with Division requirements at the time of plugging and abandonment, and in its current condition does not pose an immediate danger to life, health, and property, but requires additional work solely because the owner of the property on which the well is located proposes construction on the property that would prevent or impede access to the well for purposes of remedying a currently perceived future problem, then the owner of the property on which the well is located shall obtain all rights necessary to reabandon the well and be responsible for the reabandonment.
- 2. The person or entity causing construction over or near the well If the well was plugged and abandoned in conformance with Division requirements at the time of plugging and abandonment, and the property owner, developer, or local agency permitting the construction failed either to obtain an opinion from the supervisor or district deputy as to whether the previously abandoned well is required to be reabandoned, or to follow the advice of the supervisor or district deputy not to undertake the construction, then the person or entity causing the construction over or near the well shall obtain all rights necessary to reabandon the well and be responsible for the reabandonment.
- 3. The party or parties responsible for disturbing the integrity of the abandonment If the well was plugged and abandoned in conformance with Division requirements at the time of plugging and abandonment, and after that time someone other than the operator or an affiliate of the operator disturbed the integrity of the abandonment in the course of developing the property, then the party or parties responsible for disturbing the integrity of the abandonment shall be responsible for the reabandonment.

To view PRC 3208.1 in its entirety, please visit ftp://ftp.consrv.ca.gov/pub/oil/laws/PRC10.pdf

No well work may be performed on any oil, gas, or geothermal well without written approval from the Division. Well work requiring written approval includes, but is not limited to, mitigating leaking gas or other fluids from abandoned wells, modifications to well casings, and/or any other abandonment or re-abandonment work. The Division also regulates the top of a plugged and abandoned well's minimum and maximum depth below final grade. CCR §1723.5 states well casings shall be cut off at least 5 feet but no more than 10 feet below grade. If any well needs to be lowered or raised (i.e. casing cut down or casing riser added) to meet this regulation, a permit from the Division is required before work can start.

The Division makes the following additional recommendations to the local permitting agency, property owner, and developer:

1. To ensure that present and future property owners are aware of (a) the existence of all wells located on the property, and (b) potentially significant issues associated with any improvements near oil or gas wells, the Division recommends that information regarding the above identified well(s), and any other pertinent information obtained after the

DocuSign Envelope ID: DACF6249-E5DA-4110-9781-A7E774D5EC10

Ms. Jaclyn Lee July 26, 2019 Page 7

issuance of this letter, be communicated to the appropriate county recorder for inclusion in the title information of the subject real property.

2. The Division recommends that any soil containing hydrocarbons be disposed of in accordance with local, state, and federal laws. Please notify the appropriate authorities if soil containing significant amounts of hydrocarbons is discovered during development.

As indicated in PRC § 3106, the Division has jurisdictional authority over the drilling, operation, maintenance, and abandonment of oil, gas, and geothermal wells, and attendant facilities, to prevent, as far as possible, damage to life, health, property, and natural resources, damage to underground oil, gas, and geothermal deposits, and damage to underground and surface waters suitable for irrigation or domestic purposes. In addition to the Division's authority to order work on wells pursuant to PRC §§ 3208.1 and 3224, it has authority to issue civil and criminal penalties under PRC §§ 3236, 3236.5, and 3359 for violations within the Division's jurisdictional authority. The Division does not regulate grading, excavations, or other land use issues.

If during development activities, any wells are encountered that were not part of this review, the Division's construction site well review engineer in the Coastal District, Ventura office is to be notified immediately, and an amended site plan with well casing diagrams for Division review shall be filed. After appropriate review, the District office will send a follow-up well evaluation letter to the property owner, applicant, and local permitting agency.

Should you have any questions, please contact Justin LaForge at (805) 465-9626 or via email at <u>justin.laforge@conservation.ca.gov</u>.

Sincerely,

Ewan Beenliam

--- E7667EB15E2C469...

DocuSigned by:

Ewan Beenham Senior Oil & Gas Engineer

cc: Well Files