**Golder Associates Inc.** 230 Commerce, Suite 200 Irvine, CA USA 92602 Telephone: (714) 508-4400 Fax: (714) 508-4401



**REPORT ON** 

# PHASE I ENVIRONMENTAL SITE ASSESSMENT 4.13 ACRE PARKING LOT NORTHEAST CORNER OF WEST 190<sup>TH</sup> STREET AND CRENSHAW PLACE TORRANCE, CALIFORNIA

Prepared for:

**Travelers** 385 Washington Street – NB12a Saint Paul, Minnesota 55102

Prepared by:

**Golder Associates Inc.** 230 Commerce, Suite 200 Irvine, California 92602

Distribution:

Copies
 Copy

Travelers Golder Associates Inc.

December 26, 2007

073-91953

**Golder Associates Inc.** 230 Commerce, Suite 200 Irvine, CA USA 92602 Telephone: (714) 508-4400 Fax: (714) 508-4401



December 26, 2007

073-91953

Travelers 385 Washington Street – NB12a Saint Paul, Minnesota 55102

Attention: Mr. Robert K. O'Leary, Jr.

## RE: REPORT ON THE PHASE I ENVIRONMENTAL SITE ASSESSMENT 4.13 ACRE PARKING LOT NORTHEAST CORNER OF WEST 190<sup>TH</sup> STREET AND CRENSHAW PLACE TORRANCE, CALIFORNIA

Dear Mr. O'Leary:

Golder Associates (Golder) is pleased to present to Travelers this report of the Phase I Environmental Site Assessment conducted for the above referenced site. Information presented in this report is subject to the general limitations presented in the report and Golder's proposal dated October 17, 2007.

Golder appreciates this opportunity to assist you with your environmental needs. If you have any questions or comments regarding the information presented in this report, please call our office.

Sincerely,

**GOLDER ASSOCIATES INC.** 

Misty Vazquez Sr. Project Environmental Engineer

Jane P. Mills, CSP, CHMM Principal and Senior Consultant

## SUMMARY

Travelers (the User) retained Golder Associates Inc. (Golder) to perform a Phase I Environmental Site Assessment (ESA) of the parking lot located at the northeast corner of West 190<sup>th</sup> Street and Crenshaw Place in Torrance, California (the Site or subject property; Figure 1). The purpose of this Phase I ESA is to identify recognized environmental conditions (RECs) in connection with the subject property, to the extent feasible, pursuant to the processes prescribed in the ASTM Practice E 1527-05 entitled "Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process" (ASTM Standard), and the EPA Rule entitled, "Standards and Practices for All Appropriate Inquiries; Final Rule" (AAI Rule), 40 CFR Part 312, the Golder Proposal dated October 17, 2007 (the Proposal), and Golder's professional judgment.

This Summary is to be used only in conjunction with the attached *Phase I Environmental Site Assessment* report dated November 30, 2007 (the Report). All definitions used in this Summary have the same meanings as in the Report, and the use of this Summary is subject to the limitations and conditions contained in the Report. The Report shall govern in the event of any inconsistency between this Summary and the Report.

The subject property is located at the northeast corner of West 190<sup>th</sup> Street and Crenshaw Place in the City of Torrance, Los Angeles County, California (Figure 1). Interstate 405 (the San Diego Freeway) is located approximately 0.25 miles northeast of the Site. Site access is provided from Crenshaw Place on the west and from the adjoining parking lot on the east. The existing land use consists of an approximately 179,950 square foot (4.13 acres) asphalt paved parking lot.

The subject property is developed as a paved parking lot. The Site Assessor's Parcel Numbers (APNs) are 4090-021-032 and 4090-021-033.

The subject property was not listed on EDR-provided governmental agency databases indicating environmental impairment. The following off-site REC presents a potential environmental concern for the subject property:

• Texaco Service Station #0274 is located approximately 200 feet west (upgradient) of the subject property. A leaking diesel UST that affected groundwater was discovered on May 1, 1990. The analytical results from an on-site monitoring well sample collected on July 5, 2007 indicated that groundwater is impacted with elevated concentrations of TPHg, Benzene, MTBE, and TBA. The extent of downgradient groundwater impacts does not appear to be characterized. No additional groundwater data was found for groundwater between the Texaco Service Station and the subject property. It is Golder's opinion that this site presents a potential environmental concern for the subject property given the distance, upgradient nature, and lack of downgradient groundwater quality data.

Golder did not identify RECs or historical RECs in connection with the subject property. However, the following de minimis condition was identified at the Site:

## De minimis condition:

• Minor oil staining from automobiles was observed on the asphalt of the parking lot. It is Golder's opinion that the oil staining is a de minimis condition, because it does not present a threat to human health or the environment, and generally would not be the

subject of enforcement action if it was brought to the attention of the regulatory authorities.

\_

\_

# TABLE OF CONTENTS

Cover	Letter	
Table	of Cont	entsi
SECT	<u>'ION</u>	PAGE
SUMI	MARY.	
1.0	INTF	RODUCTION1
	1.1	Purpose1
	1.2	Detailed Scope of Services
	1.3	Significant Assumptions
	1.4	Limitations and Exceptions
	1.5	Special Terms and Conditions
	1.6	User Reliance
2.0	PRO	PERTY DESCRIPTION
	2.1	Location and Legal Description
	2.2	Site and Vicinity General Characteristics
	2.3	Current Use of the Subject Property
	2.4	Descriptions of Structures, Roads, and Other Improvements on the Subject Property 4
	2.5	Current Use of the Adjoining Properties
3.0	USEI	R PROVIDED INFORMATION
5.0	3.1	Environmental Cleanup Liens
	3.2	Activity and Land Use Limitations
	3.3	Specialized Knowledge
	3.3 3.4	Relationship of the Purchase Price to the Fair Market Value
	3.4	Commonly Known or Reasonably Ascertainable Information
	3.6	The Degree of Obviousness or the Presence of Contamination
4.0	REC	ORDS REVIEW
	4.1	Standard Environmental Record Sources, Federal and State
		4.1.1 Subject Property Database Listing
		4.1.2 Off-Site Properties Database Listings
	4.2	Additional Environmental Record Sources
		4.2.1 County of Los Angeles Certified Unified Program Agency/Public Health Investigation (CUPA/PHI)
		4.2.2 County of Los Angeles Fire Department (LAFD)
		4.2.3 Department of Toxic Substances Control (DTSC)
		4.2.4 Los Angeles Regional Water Quality Control Board (LARWQCB)
		4.2.5 South Coast Air Quality Management District (SCAQMD)
		4.2.6 Previous Environmental Assessments
	4.3	Physical Setting Sources
		1

		4.3.1 Sources Reviewed	. 12
		4.3.2 General Topographic Setting of the Area	. 12
		4.3.3 Geologic and Hydrogeologic Setting	. 12
	4.4	Historical Use Information on the Subject Property	
		4.4.1 Subject Property Historical Use Summary	
		4.4.2 Standard Historical Records	
		4.4.2.1 Aerial Photographs Review	
		4.4.2.2 Sanborn <sup>©</sup> Fire Insurance Map Review	
		4.4.2.3 Historical Topographic Map Review	
		4.4.2.4 Local Street Directories	
		4.4.2.5 Property Tax Files	
		4.4.2.6 Recorded Land Title Records	
		4.4.2.7 Building Department Records	
		4.4.2.8 Zoning and Land Use Records	
		4.4.2.9 Other Historical Records	
	15		
	4.5	Historical Use Information on Adjoining Properties	. 1 /
5.0	SITE	RECONNAISSANCE	.18
	5.1	Methodology and Limiting Conditions	
	5.2	General Site Setting	
	5.3	Exterior Observations	
	0.0	5.3.1 Property Description	
		5.3.2 Evidence of Polychlorinated Biphenyls (PCBs)	
		5.3.3 Stained Soil or Pavement	
		5.3.4 Distressed Vegetation	
		5.3.5 Solid Waste Disposal and/or Evidence of Dumping	
		5.3.6 Evidence of Pits, Ponds, Lagoons	
		5.3.7 Evidence of Wastewater	
		5.3.8 Evidence of Wells	
		5.3.9 Evidence of Septic Systems	
		5.3.10 Other Exterior Observations	
	5.4	Interior Observations	
	5.4 5.5		
	5.5	Off-Site Observations	
		5.5.1 Adjoining Properties	
		5.5.2 Other Surrounding Properties	. 19
6.0	INTE	RVIEWS	.20
	6.1	Overview	
	6.2	Interview with Owners	. 20
	6.3	Interview with Occupants	
	6.4	Interview with Local Government Officials.	
	6.5	Interviews with Others	
<b>न</b> 0	DIGG	1991 ON	<u> </u>
7.0		JSSION	
	7.1	Findings and Opinions	
		7.1.1 Recognized Environmental Conditions	
		7.1.2 Historical Recognized Environmental Conditions	
		7.1.3 De Minimis Conditions	
	7.2	Additional Investigation	. 21

Decen	nber 26,	2007 -iii-	073-91953
	7.3	Data Gaps	
8.0	CON	CLUSIONS	23
9.0	REFE	RENCES	24
10.0	-	LIFICATIONS AND SIGNATURES OF ENVIRONMENTAL ESSIONALS	25

IN ORDER FOLLOWING PAGE 25

# LIST OF TABLES

Table 1 - Summary of Facilities Identified in the Environmental Records Review

# LIST OF FIGURES

- Figure 1 Site Location Plan
- Figure 2 Site Plan
- Figure 3 Munger Map

# LIST OF APPENDICES

- Appendix A Legal Description of the Subject Property/Title Reports
- Appendix B Federal and State Regulatory Database Search
- Appendix C Historical Documentation
- Appendix D Photographs Recorded During the Subject Property Inspection
- Appendix E User Questionnaire
- Appendix F Resumes of Environmental Professionals
- Appendix G Agency Documentation

-1-

# **1.0 INTRODUCTION**

## 1.1 Purpose

Travelers (the User) retained Golder Associates Inc. (Golder) to perform a Phase I Environmental Site Assessment (ESA) of the 4.13 acre parking lot property located at the northeast corner of West 190<sup>th</sup> Street and Crenshaw Place in Torrance, California (the Site or subject property). The purpose of this Phase I ESA is to identify recognized environmental conditions (RECs) in connection with the subject property, to the extent feasible, pursuant to the processes prescribed in the ASTM Practice E 1527-05 entitled "Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process" (ASTM Standard), and the EPA Rule entitled, "Standards and Practices for All Appropriate Inquiries; Final Rule" (AAI Rule), 40 CFR Part 312, the Golder Proposal dated October 17, 2007 (the Proposal), and Golder's professional judgment. The Phase I ESA was conducted in conformance with these criteria.

The AAI Rule states that the ASTM Standard may be used to comply with the requirements of the AAI Rule, so whenever reference is made in this Report to the ASTM Standard, it shall include the AAI Rule.

The ASTM Standard defines RECs as "the presence or likely presence of any hazardous substances or petroleum products on a property under conditions that indicate an existing release, a past release, or a material threat of a release of any hazardous substances or petroleum products into structures on the property or into the ground, groundwater, or surface water of the property. The term includes hazardous substances or petroleum products even under conditions in compliance with laws."

## **1.2 Detailed Scope of Services**

The scope of services for this ESA consisted of the following tasks:

## Records Review

- Reviewed property information to confirm the legal description and location of the subject property. This information is included in Appendix A;
- Reviewed environmental record sources including federal and state regulatory databases to identify facilities with past or current regulatory enforcement actions within applicable distances of the subject property as defined in the ASTM Standard. The regulatory database search report is presented in Appendix B;
- Reviewed physical setting information sources to identify information about the geologic, hydrogeologic, hydrologic, and topographic conditions in the area of the subject property. The U.S. Geological Survey (USGS) 7.5-minute topographic map of the area of the subject property is shown on Figure 1;
- Reviewed historical record sources to identify past land use activities at the subject property and surrounding properties. Selected historical information obtained during performance of the Phase I ESA investigation is included in Appendix C.

## Site Reconnaissance

• Performing a visual inspection of the subject property and surrounding properties to identify potential sources of chemical and petroleum contamination such as aboveground

#### **Golder Associates**

storage tanks (ASTs), underground storage tanks (USTs), potential sources of polychlorinated biphenyls (PCBs), chemicals, and hazardous materials. Surficial evidence of potential RECs such as distressed vegetation, stained soils, and/or stained paving was also evaluated. Photographs recorded during the Site reconnaissance are included in Appendix D;

## Interviews

• Interviewing available individuals with knowledge of current or historical use, storage, or disposal of potentially hazardous materials or other environmentally related activities on or adjacent to the subject property. User provided information is included in Appendix E; and

#### Report Preparation

• Preparation of this report that documents the findings, opinions, and conclusions of the Phase I ESA investigation conducted at the subject property, and provides the supporting documentation and references for those findings, opinions, and conclusions (the Report). Resumes for the environmental professionals that conducted the investigation and prepared this Phase I ESA Report are included in Appendix F.

#### **1.3** Significant Assumptions

No significant assumptions were made in the preparation of this Phase I ESA.

## **1.4** Limitations and Exceptions

Golder's services were performed in accordance with the following principles, which are an integral part of the ASTM Standard: (i) No environmental site assessment can wholly eliminate uncertainty regarding the potential for RECs in connection with a property. Performance of this ESA is intended to reduce, but not eliminate, uncertainty regarding the potential for RECs in connection with the subject property, and the ASTM Standard recognizes reasonable limits of time and cost; and (ii) "all appropriate inquiry" does not mean an exhaustive assessment of a property. This ESA was performed in conformance with the ASTM Standard's principle of identifying a balance between the competing goals of limiting the costs and time demands inherent in performing an ESA and the reduction of uncertainty about unknown conditions resulting from additional information; and (iii) not every property warrants the same level of assessment. The appropriate level of assessment for this ESA was guided by the type of property subject to the assessment, the expertise and risk tolerance of the user, and the information developed in the course of the inquiry; and (iv) ESAs must be evaluated based on the reasonableness of judgments made at the time and under the circumstances in which they were made. Subsequent ESAs should not be considered valid standards to judge the appropriateness of any prior assessment based on hindsight, new information, use of developing technology or analytical techniques, or other factors.

## **1.5** Special Terms and Conditions

No special terms and conditions are applicable to this ESA.

## 1.6 User Reliance

Golder has prepared this Report at the request of the User for the sole purpose of use by the User in connection with the User's purpose as identified in Section 3.5. Use of the information contained in this Report by anyone other than User is permissible only with the prior written authorization to do so from Golder, and only under the conditions allowed by the ASTM Standard. Golder is not responsible for independent conclusions, opinions, or recommendations made by others or otherwise based on the findings presented in this Report.

# 2.0 **PROPERTY DESCRIPTION**

## 2.1 Location and Legal Description

The subject property is located at the northeast corner of West 190<sup>th</sup> Street and Crenshaw Place in the City of Torrance, Los Angeles County, California (Figure 1). Interstate 405 (the San Diego Freeway) is located approximately 0.25 miles northeast of the Site. Site access is provided from Crenshaw Place on the west and from the adjoining parking lot on the east. The existing land use consists of an approximately 179,950 square foot (4.13 acres) asphalt paved parking lot.

The subject property is located on the Torrance California 7.5 minute Series Topographic Map Quadrangle at an elevation of approximately 64 feet above mean sea level. The subject property is located at approximately 33°51′33.5″ north latitude and 118°19′33.2″ west longitude. A site location map has been provided as Figure 1. A Site and Surrounding Vicinity Plan is provided as Figure 2. A Munger Oil Map is provided as Figure 3. According to Los Angeles County Assessor's records, the Site Assessor's Parcel Numbers (APNs) are 4090-021-032 and 4090-021-033.

According to title records for the Site, the legal description for the subject property is as follows:

- Parcel # 4090-021-032: STRAWBERRY HOME TR S 325.18 FT MEASURED AT R/A TO S LINE EX OF ST OF LOT 25
- Parcel # 4090-021-033: STRAWBERRY HOME TR N 304.86 FT OF LOT 25

A more detailed legal description of the Site is provided in Appendix A.

## 2.2 Site and Vicinity General Characteristics

The subject property is currently developed as an asphalt parking lot. The rectangular shaped subject property comprises approximately 4.13 acres of land within an industrial and commercial area of Torrance. Main access to the Site is provided from Crenshaw Place on the west and an adjoining parking lot on the east.

The subject property is situated within a Heavy Industrial (I-HVY) zone of Torrance. Surrounding properties were originally developed primarily in the 1950s-1960s. The Exxon Mobil Refinery is located south of the Site across West 190<sup>th</sup> Street. The topography of the Site is relatively flat with a gradual, regional slope towards the southwest.

Figure 1 depicts the subject property in relation to the surrounding features. Figure 2 depicts the subject property with buildings and other details important to this study as well as the adjoining properties.

## 2.3 Current Use of the Subject Property

The subject property is currently used as a parking lot primarily for overflow parking for the surrounding businesses.

## 2.4 Descriptions of Structures, Roads, and Other Improvements on the Subject Property

The subject property is a paved parking lot. No buildings or structures exist on the subject property.

## 2.5 Current Use of the Adjoining Properties

The adjoining property uses are described below:

- North: The subject property is bound on the north by an industrial building with three tenants: Daltile (a ceramic and tile company); IMC (Interamerican Motor Corporation, which is an auto parts warehouse and shipping company); and Nankai Express (an international transportation company).
- East: The subject property is bound on the east by a paved parking lot for the industrial building (PC Mall) further east of the parking lot.
- South: The subject property is bound on the south by West 190<sup>th</sup> Street followed by an Exxon Mobil oil refinery.
- West: The subject property is bound on the west by Crenshaw Place followed by a commercial/industrial developed area.

# 3.0 USER PROVIDED INFORMATION

The ASTM Standard defines User as the party seeking to use Practice E 1527 to complete an ESA of the subject property. The ASTM Standard requires the User to provide certain information to the environmental professional. Golder provided a User Questionnaire to Travelers to facilitate the transfer of this information to Golder. Mr. Robert O'Leary completed the questionnaire for Travelers, the User. A copy of the questionnaire is included in Appendix E. Travelers indicated to Golder that the Phase I ESA was being performed as part of a broader due diligence evaluation associated with investment in the subject property.

## 3.1 Environmental Cleanup Liens

The User was asked about their knowledge of environmental cleanup liens that are filed or recorded under federal, tribal, state or local law against the subject property. Based on the responses to the User Questionnaire, Mr. O'Leary is not aware of environmental cleanup liens against the subject property.

## **3.2** Activity and Land Use Limitations

The User was asked about their knowledge of activity and land use limitations (AULs), such as *engineering controls*, land use restrictions or *institutional controls* that are in place on the Site or have that been filed or recorded in a registry under federal, tribal, state or local law. Based on the responses to the User Questionnaire, Mr. O'Leary has no knowledge of AULs for the subject property.

## **3.3** Specialized Knowledge

The User was asked about their specialized knowledge or experience related to the subject property or nearby properties.

Mr. O'Leary responded that Travelers is "not in the same line of business as the former owners of this parcel of land. [Travelers has] owned the adjacent office building since late 1997 and received a Phase I Environmental Assessment from the owner at that time."

## **3.4** Relationship of the Purchase Price to the Fair Market Value

The ASTM User Questionnaire requires the User to evaluate the relationship between the purchase price and the fair market value of the property if it were not contaminated.

Mr. O'Leary responded, "The purchase price for the land was set in an option agreement ten years ago. [Travelers believes] most experienced real estate professionals would consider the purchase price to be below its fair market value. The lower price is the result of the option agreement and not because of any known or potential contamination at the property."

## 3.5 Commonly Known or Reasonably Ascertainable Information

The User was asked if they were aware of commonly known or reasonably ascertainable information about the subject property that would help the environmental professional to identify conditions indicative of releases or threatened releases. The following questions were presented.

- a) Do you know the past uses of the property?
- b) Do you know of specific chemicals that are present or once were present at the property?
- c) Do you know of spills or other chemical releases that have taken place at the property?
- d) Do you know of any environmental cleanups that have taken place at the property?

Mr. O'Leary responded, "Any knowledge meeting this standard would be contained in the 1997 Phase I mentioned in Paragraph 3 or in current regulatory databases. The site is adjacent to a former manufacturing plant now owned by Honeywell. Honeywell has an environmental specialist on site, so [Travelers assumes] both chemical releases and clean ups have occurred in the past."

## **3.6** The Degree of Obviousness or the Presence of Contamination

The User was asked if, based on their knowledge and experience related to the *property*, are there any *obvious* indicators that point to the presence or likely presence of contamination at the *property*.

Mr. O'Leary responded "no. The property is currently utilized as a parking lot."

# 4.0 **RECORDS REVIEW**

## 4.1 Standard Environmental Record Sources, Federal and State

Golder retained Environmental Data Resources Inc. (EDR) of Milford, Connecticut to perform an environmental regulatory database search of the general area of the subject property, which is presented in Appendix B. In accordance with the search requirements of ASTM E-1527-05 Standard, the Federal and State regulatory agency records listed below were reviewed to identify the use, generation, storage, treatment or disposal of hazardous materials, or release incidents of such materials that might impact the subject property. A summary of significant listings in the environmental regulatory database report is presented in Table 1. The databases reviewed are listed below.

Database	Approximate Minimum Search Distance
Federal NPL (National Priorities List)	1.0 mile
Federal delisted NPL site list	0.5 mile
Federal Comprehensive Environmental	0.5 mile
Response, Compensation and Liability	
Information System (CERCLIS) site list	
Federal CERCLIS-No Further Remedial	0.5 mile
Action Planned (NFRAP) site list	
Federal Resource Conservation and	1.0 mile
Recovery Act (RCRA) CORRACTS	
(Corrective Action Report) facilities list	
Federal RCRA non-CORRACTS Treatment	0.5 mile
Storage and Disposal (TSD) facilities list	
Federal RCRA Generators list	Subject property and adjoining
	properties
Federal Institutional Control/Engineering	Subject property
Control Registries	
Federal Emergency Response Notification	Subject property
System (ERNS) list	

#### **Federal ASTM Standard Databases**

Database	Approximate Minimum Search Distance
State and tribal hazardous waste sites	1.0 mile
identified for investigation or remediation:	
NPL – equivalent sites	
State and tribal hazardous waste sites	0.5 mile
identified for investigation or remediation:	
CERCLIS – equivalent sites	
State and tribal landfill and/or solid waste	0.5 mile
disposal site list	
State and tribal leaking storage tank lists	0.5 mile
State and tribal registered storage tank lists	Subject property and adjoining
	properties
State and tribal Institutional	Subject property
Control/Engineering Control Registries	
State and tribal voluntary cleanup sites	0.5 mile
State and tribal Brownfield sites	0.5 mile

## 4.1.1 Subject Property Database Listing

The subject property was not listed on the databases included in the EDR report.

## 4.1.2 Off-Site Properties Database Listings

Three LUST/Cortese sites are located within <sup>1</sup>/<sub>4</sub> mile of the subject property; two maintain an open status and one maintains a closed status. One SLIC case is located within <sup>1</sup>/<sub>4</sub> mile of the subject property. The following is a summary of these off-site listed facilities.

Mobil Oil Refinery (EDR Site No.'s E29 and E30) is located at 3700 West 190<sup>th</sup> Street adjacent to the south (crossgradient) of the Site. This site is listed on the CHMIRS, TOXIC PITS, SLIC (Spills, Leaks, Investigation, and Cleanup list), EMI, HAZNET, RCRA-LQG, RCRA-TSDF, FINDS, TRIS, CORRACTS, CERC-NFRAP, FTTS, HIST FTTS, and ENVIROSTOR databases. The oil refinery is located to the southwest of the subject property while the refinery tank farm is located adjacent to the south of the subject property across West 190th Street. The site is listed on the CHMIRS database for multiple spills and releases caused by the following: pipe failure, overturned big rig, fuel gas treater malfunction, valve failure, compressor malfunction, and leaks on transfer pipeline. The site is listed on the EMI database for the following emissions: total organic hydrocarbon gases (1 ton/yr) and reactive organic gases (1 ton/yr) in 1990 and total organic hydrocarbon gases (47 tons/yr), reactive organic gases (24 tons/yr), carbon monoxide (1 ton/yr), and nitrogen oxides (3 tons/yr) in 2001. The SLIC database listing is for the release of PET and VOCs. According to the EDR report, remedial action is underway at the site. According to information on the State Water Resources Control Board online GeoTracker database (www.geotracker.waterboards.ca.gov), benzene is present on-site, but was non-detect in samples taken near the subject property. According to the Refinery Subsurface Cleanup Progress Report First Semester 2006, the concentrations of benzene, dissolved phase MTBE, and free-phase hydrocarbon product were low or non-detect from the samples taken near the subject property. Given the data and crossgradient location of the site, it is Golder's opinion that this site does not present an environmental concern for the subject property.

Texaco Service Station #0274 (EDR Site No.'s A2 and A3) is located at 18910 Crenshaw Boulevard, approximately 250 feet to the west (upgradient) of the Site. This site is listed on the LUST, CORTESE (Hazardous Waste and Substances Sites list), CA WDS, CHMIRS, CA FID UST, and SWEEPS UST databases. The site is listed on the CHMIRS database for a 25-gallon diesel release in 2000. A pump was used to clean up the substance and 5-gallons went to a drain. The facility maintains the following active underground storage tanks (USTs): three 12,000-gallon and two 10,000-gallon regular unleaded gasoline USTs; one 12,000-gallon diesel motor vehicle fuel regular UST; one 10,000-gallon leaded motor vehicle fuel UST; one 10,000-gallon diesel motor vehicle fuel UST; and one 550-gallon waste oil UST. The four 12,000-gallon USTs were reportedly installed in 1979. A leaking diesel UST that affected groundwater was discovered on May 1, 1990. In 1991, soil borings and groundwater monitoring wells were installed. Ouarterly monitoring has been conducted since the installation of the monitoring wells. A vapor extraction system completed in 1996 and free product recovery has been in process since 1999. Additional remedial activities consist of using a vacuum tank and stinger assembly from 2002 to 2004. According to the Third Quarter 2007 Groundwater Monitoring Report found on the GeoTracker database, an on-site well. approximately 200 feet to the west (upgradient) from the subject property, contained elevated concentrations of TPHg, Benzene, MTBE, and TBA at 27,000 µg/L, 210 µg/L, 740 µg/L, and 19,000 µg/L, respectively. No wells are located further downgradient between the Texaco Service Station and the subject property. It is Golder's opinion that this site presents a potential environmental concern for the subject property given the distance, upgradient nature, and lack of downgradient groundwater data.

**Mobil Service Station #11/18-ECP** (EDR Site No.'s B9, B10, B11, and B12) is located at 19009 Crenshaw Boulevard approximately 650 feet southwest (crossgradient) of the Site. This site is listed on the UST, CA FID UST, SWEEPS UST, LUST, CORTESE and CHMIRS databases. The facility maintains the following active underground storage tanks (USTs): one 12,000-gallon, one 10,000gallon, one 6,000-gallon, one 8,000-gallon, and one 9,940-gallon regular unleaded gasoline USTs; one 6,000-gallon and one 8,000-gallon diesel fuel USTs; and one 280-gallon waste oil UST. A leaking gasoline UST that affected groundwater was discovered on April 8, 1987. Groundwater monitoring has been conducted at the site since fourth quarter 1992. The case maintains an open status and current remedial activities include converting to a liquid phase hydrocarbon (LPH) recovery system by installing LPH skimmers during the second quarter 2007 monitoring. The most recent groundwater samples dated April and October 2007 show detectable levels of benzene, toluene, ethylbenzene, MTBE, TBA, xylenes, and TPHg. Given the distance and crossgradient location of the site, it is Golder's opinion that the site is does not present and environmental concern for the subject property.

**Honeywell (Site A)** (EDR Site No. C21, C22, and 24) is located at 2525 West 190<sup>th</sup> Street, approximately 650 feet to the east (downgradient). This site is listed on the SLIC, RCRA-LQG, FINDS, TRIS, HAZNET, CERC-NFRAP, HIST UST, EMI, and NY MANIFEST databases. Honeywell assembles industrial turbo generators, conducts degreasing operations, and contains a machine shop, electronics laboratory, and a ceramics manufacturing facility. The site has been reportedly impacted by a release of chlorinated hydrocarbons. As of December 2006, soil and groundwater beneath the site are impacted with VOCs including 1,1,1-trichloroethane (1,1,1-TCA), tetrachloroethene (PCE), 1,1-dichloroethene (1,1-DCE), and *cis* 1,2-dichloroethene (*cis* 1,2-DCE) and with lesser amounts of trichloroethene (TCE), 1,1-dichloroethane (1,1-DCA), vinyl chloride, chlorofluorocarbons (Freon 11, Freon 113), and benzene, toluene, ethylbenzene, and xylenes (BTEX). Groundwater assessment is ongoing and the on-site buildings have been equipped with soil vapor barriers and passive ventilation systems. No soil or groundwater remediation has reportedly been conducted to date. Given the distance and downgradient location of the site, it is Golder's opinion that this site does not present an environmental concern for the subject property.

Allied Signal Inc (Site A) (EDR Site No. C18 and C19) was formerly located at 2525 West 190<sup>th</sup> Street, approximately 650 feet to the east (downgradient) of the Site. This site is listed on the LUST, CORTESE, CA FID UST, SWEEPS UST, UST and EMI databases. Allied Signal manufactured printed circuit boards. The site is listed on the LUST database for a leaking gasoline UST that affected soil only on December 13, 1993. The case was closed on July 22, 1997. The site is listed on the UST database for having 25 USTs as follows: (three 1,000-gallon and one 10,000-gallon jet fuel USTs; one 3,000-gallon, one 1,000-gallon and three 500-gallon aviation gas USTs; one 12,000-gallon, one 15,000-gallon, one 5,000-gallon, two 10,000-gallon, two 25,000-gallon, and two 30,000-gallon diesel fuel USTs; two 1,000-gallon and two 10,000-gallon regular unleaded gasoline USTs; one 4,000-gallon and one 280-gallon waste oil UST; and one 12,000-gallon leaded gasoline UST. Given the distance and downgradient location of the site, it is Golder's opinion that this site does not present an environmental concern for the subject property.

A summary of the off-site facilities identified in the database obtained from EDR is provided in Table 1 (located with the Appendices).

## 4.2 Additional Environmental Record Sources

Additional environmental record sources were reviewed or queried to supplement the Federal and State standard environmental record sources. These sources included a file search at the County of Los Angeles Certified Unified Program Agency/Public Health Investigation Unit, County of Los Angeles Fire Department, Department of Toxic Substances Control, Los Angeles Regional Water Quality Control Board, and the South Coast Air Quality Management District.

## 4.2.1 <u>County of Los Angeles Certified Unified Program Agency/Public Health Investigation</u> (CUPA/PHI)

Golder contacted the County of Los Angeles Certified Unified Program Agency/Public Health Investigation (CUPA/PHI) on October 15, 2007 regarding the availability of hazardous material, waste generator permits, California ARP, spills, and/or site remediation information for the subject property. LA PHI is the CUPA (Certified Unified Program Agency) for hazardous material files in Los Angeles County. A CUPA is a local agency that has been certified by the California EPA to implement the six state environmental programs within the local agency's jurisdiction. Golder received a response on October 23, 2007 indicating that no files could be found for the Site without a specific address.

## 4.2.2 <u>County of Los Angeles Fire Department (LAFD)</u>

Golder contacted LAFD on October 12, 2007 regarding the availability of files for the subject property. Golder received a response on October 15, 2007 indicating that there were no records on file for the subject property.

## 4.2.3 Department of Toxic Substances Control (DTSC)

Golder sent a request to review records to the DTSC regional offices in Cypress and Glendale, California on October 12, 2007. The DTSC-Cypress and Glendale offices responded on October 16, 2007 and October 19, 2007, respectively, that no records were found for the subject property.

## 4.2.4 Los Angeles Regional Water Quality Control Board (LARWQCB)

Golder sent a request to the LARWQCB (UST, SLIC, WIP, NPDES, and WDR Sections) regarding the availability of files for the subject property address on October 12, 2007. The UST Section

responded on October 15, 2007 that no records were found for the subject property. The SLIC Section responded on October 16, 2007 that no records were found for the subject property. The NPDES and WDR Sections responded on October 17, 2007 that no records were found for the subject property. The WIP Section responded on October 23, 2007 and indicated that there are no records were found for the subject property.

## 4.2.5 South Coast Air Quality Management District (SCAQMD)

Golder reviewed the SCAQMD FIND database for air permit records pertaining to the subject property. No records were found for the subject property.

## 4.2.6 <u>Previous Environmental Assessments</u>

Travelers provided Golder with a copy of a previous environmental assessment report. The following is a summary of the previous report:

• Phase I Environmental Site Assessment for the Building 38, Allied Signal, Aerospace Campus, 2525 West 190<sup>th</sup> Street, Torrance, California dated June 18, 1997 and prepared by Professional Service Industries (PSI). This report was prepared for a property located adjacent to the east of the eastern adjacent parking lot. The property consists of a three-story office building. No hazardous materials, aboveground storage tanks, or underground storage tanks were observed during the site reconnaissance. PSI concluded that there was no evidence of RECs on the site and concluded that no further assessment was necessary.

This report did not discuss the subject property other than referencing that to the west of the 2525 West 190<sup>th</sup> Street site was a parking lot.

## 4.3 Physical Setting Sources

## 4.3.1 <u>Sources Reviewed</u>

The following physical setting sources were reviewed:

- Department of Water Resources (DWR), *California's Groundwater Bulletin 118, Update 2003, South Coast Hydrologic Region, Coastal Plain of Los Angeles Groundwater Basin, 2003.*
- DWR, California's Groundwater Bulletin 118, South Coast Hydrologic Region, Coastal Plain of Los Angeles Groundwater Basin, updated February 27, 2004.
- Environmental Data Resources (EDR), *The EDR Radius Map with GeoCheck*<sup>®</sup>, *Parking Lot (Lot 25), 2500 Block West 190<sup>th</sup> Street, Torrance, CA 90504*, dated October 15, 2007.

## 4.3.2 General Topographic Setting of the Area

According to the Torrance Creek 7.5-Minute Topographic Quadrangle provided by EDR (1981), the subject property is located at approximately 64 feet above mean sea level (msl). The topographic gradient slopes to the southwest in the immediate vicinity of the subject property.

## 4.3.3 <u>Geologic and Hydrogeologic Setting</u>

The subject property is located in the southwestern quadrant of the Torrance Plain in the West Coast Basin. The Torrance Plain is a broad alluvial plain composed of clay, silt, and sand. The subject

#### **Golder Associates**

property is underlain by marine and continental sediments of the Lakewood Formation of Upper Pleistocene age.

Groundwater monitoring data indicates that the direction of groundwater flow is to the east-southeast.

The subject property lies within the West Coast Groundwater Basin which includes the Lakewood and San Pedro formations. Regional groundwater depth has been reported by the County of Los Angeles Department of Public Works for public wells within approximately 0.50 miles of the subject property at depths of approximately 110 feet below ground surface. Groundwater wells within approximately two miles of the subject property indicate the presence of a perched aquifer at a depth of approximately 35 to 40 feet bgs.

No surface water was observed in the vicinity of the subject property.

## 4.4 Historical Use Information on the Subject Property

## 4.4.1 <u>Subject Property Historical Use Summary</u>

Information regarding the history of the Site was obtained by reviewing historical aerial photographs, historical topographic maps, and city directories from EDR of Milford, Connecticut. The Site appears to have been agriculturally developed prior to the 1960s. The Site has been used as a parking lot since approximately 1965 to the present day.

## 4.4.2 <u>Standard Historical Records</u>

## 4.4.2.1 Aerial Photographs Review

Historical aerial photographs were obtained from Environmental Data Resources, Inc. (EDR) for the years 1928, 1938, 1947, 1956, 1965, 1976, 1990, 1994, and 2002 and were reproduced at scales of 1" = 500', 555', 666', 400', 666', 666', 666', 666', and 666', respectively. Copies of the historical aerial photographs are provided in Appendix C. The following discussion summarizes observations from the review of these aerial photographs:

- <u>1928</u>: The quality of the aerial photograph is poor and no significant features can be depicted on the subject property. The Site and surrounding area appears to be undeveloped or agriculturally developed. A road is present in the current location of West 190<sup>th</sup> Street.
- <u>1938</u>: The subject property appears to be agriculturally developed. The surrounding areas to the north, east and west appear to be agriculturally developed. A road is present in the current location of Crenshaw Place adjacent to the west of the Site. Five small structures, possibly oil wells, are present on the agriculturally developed property adjacent to the south of the Site across West 190<sup>th</sup> Street. A tank farm and a large impoundment of unknown use, which appears to be associated with the tank farm, are located further to the south and southeast, respectively.
- <u>1947</u>: The subject property and adjacent properties appear to be agriculturally developed. The possible oil wells present in the 1938 aerial photograph are no longer visible/present. Multiple structures, possible greenhouses, are located approximately 832 feet north of the subject property. There is increased development of the oil refinery property to the south of the Site and a second large impoundment of unknown use appears to be forming.

- <u>1956</u>: The subject property appears agriculturally developed. A school has been developed adjacent to the north of the subject property. The school yard bounds the Site on the north. Property to the east is agriculturally developed. The area adjacent to the south of the Site is undeveloped. Adjacent to the west is Crenshaw Place followed by undeveloped land and now developed Crenshaw Boulevard. Beyond Crenshaw Boulevard to the west and northwest is a residentially developed area.
- <u>1965</u>: The subject property is a paved parking lot. The potential greenhouse structures to the north have been removed and the area appears to be undeveloped. The school yard remains present adjacent to the north. The area adjacent to the east is developed as a parking lot followed by an industrial facility. The area adjacent to the west between Crenshaw Place and Crenshaw Boulevard is commercially developed. The area to the west and northwest beyond Crenshaw Boulevard appears unchanged (i.e. dense residential development). The area adjacent to the south beyond West 190<sup>th</sup> Street appears undeveloped with increased development of the refinery located further to the southwest. The two large impoundments of unknown use on the southern oil refinery property remain to the southeast of the Site.
- <u>1976</u>: The subject property appears unchanged from the 1965 aerial photograph. The property adjacent to the north (former school property) has been redeveloped with two large industrial buildings, which appear similar to their present day configuration. The area to the east remains as parking lots followed by an industrial area. There is increased development on the oil refinery property to the south. The area to the west of the Site appears relatively unchanged from the 1965 aerial photograph.
- <u>1990</u>: The subject property appears generally unchanged from the 1965 and 1976 aerial photographs. The surrounding areas appear similar to the 1976 aerial photograph with the exception of an additional industrial building to the east beyond the adjacent parking lot, additional development of the oil refinery to the south, and the removal of the second (western) large oil refinery impoundment.
- <u>1994</u>: The subject property and surrounding areas appear similar to the 1990 aerial photograph with the exception of increased development of the oil refinery to the south.
- <u>2002</u>: The subject property and surrounding areas appear similar to the 1990 aerial photograph and as they do today.

## 4.4.2.2 Sanborn<sup>©</sup> Fire Insurance Map Review

According to EDR, there is no Sanborn Fire Insurance Map coverage for the subject property. EDR maintains the largest and most comprehensive collection of Sanborn Fire Insurance Maps. The "No Coverage" page is included in Appendix C of this report.

## 4.4.2.3 Historical Topographic Map Review

Historical USGS topographic quadrangle maps were obtained through EDR for the years 1896, 1901, 1924, 1934, 1948, 1951, 1964, 1972, and 1981 were produced at a scale of 1:62,500, 1:250,000, 1:24,000, 1:24,000, 1:24,000, 1:24,000, 1:24,000, and 1:24,000, respectively. Copies of the historical topographic maps are provided in Appendix C. The following paragraphs summarize our observations from the review of these historical topographic maps.

• <u>1896</u>: The map scale is not adequate to provide a detailed review of subject property features.

- <u>1901</u>: The map scale is not adequate to provide a detailed review of subject property features.
- <u>1924</u>: No structures are shown on the subject property. A dirt road is present adjacent to the north of the subject property. Two structures are present to the northeast and one structure is present adjacent to the east. A road is present adjacent to the south of the subject property in the current location of West 190<sup>th</sup> Street. Beyond West 190<sup>th</sup> Street are four structures; two to the southeast and two to the south. A road is present adjacent to the west of the subject property in the current location of Crenshaw Place.
- <u>1934</u>: The subject property and adjacent properties appear undeveloped. The structures previously located to the northeast, east and south of the Site are no longer present. A large impoundment which appears to contain water is located approximately 0.25 miles southeast of the subject property. A General Petroleum tank farm is located approximately 0.5 miles south of the subject property. An electric sub-station is located approximately 0.65 miles to the northwest of the subject property.
- <u>1948</u>: The subject property and adjacent properties appear undeveloped. The road located adjacent to the north in the 1934 topographic map is no longer present. Multiple structures are located further to the north along Perry Street. Oil wells are located approximately 0.6 miles to the southwest of the subject property.
- <u>1951</u>: The subject property appears undeveloped. Crenshaw Boulevard School is present to the north of the subject property. The area to the east of the subject property appears to be undeveloped. The oil refinery to the southwest and tank farms to the south and southwest beyond 190<sup>th</sup> Street are present. To the southeast of the subject property is a second large impoundment of unknown use that is associated with the oil refinery. Crenshaw Place is located adjacent to the west in its present day location. The area between Crenshaw Place and Crenshaw Boulevard is undeveloped. The area to the west and northwest beyond Crenshaw Boulevard is developed as a residential area.
- <u>1964</u>: No structures appear on the subject property. Crenshaw School is located to the north of the subject property. No structures are located adjacent to the east of the subject property. An industrial building and a ball park are located further to the east of the subject property. A second large impoundment is present to the southwest for the Site across 190<sup>th</sup> Street. The area adjacent to the west beyond Crenshaw Place has four structures which appear to be commercial buildings. The area to the west and northwest beyond Crenshaw Boulevard shows increased residential development. The San Diego (405) Freeway has been constructed approximately 0.25 miles to the north of the subject property.
- <u>1972</u>: No structures appear to be present on the subject property. The surrounding areas appear similar to the 1964 topographic map with the exception of increased commercial/industrial develop to the east, northeast, and west, across Crenshaw Place.
- <u>1981</u>: No structures are present on the subject property. Crenshaw School is no longer present. Adjacent to the north are three industrial buildings in their present day locations and additional industrial buildings to the northeast. Additional buildings have been developed adjacent to the west. The areas to the east and south appear similar to the 1972 topographic map.

## 4.4.2.4 Local Street Directories

Business directories including city, cross reference, and telephone directories were reviewed by EDR at one to four year intervals for the years spanning 1975 to 2006. A summary of the information was

compiled by EDR in a City Directory Abstract. A copy of the EDR City Directory Abstract is provided in Appendix C.

No address is known to be associated with the Subject Property. The subject property does not appear listed in the City Directories Abstract.

## 4.4.2.5 Property Tax Files

According to the Los Angeles County Office of the Assessor, the subject property assessor's parcel numbers are 4090-021-032 and 4090-021-33.

The subject property parcel information is included in Appendix A.

## 4.4.2.6 *Recorded Land Title Records*

Golder ordered an environmental lien search from EDR. According to the lien search document, no environmental liens were indicated in the title records reviewed.

A summary of the information provided in the Lien Search report is presented in the following table:

Date	Type of Document	Grantors/Grantees
1958	Grant Deed 10-16-1958	Grantor: Jack Toshiki Sakioka and Johnny Katsui Sakioka
		Grantee: The Garrett Corporation
1989	Certificate of Merger 02-09-1989	Grantor: The Garrett Corporation Grantee: Allied Signal, Inc.

## 4.4.2.7 Building Department Records

According to the City of Torrance Building Department, no building permits are on record for the subject property.

## 4.4.2.8 Zoning and Land Use Records

According to the City of Torrance General Plan map, the subject property is zoned as Heavy Industrial (I-HVY).

## 4.4.2.9 Other Historical Records

Additional environmental record sources were reviewed or queried to supplement the Federal and State standard environmental record sources. These sources included a file search at the County of Los Angeles Certified Unified Program Agency/Public Health Investigation, County of Los Angeles Fire Department, Department of Toxic Substances Control, Los Angeles Regional Water Quality Control Board, and the South Coast Air Quality Management District. Records from these sources were previously discussed in Section 4.2.

The Munger Map Book for California-Alaska Oil and Gas Fields (August 2003) provides data on wells from the California Department of Conservation, Division of Oil and Gas, oil operators, Munger oilogram, and other sources. According to the Munger Map Book (page W-63), no oil or gas wells were identified on the subject property or adjacent properties. The STD. NO. Torrance Core Hole is located approximately 1,500 feet southwest and the Imp. Gypsum McDonnell oil well is

located approximately 1,500 feet northeast of the subject property. A copy of the Munger Map page is included as Figure 3.

## 4.5 Historical Use Information on Adjoining Properties

Based on information obtained from a review of historical topographic maps, aerial photographs, and city directories, the adjoining properties to the north, east and west were used for agricultural purposes until the 1950's. The area adjacent to the west was developed by the mid 1960's as a commercial area and developed as a residential area beyond Crenshaw Boulevard in the mid 1950's. The area to the north was industrially developed by the mid 1950's. The area to the east was industrially developed by the mid 1960's. The area to the south has been an oil refinery since the late 1920's.

## 5.0 SITE RECONNAISSANCE

A visual inspection of the subject property was performed by Ms. Kristina Byrne of Golder Associates Inc. on October 19, 2007 to identify potential sources of chemical and petroleum contamination such as ASTs, USTs, and potential sources of PCBs, chemicals, and hazardous materials. Surficial evidence of potential recognized environmental conditions such as waste or refuse dumping, distressed vegetation, stained soils, and/or stained paving was also evaluated. Photographs recorded during the Site assessment are presented in Appendix D.

## 5.1 Methodology and Limiting Conditions

Golder visually inspected the subject property beginning with a walk starting from the northern portion of the Site then moving south. The Site perimeter and surrounding Site areas were subsequently walked. Surrounding properties were reviewed by walking the surrounding commercial and industrial areas and streets.

## 5.2 General Site Setting

The subject property is located in an area of Torrance developed with industrial, commercial and residential properties. The Site is currently used as overflow parking by the surrounding commercial/industrial facilities.

## 5.3 Exterior Observations

## 5.3.1 <u>Property Description</u>

The subject property consists of a deteriorated asphalt parking lot with a perimeter fence and landscaping along the northern, western and southern boundary. An access road to the Site and eastern parking lot bisects the property from the west entrance to the east.

Golder did not observe evidence of current or former underground storage tanks (USTs) or aboveground storage tanks (ASTs) during the Site visit. Multiple patches were observed on the subject property during the Site reconnaissance and appear as general repairs to the asphalt.

## 5.3.2 Evidence of Polychlorinated Biphenyls (PCBs)

Golder did not observe any PCB containing materials currently or historically on Site.

## 5.3.3 <u>Stained Soil or Pavement</u>

De minimis oil staining from automobiles was observed on the subject property.

## 5.3.4 Distressed Vegetation

No distressed vegetation was observed on the subject property.

## 5.3.5 Solid Waste Disposal and/or Evidence of Dumping

Golder did not identify evidence of current or historic solid waste disposal activities on the subject property.

#### 5.3.6 Evidence of Pits, Ponds, Lagoons

No evidence of pits, ponds, or lagoons was observed on the subject property during the Site reconnaissance.

#### 5.3.7 Evidence of Wastewater

No evidence of current or former process wastewater generation was observed on the subject property during the Site reconnaissance.

#### 5.3.8 Evidence of Wells

No evidence of wells was observed on the subject property during the Site reconnaissance.

#### 5.3.9 Evidence of Septic Systems

No evidence of septic systems was observed on the subject property.

#### 5.3.10 Other Exterior Observations

The northern section and approximately one-third of the southern section of the parking lot are in poor condition with numerous cracks, patches and uneven areas. The rest of the subject property consisting of two-thirds of the southern section and the access road are in a slightly better condition. Numerous asphalt patches were observed on the subject property, mostly in the northern section.

A row of circular asphalt patches was observed just north of the access road from the eastern boundary to approximately halfway to the western boundary. Adjacent to the south along these patches was a concrete strip that appeared to be present by the 1990 aerial photograph and extended from the eastern boundary to halfway to the western boundary. The origin of the patches and concrete strip is unknown.

## 5.4 Interior Observations

There were no buildings or structures located on-Site (i.e., no interior areas exist on-Site).

## 5.5 Off-Site Observations

## 5.5.1 <u>Adjoining Properties</u>

Adjoining properties are commercially/industrially developed to the north, east, south, and west. The multiple commercial/industrial buildings adjacent to the west contain a mixture of restaurants, service facilities, automobile repair shops, offices, and a furniture store. The area to the south beyond 190<sup>th</sup> Street is developed as an oil refinery and tank farm. Golder did not observe any RECs or environmental concerns on adjoining properties.

## 5.5.2 Other Surrounding Properties

Surrounding properties are primarily commercially and industrially developed with residential developments located to the west and northwest of the Site beyond Crenshaw Boulevard.

## 6.0 INTERVIEWS

## 6.1 Overview

The purpose of interviews with past and present owners and occupants is to obtain information indicating RECs in connection with the subject property. Information obtained through these interviews is discussed here and in relevant sections of this Report.

## 6.2 Interview with Owners

Golder contacted the Site owner (Honeywell) for information on the subject property. According to Honeywell, the Site has been developed and used as a parking lot since the late 1950's or early 1960's. The Site was reportedly owned by Garrett Research since the late 1950's. Garrett Research was reportedly purchased by/merged with Allied Signal who later merged with Honeywell who owns the Site today.

## 6.3 Interview with Occupants

No occupants are located on-Site and therefore no occupant interviews were conducted by Golder.

## 6.4 Interview with Local Government Officials

Refer to Section 4.2 for interviews conducted with local government officials.

## 6.5 Interviews with Others

No other individuals were interviewed as part of this Phase I ESA.

## 7.0 **DISCUSSION**

This section identifies the known or suspect RECs, historical RECs, and de minimis conditions identified during the assessment.

## 7.1 Findings and Opinions

This section identifies findings, which includes known or suspect RECs, historical RECs, and *de minimis* conditions identified during the assessment.

## 7.1.1 <u>Recognized Environmental Conditions</u>

Golder did not identify Recognized Environmental Conditions (RECs) in connection with the subject property. However, the following off-site REC was identified, which presents a potential environmental concern for the subject property:

FINDING: Texaco Service Station #0274 is located approximately 200 feet west (upgradient) of the subject property. A leaking diesel UST that affected groundwater was discovered on May 1, 1990. The analytical results from an on-site monitoring well sample collected on July 5, 2007 indicated that groundwater is impacted with elevated concentrations of TPHg, Benzene, MTBE, and TBA. The extent of downgradient groundwater impacts does not appear to be characterized. No additional groundwater data was found for groundwater between the Texaco Service Station and the subject property.

OPINION: It is Golder's opinion that this site presents a potential environmental concern for the subject property given the distance, upgradient nature, and lack of downgradient groundwater quality data.

## 7.1.2 <u>Historical Recognized Environmental Conditions</u>

Golder did not identify potential Historical Recognized Environmental Conditions (HRECs) in connection with the subject property.

## 7.1.3 <u>De Minimis Conditions</u>

The following de minimis conditions were identified at the Site:

- FINDING: Minor oil staining was observed on the paved parking lot likely caused from parked cars on the subject property.
- OPINION: It is Golder's opinion that the oil staining is a de minimis condition, because it does not present a threat to human health or the environment, and generally would not be the subject of enforcement action if it was brought to the attention of the regulatory authorities.

## 7.2 Additional Investigation

No additional investigation is recommended based on the information gathered during this Phase I ESA.

# 7.3 Data Gaps

Data gaps are defined as the lack or inability to obtain information required by the ASTM standard despite good faith efforts by the environmental professional to gather such information. No significant data gaps were identified during this assessment.

# 8.0 CONCLUSIONS

Golder has performed a Phase I ESA of the property located at the northeast corner of West 190<sup>th</sup> Street and Crenshaw Place in Torrance, California in conformance with the scope and limitations of the ASTM Standard. Any exceptions to, or deletions from, the ASTM Standard are described in the appropriate sections of this report.

This assessment has revealed no RECs in connection with the subject property.

# 9.0 **REFERENCES**

The published reference sources relied upon in preparing the Phase I ESA were annotated in the relevant sections of this Report.

# 10.0 QUALIFICATIONS AND SIGNATURES OF ENVIRONMENTAL PROFESSIONALS

Kristina Byrne, an environmental Engineer, conducted the Site visit and prepared this Report. Misty Vazquez, Senior Project Environmental Engineer with over eight years of professional experience provided project oversight and reviewed this report. Ms. Jane Mills, a senior engineer with over 20 years of professional experience, served as the Quality Assurance/Quality Control (QA/QC) reviewer of the Report. Resumes for members of the project team are included in Appendix F.

"We declare that, to the best of our professional knowledge and belief, we meet the definition of Environmental Professional as defined in Section 312.10 of 40 CFR Part 312.

We have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the subject property. We have developed and performed the all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312."

## GOLDER ASSOCIATES INC.

MPA

Kristina Byrne Environmental Engineer

rist M. B

Misty Vazquez Senior Project Environmental Engineer

June P. Mills, CSP, CHMM Principal, Senior Engineer

TABLE

Facility Name	Database	EDR ID #	Distance (miles)/ Direction From Site	Location Relative to Inferred Groundwater Flow Direction	Comments	Classification
Pelican Hi Performance 18905 Crenshaw Place Torrance, Ca 90504	RCRA-SQG, FINDS	1	Adjacent west	Upgradient	No violations reported.	Low
	LUST, CORTESE		<1/8 miles west	Upgradient	A leaking diesel UST that affected groundwater was discovered on May 1, 1990. The case is currently active and remedial action is underway.	See Section 4.1.2
Texaco Service	CA WDS	A2, - A3			Listed as active.	
Station 18910 Crenshaw	CHMIRS				Listed for a diesel spill of approximately 25 gallons dated of July 19, 2000. No reported completion date. It was cleaned up and approximately 5 gallons went to a drain.	
Boulevard Torrance, Ca 90504	CA FID UST, SWEEPS UST				Listed for having nine active UST's (three 12,000-gallon regular unleaded motor vehicle fuel, one 12,000-gallon diesel motor vehicle fuel, two 10,000-gallon regular unleaded motor vehicle fuel, one 10,000-gallon leaded motor vehicle fuel, one 10,000-gallon diesel motor vehicle fuel, and one 550-gallon waste oil).	
Shell Station #121744 18910 Crenshaw Boulevard Torrance, Ca 90504	UST	4	<1/8 miles west	Upgradient	Listed as active.	Low
Sakura Finetek USA Inc 18700 Crenshaw Boulevard Torrance, Ca 90504	RCRA-SQG, FINDS	5	<1/8 miles north	Crossgradient	No violations reported.	Low

Facility Name	Database	EDR ID #	Distance (miles)/ Direction From Site	Location Relative to Inferred Groundwater Flow Direction	Comments	Classification
Site A 2545 West 190th Street Torrance, Ca 90504	RCRA-LQG, FINDS HAZNET	6	<1/8 miles east	Downgradient	No violations reported. Listed for the disposal of contaminated soil from site clean-ups through a transfer station and land fill and aqueous solution with less than 10% total organic residues through a recycler and unknown means.	Low
Low Quaker State Minit- Lube Inc 3209 West 190th Street Torrance, Ca 90504	CA FID UST, SWEEPS UST RCRA-SQG HAZNET	B7, B8	<1/8 miles west	Crossgradient	Listed as having an active 5790-gallon oil UST. No violations reported. Listed for the disposal of unspecified oil-containing waste through a recycler.	Low
Mobil Service Station #11/18- ECP 19009 Crenshaw Boulevard Torrance, Ca 90504	UST, CA FID UST, SWEEPS UST LUST, CORTESE CHMIRS	B9, B10, B11, B12	<1/8 miles west	Crossgradient	Listed as having eight active UST's (one 12,000-gallon, one 10,000- gallon, one 6,000-gallon, one 8,000-gallon, and one 9,940-gallon regular unleaded motor vehicle fuel, one 6,000 and 8,000-gallon diesel motor vehicle fuel, and one 280-gallon waste oil). A leaking gasoline UST that affected groundwater was discovered on April 8, 1987. Case is still active. Listed for a gasoline incident dated August 24, 2005. No completion date reported.	See Section 4.1.2
S. Sung 19009 Crenshaw Boulevard Torrance, Ca 90504	HAZNET HIST UST	B13	<1/8 miles west	Crossgradient	Listed for the disposal of organic solids through a transfer station and unspecified oil-containing waste and aqueous solution with 10% or more total organic residues through a treatment tank. Listed for having four historic UST's (one 280-gallon waste oil, one 6,000-gallon regular product, one 8,000-gallon premium product, and one 10,000-gallon unleaded product.	Low

Facility Name	Database	EDR ID #	Distance (miles)/ Direction From Site	Location Relative to Inferred Groundwater Flow Direction	Comments	Classification
Takane USA Inc.	RCRA-SQG, FINDS			Crossgradient	No violations reported.	Low
18640 Crenshaw Boulevard Torrance, Ca 90504	HAZNET	14	<1/8 miles north		Listed for the disposal of unspecified solvent mixture waste through a transfer station.	
Mohawk Service Station #04067 18910 Crenshaw Torrance, Ca 90504	HIST UST	B15	1/8 - 1/4 miles north	Crossgradient	Listed for having four historical USTs (12,000-gallon unleaded product, 12,000-gallon regular product, 12,000-gallon premium product, and 12,000-gallon diesel product).	Low
Mcgee's Service Mobil Products 2701 West 190th Street Redondo Beach, Ca 90277	EDR HISTORICAL STATIONS	16	1/8 - 1/4 miles east	Downgradient	Listed as a historical service station in 1963.	Low
George P Johnson Co. 18500	HAZNET	17			Listed for the disposal of an unknown waste through a transfer station, other organic solids through a transfer station and unknown method, unspecified solvent mixture waste through a recycler and latex waste through an unknown method.	Low
18500 Crenshaw	CLEANERS		1/8 - 1/4 miles north	Crossgradient	Listed as a dry cleaning and laundry service in 1999.	
Boulevard Torrance, Ca 90504	EMI	17		crossgrautent	Listed for the emission of total organic hydrocarbon gases (1 ton/yr) and reactive organic gases (1 ton/yr) in 2002 and 2003, total organic hydrocarbon gases (1.1699 ton/yr) and reactive organic gases (1.06 ton/yr) in 2004, and total organic hydrocarbon gases (1.0141 ton/yr) and reactive organic gases (.9293 ton/yr) in 2005.	

Facility Name	Database	EDR ID #	Distance (miles)/ Direction From Site	Location Relative to Inferred Groundwater Flow Direction	Comments	Classification		
	LUST, CORTESE				A leaking gasoline UST that affected soil only was discovered on December 13, 1993. Case closed on July 22, 1997.			
Allied Signal Inc (Site A) 2525 190th Street West Torrance, Ca 90504	CA FID UST, SWEEPS UST, UST	C18, C19	<1/8 miles east- northeast	Downgradient	Listed as having 25 USTs (three 1,000-gallon and one 10,000-gallon jet fuel, one 3,000-gallon, one 1,000-gallon and three 500-gallon aviation gas, one 12.000-gallon, one 15,000-gallon, one 5,000-gallon, two 10,000-gallon, two 25,000-gallon, and two 30,000-gallon diesel fuel, two 1,000-gallon and two 10,000-gallon regular unleaded motor vehicle fuel, one 4,000-gallon and one 280-gallon waste oil, and one 12,000-gallon leaded motor vehicle fuel.	See Section 4.1.2		
	EMI		normeast		Listed for the emission of total organic hydrocarbon gases (2 tons/yr), nitrogen oxides (1 ton/yr), particulate matter (2 tons/yr), and particulate matter 10 micrometers and smaller (1 ton/yr) in 1990, total organic hydrocarbon gases (2 tons/yr), reactive organic gases (2 tons/yr), particulate matter (2 tons/yr), and particulate matter 10 micrometers and smaller (1 ton/yr) in 1990, total organic hydrocarbon gases (2 tons/yr), and particulate matter 10 micrometers and smaller (1 ton/yr) in 1990, total organic hydrocarbon gases (2 tons/yr) and reactive organic gases (2 tons/yr) in 1990.			
Garret	SLIC				Listed with a facility status of pollution characterization.			
Airesearch 2525 West 190th Street Torrance, Ca 90509	EMI	C20	1/8 - 1/4 miles east- northeast	miles east- Downgradient	Downgradient	st- Downgradient	Listed for the emission of total organic hydrocarbon gases (8 tons/yr), reactive organic gases (2 ton/yr), particulate matter (1 ton/yr), and particulate matter 10 micrometers and smaller (1 ton/yr).	Low

Facility Name	Database	EDR ID #	Distance (miles)/ Direction From Site	Location Relative to Inferred Groundwater Flow Direction	Comments	Classification
	SLIC RCRA-LQG, FINDS, TRIS HAZNET CERC-NFRAP HIST UST				Listed with a facility status of site assessment for the VOCs. Listed with three violations for generator land ban requirements, generator pre transport requirements and generator manifest requirements in 1992. Listed for the disposal of aqueous solution with 10% or more total organic residues through a recycler. Listed with no further remedial action planned as of June 8, 1993. Listed as having historical UST's (one 1,000-gallon premium product, one 1,000-gallon unleaded product, one 12,000-gallon, two 25,000-gallon diesel product, one 12,000-gallon product, and one 4,000-gallon and one 1,000-gallon waste oil.	See Section 4.1.2
Honeywell (Site A) 2525 West 190th Street Torrance, Ca 90504	EMI	C21, C22, 24	< 1/8 miles east- northeast	Downgradient	Listed for the emission of total organic hydrocarbon gases (231 tons/yr), reactive organic gases (38 tons/yr), carbon monoxide (5 tons/yr), nitrogen oxides (17 tons/yr), sulfur oxides (1 ton/yr), particulate matter (2 tons/yr), and particulate matter 10 micrometers and smaller (1 ton/yr) in 1987, total organic hydrocarbon gases (151 tons/yr), reactive organic gases (25 tons/yr), carbon monoxide (259 tons/yr), nitrogen oxides (26 tons/yr), sulfur oxides (1 ton/yr), particulate matter (2 tons/yr), sulfur oxides (1 ton/yr), particulate matter (2 tons/yr), and particulate matter 10 micrometers and smaller (2 tons/yr) in 1990, total organic hydrocarbon gases (73 tons/yr), reactive organic gases (18 tons/yr), carbon monoxide (3 tons/yr), nitrogen oxides (10 tons/yr), particulate matter (1 ton/yr) in 1993, total organic hydrocarbon gases (73 tons/yr), nitrogen oxides (10 tons/yr), reactive organic gases (18 tons/yr), carbon monoxide (3 tons/yr), and particulate matter 10 micrometers and smaller (1 ton/yr) in 1993, total organic hydrocarbon gases (73 tons/yr), reactive organic gases (18 tons/yr), carbon monoxide (3 tons/yr), and particulate matter 10 micrometers and smaller (1 ton/yr) in 1995, total organic hydrocarbon gases (36 tons/yr), reactive organic gases (18 tons/yr), nitrogen oxides (10 tons/yr), particulate matter (1 ton/yr) in 1995, total organic hydrocarbon gases (36 tons/yr), reactive organic gases (13 tons/yr), carbon monoxide (3 tons/yr), nitrogen oxides (5 tons/yr), particulate matter (1 ton/yr), and particulate matter 10 micrometers and smaller (1 ton/yr) in 1995, total organic hydrocarbon gases (36 tons/yr), reactive organic gases (13 tons/yr), carbon monoxide (3 tons/yr), nitrogen oxides (5 tons/yr), particulate matter (1 ton/yr) in 1996, total organic hydrocarbon	

Honeywell (Site A)         EMI (Continued)         C21, 24         < 1/8 miles east- northeast         Downgradiet           Iobot 4         EMI (Site A)         C21, 24         < 1/8 miles east- northeast         Iobot 5/20, 24           Iobot 5/20, 24          Iobot 5/20, 24          Iobot 5/20, 24         Iobot 5	Facility Name	Database	EDR ID #	Distance (miles)/ Direction From Site	Location Relative to Inferred Groundwater Flow Direction	Comments	Classification
SLIC Case listed as open.	(Site A) 2525 West 190th Street Torrance, Ca	(Continued) NY MANIFEST	C22,	east-	Downgradient	(2 tons/yr), nitrogen oxides (4 tons/yr), particulate matter (1 ton/yr), and particulate matter 10 micrometers and smaller (1 ton/yr) in 1997, total organic hydrocarbon gases (58 tons/yr), reactive organic gases (30 tons/yr), carbon monoxide (2 tons/yr), nitrogen oxides (4 tons/yr), particulate matter (1 ton/yr) and particulate matter 10 micrometers and smaller (1 ton/yr) in 1998, total organic hydrocarbon gases (76 tons/yr), reactive organic gases (37 tons/yr), carbon monoxide (2 tons/yr), nitrogen oxides (4 tons/yr), particulate matter (1 ton/yr), and particulate matter 10 micrometers and smaller (1 ton/yr) in 1999, total organic hydrocarbon gases (76 tons/yr), reactive organic gases (37 tons/yr), carbon monoxide (2 tons/yr), nitrogen oxides (4 tons/yr), particulate matter (1 ton/yr), and particulate matter 10 micrometers and smaller (1 ton/yr) in 2000, total organic hydrocarbon gases (55 tons/yr), reactive organic gases (26 tons/yr), carbon monoxide (13 tons/yr), nitrogen oxides (6 tons/yr), particulate matter (1 ton/yr), and particulate matter 10 micrometers and smaller (1 ton/yr) in 2001, total organic hydrocarbon gases (30 tons/yr), reactive organic gases (15 tons/yr), carbon monoxide (4 tons/yr), nitrogen oxides (4 tons/yr), particulate matter (1 ton/yr), and particulate matter 10 micrometers and smaller (1 ton/yr) in 2002 and 2003, total organic hydrocarbon gases (30.29 tons/yr), reactive organic gases (15.48 tons/yr), carbon monoxide (4.12 tons/yr), nitrogen oxides (3.74 tons/yr), sulfur oxides (0.04 tons/yr), particulate matter (1.046 tons/yr), and particulate matter 10 micrometers and smaller (0.84 tons/yr) in 2004, total organic hydrocarbon gases (12.6 tons/yr), reactive organic gases (7.51 tons/yr), carbon monoxide (3.94 tons/yr), nitrogen oxides (3.26 tons/yr), particulate matter (1 ton/yr), sulfur oxides (0.041 tons/yr) and particulate matter 10 micrometers and smaller (0.595 ton/yr) and particulate matter 10 micrometers and smaller (0.595 ton/yr) in 2005. Listed with a waste code of ignitable wa	

Facility Name	Database	EDR ID #	Distance (miles)/ Direction From Site	Location Relative to Inferred Groundwater Flow Direction	Relative       to Inferred       Groundwater	
Chevron USA SS 931 2623 West 190th Street Redondo Beach, Ca	CA FID UST, SWEEPS UST	23	1/8 - 1/4 miles east	Downgradient	Listed as having four active UST's with unknown contents.	Low
Arco #0154 3015 West 182nd Street Torrance, Ca 90504	LUST, CORTESE	25	1/4 - 1/2 miles north	Crossgradient	A leaking gasoline UST that affected groundwater was discovered on March 14, 1989. Case is still active.	Low
Mobil 18-D9E 18200	HAZNET				Listed for the disposal of unspecified oil-containing waste through a treatment tank and other organic solids through an unknown method.	
Crenshaw Boulevard Torrance, Ca 9054	LUST, CORTESE	D26	1/4 - 1/2 miles north	h	A leaking gasoline UST that affected groundwater was discovered on October 19, 1990. Case is still open.	Low
Exxon #7-8712 18201 Crenshaw Boulevard Torrance, Ca 90504	LUST, CORTESE	D27	1/4 - 1/2 miles north	Crossgradient	A leaking gasoline UST that affected groundwater was discovered on April 30, 1992. Case is still open.	Low
Yniguez Family Trust 18145 Crenshaw Boulevard Torrance, Ca 90504	LUST, CORTESE	D28	1/4 - 1/2 miles north		A leaking gasoline UST that affected groundwater was discovered on December 15, 1995. Case is open.	Low

Facility Name	Database	EDR ID #	Distance (miles)/ Direction From Site	Location Relative to Inferred Groundwater Flow Direction	Comments	Classification	
Mobil, Torrance Refinery and Oil Corp 3700 West 190th Street Torrance, Ca 90509	CHMIRS TOXIC PITS SLIC		<1/8 miles south	Crossgradient	Listed for multiple spills and releases which include the following: pipe failure, overturned big rig, fuel gas treater malfunction, valve failure, compressor malfunction, and leak on transfer pipeline. Closure completed on August 1, 1991 Listed with a status of remedial action underway. Listed for the emission of total organic hydrocarbon gases (1 ton/yr) and reactive organic gases (1 ton/yr) in 1990 and total organic hydrocarbon		
	EMI HAZNET	E29, E30			gases (47 tons/yr), reactive organic gases (24 tons/yr), carbon monoxide (1 ton/yr), and nitrogen oxides (3 tons/yr) in 2001. Listed for the disposal liquids with polychlorinated biphenyls > 50 mg/L and other organic solids through a recycler, an unknown waste and unspecified solvent mixture waste through a transfer station, aqueous solution with less than 10% total organic residues through an unreported	See Section 4.1.2	
	RCRA-LQG, RCRA-TSDF, FINDS, TRIS CORRACTS CERC-NFRAP FTTS, HIST FTTS	-			means. Listed with multiple violations for generator pre-transport requirements, TSD preparedness/prevention requirements, TSD general standards, generator-all requirements, TSD-other requirements, TSD-land ban requirements, TSD-financial responsibility requirements, generator-land ban requirements, and TSD closure/post-closure requirements. Listed for contaminated groundwater. Listed with no further remedial action planned as of May 21, 1990. Listed with violations.		
Hughes Aircraft Co./SCG 19300 Gramercy Place Torrance, Ca 90503	ENVIROSTOR ENVIROSTOR RCRA-SQG, RCRA-TSDF, FINDS CORRACTS CERC-NFRAP	F31, F32	1/2 - 1 miles east- northeast	Downgradient	Listed as an active facility and therefore cannot be considered remediated. Listed with a status of no further action. No violations reported. Facility assigned a medium corrective action priority. Listed with no further remedial action planned as of February 5, 2003.	Low	

Facility Name	Database	EDR ID #	Distance (miles)/ Direction From Site	Location Relative to Inferred Groundwater Flow Direction	Comments	Classification	
305 Crenshaw Torrance, Ca	CHMIRS CA WDS	G33	1/2 - 1	Crossgradient	Listed for a styrene spill. Facility listed as active.	Low	
90503	ENVIROSTOR	033	miles south	crossgradient	Listed with a status date of March 1, 1995.	Low	
Dowell Div of Dow Chemical 301 Crenshaw Boulevard	RCRA-SQG, FINDS	G34	1/2 - 1 miles south	Crossgradient	Listed with 13 violations for TSD container requirements, TSD chemical/physical/biological requirements, TSD tank requirements, generator recordkeeping requirements, TSD closure/post-closure requirements, TSD financial responsibility requirements, and TSD and generator land bad requirements.	Low	
Torrance, Ca 90510	CORRACTS	]			Listed with a low corrective action priority.		
	CERC-NFRAP				Listed as an archive site as of January 23, 1996.	<u> </u>	
Dow Chemical Co. Torrance Plant 305 Crenshaw	RCRA-LQG, RCRA-TSDF, FINDS, TRIS	Н35	5 $\frac{1/2}{1}$ - 1 Crossgradi		Listed with 29 violations for TSD financial responsibility requirements, TSD container requirements, generator and TSD land ban requirements, generator general requirements, generator all requirements, TSD closure/post-closure,	Low	
Boulevard	CORRACTS	]	miles south	C	Listed with an approved workplan as of December 6, 2000.		
Torrance, Ca 90503	CERC-NFRAP				Listed with no further remedial action planned as of January 1, 1987.		
American Standard Inc.	RCRA-SQG, FINDS				No violations reported.		
360 Crenshaw	CERC-NFRAP	H36	1/2 - 1	Crossgradient	Listed with no further remedial action planned as of October 18, 1991.	Low	
Boulevard Torrance, Ca 90503	ENVIROSTOR	1100	miles south	eressgruaterie	Listed with a completion date of April 11, 1995.	LOW	
Francisco's	HAZNET				Listed for the disposal of an unknown waste and halogenated solvents through a recycler.		
Cleaners 1830 West	LA CO. SITE MITIGATION	37	1/2 - 1	-/	Listed with an abated date of November 3, 2003.	Law	
182nd Street	CLEANERS	57	miles east- Crossgra	Crossgradient	Listed as inactive date of June 30, 1999.	Low	
Torrance, Ca 90504	EMI	]	normoust		Listed for the emission of total organic hydrocarbon gases (1 ton/yr) in 1987 and 1990.		
	ENVIROSTOR				Listed with a referral status to a local agency as of July 24, 2002.		

Facility Name	Database	EDR ID #	Distance (miles)/ Direction From Site	Location Relative to Inferred Groundwater Flow Direction	Comments	Classification	
International Light Metals	ENVIROSTOR RCRA-LQG,				Listed with a referral status to RCRA as of August 28, 1995.		
19200 South Western	RCRA-LQO, RCRA-TSDF, FINDS	I38, I39	1/2 - 1 miles east-	Downgradient	Downgradient Listed with 5 violations exist for TSD and generator land ban requirements and other TSD requirements.		
Avenue Torrance, Ca	CORRACTS	139	southeast		Listed as corrective action process terminated with no further action as of May 13, 1999.		
90501	CERC-NFRAP				Listed as an archive site as of January 23, 1996.		
Phenomenex Inc (building 4) 431 Amapola Avenue Torrance, Ca 90501	ENVIROSTOR	40	1/2 - 1 miles south	Crossgradient	Listed as active as of March 1, 2001.	Low	
PPG Industries Inc 465 Crenshaw Boulevard Torrance, Ca 90509	RCRA-LQG, RCRA-TSDF, RAATS, CORRACTS	41	1/2 - 1 miles south	Crossgradient	Listed with 7 violations for TSD other requirements and generator all requirements.	Low	


#### Notes:

1. Source - Environmental Data Resources, Inc. EDR Radius Map with GeoCheck, October 15, 2007 - Included in Appendix B.


2. Inferred groundwater flow direction is to the east-southeast.

Six facilities listed in the EDR report were shown as "orphan sites." These are sites that are listed in environmental databases, but which EDR has been unable to locate with adequate precision to determine whether they are pertinent to the investigation at the subject property. Golder was able to determine to a reasonable degree of certainty that the orphan sites were not listed on databases that indicated environmental impairment and/or were not within the specified database search distances.


FIGURES



PLOT DATE: November 29, 2007 FILENAME: S:\projects\073\073-91953 Travelers Torrance Phase I\FIGURES\Figure 1



Torrance Travelers S:\projects\073\073-91953 2007 29, November DATE: FILENAME: PLOT



**Golder Associates** 

APPENDIX A

LEGAL DESCRIPTION OF THE SUBJECT PROPERTY/ TITLE REPORT

Records for this property are kept at the Headquarters Office					
(How frequently is the information updated on this site?)					
Property Information					
Assessor's ID No.	4090-021-032				
Site Address	No Address Available				
Property Type	Commercial / Industrial				
Region / Cluster	29 / 29880				
Tax Rate Area (TRA)	09340				
Click Here to	View Assessor's Map				
(Click Here to View Index Map)					
Recent Sale Information					

Latest Sale Date Indicated Sale Price

Search for Recent Sales

2007 Roll Values	
Recording Date	09/18/1985
Land	\$1,896,819
Improvements	\$12,152
Personal Property	\$0
Fixtures	\$0
Homeowners' Exemption	\$0
Real Estate Exemption	\$0
Personal Property Exemption	\$0
Fixture Exemption	\$0
Click Here for 2007 A	Innual Taxes

**Estimate Supplemental Taxes** 

**Property Boundary Description** STRAWBERRY HOME TR S 325.18 FT MEASURED AT R/A TO S LINE EX OF ST OF LOT 25

#### **Building Description**(s)

Impro	vement 1
Square Footage	90,950
Year Built / Effective Year Built	1960 / 1962
Bedrooms / Bathrooms	0 / 0
Units	0

Click Here for Another Search

Records for this pro	perty are	kept at the l	Headquarter	s Office
(How frequently	is the infor	mation updat	ed on this site	<u>?</u> )

Property Info	rmation		
Assessor's ID No		4090-021-033	
Site Address		No Address Available	
Property Type		Commercial / Industrial	
Region / Cluster		29 / 29880	
Tax Rate Area (T	RA)	09340	
	Click Here to View Assessor's Map		

(Click Here to View Index Map)

#### Recent Sale Information Latest Sale Date Indicated Sale Price

Search for Recent Sales

2007 Roll Values		
Recording Date	09/18/1985	
Land	\$1,820,945	
Improvements	\$12,152	
Personal Property	\$0	
Fixtures	\$0	
Homeowners' Exemption	\$0	
Real Estate Exemption	\$0	
Personal Property Exemption	\$0	
Fixture Exemption	\$0	
Click Here for 2007 Annual Taxes		

Estimate Supplemental Taxes

**Property Boundary Description** STRAWBERRY HOME TR N 304.86 FT OF LOT 25

## **Building Description(s)**

Improven	Improvement 1	
Square Footage	88,460	
Year Built / Effective Year Built	1960 / 1962	
Bedrooms / Bathrooms	0 / 0	
Units	0	

Click Here for Another Search



# The EDR Environmental Lien Search Report

# PARKING LOT (LOT 25) 2500 BLOCK WEST 190TH STREET TORRANCE, CALIFORNIA

Wednesday, October 24, 2007

Project Number: L07-09330

# The Standard In Environmental Risk Management Information

440 Wheelers Farm Road Milford, Connecticut 06460

# **Nationwide Customer Service**

Telephone: 1-800-352-0050 Fax: 1-800-231-6802

# **ENVIRONMENTAL LIEN REPORT**

The EDR Environmental LienSearch Report provides results from a search of available current land title records for environmental cleanup liens and other activity and use limitations, such as engineering controls and institutional controls.

A network of professional, trained researchers, following established procedures, uses client supplied property information to:

- search for parcel information and/or legal description;
- search for ownership information;
- research official land title documents recorded at jurisdictional agencies such as recorders' office, registries of deed, county clerks' offices, etc.;
- access a copy of the deed;
- search for environmental encumbering instrument(s) associated with the deed;
- provide a copy of any environmental encumbrance(s) based upon a review of key words in the instrument(s) (title, parties involved and description); and
- provide a copy of the deed or cite documents reviewed;

## Thank you for your business

Please contact EDR at 1-800-352-0050 with any questions or comments

#### Disclaimer - Copyright and Trademark Notice

This report was prepared for the use of Environmental Data Resources, Inc., and Golder Associates, Inc., exclusively. This report is neither a guarantee of title, a commitment to insure, nor a policy of title insurance. **NO WARRANTY, EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT.** Environmental Data Resources, Inc. (EDR) and Nationwide Environmental Title Research (NETR) specifically disclaim the making of any such warranties, including without limitation, merchantability or fitness for a particular use or purpose. The information contained in this report is retrieved as it is recorded from the various agencies that make it available. The total liability is limited to the fee paid for this report.

Copyright 2006 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission

EDR and its logos are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

# **ENVIRONMENTAL LIEN REPORT**

The EDR Environmental Lien Search Report is intended to assist in the search for environmental liens filed in land title records.

## TARGET PROPERTY INFORMATION

## **ADDRESS**

Parking Lot (Lot 25) 2500 Block West 190th Street Torrance, California

### **RESEARCH SOURCE**

Source: Los Angeles County Assessor Los Angeles County Recorder

## DEED INFORMATION

Type of Instrument: Grant Deed

Title is vested in: The Garrett Corporation, a corporation

Title received from: Jack Toshiki Sakioka, a married man, and Johnny Katsui Sakioka, a married man, who acquired title as a single man

Deed Dated: 10/16/1958 Deed Recorded: 03/18/1959 Instrument: 1923

Type of Instrument: Certificate of Merger

Title is vested in: Allied Signal, Inc., a corporation organized under the laws of the State of Delaware

Title received from: The Garrett Corporation

Deed Dated: 02/09/1989 Deed Recorded: 03/24/1989 Instrument: 89-457549

## LEGAL DESCRIPTION

Lot 25, of the Strawberry Homes Tract, according to the map or plat thereof, as filed of record in Book 6, Page 119 of Maps, Los Angeles County, State of California

Assessor's Parcel Number(s): 4090-021-032 and 4090-021-033

## **ENVIRONMENTAL LIEN**


Environmental Lien: Found D Not Found 🛛


# **ENVIRONMENTAL LIEN REPORT**

## OTHER ACTIVITY AND USE LIMITATIONS (AULs)

Other AULs: Found □ Not Found ⊠

PECOPOING PEQUESTED 31 - 07 - BQ 3 RELIMENTAL IN CONDIAL ALCOHOS WHEN RECORDED MAIL TO OF LOS ANGELES COUNTY, CALIF. Title Insurance and Trust Company 433 So. Spring Street Los Angeles, California Attn: 3. J. Stevens NAM 18 1959 ATSAM RAY E. LEE, County Recorder PACE ABOVE THIS LINE FOR RECORDER'S VILLA S. S. NONE is This SPACE Grant Deed THIS FORM FURNISHED BY TITLE INSURANCE AND TRUST COMPANY đjt. ..... ..... FOR A VALUABLE CONSIDERATION, respired which is hereby acknowledged. JACK TOSHIKI (SALLUES) a married man, and JOHNNY KATSUT SAKICKA, a married man, who acquired title a single wan. burch thiANT'S to THE GARRETT CORPORATION, a corporation. city of Torrance, the following described real property in the state of California: See attached rider. county of Los Angeles ....... Lots 1, 2, 3, 4, 5, 6, 25, 26, 27, 28, 29, 30, 31, 32, 35, and 36 of Strayberry House Tracing the city of Torrance, county of Los Angeles, state of California, as per may recorded a book 6 page 119 of Maps, in the office of the county recorder of said county. EXCEPTING therefrom that portion of lot 35, as described in final degree of condemnation entered in Los Angeles County Superior Court Case No. 581190, a certified copy of which was recorded July 24, 1951 in book 36833 page 103, Official Records. ALSO EXCEPTING therefrom all minorals, oil, gas, petroleum, maphtha and other hydrocarbon substances underlying said land without right of surface entry the sto as reserved by the Farmers and Merchants National Bank of Los Angeles in deed recorded October 23, 1952 in book 40142 page 297, Official Records. Dated: October 16, 1958 JACK TOSHINI SANIOKA 1.0.0 JOHNNY KATSUL SAKLOKA STATE OF CALIFORNIA The Strate States - - 8 , 17 5 0 before me, the under nonts and State, permutally opend, a Notary Public Jack Toshiki Sakicka and to an all Johnny Katsul Sakioka . Known to me in the president C where particular are subscribed to the within extrement and acknowledged that they exertined the same WEENS IN HIS BAND and official seal 56 a D toriary Phylote in and for early opposed wrate Title Order No. . Escrow No. 5005489-WJ3:djt transmith to a comparation the Corporation born of to knowledgement must be used e ......






LOS ANGELES,CA Document: AG 1989.457549 Printed on 10/23/2007 4:23:05 PM Provided by Data Trace System

Page 1 of 5

. D24900% Gatate at Bulabars 462455 001 · Office of Secretary of State I. MICHAEL HARMING. SECRETARY OF STATE OF THE SPATE OF DELAMARE OF MENLET CORPTE THE ATTACHED IS A TRUE AND CORRECT COPY OF THE CENTIFICATE OF ONHERDHEP OF ALLES-SIGNAL INC., A CORPORATION ORDANIZED AND CRISTING UNDER THE LANS OF THE STATE OF OFLAMARE . HENDING THE CAREET CORPORATION & CORPORATION ORDANIZED AND SYLATING UNDER THE LANS OF THE STATE OF CALIFORNIA, FUR WANT TO SECTION 253 OF THE DENSARL CONFORMILOR LAN OF THE STATE OF DELONARE, AS RECEIVED AND FILED IN THIS OFFICE THE INSATISTI DAY OF SCHICHBER, A.D. 1987, AT 4110 OFCLOCK P.H. AND & DO HERCEY PURTHER CERTIFY THAT THE AFORESAID CONFORMTION SHALL BE ODVENNED BY THE LAND OF THE STATE OF DELAWARE. 1 1 1 1 4 1 1 1 1 1 AUTHINTICATION 10481415 DATE 727274030 10/01/1907 LOS ANGELES,CA Document: AG 1989.457549 Page 2 of 5 Printed on 10/23/2007 4:23:06 PM Provided by Data Trace System



ALLIND-GICHAL INC.

ALLED-SIGMAL INC., & corporation organized under the lowe of the State of Delevare, heighty cettifies as follows:

FIRE': This Corporation was incorporated on May 13, 1905 under by name East-Awart Monto Corporation,

HECOMD: This appreciation dwith all of the outstanding shares of whom of The California Composition, incomposited in the State of California on Departmen 10, 1953.

THISD. The laws of the Shake of California pendit the Merget of e Commutic Compotation into a composition organized under the laws of whether Shake.

Filler: This exponsion, by the following familutions of its Board of Dissetties, duly adopted at a meeting held on September 25, 1987, determined to merge into itemp17 The Garrett Corporation:

> RESERVED: The School and chication more into itself and Graphnian III the lightlike and chications of the signal dependent for approximation Aligo Corporation, a new New Sock School and The Carrett Corporation, a california

TREALMED: That the struct of the signal Companies, inc. into the Corporations shall be effective on Repionder 30, 1967, et Jaili and both that the struct of allowed Companies to 1978, ab too provide the structure of the Generatic Companies (COT) and Long that is affective on September 30, 1987, ab too be Companyition shall be effective on September 20, 1987, about the Companyition shall be effective on September 20, 1987, and the September 20, 1987.

王统山的学行为3755天日的大学之外的第三人称单数


LOS ANGELES,CA Document: AG 1989.457549 Printed on 10/23/2007 4:23:08 PM Provided by Data Trace System

J,


Page 3 of 5


. . . .

3



Page 4 of 5





CITY OF TORRANCE General Plan

February 2005

**APPENDIX B** 

FEDERAL AND STATE REGULATORY DATABASE SEARCH

# **The EDR Radius Map** with GeoCheck<sup>®</sup>

Parking Lot (Lot 25) 2500 Block W. 190th Street Torrance, CA 90504

Inquiry Number: 2051883.2s

October 15, 2007

# The Standard in Environmental Risk Information

**EDR**<sup>®</sup> Environmental

Data Resources Inc

440 Wheelers Farms Road Milford, Connecticut 06461

## **Nationwide Customer Service**

 Telephone:
 1-800-352-0050

 Fax:
 1-800-231-6802

 Internet:
 www.edrnet.com

# TABLE OF CONTENTS

#### SECTION

#### PAGE

Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	6
Orphan Summary	358
EPA Waste Codes	EPA-1
Government Records Searched/Data Currency Tracking	GR-1

### **GEOCHECK ADDENDUM**

Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting Source Map	A-7
Physical Setting Source Map Findings	A-8
Physical Setting Source Records Searched	A-37

*Thank you for your business.* Please contact EDR at 1-800-352-0050 with any questions or comments.

#### **Disclaimer - Copyright and Trademark Notice**

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental St Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2007 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-05) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

#### TARGET PROPERTY INFORMATION

#### ADDRESS

2500 BLOCK W. 190TH STREET TORRANCE, CA 90504

#### COORDINATES

Latitude (North):	33.859300 - 33° 51' 33.5"
Longitude (West):	118.325900 - 118° 19' 33.2"
Universal Tranverse Mercator:	Zone 11
UTM X (Meters):	377347.6
UTM Y (Meters):	3747152.5
Elevation:	64 ft. above sea level

#### USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:	33118-G3 TORRANCE, CA
Most Recent Revision:	1981
North Map:	33118-H3 INGLEWOOD, CA
Most Recent Revision:	1981

TARGET PROPERTY SEARCH RESULTS

The target property was not listed in any of the databases searched by EDR.

#### DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

#### FEDERAL RECORDS

NPL	. National Priority List
Proposed NPL	Proposed National Priority List Sites
Delisted NPL	National Priority List Deletions
NPL LIENS	. Federal Superfund Liens
CERCLIS	Comprehensive Environmental Response, Compensation, and Liability Information System
RCRA-TSDF	Resource Conservation and Recovery Act Information
ERNS	Emergency Response Notification System

	- Hazardous Materials Information Reporting System
	Engineering Controls Sites List
	_ Sites with Institutional Controls
DOD	Department of Defense Sites
FUDS	Formerly Used Defense Sites
US BROWNFIELDS	_ A Listing of Brownfields Sites
	Superfund (CERCLA) Consent Decrees
ROD	
UMTRA	
ODI	
TRIS	Toxic Chemical Release Inventory System
	Toxic Substances Control Act
	FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide
	Act)/TSCA (Toxic Substances Control Act)
SSTS	Act)/TSCA (Toxic Substances Control Act) Section 7 Tracking Systems
DOT OPS	
	Torres Martinez Reservation Illegal Dump Site Locations
	Integrated Compliance Information System
	. Land Use Control Information System
US CDL	
	_ Radiation Information Database
LIENS 2	
	_ FIFRA/TSCA Tracking System Administrative Case Listing
PADS	PCB Activity Database System
	_ Material Licensing Tracking System
MINES	
	. Facility Index System/Facility Registry System
RAATS	RCRA Administrative Action Tracking System
	Norv Administrative Action Hacking Oystem

STATE AND LOCAL RECORDS

SWF/LF CA WDS	Bond Expenditure Plan School Property Evaluation Program Solid Waste Information System Waste Discharge System Waste Management Unit Database
AOCONCERN	San Gabriel Valley Areas of Concern
	Aboveground Petroleum Storage Tank Facilities
LIENS	Environmental Liens Listing
	California Hazardous Material Incident Report System
Notify 65	Proposition 65 Records
LA Co. Site Mitigation	Site Mitigation List
DEED	Deed Restriction Listing
VCP	Voluntary Cleanup Program Properties
WIP	Well Investigation Program Case List
LOS ANGELES CO. HMS	
CDL	Clandestine Drug Labs
RESPONSE	State Response Sites
HAZNET	Facility and Manifest Data
EMI	
HAULERS	Registered Waste Tire Haulers Listing

TRIBAL RECORDS

INDIAN RESERV...... Indian Reservations

INDIAN LUST	Leaking Underground Storage Tanks on Indian Land
INDIAN UST	Underground Storage Tanks on Indian Land

#### EDR PROPRIETARY RECORDS

**Manufactured Gas Plants**\_\_\_\_ EDR Proprietary Manufactured Gas Plants **EDR Historical Cleaners**\_\_\_\_\_ EDR Proprietary Historic Dry Cleaners

#### SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property. Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in **bold italics** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

#### FEDERAL RECORDS

**CERCLIS-NFRAP:** Archived sites are sites that have been removed and archived from the inventory of CERCLIS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

A review of the CERC-NFRAP list, as provided by EDR, and dated 06/21/2007 has revealed that there is 1 CERC-NFRAP site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
HONEYWELL	2525 W 190TH ST	1/8 - 1/4 ENE	C22	46

**CORRACTS:** CORRACTS is a list of handlers with RCRA Corrective Action Activity. This report shows which nationally-defined corrective action core events have occurred for every handler that has had corrective action activity.

A review of the CORRACTS list, as provided by EDR, and dated 06/26/2007 has revealed that there are 6 CORRACTS sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
MOBIL OIL CORP	3700 W 190TH ST	1/2 - 1 W	E30	299
HUGHES AIRCRAFT COMPANY SCG	19300 GRAMERCY PLACE	1/2 - 1 ESE	F32	315
DOWELL DIV OF DOW CHEMICAL	301 CRENSHAW BLVD	1/2 - 1 S	G34	327
DOW CHEMICAL CO TORRANCE PLANT	305 CRENSHAW BLVD	1/2 - 1 S	H35	331
P P G INDUSTRIES INC	465 CRENSHAW BLVD	1/2 - 1 S	41	355
Lower Elevation	Address	Dist / Dir	Map ID	Page
INTEL LIGHT METALS CORP	19200 S WESTERN AVE	1/2 - 1 ESE	139	348

**RCRAInfo:** RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRAInfo replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System(RCRIS). The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month. Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month Large quantity generators generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month. Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

A review of the RCRA-LQG list, as provided by EDR, and dated 06/13/2006 has revealed that there are 2 RCRA-LQG sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
SITE A	2545 W 190TH ST	0 - 1/8 E	•	14
HONEYWELL	2525 W 190TH ST	1/8 - 1/4ENE		46

**RCRAInfo:** RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRAInfo replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System(RCRIS). The database includes selective information on sites which generate, transport, store , treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month. Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month Large quantity generators generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month. Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

A review of the RCRA-SQG list, as provided by EDR, and dated 06/13/2006 has revealed that there are 4 RCRA-SQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
SAKURA FINETEK U S A INC	18700 CRENSHAW BLVD	0 - 1/8 N	5	14
TAKANE USA INC	18640 CRENSHAW BLVD	0 - 1/8 N	14	27
Lower Elevation	Address	Dist / Dir	Map ID	Page
PELICAN HI PERFORMANCE	18905 CRENSHAW PLACE	0 - 1/8	1	6
MINIT LUBE NO 1298	3209 WEST 190TH	0 - 1/8 W	B8	17

#### STATE AND LOCAL RECORDS

**TOXIC PITS:** The Toxic Pits Cleanup Act Sites database identifies sites suspected of containing hazardous substances where cleanup has not yet been completed. The data come from the State Water Resources Control Board.

A review of the Toxic Pits list, as provided by EDR, and dated 07/01/1995 has revealed that there is 1 Toxic Pits site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
MOBIL, TORRANCE REFINERY Closure Date: 08/01/91	3700 W. 190TH STREET	1/2 - 1 W	E29	69

**CORTESE:** This database identifies public drinking water wells with detectable levels of contamination, hazardous substance sites selected for remedial action, sites with known toxic material identified through the abandoned site assessment program, sites with USTs having a reportable release and all solid waste disposal facilities from which there is known migration. The source is the California Environmental Protection Agency/Office of Emergency Information.

A review of the Cortese list, as provided by EDR, and dated 04/01/2001 has revealed that there are 7 Cortese sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
ARCO #0154	3015 182ND ST W	1/4 - 1/2 N	25	59
MOBIL 18-D9E	18200 CRENSHAW BLVD	1/4 - 1/2 N	D26	61
EXXON #7-8712	18201 CRENSHAW BLVD S	1/4 - 1/2 N	D27	64
YNIGUEZ FAMILY TRUST	18145 CRENSHAW BLVD	1/4 - 1/2 N	D28	67
Lower Elevation	Address	Dist / Dir	Map ID	Page
ΤΕΧΑCΟ	18910 CRENSHAW BLVD	0-1/8 W	A2	6
MOBIL #18-ECP (FORMER #11	19009 CRENSHAW	0-1/8 W	B11	22
ALLIED SIGNAL INC (SITE A)	2525 190TH ST W	1/8 - 1/4 ENE	C18	34

**LUST:** The Leaking Underground Storage Tank Incident Reports contain an inventory of reported leaking underground storage tank incidents. The data come from the State Water Resources Control Board Leaking Underground Storage Tank Information System.

A review of the LUST list, as provided by EDR, and dated 07/10/2007 has revealed that there are 7 LUST sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
ARCO #0154 Facility Status: Remedial action (cleanup) Un	<b>3015 182ND ST W</b> derway	1/4 - 1/2N	25	59
<b>MOBIL 18-D9E</b> Facility Status: Remedial action (cleanup) Un	18200 CRENSHAW BLVD derway	1/4 - 1/2N	D26	61
EXXON #7-8712 Facility Status: Post remedial action monitorin	18201 CRENSHAW BLVD S	1/4 - 1/2N	D27	64
<b>YNIGUEZ FAMILY TRUST</b> Facility Status: Preliminary site assessment u	18145 CRENSHAW BLVD nderway	1/4 - 1/2 N	D28	67
Lower Elevation	Address	Dist / Dir	Map ID	Page
<b>TEXACO</b> Facility Status: Remedial action (cleanup) Un	18910 CRENSHAW BLVD derway	0 - 1/8 W	A2	6
MOBIL #18-ECP (FORMER #11-ECP) Facility Status: Pollution Characterization	19009 CRENSHAW BLVD	0-1/8 W	B10	18
ALLIED SIGNAL INC (SITE A) Facility Status: Case Closed	2525 190TH ST W	1/8 - 1/4 <i>ENE</i>	C18	34

**CA FID:** The Facility Inventory Database contains active and inactive underground storage tank locations. The source is the State Water Resource Control Board.

A review of the CA FID UST list, as provided by EDR, and dated 10/31/1994 has revealed that there are 5 CA FID UST sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
TEXACO SERVICE STATION #0274	18910 S CRENSHAW BLVD	0-1/8 W	A3	11
QUAKER STATE MINIT-LUBE INC.	3209 W 190TH ST	0-1/8 W	B7	16
MOBIL SERVICE STATION 11-ECP C	19009 S CRENSHAW BLVD	0-1/8 W	B12	22
ALLIED SIGNAL INC (SITE A)	2525 190TH ST W	1/8 - 1/4 ENE	C18	34
CHEVRON USA SS 931	2623 W 190TH ST	1/8 - 1/4 <i>E</i>	23	57

CA SLIC: SLIC Region comes from the California Regional Water Quality Control Board.

A review of the SLIC list, as provided by EDR, and dated 08/03/2007 has revealed that there are 3 SLIC sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
GARRET AIRESEARCH Facility Status: Pollution Characterization	2525 W. 190TH ST.	1/8 - 1/4 <i>ENE</i>	C20	45
HONEYWELL SITE A HONEYWELL SITE A Facility Status: Case Open	2525 190TH 2525 W. 190TH STREET	1/8 - 1/4ENE 1/4 - 1/2E	C21 24	46 59

**UST:** The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the State Water Resources Control Board's Hazardous Substance Storage Container Database.

A review of the UST list, as provided by EDR, and dated 07/10/2007 has revealed that there are 3 UST sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
SHELL STATION #121744	18910 CRENSHAW BLVD	0 - 1/8 W	4	14
MOBIL SERVICE STATION 11-ECP	19009 CRENSHAW BLVD	0 - 1/8 W	B9	18
ALLIED-SIGNAL	2525 W 190TH ST	1/8 - 1/4ENE	C19	45

HIST UST: Historical UST Registered Database.

A review of the HIST UST list, as provided by EDR, and dated 10/15/1990 has revealed that there are 3 HIST UST sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
<i>S. SUNG</i>	<b>19009 CRENSHAW BLVD</b>	<b>0 - 1/8 W</b>	<b>B13</b>	<b>25</b>
MOHAWK SERVICE STATION #04067	18910 CRENSHAW	1/8 - 1/4W	B15	28
<i>HONEYWELL</i>	<b>2525 W 190TH ST</b>	<b>1/8 - 1/4ENE</b>	<b>C22</b>	<b>46</b>

**SWEEPS:** Statewide Environmental Evaluation and Planning System. This underground storage tank listing was updated and maintained by a company contacted by the SWRCB in the early 1980's. The listing is no longer updated or maintained. The local agency is the contact for more information on a site on the SWEEPS list.

A review of the SWEEPS UST list, as provided by EDR, and dated 06/01/1994 has revealed that there are 5 SWEEPS UST sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
TEXACO SERVICE STATION #0274	18910 S CRENSHAW BLVD	0-1/8 W	A3	11
QUAKER STATE MINIT-LUBE INC.	3209 W 190TH ST	0-1/8 W	B7	16
MOBIL SERVICE STATION 11-ECP C	19009 S CRENSHAW BLVD	0-1/8 W	B12	22
ALLIED SIGNAL INC (SITE A)	2525 190TH ST W	1/8 - 1/4 ENE	C18	34
CHEVRON USA SS 931	2623 W 190TH ST	1/8 - 1/4 <i>E</i>	23	57

**DRYCLEANERS:** A list of drycleaner related facilities that have EPA ID numbers. These are facilities with certain SIC codes: power laundries, family and commercial; garment pressing and cleaners' agents; linen supply; coin-operated laundries and cleaning; drycleaning plants except rugs; carpet and upholster cleaning; industrial launderers; laundry and garment services.

A review of the CLEANERS list, as provided by EDR, and dated 07/31/2007 has revealed that there is 1 CLEANERS site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
GEORGE P JOHNSON CO	18500 CRENSHAW BLVD	1/8 - 1/4N	17	29

**ENVIROSTOR:** The Department of Toxic Substances Control's (DTSC's) Site Mitigation and Brownfields Reuse Program's (SMBRP's) EnviroStor database identifes sites that have known contamination or sites for which there may be reasons to investigate further. The database includes the following site types: Federal Superfund sites (National Priorities List (NPL)); State Response, including Military Facilities and State Superfund; Voluntary Cleanup; and School sites. EnviroStor provides similar information to the information that was available in CalSites, and provides additional site information, including, but not limited to, identification of formerly-contaminated properties that have been released for reuse, properties where environmental deed restrictions have been recorded to prevent inappropriate land uses, and risk characterization information that is used to assess potential impacts to public health and the environment at contaminated sites.

A review of the ENVIROSTOR list, as provided by EDR, and dated 08/28/2007 has revealed that there are 7 ENVIROSTOR sites within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
MOBIL OIL CORP Facility Status: Refer: RCRA	3700 W 190TH ST	1/2 - 1 W	E30	299
HUGHES AIRCRAFT CO./SCG Facility Status: No Further Action	19300 GRAMERCY PLACE	1/2 - 1 ESE	F31	314
<b>Not reported</b> Facility Status: Refer: RCRA	305 CRENSHAW	1/2 - 1 S	G33	317
AMERICAN STANDARD INC Facility Status: Refer: Other Agency	360 CRENSHAW BLVD	1/2 - 1 S	H36	340
PHENOMENEX, INC. (BLDG. 4) Facility Status: Active	431 AMAPOLA AVE.	1/2 - 1 S	40	354
Lower Elevation	Address	Dist / Dir	Map ID	Page
FRANCISCO'S CLEANERS Facility Status: Refer: 1248 Local Agency	1830 W 182ND ST	1/2 - 1 ENE	37	342

# **EXECUTIVE SUMMARY**

# L

Lower Elevation	Address	Dist / Dir	Map ID	Page
INTERNATIONAL LIGHT METALS Facility Status: Refer: RCRA	19200 SOUTH WESTERN AVE	1/2 - 1 ESE	138	347

# EDR PROPRIETARY RECORDS

EDR Historical Auto Stations: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc.

A review of the EDR Historical Auto Stations list, as provided by EDR, has revealed that there is 1 EDR Historical Auto Stations site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
MCGEE'S SERVICE MOBIL PRODUCTS	2701 W 190TH ST	1/8 - 1/4 E	16	29

# **EXECUTIVE SUMMARY**


Due to poor or inadequate address information, the following sites were not mapped:

Site Name

1X MCKESSON DRUG CO TORRANCE LDFL MOBIL SHELL SERVICE STATION IN A VACANT LOT ON THE SW CORNER ON 190TH STREET AND PACIFIC SW COR/190TH ST & PAC GATEWY DR/VAC LOT Database(s)

HAZNET, LUST, CHMIRS CERC-NFRAP LUST HAZNET, RCRA-LQG ERNS ERNS

**OVERVIEW MAP - 2051883.2s** 



SITE NAME: Parking Lot (Lot 25)	CLIENT: Golder Associates, Inc.
ADDRESS: 2500 Block W. 190th Street	CONTACT: Misty Vazquez
Torrance CA 90504	INQUIRY #: 2051883.2s
LAT/LONG: 33.8593 / 118.3259	DATE: October 15, 2007 1:21 pm
LAT/LONG: 33.8593 / 118.3259	DATE: October 15, 2007 1:21 pm

DETAIL MAP - 2051883.2s 4 enburn Ave d a Faysmith Fal Elgar W Ανe 14 W 186th St W 186th St W 187t St W 187th St W 187th W 187th PI P W 188th W 188th St 89th St W 189th St CRENSHAW CHILDREN'S CENTER в у AIIey CRENSHAW CHILDREN'S CTR **◆**<sup>6</sup> W 19 th St St W 19<u>29</u>3th St W 190t 24 B15 6 0 Mobile ◆<sup>B</sup> 0 8 Crenshaw Mobile Oil Moble 1.1 Mobile 0 i 1 Mobile Mobile Oli Mobile Oil 0 1/16 1/8 1/4 Miles Target Property N Sites at elevations higher than or equal to the target property Indian Reservations BIA Areas of Concern Sites at elevations lower than Oil & Gas pipelines the target property Ħ 100-year flood zone Manufactured Gas Plants 500-year flood zone Sensitive Receptors 4 National Wetland Inventory National Priority List Sites

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

Dept. Defense Sites

# **MAP FINDINGS SUMMARY**

Database	Target Property	Search Distance (Miles)	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
FEDERAL RECORDS								
NPL Proposed NPL Delisted NPL NPL LIENS CERCLIS CERC-NFRAP CORRACTS RCRA TSD RCRA Lg. Quan. Gen. RCRA Sm. Quan. Gen. ERNS HMIRS US ENG CONTROLS US INST CONTROL DOD FUDS US BROWNFIELDS CONSENT ROD UMTRA ODI TRIS TSCA FTTS SSTS DOT OPS DEBRIS REGION 9 ICIS LUCIS CDL RADINFO LIENS 2 HIST FTTS PADS MLTS MINES FINDS		1.000 1.000 TP 0.500 0.500 1.000 0.250 0.250 TP TP 0.500 0.500 1.000 1.000 1.000 1.000 1.000 0.500 1.000 0.500 TP TP TP TP TP TP TP TP TP TP TP TP TP	0 0 0 R 0 0 0 1 4 RR 0 0 0 0 0 0 0 0 0 0 0 RR RR 0 R 0	0 0 0 R 0 1 0 0 R 0 0 0 0 0 0 0 0 0 0 0	0 0 0 R 0 0 0 0 R R R R 0 0 0 0 0 0 0 0	0 0 0 RR R 6 RR RR RR R 0 0 R 0 0 RR RR RR RR RR RR	R R R R R R R R R R R R R R R R R R R	$\begin{array}{c} 0 \\ 0 \\ 0 \\ 0 \\ 1 \\ 6 \\ 0 \\ 2 \\ 4 \\ 0 \\ 0 \\ 0 \\ 0 \\ 0 \\ 0 \\ 0 \\ 0 \\ 0$
RAATS STATE AND LOCAL RECOR	2DS	TP	NR	NR	NR	NR	NR	0
Hist Cal-Sites CA Bond Exp. Plan SCH Toxic Pits State Landfill CA WDS WMUDS/SWAT		1.000 1.000 0.250 1.000 0.500 TP 0.500	0 0 0 0 NR 0	0 0 0 0 NR 0	0 0 NR 0 0 NR 0	0 NR 1 NR NR NR	NR NR NR NR NR NR	0 0 1 0 0

# **MAP FINDINGS SUMMARY**

Database	Target Property	Search Distance (Miles)	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
Cortese		0.500	2	1	4	NR	NR	7
SWRCY		0.500	0	0	0	NR	NR	0
LUST		0.500	2	1	4	NR	NR	7
CA FID UST		0.250	3	2	NR	NR	NR	5
SLIC		0.500	Õ	2	1	NR	NR	3
AOCONCERN		1.000	Õ	0	0 0	0	NR	Õ
UST		0.250	2	1	NR	NR	NR	3
HIST UST		0.250	1	2	NR	NR	NR	3
AST		0.250	0	0	NR	NR	NR	0
LIENS		TP	NR	NR	NR	NR	NR	0
SWEEPS UST		0.250	3	2	NR	NR	NR	5
CHMIRS		TP	NR	NR	NR	NR	NR	0
Notify 65		1.000	0	0	0	0	NR	0
LA Co. Site Mitigation		TP	NR	NR	NR	NR	NR	0
DEED		0.500	0	0	0	NR	NR	0
VCP		0.500	0	0	0	NR	NR	0
DRYCLEANERS		0.250	0	1	NR	NR	NR	1
WIP		0.250	0	0	NR	NR	NR	0
Los Angeles Co. HMS		TP	NR	NR	NR	NR	NR	0
CDL		TP	NR	NR	NR	NR	NR	0
RESPONSE		1.000	0	0	0	0	NR	0
HAZNET		TP	NR	NR	NR	NR	NR	0
EMI		TP	NR	NR	NR	NR	NR	0
ENVIROSTOR		1.000	0	0	0	7	NR	7
HAULERS		TP	NR	NR	NR	NR	NR	0
TRIBAL RECORDS								
INDIAN RESERV		1.000	0	0	0	0	NR	0
INDIAN LUST		0.500	0	0	ŏ	NR	NR	0
INDIAN UST		0.250	Ő	õ	NR	NR	NR	õ
		0.200	U	Ū				0
EDR PROPRIETARY RECOR	DS							
Manufactured Gas Plants		1.000	0	0	0	0	NR	0
EDR Historical Auto Statio	ns	0.250	0	1	NR	NR	NR	1
EDR Historical Cleaners	10	0.250	0	0	NR	NR	NR	0
		0.200	U	0	INIX	1417	INIX	0

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

MAP FINDINGS

Database(s)

EDR ID Number **EPA ID Number** 

### RCRAInfo: **Relative:** Owner: NOT REQUIRED Lower (415) 555-1212 Actual: EPA ID: CAD981570526 62 ft. Contact: Not reported Classification: Small Quantity Generator TSDF Activities: Not reported

Violation Status: No violations found

# FINDS:

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

A2 West < 1/8 310 ft.	TEXACO 18910 CRENSHAW BLV TORRANCE, CA 90504 Site 1 of 2 in cluster A	D	LUST CHMIRS Cortese CA WDS	S102438546 N/A
Relative: Lower	LUST:	07475		
Actual:	Region: Case Type:	STATE Other ground water affected		
57 ft.	Cross Street:	190TH ST		
	Enf Type:	DLSEL		
	Funding:	Not reported		
	How Discovered:	OM		
	How Stopped:	Not reported		
	Leak Cause:	Structure Failure		
	Leak Source:	Piping		
	Global Id: Stop Date:	T0603701495 Not reported		
	Confirm Leak:	Not reported		
	Workplan:	Not reported		
	Prelim Assess:	Not reported		
	Pollution Char:	2005-04-15 00:00:00		
	Remed Plan:	2001-10-12 00:00:00		
	Remed Action:	2005-08-23 00:00:00		
	Monitoring:	Not reported		
	Close Date:	Not reported		
	Discover Date:	1990-05-01 00:00:00		
	Enforcement Dt:	Not reported		
	Release Date:	1990-08-17 00:00:00		
	Review Date: Enter Date:	Not reported 1990-12-02 00:00:00		
	MTBE Date:	1990-12-02 00:00:00 1999-07-29 00:00:00		
	GW Qualifier:	Not reported		

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

# TEXACO (Continued)

S102438546

Soil Qualifier:	Not reported
Max MTBE GW ppb:	
Max MTBE Soil ppb:	
County:	19
Org Name:	Not reported
Reg Board:	Los Angeles Region
Status:	Remedial action (cleanup) Underway
Chemical:	Diesel
Contact Person:	Not reported
Responsible Party:	EDWARD PADEN
RP Address:	911 S. PRIMROSE AVE., SUITE K
Interim:	Not reported
Oversight Prgm:	LUST
MTBE Class:	*
MTBE Conc:	1
MTBE Fuel:	0
MTBE Tested:	MTBE Detected. Site tested for MTBE and MTBE detected
Staff:	CEC
Staff Initials:	RVB
Lead Agency:	Regional Board
Local Agency:	19038
Hydr Basin #:	SAN FERNANDO VALLEY
Beneficial:	Not reported
Priority:	Not reported
Cleanup Fund Id:	Not reported
Work Suspended:	Not reported
Local Case #:	Not reported
Case Number:	905040216
Qty Leaked:	Not reported
Abate Method:	Remove Free Product - remove floating product from water table
Operator:	SAWERES/ABDELLMEBSH
Water System Name	
Well Name:	Not reported
Distance To Lust:	0
Waste Discharge Glo	•
	ed Name: Not reported
	RACK IN UNDERGROUND PRODUCT LINE; SINGLEWALL FIBERGLASS. PROBABLE CAUSE;
	ONG TERM VEHICLE WEIGHT ON DRIVE SLAB. PREVIOUS PLAN INITIATED LATE 1990;
7/1	13/00 2ND QTR GW MON RPT 2000; 9/5/00; 9/5/00 3RD QTR GW MON RPT

# LUST:

Region:	4
Staff:	CEC
County:	Los Angeles
Local Agency:	19038
Lead Agency:	Regional Board
Case Type:	Groundwater
Status:	Remediation Plan
Substance:	Diesel
Cross Street:	190TH ST
Global ID:	T0603701495
Enforcement Type:	LET
Date Leak Discovered:	5/1/1990
Date Leak Record Entered:	12/2/1990
How Leak Discovered:	OM
How Leak Stopped:	Not reported
Cause of Leak:	Structure Failure

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number **EPA ID Number** 

S102438546

# **TEXACO** (Continued)

Leak Source: Piping Date Leak Stopped: Not reported Date Confirmation Began: Not reported SAWERES/ABDELLMEBSH Operator: Water System: Not reported Well Name: Not reported Approx. Dist To Production Well (ft): 3430.6518426710299234240420484 Abatement Method Used at the Site: Remove Free Product Source of Cleanup Funding: **Remove Free Product** Date Leak First Reported: 8/17/1990 Preliminary Site Assessment Workplan Submitted: Not reported Preliminary Site Assessment Began: Not reported Pollution Characterization Began: 3/15/2001 Remediation Plan Submitted: 10/12/2001 Remedial Action Underway: Not reported Post Remedial Action Monitoring Began: Not reported Date the Case was Closed: Not reported Date Case Last Changed on Database: 7/17/2002 Enforcement Action Date: Not reported 7/29/2002 Historical Max MTBE Date: Hist Max MTBE Conc in Groundwater: 430000 Hist Max MTBE Conc in Soil: Not reported Significant Interim Remedial Action Taken: Not reported GW Qualifier: Soil Qualifier: Not reported Organization: Not reported **Regional Board:** 04 **Owner Contact:** Not reported Responsible Party: EDWARD PADEN **RP** Address: 10 UNIVERSAL CITY PLAZA, 10TH FL, Program: LUST Lat/Long: 33.8585577 / -1 Local Agency Staff: RVB Beneficial Use: Not reported Not reported Priority: Cleanup Fund Id: Not reported Suspended: Not reported Local Case No: Not reported Substance Quantity: Not reported Assigned Name: Not reported W Global ID: Not reported CRACK IN UNDERGROUND PRODUCT LINE: SINGLEWALL FIBERGLASS. PROBABLE Summary: CAUSE; LONG TERM VEHICLE WEIGHT ON DRIVE SLAB. PREVIOUS PLAN INITIATED LATE 1990; 7/13/00 2ND QTR GW MON RPT 2000; 9/5/00; 9/5/00 3RD QTR GW MON RPT CHMIRS: 00-3243 **OES Incident Number:** OES notification: 7/20/200003:39:36 PM OES Date: Not reported OES Time: Not reported Incident Date:

Not reported Not reported **Date Completed:** Not reported Agency Id Number: Not reported Agency Incident Number: Not reported

Not reported

Property Use:

Time Notified:

Map ID Direction Distance Distance (ft.) Elevation Site

# Database(s)

EDR ID Number EPA ID Number

# S102438546

# **TEXACO** (Continued)

ACO (Continued)	
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances I	
Resp Agncy Personel # Of De	
Responding Agency Personel	
Responding Agency Personel	
Others Number Of Decontami	
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	No Not reported
Waterway:	Not reported
Spill Site: Cleanup By:	Not reported Contractor
Containment:	Not reported
What Happened:	Not reported
Туре:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	2000
Agency:	Equiva Services
Incident Date:	7/19/200012:00:00 AM
Admin Agency:	Torrance Fire Department
Amount:	Not reported
Contained:	Yes
Site Type:	Service Station
E Date:	Not reported
Substance:	diesel
Quantity Released:	Not reported
BBLS:	0
Cups:	0
CUFT:	0
Gallons:	25
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0

EDR ID Database(s) EPA ID

# EDR ID Number EPA ID Number

### **TEXACO** (Continued) S102438546 Sheen: 0 0 Tons: Unknown: 0 Not reported Description: Evacuations: 0 Number of Injuries: 0 Number of Fatalities: 0 Description: Citizen used a pump that was out of order. about 5 gal went to a drain. All cleaned up and out. Cortese: CORTESE Region: Facility Addr2: 18910 CRENSHAW BLVD CA WDS: Facility ID: Los Angeles River 196600172 Facility Type: Other - Does not fall into the category of Municipal/Domestic, Industrial, Agricultural or Solid Waste (Class I, II or III) Facility Status: Active - Any facility with a continuous or seasonal discharge that is under Waste Discharge Requirements. NPDES Number: CAG834001 The 1st 2 characters designate the state. The remaining 7 are assigned by the Regional Board Subregion: 4 Facility Telephone: 3108162075 Facility Contact: Edward Payden EQUILON ENTERPRISES LLC Agency Name: Agency Address: Not reported Agency City, St, Zip: 0 Agency Contact: Not reported Agency Telephone: Not reported Agency Type: Private SIC Code: 2999 SIC Code 2: Not reported Contaminated Ground Water Primary Waste: Primary Waste Type: Designated/Influent or Solid Wastes that pose a significant threat to water quality because of their high concentrations (E.G., BOD, Hardness, TRF, Chloride). 'Manageable' hazardous wastes (E.G., inorganic salts and heavy metals) are included in this category. Secondary Waste: Not reported Secondary Waste Type: Not reported Design Flow: 0 **Baseline Flow:** 0 Reclamation: No reclamation requirements associated with this facility. POTW: The facility is not a POTW. Treat To Water: Moderate Threat to Water Quality. A violation could have a major adverse impact on receiving biota, can cause aesthetic impairment to a significant human population, or render unusable a potential domestic or municipal water supply. Awsthetic impairment would include nuisance from a waste treatment facility. Complexity: Category B - Any facility having a physical, chemical, or biological waste treatment system (except for septic systems with subsurface disposal), or any Class II or III disposal site, or facilities without treatment systems that are complex, such as marinas with petroleum products, solid wastes, and sewage pump out facilities.

Database(s)

EDR ID Number EPA ID Number

A3 West < 1/8 310 ft.	TEXACO SERVICE STATIO 18910 S CRENSHAW BLV TORRANCE, CA 90504		CA FID UST SWEEPS UST	S101583144 N/A
310 ft.	Site 2 of 2 in cluster A			
Relative: Lower	CA FID UST:	0000707		
	CA FID UST: Facility ID: Regulated By: Regulated ID: Cortese Code: SIC Code: Facility Phone: Mail To: Mailing Address: Mailing Address: Mailing Address 2: Mailing Address 2: Mailing Address 2: Mailing City,St,Zip: Contact: Mailing City,St,Zip: Contact: Mailing City,St,Zip: Contact: Mailing City,St,Zip: Contact: Mailing City,St,Zip: Contact: Mailing City,St,Zip: Contact: Mailing City,St,Zip: Contact: Mailing City,St,Zip: Contact: Mailing City,St,Zip: Contact: Mailing City,St,Zip: SWEEPS UST: Status: Comp Number: Number: Board Of Equalization Ref Date: Act Date: Created Date: Tank Status: Owner Tank Id: Swrcb Tank Id: Actv Date: Capacity:	05-21-93 05-21-93 02-29-88 A SS112UP01 19-038-006557-000001 04-23-92 12000		
	Tank Use: Stg: Content: Number Of Tanks: Status:	M.V. FUEL P REG UNLEADED 4		
	Comp Number: Number: Board Of Equalization Ref Date: Act Date: Created Date: Tank Status: Owner Tank Id: Swrcb Tank Id: Actv Date: Capacity: Tank Use: Stg: Content: Number Of Tanks:	A 6557 1 44-000217 05-21-93 05-21-93 02-29-88 A SS112SU02 19-038-006557-000002 08-09-90 12000 M.V. FUEL P REG UNLEADED Not reported		

Database(s)

EDR ID Number EPA ID Number

	()
Status:	A
Comp Number:	6557
Number:	1
Board Of Equalization:	44-000217
Ref Date:	05-21-93
Act Date:	05-21-93
Created Date:	02-29-88
Tank Status:	A
Owner Tank Id:	SS112UN03
Swrcb Tank Id:	19-038-006557-000003
Actv Date:	08-09-90
Capacity:	12000
Tank Use:	M.V. FUEL
Stg:	P
Content:	REG UNLEADED
Number Of Tanks:	Not reported
Status:	A
Comp Number:	6557
Number:	1
Board Of Equalization:	44-000217
Ref Date:	05-21-93
Act Date:	05-21-93
Created Date:	02-29-88
Tank Status:	A
Owner Tank Id:	SS112DE04
Swrcb Tank Id:	19-038-006557-000004
Actv Date:	08-09-90
Capacity:	12000
Tank Use:	M.V. FUEL
Stg:	P
Content:	DIESEL
Number Of Tanks:	Not reported
Status: Comp Number: Number: Board Of Equalization: Ref Date: Act Date: Created Date: Tank Status: Owner Tank Id: Swrcb Tank Id: Swrcb Tank Id: Actv Date: Capacity: Tank Use: Stg: Content: Number Of Tanks:	Not reported 6557 Not reported 44-000217 Not reported Not reported Not reported Not reported 19-038-006557-000005 Not reported 10000 M.V. FUEL PRODUCT REG UNLEADED 5
Status:	Not reported
Comp Number:	6557
Number:	Not reported
Board Of Equalization:	44-000217
Ref Date:	Not reported
Act Date:	Not reported

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

# **TEXACO SERVICE STATION #0274 (Continued)**

Created Date: Tank Status: Owner Tank Id: Swrcb Tank Id: Actv Date: Capacity: Tank Use: Stg: Content: Number Of Tanks:	Not reported Not reported 19-038-006557-000006 Not reported 10000 M.V. FUEL PRODUCT REG UNLEADED Not reported
Status: Comp Number: Number: Board Of Equalization: Ref Date: Act Date: Created Date: Tank Status: Owner Tank Id: Swrcb Tank Id: Swrcb Tank Id: Actv Date: Capacity: Tank Use: Stg: Content: Number Of Tanks:	Not reported 6557 Not reported 44-000217 Not reported Not reported Not reported Not reported 19-038-006557-000007 Not reported 10000 M.V. FUEL PRODUCT LEADED Not reported
Status: Comp Number: Number: Board Of Equalization: Ref Date: Act Date: Created Date: Tank Status: Owner Tank Id: Swrcb Tank Id: Swrcb Tank Id: Actv Date: Capacity: Tank Use: Stg: Content: Number Of Tanks:	Not reported 6557 Not reported 44-000217 Not reported Not reported Not reported Not reported 19-038-006557-000008 Not reported 10000 M.V. FUEL PRODUCT DIESEL Not reported
Status: Comp Number: Number: Board Of Equalization: Ref Date: Act Date: Created Date: Tank Status: Owner Tank Id: Swrcb Tank Id: Actv Date: Capacity:	Not reported 6557 Not reported 44-000217 Not reported Not reported Not reported Not reported Not reported 19-038-006557-000009 Not reported 550

Map ID		MAP FINDINGS		
Direction Distance Distance (ft. Elevation	) Site		Database(s)	EDR ID Number EPA ID Number
	TEXACO SERVICE S	TATION #0274 (Continued)		S101583144
	Tank Use: Stg: Content: Number Of Tanł	OIL WASTE WASTE OIL s: Not reported		
4 West < 1/8 320 ft.	SHELL STATION #1 18910 CRENSHAW E , CA		UST	U003805425 N/A
Relative: Lower	UST: Region:	TORRANCE		
Actual: 55 ft.	Facility ID: Facility Status:	6557 Active		
5 North < 1/8 366 ft.	SAKURA FINETEK U 18700 CRENSHAW E TORRANCE, CA 905	BLVD	RCRA-SQG FINDS	1000978389 CA0001010016
Relative: Higher	RCRAInfo: Owner:	SAKURA FINETEK U S A INC (310) 516-5222		
Actual: 65 ft.	EPA ID:			
	Contact:	HISAHIDE KIMURA (310) 516-5222		
	Classification: TSDF Activities:	Small Quantity Generator Not reported		
	Violation Status:	No violations found		
	FINDS: Other Pertinent	Environmental Activity Identified at Site		
		RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.		
6 East < 1/8 509 ft.	SITE A 2545 W 190TH ST TORRANCE, CA 905	504	FINDS HAZNET RCRA-LQG	1004677942 CAR000103259
Relative: Lower	FINDS: Other Pertinent	Environmental Activity Identified at Site		
Actual: 63 ft.		RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA		

Database(s)

EDR ID Number EPA ID Number

# SITE A (Continued)

program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZNET: Gepaid: Contact: Telephone: Facility Addr2: Mailing Name: Mailing Address: Mailing City,St,Zip: Gen County: TSD EPA ID: TSD County: Waste Category: Disposal Method: Tons: Facility County:	CAR000103259 BENNY DEHGHI 3105122296 Not reported BENNY DEHGHI/PROJECT MGR 2525 W 190TH ST MS 23 1 80 TORRANCE, CA 905040000 Los Angeles CAD008302903 Los Angeles Contaminated soil from site clean-ups Transfer Station 0.03 Los Angeles
Gepaid:	CAR000103259
Contact:	BENNY DEHGHI
Telephone:	3105122296
Facility Addr2:	Not reported
Mailing Name:	BENNY DEHGHI/PROJECT MGR
Mailing Address:	2525 W 190TH ST MS 23 1 80
Mailing City,St,Zip:	TORRANCE, CA 905040000
Gen County:	Los Angeles
TSD EPA ID:	CAD008302903
TSD County:	Los Angeles
Waste Category:	Aqueous solution with less than 10% total organic residues
Disposal Method:	Recycler
Tons:	5.28
Facility County:	Los Angeles
Gepaid: Contact: Telephone: Facility Addr2: Mailing Name: Mailing Address: Mailing City,St,Zip: Gen County: TSD EPA ID: TSD County: Waste Category: Disposal Method: Tons: Facility County:	CAR000103259 BENNY DEHGHI, MANAGER 3105122296 Not reported 2525 W 190TH ST STOP 23 1 80 TORRANCE, CA 905040000 Los Angeles CAD008302903 Los Angeles Aqueous solution with less than 10% total organic residues Not reported 1.4 Not reported
Gepaid:	CAR000103259
Contact:	BENNY DEHGHI, MANAGER
Telephone:	3105122296
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	2525 W 190TH ST STOP 23 1 80
Mailing City,St,Zip:	TORRANCE, CA 905040000

# 1004677942

Database(s)

EDR ID Number EPA ID Number

# SITE A (Continued)

Gen County: TSD EPA ID: TSD County: Waste Category: Disposal Method: Tons: Facility County:	Los Angeles CAD008302903 Los Angeles Aqueous solution with less than 10% total organic residues Not reported 1.4 Not reported
Gepaid:	CAR000103259
Contact:	EHIHHUNG HSIA/PROJECT ENG
Telephone:	3105122296
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	2525 W 190TH ST MS 23 1 80
Mailing City,St,Zip:	TORRANCE, CA 905040000
Gen County:	Los Angeles
TSD EPA ID:	Not reported
TSD County:	Kings
Waste Category:	Contaminated soil from site clean-ups
Disposal Method:	Disposal, Land Fill
Tons:	42.19
Facility County:	Not reported

<u>Click this hyperlink</u> while viewing on your computer to access 4 additional CA\_HAZNET: record(s) in the EDR Site Report.

# RCRAInfo:

NTURES
-2525
03259
DEHGHI -2296

Classification: Large Quantity Generator TSDF Activities: Not reported

# **BIENNIAL REPORTS:**

Last Biennial Reporting Year: 2005

<u>Waste</u>	Quantity (Lbs)	Waste
D029	17640.00	D039
D040	17640.00	

Violation Status: No violations found

# B7 QUAKER STATE MINIT-LUBE INC. West 3209 W 190TH ST

# < 1/8 TORRANCE, CA 90503

563 ft.

Actual:

59 ft.

# Site 1 of 8 in cluster B

Relative: Lower CA FID UST: Facility ID:

# Facility ID:19034831Regulated By:UTNKARegulated ID:Not reportedCortese Code:Not reportedSIC Code:Not reportedFacility Phone:Not reportedMail To:Not reported

CA FID UST S101585959 SWEEPS UST N/A

Quantity (Lbs)

17640.00

# 1004677942

## Map ID Direction Distance Distance (ft.) Site Elevation

MAP FINDINGS

Database(s)

EDR ID Number **EPA ID Number** 

S101585959

Mailing Address:	2130 E 4TH ST
Mailing Address 2:	Not reported
Mailing City,St,Zip:	TORRANCE 90503
Contact:	Not reported
Contact Phone:	Not reported
DUNs Number:	Not reported
NPDES Number:	Not reported
EPA ID:	Not reported
Comments:	Not reported
Comments:	Not reported
Status:	Active

# SWEEPS UST:

Status:	A
Comp Number:	7596
Number:	1
Board Of Equalization:	44-010619
Ref Date:	09-26-90
Act Date:	09-26-90
Created Date:	09-26-90
Tank Status:	A
Owner Tank Id:	UT466NL01
Swrcb Tank Id:	19-038-007596-000001
Actv Date:	05-18-93
Capacity:	5790
Tank Use:	OIL
Stg:	Р
Content:	3 COMP. TANK
Number Of Tanks:	1

### **B**8 MINIT LUBE NO 1298 West 3209 WEST 190TH < 1/8

TORRANCE, CA	90504

# Site 2 of 8 in cluster B

Deletion	Site 2 of 8 in cluster B	
Relative: Lower	RCRAInfo:	
Actual: 59 ft.	Owner: EPA ID:	QUAKER STATE MINIT LUBE INC (801) 972-6667 CAD983598822
	Contact:	MARTIN ESCOBAR (213) 329-2277
	Classification:	Small Quantity Generator

Classification: Small Quantity Generator TSDF Activities: Not reported

Violation Status: No violations found

# HAZNET:

Gepaid:	CAD983598822
Contact:	QUAKER STATE MINIT LUBE INC
Telephone:	8019726667
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	3209 W 190TH ST
Mailing City,St,Zip:	TORRANCE, CA 905045902
Gen County:	Los Angeles
TSD EPA ID:	CAT080013352

RCRA-SQG 1000595924 HAZNET CAD983598822

TC2051883.2s Page 17

Database(s)

EDR ID Number EPA ID Number

	MINIT LUBE NO 1298 (	(Continued)		1000595924
	TSD County: Waste Category:	Los Angeles Unspecified oil-containing waste		
	Waste Category: Disposal Method:	Recycler		
	Tons:	.9382		
	Facility County:	Los Angeles		
	r dointy obdinty.			
B9	MOBIL SERVICE STATI		UST	U003805368
West	19009 CRENSHAW BLV	/D		N/A
< 1/8	, CA			
648 ft.	Site 3 of 8 in cluster B			
Relative:				
Lower	UST:			
	5	ORRANCE		
Actual:	5	39945		
61 ft.	Facility Status: A	Active		
B10	MOBIL #18-ECP (FORM	IER #11-ECP)	LUST	S103286028
West	19009 CRENSHAW BLV	/D	CHMIRS	N/A
< 1/8	TORRANCE, CA 90504			
648 ft.				
Relative:	Site 4 of 8 in cluster B			
Lower	LUST:			
	Region:	STATE		
Actual:	Case Type:	Other ground water affected		
61 ft.	Cross Street:	190TH ST		
	Enf Type:	DLLET		
	Funding:	Not reported		
	How Discovered: How Stopped:	Subsurface Monitoring Not reported		
	Leak Cause:	UNK		
	Leak Source:	UNK		
	Global Id:	T0603701490		
	Stop Date:	Not reported		
	Confirm Leak:	Not reported		
	Workplan:	Not reported		
	Prelim Assess:	Not reported		
	Pollution Char:	2005-04-27 00:00:00		
	Remed Plan:	Not reported		
	Remed Action:	Not reported		
	Monitoring: Close Date:	Not reported		
	Discover Date:	Not reported 1987-04-08 00:00:00		
	Enforcement Dt:	Not reported		
	Release Date:	1987-04-08 00:00:00		
	Review Date:	Not reported		
	Enter Date:	1987-08-14 00:00:00		
	MTBE Date:	1965-01-01 00:00:00		
	GW Qualifier:	Not reported		
	Soil Qualifier:	Not reported		
	Max MTBE GW ppt			
	Max MTBE Soil ppt			
	County:	19		
	Org Name:	Not reported		
	Reg Board:	Los Angeles Region		

# Map ID Direction Distance Distance (ft.) Elevation Site

MAP FINDINGS

Database(s)

EDR ID Number EPA ID Number

# S103286028

# MOBIL #18-ECP (FORMER #11-ECP) (Continued)

Status: **Pollution Characterization** Chemical: Gasoline Contact Person: Not reported Responsible Party: LIZANNE SIMMONS 9555 CHESAPEAKE DR., #101 **RP Address:** Interim: Not reported Oversight Prgm: LUST MTBE Class: MTBE Conc: 1 MTBE Fuel: 1 MTBE Detected. Site tested for MTBE and MTBE detected MTBE Tested: Staff: AT Staff Initials: RVB Lead Agency: **Regional Board** 19038 Local Agency: SAN FERNANDO VALLEY Hydr Basin #: Not reported Beneficial: Not reported Priority: Cleanup Fund Id: Not reported Work Suspended: Not reported Local Case #: Not reported 905040161 Case Number: Qty Leaked: Not reported Abate Method: Remove Free Product - remove floating product from water table Operator: Not reported Water System Name:Not reported Well Name: Not reported Distance To Lust: 0 Waste Discharge Global ID: Not reported Waste Disch Assigned Name: Not reported 11/15/96 - CLOSURE DENIED DUE TO FP & DIFFERENT AQUIFER CONTBY MOBIL REFINERY, Summary: DRINKING WATER WELL @1 MILE, VERY CLOSE GARDENA AQUIFER (15 FEET) ; 1/11/01 4TH QTR GW MON RPT 2000; 3/16/01 1ST QTR GW MON RPT 2001

# LUST:

Region:	4
Staff:	AT
County:	Los Angeles
Local Agency:	19038
Lead Agency:	Regional Board
Case Type:	Groundwater
Status:	Pollution Characterization
Substance:	Gasoline
Cross Street:	190TH ST
Global ID:	T0603701490
Enforcement Type:	None Taken
Date Leak Discovered:	4/8/1987
Date Leak Record Entered:	8/14/1987
How Leak Discovered:	Subsurface Monitoring
How Leak Stopped:	Not reported
Cause of Leak:	UNK
Leak Source:	UNK
Date Leak Stopped:	Not reported
Date Confirmation Began:	Not reported
Operator:	Not reported
Water System:	Not reported
Well Name:	Not reported

Mag. 15					
Map ID Direction	L_	M	AP FINDINGS		
Distance Distance (ft Elevation	.) Site			Database(s)	EDR ID Number EPA ID Number
	MOBIL #18-ECP (FORMER #11	-ECP) (Continued	)		S103286028
	Approx. Dist To Production	n Well (ft):	3454.9316187003680657323498	362	
	Abatement Method Used a		Remove Free Product		
	Source of Cleanup Funding	g:	Remove Free Product		
	Date Leak First Reported:		4/8/1987		
	Preliminary Site Assessme	•	· · · ·		
	Preliminary Site Assessme Pollution Characterization	-	Not reported 5/7/1998		
	Remediation Plan Submitte	0	Not reported		
	Remedial Action Underway		Not reported		
	Post Remedial Action Mon		Not reported		
	Date the Case was Closed	:	Not reported		
	Date Case Last Changed of	on Database:	10/16/2002		
	Enforcement Action Date:		Not reported		
	Historical Max MTBE Date		1/1/1965		
	Hist Max MTBE Conc in G Hist Max MTBE Conc in So		38000 Not reported		
	Significant Interim Remedia		Not reported		
	GW Qualifier:	Not reported	Heriopolied		
	Soil Qualifier:	Not reported			
	Organization:	Not reported			
	Regional Board:	04			
	Owner Contact:	Not reported			
	Responsible Party:	JOHN MEDRANO			
	RP Address: Program:	3700 W. 190TH S LUST	1., IPI-2		
	Lat/Long:	33.8581867 / -1			
	Local Agency Staff:	RVB			
	Beneficial Use:	Not reported			
	Priority:	Not reported			
	Cleanup Fund Id:	Not reported			
	Suspended:	Not reported			
	Local Case No:	Not reported			
	Substance Quantity: Assigned Name:	Not reported Not reported			
	W Global ID:	Not reported			
	Summary:		JRE DENIED DUE TO FP & DIFFERE	NT AQUIFER CON	TBY MOBIL
			KING WATER WELL @1 MILE, VERY		
		, .	TH QTR GW MON RPT 2000; 3/16/01	1 1ST QTR GW MC	N RPT
		2001			
	CHMIRS:				
	OES Incident Number:	05-4952	04 <b>DM</b>		
	OES notification:	8/24/200512:16	:04 PM		
	OES Date: OES Time:	Not reported Not reported			
	Incident Date:	Not reported			
	Date Completed:	Not reported			
	Property Use:	Not reported			
	Agency Id Number:	Not reported			
	Agency Incident Number:	Not reported			
	Time Notified:	Not reported			
	Time Completed:	Not reported			
	Surrounding Area:	Not reported			
	Estimated Temperature:	Not reported			

Not reported Not reported Not reported Not reported

Not reported Not reported Not reported

Estimated Temperature:

Property Management: Special Studies 1: Special Studies 2:

Map ID Direction Distance Distance (ft.) Elevation Site

TINDINGS

Database(s)

EDR ID Number EPA ID Number

# MOBIL #18-ECP (FORMER #11-ECP) (Continued)

**Special Studies 3:** Not reported Special Studies 4: Not reported Special Studies 5: Not reported Special Studies 6: Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Vehicle License Number: Not reported Vehicle State: Not reported Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Company Name: Not reported Reporting Officer Name/ID: Not reported Report Date: Not reported Comments: Not reported Facility Telephone: Not reported Waterway Involved: Not reported Not reported Waterway: Spill Site: Not reported Cleanup By: **Responsible Party** Containment: Not reported What Happened: Not reported Type: Not reported Measure: Not reported Not reported Other: Not reported Date/Time: Year: 2005 Agency: Veeder Root Incident Date: 8/24/200512:00:00 AM Admin Agency: **Torrance Fire Department** Not reported Amount: Contained: Yes Site Type: Service Station E Date: Not reported Substance: Gasoline Quantity Released: Not reported BBLS: 0 Cups: 0 CUFT: 0 0.000000 Gallons: Grams: 0 Pounds: 0 Liters: 0 Ounces: 0 Pints: 0 Quarts: 0 Sheen: 0 Tons: 0 Unknown: 0 Description: Not reported Evacuations: 0 Number of Injuries: 0

	MAP FINDINGS		
) Site		Database(s)	EDR ID Numbe EPA ID Numbe
MOBIL #18-ECP (FORM	ER #11-ECP) (Continued)		S103286028
Number of Fatalities Description:	<ul> <li>0</li> <li>Substance was released from dispenser</li> </ul>	number 12 due to auto-shutoff fa	ilure.
MOBIL #18-ECP (FORM 19009 CRENSHAW TORRANCE, CA 90504	ER #11	Cortese	S102433535 N/A
Site 5 of 8 in cluster B			
- 3 -	CORTESE Not reported		
MOBIL SERVICE STATI 19009 S CRENSHAW BI TORRANCE, CA 90504	ON 11-ECP C/O KEN PEZESHK (DEAL _VD	CA FID UST SWEEPS UST	S101582778 N/A
Site 6 of 8 in cluster B			
CA FID UST:			
Facility ID: Regulated By: Regulated ID: Cortese Code: SIC Code: Facility Phone: Mail To: Mailing Address: Mailing Address 2: Mailing City,St,Zip: Contact: Contact Phone: DUNs Number: NPDES Number: EPA ID: Comments: Status:	19001354 UTNKA 00039945 Not reported 3102126023 Not reported 3225 GALLOWS RD Not reported TORRANCE 90504 Not reported Not reported Active		
SWEEPS UST: Status: Comp Number: Number:	A 39945 1		
Board Of Equalizati Ref Date: Act Date: Created Date: Tank Status:	03-11-92 03-11-92 02-29-88		
Owner Tank Id: Swrcb Tank Id: Actv Date: Capacity:	A SS113UN01 19-038-039945-000001 07-22-92 12000		
Tank Use: Stg: Content:	M.V. FUEL P REG UNLEADED		

Database(s)

EDR ID Number EPA ID Number

Status:	A
Comp Number:	39945
Number:	1
Board Of Equalization:	44-000400
Ref Date:	03-11-92
Act Date:	03-11-92
Created Date:	02-29-88
Tank Status:	A
Owner Tank Id:	SS113SU02
Swrcb Tank Id:	19-038-039945-000002
Actv Date:	07-22-92
Capacity:	10000
Tank Use:	M.V. FUEL
Stg:	P
Content:	REG UNLEADED
Number Of Tanks:	Not reported
Status:	A
Comp Number:	39945
Number:	1
Board Of Equalization:	
Ref Date:	03-11-92
Act Date:	03-11-92
Created Date:	02-29-88
Tank Status:	A
Owner Tank Id:	SS113UP03
Swrcb Tank Id:	19-038-039945-000003
Actv Date:	07-22-92
Capacity: Tank Use:	6000 M.V. FUEL
Stg:	P
Content:	' REG UNLEADED
Number Of Tanks:	Not reported
Number of Tanks.	Notreported
Status:	A
Comp Number:	39945
Number:	1
Board Of Equalization:	
Ref Date: Act Date:	03-11-92
Created Date:	03-11-92 02-29-88
Tank Status:	02-29-66 A
Owner Tank Id:	SS113DE04
Swrcb Tank Id:	19-038-039945-000004
Actv Date:	07-22-92
Capacity:	6000
Tank Use:	M.V. FUEL
Stg:	P
Content:	DIESEL
Number Of Tanks:	Not reported
Status:	Not reported
Comp Number:	39945
Number:	Not reported
Board Of Equalization:	44-000400
Ref Date:	Not reported

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

Created Date:	Not reported	
Tank Status:	Not reported	
Owner Tank Id:	Not reported	
Swrcb Tank Id:	19-038-039945-000005	
Actv Date:	Not reported	
Capacity:	9940	
Tank Use:	M.V. FUEL	
Stg:	PRODUCT	
Content: Number Of Tanks:	REG UNLEADED 4	
Status:	Not reported	
Comp Number:	39945	
Number:	Not reported	
Board Of Equalization:	44-000400	
Ref Date:	Not reported	
Act Date:	Not reported	
Created Date:	Not reported	
Tank Status:	Not reported	
Owner Tank Id:	Not reported	
Swrcb Tank Id:	19-038-039945-000006	
Actv Date:	Not reported	
Capacity:	8000	
Tank Use:	M.V. FUEL	
Stg:	PRODUCT	
Content:	REG UNLEADED	
Number Of Tanks:		
Number Of Tanks:	Not reported	
Status:	Not reported	
Comp Number:	39945	
Number:	Not reported	
Board Of Equalization:	44-000400	
Ref Date:	Not reported	
Act Date:	Not reported	
Created Date:	Not reported	
Tank Status:	Not reported	
Owner Tank Id:	Not reported	
Swrcb Tank Id:	19-038-039945-000007	
Actv Date:	Not reported	
Capacity:	280	
Tank Use:	OIL	
Stg:	WASTE	
Content:	WASTE OIL	
Number Of Tanks:	Not reported	
Status:	Not reported	
Comp Number:	39945	
Number:	Not reported	
Board Of Equalization:	44-000400	
Ref Date:	Not reported	
Act Date:	Not reported	
Created Date:	Not reported	
Tank Status:	Not reported	
Owner Tank Id:	Not reported	
Swrcb Tank Id:	19-038-039945-000008	
Actv Date:	Not reported	
Capacity:	6000	

Map ID Direction		MAP FINDINGS		
Distance				
Distance (ft Elevation	.) Site		Database(s)	EDR ID Number EPA ID Number
	MOBIL SERVICE STATIO	DN 11-ECP C/O KEN PEZESHK (DEAL (Continued)		S101582778
	Tank Use:	M.V. FUEL		
	Stg:	PRODUCT		
	Content: Number Of Tanks:	DIESEL Not reported		
-				
B13 West	S. SUNG 19009 CRENSHAW BLV	D	HAZNET HIST UST	U001564187 N/A
< 1/8	TORRANCE, CA 90504	-		
648 ft.	Site 7 of 8 in cluster B			
Relative: Lower	HAZNET:			
Lower	Gepaid:	CAL000056165		
Actual: 61 ft.	Contact:	DALE VIATOR, ENVT'L ADVISOR		
0111.	Telephone: Facility Addr2:	2816548470 Not reported		
	Mailing Name:	TANKNOLOGY NDE		
	Mailing Address:	16825 NORTHCHASE DRIVE RM 911		
	Mailing City,St,Zip: Gen County:	HOUSTON, TX 770600000 Los Angeles		
	TSD EPA ID:	CAT080014079		
	TSD County:	Los Angeles		
	Waste Category:	Other organic solids		
	Disposal Method: Tons:	Transfer Station 0.08		
	Facility County:	Los Angeles		
	Gepaid:	CAL000056165		
	Contact:	DALE VIATOR, ENVT'L ADVISOR		
	Telephone:	2816548470		
	Facility Addr2: Mailing Name:	Not reported TANKNOLOGY NDE		
	Mailing Address:	16825 NORTHCHASE DRIVE RM 911		
	Mailing City,St,Zip:			
	Gen County: TSD EPA ID:	Los Angeles CAD028409019		
	TSD County:	Los Angeles		
	Waste Category:	Unspecified oil-containing waste		
	Disposal Method: Tons:	Treatment, Tank 0.03		
	Facility County:	Los Angeles		
	Gepaid:	CAL000056165		
	Contact:	DALE VIATOR, ENVT'L ADVISOR		
	Telephone: Facility Addr2:	2816548470 Not reported		
	Mailing Name:	Not reported		
	Mailing Address:	16825 NORTHCHASE DRIVE RM 911		
	Mailing City,St,Zip:	HOUSTON, TX 770600000		
	Gen County: TSD EPA ID:	Los Angeles CAD028409019		
	TSD County:	Los Angeles		
	Waste Category:	Aqueous solution with 10% or more total organic residues		
	Disposal Method: Tons:	Treatment, Tank 0.45		
	Facility County:	Not reported		

Database(s)

EDR ID Number EPA ID Number

# S. SUNG (Continued)

### HIST UST: STATE Region: Facility ID: 0000039945 Tank Num: 001 Container Num: 1 1968 Year Installed: 00000280 Tank Capacity: Gas Station Facility Type: Other Type: Not reported Total Tanks: 0004 Tank Used for: WASTE WASTE OIL Type of Fuel: Tank Construction: Not reported Leak Detection: Stock Inventor SAME Contact Name: 2133282800 Telephone: Owner Name: MOBIL OIL CORP Owner Address: 612 S. FLOWER ST Owner City, St, Zip: LOS ANGELES, CA 90017 STATE Region: Facility ID: 0000039945 Tank Num: 002 Container Num: 2 Year Installed: 1982 Tank Capacity: 00006000 Gas Station Facility Type: Other Type: Not reported Total Tanks: 0004 PRODUCT Tank Used for: REGULAR Type of Fuel: Tank Construction: Not reported Leak Detection: Stock Inventor SAME Contact Name: Telephone: 2133282800 Owner Name: MOBIL OIL CORP Owner Address: 612 S. FLOWER ST Owner City, St, Zip: LOS ANGELES, CA 90017 STATE Region: Facility ID: 0000039945 Tank Num: 003 Container Num: 3 Year Installed: 1982 Tank Capacity: 0008000 Gas Station Facility Type: Other Type: Not reported 0004 Total Tanks: PRODUCT Tank Used for: Type of Fuel: PREMIUM Tank Construction: Not reported Leak Detection: Stock Inventor Contact Name: SAME 2133282800 Telephone: Owner Name: MOBIL OIL CORP

612 S. FLOWER ST

LOS ANGELES, CA 90017

Owner Address:

Owner City,St,Zip:

# U001564187

Database(s)

EDR ID Number EPA ID Number

U001564187

# S. SUNG (Continued)

Region:	STATE
Facility ID:	0000039945
Tank Num:	004
Container Num:	4
Year Installed:	1982
Tank Capacity:	00010000
Facility Type:	Gas Station
Other Type:	Not reported
Total Tanks:	0004
Tank Used for:	PRODUCT
Type of Fuel:	UNLEADED
Tank Construction:	Not reported
Leak Detection:	Stock Inventor
Contact Name:	SAME
Telephone:	2133282800
Owner Name:	MOBIL OIL CORP
Owner Address:	612 S. FLOWER ST
Owner City,St,Zip:	LOS ANGELES, CA 90017

# 14 TAKANE USA INC North 18640 CRENSHAW BLVD

# < 1/8 TORRANCE, CA 90504 649 ft.

Relative:	RCRAInfo:	TAKEO HANAOKA
Higher	Owner:	(415) 555-1212
Actual:	EPA ID:	CAD981970288
66 ft.	Contact:	ENVIRONMENTAL MANAGER
	Classification:	(213) 538-4920 Small Quantity Generator
	TSDF Activities:	Not reported

Violation Status: No violations found

# FINDS:

Other Pertinent Environmental Activity Identified at Site

California - Hazardous Waste Tracking System - Datamart

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

# HAZNET:

Gepaid:	CAC002250617
Contact:	TAKANE USA INC
Telephone:	3105384920
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	18640 CRENSHAW BLVD
Mailing City,St,Zip:	TORRANCE, CA 905040000

# RCRA-SQG 1000152173 FINDS CAD981970288 HAZNET

Database(s)

EDR ID Number EPA ID Number

# TAKANE USA INC (Continued)

Gen County:	Los Angeles
TSD EPA ID:	CAD028409019
TSD County:	Los Angeles
Waste Category:	Unspecified solvent mixture Waste
Disposal Method:	Transfer Station
Tons:	.4170
Facility County:	Los Angeles

B15 West 1/8-1/4	MOHAWK SERVICE STA 18910 CRENSHAW TORRANCE, CA 90504	ATION #04067	HIST UST
672 ft. Relative:	Site 8 of 8 in cluster B		
Lower Actual: 61 ft.	HIST UST: Region: Facility ID: Tank Num: Container Num: Year Installed: Tank Capacity: Facility Type: Other Type: Other Type: Total Tanks: Tank Used for: Type of Fuel: Tank Construction: Leak Detection: Contact Name: Telephone: Owner Name: Owner Address: Owner City, St, Zip:	STATE 0000006557 001 1 1979 00012000 Gas Station Not reported 0004 PRODUCT UNLEADED 1/4 inches Stock Inventor TERI TOLEDO 2135157647 GETTY REFINING & MARKETING COM P.O. BOX 1476 BAKERSFIELD, CA 93302	
	Region: Facility ID: Tank Num: Container Num: Year Installed: Tank Capacity: Facility Type: Other Type: Total Tanks: Tank Used for: Type of Fuel: Tank Construction: Leak Detection: Contact Name: Telephone: Owner Name: Owner Address: Owner City,St,Zip:	STATE 0000006557 002 2 1979 00012000 Gas Station Not reported 0004 PRODUCT REGULAR 1/4 inches Stock Inventor TERI TOLEDO 2135157647 GETTY REFINING & MARKETING COM P.O. BOX 1476 BAKERSFIELD, CA 93302	
	Region: Facility ID: Tank Num: Container Num: Year Installed:	STATE 00000006557 003 3 1979	

HIST UST U001564183 N/A

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

# MOHAWK SERVICE STATION #04067 (Continued)

0004

PRODUCT

DIESEL

1/4 inches

Stock Inventor

**TERI TOLEDO** 

P.O. BOX 1476

BAKERSFIELD, CA 93302

**GETTY REFINING & MARKETING COM** 

2135157647

Mailing City, St, Zip: TORRANCE, CA 905040000

Total Tanks:

Tank Used for:

Leak Detection:

Contact Name:

Owner Name:

Owner Address: Owner City,St,Zip:

Telephone:

Tank Construction:

Type of Fuel:

Tank Capacity: 00012000 Facility Type: Gas Station Other Type: Not reported Total Tanks: 0004 Tank Used for: PRODUCT Type of Fuel: PREMIUM Tank Construction: 1/4 inches Leak Detection: Stock Inventor Contact Name: TERI TOLEDO Telephone: 2135157647 **GETTY REFINING & MARKETING COM** Owner Name: P.O. BOX 1476 Owner Address: Owner City,St,Zip: BAKERSFIELD, CA 93302 Region: STATE Facility ID: 0000006557 Tank Num: 004 Container Num: 4 Year Installed: 1979 00012000 Tank Capacity: Facility Type: Gas Station Other Type: Not reported

U0	015	641	83
----	-----	-----	----

16 East 1/8-1/4 813 ft.	MCGEE'S SERVICE MOBIL PRODUCTS 2701 W 190TH ST REDONDO BEACH, CA 90277		EDR Historical Auto Stations	1008996420 N/A
Relative: Lower	EDR Historical Auto S Name: Year:	Stations: MCGEE'S SERVICE MOBIL PRODUCTS 1963		
Actual: 62 ft.	Туре:	Not reported		
17 North 1/8-1/4 912 ft.	GEORGE P JOHNSON 18500 CRENSHAW BL' TORRANCE, CA 90504	VD	HAZNET CLEANERS EMI	S104583125 N/A
Relative: Higher Actual: 71 ft.	HAZNET: Gepaid: Contact: Telephone: Facility Addr2: Mailing Name:	CAL000209124 VALLEE ROBERT SR 3109654326 Not reported Not reported		

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

# S104583125

# **GEORGE P JOHNSON CO (Continued)**

Gen County: TSD EPA ID: TSD County: Waste Category: Disposal Method: Tons: Facility County:	Los Angeles CAD008252405 Los Angeles Not reported Transfer Station .0000 Los Angeles
Gepaid: Contact: Telephone: Facility Addr2: Mailing Name: Mailing Address: Mailing City,St,Zip: Gen County: TSD EPA ID: TSD County: Waste Category: Disposal Method: Tons: Facility County:	CAL000209124 VALLEE ROBERT SR 3109654326 Not reported 18500 CRENSHAW BLVD TORRANCE, CA 905040000 Los Angeles CAD008252405 Los Angeles Other organic solids Transfer Station 2.7250 Los Angeles
Gepaid: Contact: Telephone: Facility Addr2: Mailing Name: Mailing Address: Mailing City,St,Zip: Gen County: TSD EPA ID: TSD County: Waste Category: Disposal Method: Tons: Facility County:	CAL000209124 VALLEE ROBERT SR 3109654326 Not reported 18500 CRENSHAW BLVD TORRANCE, CA 905040000 Los Angeles CAD008252405 Los Angeles Unspecified solvent mixture Waste Recycler .0750 Los Angeles
Gepaid: Contact: Telephone: Facility Addr2: Mailing Name: Mailing Address: Mailing City,St,Zip: Gen County: TSD EPA ID: TSD County: Waste Category: Disposal Method: Tons: Facility County:	CAL000209124 VALLEE ROBERT SR 3109654326 Not reported 18500 CRENSHAW BLVD TORRANCE, CA 905040000 Los Angeles CAD008252405 Los Angeles Other organic solids Not reported 2.9435 Los Angeles
Gepaid: Contact: Telephone: Facility Addr2:	CAL000209124 VALLEE ROBERT SR 3109654326 Not reported

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

# S104583125

# **GEORGE P JOHNSON CO (Continued)**

Mailing Name: Mailing Address:	Not reported 18500 CRENSHAW BLVD
Mailing City,St,Zip:	TORRANCE, CA 905040000
Gen County:	Los Angeles
TSD EPA ID:	CAD008252405
TSD County:	Los Angeles Latex waste
Waste Category: Disposal Method:	Not reported
Tons:	4.7955
Facility County:	Los Angeles

<u>Click this hyperlink</u> while viewing on your computer to access 21 additional CA\_HAZNET: record(s) in the EDR Site Report.

# CLEANERS:

EPA ld:	CAL000209124
NAICS Code:	81232
NAICS Description:	Drycleaning and Laundry Services (except Coin-Operated)
SIC Code:	7211
Create Date:	10/13/1999
Facility Active:	Yes
Inactive Date:	Not reported
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	18500 CRENSHAW BLVD
Mailing Address 2:	Not reported
Mailing State:	CA
Mailing Zip:	905040000
Region Code:	3
Owner Name:	VALLEE ROBERT SR
Owner Address:	18500 CRENSHAW BLVD
Owner Address 2:	Not reported
Owner Telephone:	Not reported
Contact Name:	JEFF MARCON/PRODUCTION MGR
Contact Address:	18500 CRANSHAW BLVD
Contact Address 2:	Not reported
Contact Telephone:	3109654300
SIC Description: G	arment Pressing and Agents for Laundries and DrycleanersDrycleaning Plants
E	xcept Rug CleaningPower Laundries Family and CommercialLaundry and Garment
S	ervices NEC (except diaper service and clothing alteration and repair)

EPA Id: CA	AL000209124
NAICS Code: 81	1232
NAICS Description: Dr	rycleaning and Laundry Services (except Coin-Operated)
SIC Code: 72	216
Create Date: 10	D/13/1999
Facility Active: Ye	es
Inactive Date: No	ot reported
Facility Addr2: No	ot reported
Mailing Name: No	ot reported
Mailing Address: 18	3500 CRENSHAW BLVD
Mailing Address 2: No	ot reported
Mailing State: CA	A
Mailing Zip: 90	05040000
Region Code: 3	
Owner Name: VA	ALLEE ROBERT SR
Owner Address: 18	3500 CRENSHAW BLVD

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

# **GEORGE P JOHNSON CO (Continued)**

	O (Continuea)	5104
Owner Address 2:	Not reported	
Owner Telephone:	Not reported	
Contact Name:	JEFF MARCON/PRODUCTION MGR	
Contact Address:	18500 CRANSHAW BLVD	
Contact Address 2:	Not reported	
Contact Telephone:		
SIC Description: G	arment Pressing and Agents for Laundries and DrycleanersDrycleaning Plants	
	ccept Rug CleaningPower Laundries Family and CommercialLaundry and Garment ervices NEC (except diaper service and clothing alteration and repair)	
EPA Id:	CAL000209124	
NAICS Code:	81232	
•	Drycleaning and Laundry Services (except Coin-Operated)	
SIC Code:	7212	
Create Date:	10/13/1999	
Facility Active:	Yes	
Inactive Date:	Not reported	
Facility Addr2:	Not reported	
Mailing Name:	Not reported	
Mailing Address:	18500 CRENSHAW BLVD	
Mailing Address 2:	Not reported	
Mailing State:	CA	
Mailing Zip:	905040000	
Region Code:		
Owner Name:	VALLEE ROBERT SR	
Owner Address:	18500 CRENSHAW BLVD	
Owner Address 2:	Not reported	
Owner Telephone:		
Contact Name: Contact Address:	JEFF MARCON/PRODUCTION MGR 18500 CRANSHAW BLVD	
Contact Address 2:		
Contact Telephone:		
•	arment Pressing and Agents for Laundries and DrycleanersDrycleaning Plants	
E	ccept Rug CleaningPower Laundries Family and CommercialLaundry and Garment ervices NEC (except diaper service and clothing alteration and repair)	
EPA Id:	CAL000209124	
NAICS Code:	81232	
	Drycleaning and Laundry Services (except Coin-Operated)	
SIC Code:	7219	
Create Date:	10/13/1999	
Facility Active:	Yes	
Inactive Date:	Not reported	
Facility Addr2: Mailing Name:	Not reported Not reported	
Mailing Address:	18500 CRENSHAW BLVD	
Mailing Address 2:	Not reported	
Mailing State:	CA	
Mailing Zip:	905040000	
Region Code:	3	
Owner Name:	VALLEE ROBERT SR	
Owner Address:	18500 CRENSHAW BLVD	
Owner Address 2:	Not reported	
Owner Telephone:	Not reported	
Contact Name:	JEFF MARCON/PRODUCTION MGR	
Contact Address:	18500 CRANSHAW BLVD	
Contact Address 2:	Not reported	

EDR ID Number EPA ID Number

Database(s)

# **GEORGE P JOHNSON CO (Continued)**

Contact Telephone: 3109654300

SIC Description: Garment Pressing and Agents for Laundries and DrycleanersDrycleaning Plants Except Rug CleaningPower Laundries Family and CommercialLaundry and Garment Services NEC (except diaper service and clothing alteration and repair)

EMI:	
Year:	2002
Carbon Monoxide Emissions Tons/Yr:	19
Air Basin:	SC
Facility ID:	120510
	SC
Air District Name:	
SIC Code:	3993
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0
Year:	2003
Carbon Monoxide Emissions Tons/Yr:	19
Air Basin:	SC
Facility ID:	120510
Air District Name:	SC
SIC Code:	3993
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0
	0
Year:	2004
Carbon Monoxide Emissions Tons/Yr:	19
Air Basin:	SC
Facility ID:	120510
Air District Name:	SC
SIC Code:	3993
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	1.1699
Reactive Organic Gases Tons/Yr:	1.06
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0

Map ID		М	AP FINDINGS		
Direction Distance Distance (ft Elevation	.) Site	۲		Database(s)	EDR ID Number EPA ID Number
	GEORGE P JOHNSON C	O (Continued)			S104583125
Year: Carbon Monoxide Emissions Tons/Yr: Air Basin: Facility ID: Air District Name: SIC Code: Air District Name: Community Health Air Pollution Info System: Consolidated Emission Reporting Rule: Total Organic Hydrocarbon Gases Tons/Yr: Reactive Organic Gases Tons/Yr: Carbon Monoxide Emissions Tons/Yr: NOX - Oxides of Nitrogen Tons/Yr: SOX - Oxides of Sulphur Tons/Yr: Particulate Matter Tons/Yr: Part. Matter 10 Micrometers & Smllr Tons/Yr:		2005 19 SC 120510 SC 3993 SOUTH COAST AQMD Not reported Not reported 1.0141 .92931102 0 0 0 0 0			
C18 ENE 1/8-1/4 1039 ft.	ALLIED SIGNAL INC (SIT 2525 190TH ST W TORRANCE, CA 90504 Site 1 of 5 in cluster C	ΈA)		LUST Cortese CA FID UST EMI SWEEPS UST	S101585798 N/A
Relative: Lower	LUST: Region:	STATE			
Actual: 63 ft.	Case Type: Cross Street: Enf Type: Funding: How Discovered: How Stopped: Leak Cause: Leak Source: Global Id: Stop Date: Confirm Leak: Workplan: Prelim Assess: Pollution Char: Remed Plan: Remed Plan: Remed Plan: Remed Action: Monitoring: Close Date: Discover Date: Enforcement Dt: Release Date: Enforcement Dt: Release Date: Enter Date: GW Qualifier: Soil Qualifier: Max MTBE Date: GW Qualifier: Max MTBE GW ppb: Max MTBE Soil ppb: County: Org Name: Reg Board: Status: Chemical:	Soil only Not reported Not reported Not reported Not reported Not reported UNK UNK T0603701486 Not reported 1993-07-20 00:00:00 Not reported Not reported 1997-07-22 00:00:00 Not reported 1993-12-13 00:00:00 1993-12-15 00:00:00 Not reported Not reported			

Database(s)

EDR ID Number EPA ID Number

# ALLIED SIGNAL INC (SITE A) (Continued)

Contact Person: Not reported ALLIED SIGNAL INC. Responsible Party: **RP** Address: 2525 190 ST, TORRANCE, CA 90504-6099 Not reported Interim: Oversight Prgm: LUFT MTBE Class: MTBE Conc: 0 MTBE Fuel: 1 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed. Staff: BRC RVB Staff Initials: **Regional Board** Lead Agency: Local Agency: 19038 Hydr Basin #: SAN FERNANDO VALLEY Not reported Beneficial: Priority: Not reported Cleanup Fund Id: Not reported Work Suspended: Not reported Local Case #: Not reported 905040125 Case Number: Qty Leaked: Not reported Abate Method: Not reported Not reported Operator: Water System Name:Not reported Well Name: Not reported Distance To Lust: 0 Not reported Waste Discharge Global ID: Waste Disch Assigned Name: Not reported Summary: FILE NO. 96-44 LUST: Region: 4 BRC Staff: Los Angeles County: 19038 Local Agency: Lead Agency: **Regional Board** Case Type: Soil Status: Case Closed Substance: Gasoline Not reported Cross Street: T0603701486 Global ID: Enforcement Type: Not reported Date Leak Discovered: Not reported Date Leak Record Entered: 12/15/1993 Not reported How Leak Discovered: How Leak Stopped: Not reported Cause of Leak: UNK UNK Leak Source: Date Leak Stopped: Not reported 7/20/1993 Date Confirmation Began: Operator: Not reported Water System: Not reported Well Name: Not reported Approx. Dist To Production Well (ft): 4827.4417167409743951584581875 Abatement Method Used at the Site: Not reported Source of Cleanup Funding: Not reported Date Leak First Reported: 12/13/1993

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

# ALLIED SIGNAL INC (SITE A) (Continued)

Preliminary Site Assessme Preliminary Site Assessme Pollution Characterization Remediation Plan Submitt Remedial Action Underwa Post Remedial Action Mor Date the Case was Closed Date Case Last Changed Enforcement Action Date: Historical Max MTBE Date Hist Max MTBE Conc in G	ent Began: Began: ed: y: hitoring Began: d: on Database:	: Not reported Not reported Not reported Not reported Not reported 7/22/1997 7/22/1997 Not reported Not reported Not reported Not reported
Hist Max MTBE Conc in S		Not reported
Significant Interim Remed		Not reported
GW Qualifier:	Not reported	Notropolica
Soil Qualifier:	Not reported	
Organization:	Not reported	
Regional Board:	04	
Owner Contact:	Not reported	
Responsible Party:	ALLIED SIGNAL INC	
RP Address:	2525 190 ST, TORR/	ANCE, CA 90504-6099
Program:	SLIC	
Lat/Long:	33.8583858 / -1	
Local Agency Staff:	RVB	
Beneficial Use:	Not reported	
Priority:	Not reported	
Cleanup Fund Id:	Not reported	
Suspended: Local Case No:	Not reported	
Substance Quantity:	Not reported Not reported	
Assigned Name:	Not reported	
W Global ID:	Not reported	
Summary:	FILE NO. 96-44	
Cortese:		
Region: CORT	ESE	
Facility Addr2: Not re		
CA FID UST:		
	29787	
Regulated By: UTN		
	)3605	
	reported	
	reported	
	3239500	
	reported	
Mailing Address: P.O.	BOX	
	reported	
0 7 1	RANCE 905046099	
	reported	
	reported reported	
Status: Activ		

Active

Status:

Database(s)

EDR ID Number EPA ID Number

# ALLIED SIGNAL INC (SITE A) (Continued)

Comp Number:

Number:

3605

1

EMI:	
Year:	1990
Carbon Monoxide Emissions Tons/Yr:	1950
Air Basin:	SC
Facility ID:	63647
Air District Name:	SC
SIC Code:	3764
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	1
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	2
Part. Matter 10 Micrometers & Smllr Tons/Yr:	_ 1
Year:	1990
Carbon Monoxide Emissions Tons/Yr:	19
Air Basin:	SC
Facility ID:	60142
Air District Name:	SC
SIC Code:	3764
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2
Reactive Organic Gases Tons/Yr:	2
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	1
Part. Matter 10 Micrometers & Smllr Tons/Yr:	1
Year:	1990
Carbon Monoxide Emissions Tons/Yr:	19
Air Basin:	SC
Facility ID:	54597
Air District Name:	SC
SIC Code:	3764
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	2
Reactive Organic Gases Tons/Yr:	2
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons/Yr:	0
SWEEPS UST:	
Status: A	

Database(s)

EDR ID Number EPA ID Number

# ALLIED SIGNAL INC (SITE A) (Continued)

	) ()
Board Of Equalization:	44-010602
Ref Date:	04-24-91
Act Date:	04-24-91
Created Date:	02-29-88
Tank Status:	A
Owner Tank Id:	UT446WF13
Swrcb Tank Id:	19-038-003605-000013
Actv Date:	04-24-91
Capacity:	1000
Tank Use:	PETROLEUM
Stg:	W
Content:	JET FUEL
Number Of Tanks:	10
Status: Comp Number: Number: Board Of Equalization: Ref Date: Act Date: Created Date: Tank Status: Owner Tank Id: Swrcb Tank Id: Swrcb Tank Id: Actv Date: Capacity: Tank Use: Stg: Content: Number Of Tanks:	A 3605 1 44-010602 04-24-91 04-24-91 02-29-88 A UT446WF14 19-038-003605-000014 04-24-91 1000 PETROLEUM W JET FUEL Not reported
Status:	A
Comp Number:	3605
Number:	1
Board Of Equalization:	44-010602
Ref Date:	04-24-91
Act Date:	04-24-91
Created Date:	02-29-88
Tank Status:	A
Owner Tank Id:	UT446WF15
Swrcb Tank Id:	19-038-003605-000015
Actv Date:	04-24-91
Capacity:	3000
Tank Use:	M.V. FUEL
Stg:	W
Content:	AVIA. GAS
Number Of Tanks:	Not reported
Status:	A
Comp Number:	3605
Number:	1
Board Of Equalization:	44-010602
Ref Date:	04-24-91
Act Date:	04-24-91
Created Date:	02-29-88
Tank Status:	A
Owner Tank Id:	UT446WF16

#### Map ID Direction Distance Distance (ft.) Elevation Site

# MAP FINDINGS

Database(s)

EDR ID Number EPA ID Number

# ALLIED SIGNAL INC (SITE A) (Continued)

Swrcb Tank Id: Actv Date: Capacity:	19-038-003605-000016 04-24-91 1000
Tank Use: Stg:	M.V. FUEL W
Content:	AVIA. GAS
Number Of Tanks:	Not reported
	notroponou
Status:	А
Comp Number:	3605
Number:	1
Board Of Equalization: Ref Date:	44-010602 04-24-91
Act Date:	04-24-91
Created Date:	02-29-88
Tank Status:	A
Owner Tank Id:	UT446WF17
Swrcb Tank Id:	19-038-003605-000017
Actv Date:	04-24-91
Capacity:	500
Tank Use:	M.V. FUEL
Stg: Content:	W AVIA. GAS
Number Of Tanks:	Not reported
Number Of Tanks.	Not reported
Status:	А
Comp Number:	3605
Number:	1
Board Of Equalization:	44-010602
Ref Date:	04-24-91
Act Date: Created Date:	04-24-91 02-29-88
Tank Status:	A
Owner Tank Id:	UT446WF18
Swrcb Tank Id:	19-038-003605-000018
Actv Date:	04-24-91
Capacity:	500
Tank Use:	M.V. FUEL
Stg:	W
Content: Number Of Tanks:	AVIA. GAS Not reported
Number Of Tanks.	Not reported
Status:	А
Comp Number:	3605
Number:	1
Board Of Equalization:	44-010602
Ref Date:	04-24-91
Act Date: Created Date:	04-24-91 02-29-88
Tank Status:	A
Owner Tank Id:	UT446WF19
Swrcb Tank Id:	19-038-003605-000019
Actv Date:	04-24-91
Capacity:	500
Tank Use:	M.V. FUEL
Stg:	W
Content:	AVIA. GAS

Database(s)

EDR ID Number EPA ID Number

# ALLIED SIGNAL INC (SITE A) (Continued)

Number Of Tanks:	Not reported
Status: Comp Number: Number: Board Of Equalization: Ref Date: Act Date: Created Date: Tank Status: Owner Tank Id: Swrcb Tank Id: Swrcb Tank Id: Actv Date: Capacity: Tank Use: Stg: Content: Number Of Tanks:	A 3605 1 44-010602 04-24-91 04-24-91 02-29-88 A UT446WF23 19-038-003605-000023 04-24-91 12000 M.V. FUEL P DIESEL Not reported
Status: Comp Number: Number: Board Of Equalization: Ref Date: Act Date: Created Date: Tank Status: Owner Tank Id: Swrcb Tank Id: Swrcb Tank Id: Actv Date: Capacity: Tank Use: Stg: Content: Number Of Tanks:	A 3605 1 44-010602 04-24-91 04-24-91 02-29-88 A UT446WF24 19-038-003605-000024 08-19-91 15000 M.V. FUEL P DIESEL Not reported
Status: Comp Number: Number: Board Of Equalization: Ref Date: Act Date: Created Date: Tank Status: Owner Tank Id: Swrcb Tank Id: Swrcb Tank Id: Actv Date: Capacity: Tank Use: Stg: Content: Number Of Tanks:	04-24-91 04-24-91 02-29-88 A UT446WF25 19-038-003605-000025 08-19-91 5000 M.V. FUEL P DIESEL Not reported
Comp Number: Number: Board Of Equalization:	3605 Not reported 44-010602

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

	(eentinaed)
Ref Date: Act Date: Created Date: Tank Status: Owner Tank Id: Swrcb Tank Id: Actv Date: Capacity: Tank Use: Stg: Content: Number Of Tanks:	Not reported Not reported Not reported Not reported 19-038-003605-000001 Not reported 1000 M.V. FUEL PRODUCT REG UNLEADED 15
Status: Comp Number: Number: Board Of Equalization: Ref Date: Act Date: Created Date: Tank Status: Owner Tank Id: Swrcb Tank Id: Swrcb Tank Id: Actv Date: Capacity: Tank Use: Stg: Content: Number Of Tanks:	Not reported 3605 Not reported 44-010602 Not reported Not reported Not reported Not reported 19-038-003605-000002 Not reported 1000 M.V. FUEL PRODUCT REG UNLEADED Not reported
Status: Comp Number: Number: Board Of Equalization: Ref Date: Act Date: Created Date: Tank Status: Owner Tank Id: Swrcb Tank Id: Swrcb Tank Id: Actv Date: Capacity: Tank Use: Stg: Content: Number Of Tanks:	Not reported 3605 Not reported 44-010602 Not reported Not reported Not reported Not reported 19-038-003605-000003 Not reported 10000 M.V. FUEL PRODUCT DIESEL Not reported
Status: Comp Number: Number: Board Of Equalization: Ref Date: Act Date: Created Date: Tank Status: Owner Tank Id: Swrcb Tank Id:	Not reported 3605 Not reported 44-010602 Not reported Not reported Not reported Not reported Not reported Not reported 19-038-003605-000004

Database(s)

EDR ID Number EPA ID Number

Actv Date:	Not reported
Capacity:	10000
Tank Use:	M.V. FUEL
Stg:	PRODUCT
Content:	JET FUEL
Number Of Tanks:	Not reported
Status:	Not reported
Comp Number:	3605
Number:	Not reported
Board Of Equalization:	44-010602
Ref Date:	Not reported
Act Date:	Not reported
Created Date:	Not reported
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	19-038-003605-000005
Actv Date:	Not reported
Capacity: Tank Use:	25000 M.V. FUEL
Stg:	PRODUCT
Content:	DIESEL
Number Of Tanks:	Not reported
rumber of rume.	Notropolica
Status:	Not reported
Comp Number:	3605
Number:	Not reported
Board Of Equalization:	44-010602
Ref Date:	Not reported
Act Date: Created Date:	Not reported
Tank Status:	Not reported Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	19-038-003605-000006
Actv Date:	Not reported
Capacity:	25000
Tank Use:	M.V. FUEL
Stg:	PRODUCT
Content:	DIESEL
Number Of Tanks:	Not reported
Status:	Not reported
Comp Number:	3605
Number:	Not reported
Board Of Equalization:	44-010602
Ref Date:	Not reported
Act Date:	Not reported
Created Date:	Not reported
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id: Actv Date:	19-038-003605-000007 Not reported
Capacity:	4000
Tank Use:	OIL
Stg:	WASTE
Content:	WASTE OIL
Number Of Tanks:	Not reported
	•

Database(s)

EDR ID Number EPA ID Number

# ALLIED SIGNAL INC (SITE A) (Continued)

Status: Comp Number: Number: Board Of Equalization: Ref Date: Act Date: Created Date: Tank Status: Owner Tank Id: Swrcb Tank Id: Actv Date: Capacity: Tank Use: Stg: Content: Number Of Tanks:	Not reported 3605 Not reported 44-010602 Not reported Not reported Not reported Not reported 19-038-003605-000008 Not reported 10000 M.V. FUEL PRODUCT REG UNLEADED Not reported
Status: Comp Number: Number: Board Of Equalization: Ref Date: Act Date: Created Date: Tank Status: Owner Tank Id: Swrcb Tank Id: Actv Date: Capacity: Tank Use: Stg: Content: Number Of Tanks:	Not reported 3605 Not reported 44-010602 Not reported Not reported Not reported Not reported 19-038-003605-000009 Not reported 10000 M.V. FUEL PRODUCT REG UNLEADED Not reported
Status:	Not reported
Comp Number:	3605
Number:	Not reported
Board Of Equalization:	44-010602
Ref Date:	Not reported
Act Date:	Not reported
Created Date:	Not reported
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	19-038-003605-000010
Actv Date:	Not reported
Capacity:	12000
Tank Use:	M.V. FUEL
Stg:	PRODUCT
Content:	LEADED
Number Of Tanks:	Not reported
Status:	Not reported
Comp Number:	3605
Number:	Not reported
Board Of Equalization:	44-010602
Ref Date:	Not reported
Act Date:	Not reported

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

# ALLIED SIGNAL INC (SITE A) (Continued)

Created Date: Tank Status: Owner Tank Id: Swrcb Tank Id: Actv Date: Capacity: Tank Use: Stg: Content: Number Of Tanks:	Not reported Not reported 19-038-003605-000011 Not reported 10000 M.V. FUEL PRODUCT DIESEL Not reported
Status: Comp Number: Number: Board Of Equalization: Ref Date: Act Date: Created Date: Tank Status: Owner Tank Id: Swrcb Tank Id: Swrcb Tank Id: Actv Date: Capacity: Tank Use: Stg: Content: Number Of Tanks:	Not reported 3605 Not reported 44-010602 Not reported Not reported Not reported Not reported 19-038-003605-000012 Not reported 280 OIL WASTE WASTE OIL Not reported
Status: Comp Number: Number: Board Of Equalization: Ref Date: Act Date: Created Date: Tank Status: Owner Tank Id: Swrcb Tank Id: Swrcb Tank Id: Actv Date: Capacity: Tank Use: Stg: Content: Number Of Tanks:	Not reported 3605 Not reported 44-010602 Not reported Not reported Not reported Not reported 19-038-003605-000020 Not reported 1000 M.V. FUEL WASTE JET FUEL Not reported
Status: Comp Number: Number: Board Of Equalization: Ref Date: Act Date: Created Date: Tank Status: Owner Tank Id: Swrcb Tank Id: Actv Date: Capacity:	Not reported 3605 Not reported 44-010602 Not reported Not reported Not reported Not reported 19-038-003605-000021 Not reported 30000

Database(s)

EDR ID Number EPA ID Number

S101585798

•	, ( ,
Tank Use: Stg: Content:	M.V. FUEL PRODUCT DIESEL
Number Of Tanks:	Not reported
Status:	Not reported
Comp Number:	3605
Number:	Not reported
Board Of Equalization:	44-010602
Ref Date:	Not reported
Act Date:	Not reported
Created Date:	Not reported
Tank Status:	Not reported
Owner Tank Id:	Not reported
Swrcb Tank Id:	19-038-003605-000022
Actv Date:	Not reported
Capacity:	30000
Tank Use:	M.V. FUEL
Stg:	PRODUCT
Content:	DIESEL
Number Of Tanks:	Not reported

C19 ALLIED-SIGNAL

ENE 2525 W 190TH ST

1/8-1/4 TORRANCE, CA 90504 1039 ft.

#### Site 2 of 5 in cluster C

Relative:		
Lower	UST:	
	Region:	STATE
Actual:	Local Agency:	Torrance, Los Angeles County
63 ft.	Facility ID:	3605

#### C20 GARRET AIRESEARCH

ENE	2525 W. 190TH ST.
410 414	TODDANOF OA AAFAA

1/8-1/4	TORRANCE, CA	90509
1039 ft.		

Site 3 of 5 in cluster C

**Relative:** SLIC: Lower Region: STATE Actual: Global Id: SL0603785389 63 ft. Assigned Name: SLICSITE Lead Agency Contact: STEVE ROWE Lead Agency: LOS ANGELES RWQCB (REGION 4) Lead Agency Case Number: 1043 Responsible Party: Not reported Recent Dtw: Not reported Substance Released: Not reported **Facility Status: Pollution Characterization** 

1987
19
SC
20965

UST U003644113 N/A

SLIC S106483583 EMI N/A

Map ID Direction		INGS		
Distance Distance (ft Elevation	.) Site	Data	base(s)	EDR ID Number EPA ID Number
	GARRET AIRESEARCH (Continued)			S106483583
	Air District Name:SCSIC Code:3720Air District Name:SOUTHCommunity Health Air Pollution Info System:Not repConsolidated Emission Reporting Rule:Not repTotal Organic Hydrocarbon Gases Tons/Yr:8Reactive Organic Gases Tons/Yr:2Carbon Monoxide Emissions Tons/Yr:0NOX - Oxides of Nitrogen Tons/Yr:0SOX - Oxides of Sulphur Tons/Yr:1Particulate Matter 10 Micrometers & Smllr Tons/Yr:1			
C21 ENE 1/8-1/4	HONEYWELL SITE A 2525 190TH TORRANCE, CA 90504		SLIC	1005976414 N/A
1039 ft.	Site 4 of 5 in cluster C			
Relative: Lower	SLIC:			
Actual: 63 ft.	Region:4Facility Status:Site AssessmentSLIC:1043Substance:VOCsStaff:DBR			
C22 ENE 1/8-1/4 1039 ft.	HONEYWELL 2525 W 190TH ST TORRANCE, CA 90504		FINDS IAZNET RA-LQG TRIS	1000221945 90509LLDSG25
Relative: Lower	Site 5 of 5 in cluster C	HI	-NFRAP IST UST EMI	
Actual: 63 ft.	FINDS: Other Pertinent Environmental Activity Identified at Site		NIFEST	
	AFS (Aerometric Information Retriev Subsystem) replaces the former Cor National Emission Data System (NE Aerometric Data (SAROAD). AIRS is information concerning airborne poll	npliance Data System (CDS), the DS), and the Storage and Retrieval of s the national repository for		

information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

California - Hazardous Waste Tracking System - Datamart

NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions,

Database(s)

EDR ID Number

HONEYWELL (Continu	led)	1000221945
•	and settlements.	1000221343
	TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.	
	The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).	
	RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCR program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.	
	RACT/BACT/LAER Clearinghouse (RBLC) data base contains case-specinformation on the 'Best Available' air pollution technologies that have been required to reduce the emission of air pollutants from stationary sources (e.g., power plants, steel mills, chemical plants, etc.). This information has been provided by State and local permitting agencies. The Clearinghouse also contains a regulation data base that summarizes EPA emission limits required in New Source Performance Standards (NSPS), National Emission Standards for Hazardous Air Pollutants (NESHAP), and Maximum Achievable Control Technology (MACT) standards.	
HAZNET:	CAD071806336	
Gepaid: Contact:	CAD071896336 MARIA TETTMAN	
Telephone:	3105122539	
Facility Addr2:	Not reported	
Mailing Name:	Not reported	
Mailing Address:	2525 W 190TH ST	
Mailing City, St, Zip:		
Gen County:	Los Angeles	
TSD EPA ID:	AZD009015389	
TSD County:	99	
Waste Category:	Aqueous solution with 10% or more total organic residues	
Disposal Method:	Recycler	
Tons: Facility County:	1.25 Not reported	
Gepaid:	CAD071896336	
Contact:	MARIA TETTMAN	
Telephone:	3105122539	
Facility Addr2:	Not reported	
Mailing Name:	Not reported	
Mailing Address:	2525 W 190TH ST	
Mailing City,St,Zip:		
Gen County:		

Waste Category: Aqueous solution with 10% or more total organic residues

99

AZD009015389

TSD EPA ID:

TSD County:

Database(s)

EDR ID Number EPA ID Number

HONEYWELL (Contin Disposal Method	-		1000221945
Tons:	1.25		
Facility County:	Not reported		
RCRAInfo:			
	NOT REQUIRED (415) 555-1212		
	CAD071896336		
	ENVIRONMENTAL MA		
Classification: TSDF Activities:	Large Quantity General Not reported	tor	
BIENNIAL REPORT Last Biennial Rep	rS: porting Year: 2005		
<u>Waste Qu</u> D001 D005 D011 F002 F005	antity (Lbs) 121944.00 1986.00 1536.00 5868.00 88954.00	WasteQuantity (Lbs)D00271172.46D00714672.46D03544450.00F00387418.00U1341536.00	
Violation Status:	Violations exist		
Regulation Viola Area of Violation Date Violation D Actual Date Act	n:	Not reported GENERATOR-LAND BAN REQUIREMENTS 09/18/1992 10/23/1992	
Enforcement Enforcement Penalty Type:	Action Date:	WRITTEN INFORMAL 10/01/1992 Not reported	
Regulation Viola Area of Violation Date Violation D Actual Date Act	n:	Not reported GENERATOR-PRE-TRANSPORT REQUIREMENTS 09/18/1992 10/23/1992	
Enforcement / Enforcement / Penalty Type:	Action Date:	WRITTEN INFORMAL 10/01/1992 Not reported	
Regulation Viola Area of Violation Date Violation D Actual Date Act	n:	Not reported GENERATOR-MANIFEST REQUIREMENTS 09/18/1992 10/23/1992	
Enforcement Enforcement Penalty Type:	Action Date:	WRITTEN INFORMAL 10/01/1992 Not reported	
There are 3 viola	tion record(s) reported	at this site.	
THELE ALE S VIULA		מו נוווס סווכ.	Date of
Evoluction		Area of Violation	Compliance

Evaluation Compliance Evaluation Ins	spection	Area of Violation GENERATOR-MANIFEST REQUIREMENTS GENERATOR-PRE-TRANSPORT REQUIREMENTS GENERATOR-LAND BAN REQUIREMENTS	<u>Compliance</u> 19921023 19921023 19921023
CERC-NFRAP: Site ID:	0904524		

Database(s)

EDR ID Number EPA ID Number

HONEYWELL (Continue	ed)	
Federal Facility:	Not a Federal Facility	
NPL Status:	Not on the NPL	
Non NPL Status:	NFRAP	
CERCLIS-NFRAP Site	Contact Name(s):	
Contact Name:	Matt Mitguard	
Contact Tel:	(415) 972-3096	
Contact Title:	Site Assessment Manager (SAM)	
Contact Name:	Jere Johnson	
Contact Tel:	(415) 972-3094	
Contact Title:	Site Assessment Manager (SAM)	
CERCLIS-NFRAP Site	Alias Name(s):	
Alias Name:	GARRETT-AIRSEARCH CASTING CO.	
Alias Address:	Not reported	
	CA	
Site Description: No	ot reported	
CERCLIS-NFRAP Asse	,	
Action:	DISCOVERY	
Date Started:	Not reported 07/23/1992	
Date Completed: Priority Level:	Not reported	
Thomy Level.	Notrepolled	
Action:	ARCHIVE SITE	
Date Started:	Not reported	
Date Completed:	06/08/1993	
Priority Level:	Not reported	
Action:	PRELIMINARY ASSESSMENT	
Date Started:	Not reported	
Date Completed:	06/08/1993	
Priority Level:	NFRAP (No Futher Remedial Action Planned	
HIST UST:		
Region:	STATE	
Facility ID:	0000003605	
Tank Num:	001	
Container Num:	20	
Year Installed: Tank Capacity:	1970 00001000	
Facility Type:	Other	
Other Type:	MANUFACTURER, AEROSP	
Total Tanks:	0008	
Tank Used for:	PRODUCT	
Type of Fuel: Tank Construction:	PREMIUM 3/16 inches	
Leak Detection:	None	
Contact Name:	DEL DONNER	
Telephone:	2135122980	
Owner Name:	AIRESEARCH MANUFACTURING CO.,D	
Owner Address:	9851 SEPULVEDA BLVD9	
Owner City,St,Zip:	LOS ANGELES, CA 90009	
Region:	STATE	

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

1000221945

#### HONEYWELL (Continued)

Facility ID: 0000003605 Tank Num: 002 Container Num: 21 Year Installed: 1970 Tank Capacity: 00001000 Facility Type: Other MANUFACTURER, AEROSP Other Type: Total Tanks: 0008 Tank Used for: PRODUCT Type of Fuel: UNLEADED Tank Construction: 3/16 unknown Leak Detection: None DEL DONNER Contact Name: Telephone: 2135122980 AIRESEARCH MANUFACTURING CO.,D Owner Name: Owner Address: 9851 SEPULVEDA BLVD9 LOS ANGELES, CA 90009 Owner City, St, Zip: Region: STATE 0000003605 Facility ID: Tank Num: 003 Container Num: 22 Not reported Year Installed: Tank Capacity: 00012000 Facility Type: Other Other Type: MANUFACTURER, AEROSP Total Tanks: 0008 Tank Used for: PRODUCT Type of Fuel: DIESEL Tank Construction: 3/16 inches Leak Detection: None Contact Name: **DEL DONNER** Telephone: 2135122980 Owner Name: AIRESEARCH MANUFACTURING CO.,D Owner Address: 9851 SEPULVEDA BLVD9 Owner City,St,Zip: LOS ANGELES, CA 90009 Region: STATE 0000003605 Facility ID: Tank Num: 004 Container Num: 23 Year Installed: Not reported Tank Capacity: 00012000 Facility Type: Other Other Type: MANUFACTURER, AEROSP Total Tanks: 0008 Tank Used for: PRODUCT Type of Fuel: 06 Tank Construction: 3/16 inches Leak Detection: None Contact Name: **DEL DONNER** Telephone: 2135122980 AIRESEARCH MANUFACTURING CO.,D Owner Name: 9851 SEPULVEDA BLVD9 Owner Address: Owner City,St,Zip: LOS ANGELES, CA 90009

Region:

STATE

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

1000221945

#### HONEYWELL (Continued)

Facility ID: 0000003605 Tank Num: 005 Container Num: 24 Year Installed: 1978 Tank Capacity: 00025000 Facility Type: Other MANUFACTURER, AEROSP Other Type: Total Tanks: 0008 Tank Used for: PRODUCT Type of Fuel: DIESEL Tank Construction: 3/8 inches Leak Detection: None DEL DONNER Contact Name: Telephone: 2135122980 AIRESEARCH MANUFACTURING CO.,D Owner Name: Owner Address: 9851 SEPULVEDA BLVD9 LOS ANGELES, CA 90009 Owner City, St, Zip: Region: STATE 0000003605 Facility ID: Tank Num: 006 Container Num: 25 1978 Year Installed: Tank Capacity: 00025000 Facility Type: Other Other Type: MANUFACTURER, AEROSP Total Tanks: 0008 Tank Used for: PRODUCT Type of Fuel: DIESEL Tank Construction: 3/8 inches Leak Detection: None Contact Name: **DEL DONNER** Telephone: 2135122980 Owner Name: AIRESEARCH MANUFACTURING CO.,D Owner Address: 9851 SEPULVEDA BLVD9 Owner City,St,Zip: LOS ANGELES, CA 90009 Region: STATE 0000003605 Facility ID: Tank Num: 007 Container Num: 26 Year Installed: 1983 Tank Capacity: 00004000 Facility Type: Other MANUFACTURER, AEROSP Other Type: Total Tanks: 0008 Tank Used for: WASTE Type of Fuel: WASTE OIL Tank Construction: 3/16 inches Leak Detection: None Contact Name: **DEL DONNER** Telephone: 2135122980 AIRESEARCH MANUFACTURING CO.,D Owner Name: 9851 SEPULVEDA BLVD9 Owner Address: Owner City,St,Zip: LOS ANGELES, CA 90009

Region:

STATE

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

# HONEYWELL (Continued)

Facility ID:	0000003605
Tank Num:	008
Container Num:	27
Year Installed:	Not reported
Tank Capacity:	00001000
Facility Type:	Other
Other Type:	MANUFACTURER, AEROSP
Total Tanks:	0008
Tank Used for:	WASTE
Type of Fuel:	WASTE OIL
Tank Construction:	Not reported
Leak Detection:	Visual
Contact Name:	DEL DONNER
Telephone:	2135122980
Owner Name:	AIRESEARCH MANUFACTURING CO.,D
Owner Address:	9851 SEPULVEDA BLVD9
Owner City,St,Zip:	LOS ANGELES, CA 90009

#### EMI:

VII.	
Year: Carbon Monoxide Emissions Tons/Yr: Air Basin: Facility ID:	1987 19 SC 800003
Air District Name:	SC
SIC Code: Air District Name:	3764 SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	231 38
Reactive Organic Gases Tons/Yr: Carbon Monoxide Emissions Tons/Yr:	5
NOX - Oxides of Nitrogen Tons/Yr:	17
SOX - Oxides of Sulphur Tons/Yr: Particulate Matter Tons/Yr:	1 1
Part. Matter 10 Micrometers & Smllr Tons/Yr:	1
Year:	1990
Carbon Monoxide Emissions Tons/Yr:	1990
Air Basin:	SC
Facility ID:	800003
Air District Name: SIC Code:	SC 3764
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule: Total Organic Hydrocarbon Gases Tons/Yr:	Not reported 151
Reactive Organic Gases Tons/Yr:	25
Carbon Monoxide Emissions Tons/Yr:	259
NOX - Oxides of Nitrogen Tons/Yr:	26
SOX - Oxides of Sulphur Tons/Yr: Particulate Matter Tons/Yr:	1 2
Part. Matter 10 Micrometers & Smllr Tons/Yr:	2
Year:	1993
Carbon Monoxide Emissions Tons/Yr:	19
Air Basin:	SC 800003
Facility ID:	000003

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

# HONEYWELL (Continued)

Air District Name: SIC Code: Air District Name: Community Health Air Pollution Info System: Consolidated Emission Reporting Rule: Total Organic Hydrocarbon Gases Tons/Yr: Reactive Organic Gases Tons/Yr: Carbon Monoxide Emissions Tons/Yr: NOX - Oxides of Nitrogen Tons/Yr: SOX - Oxides of Sulphur Tons/Yr: Particulate Matter Tons/Yr: Part. Matter 10 Micrometers & Smllr Tons/Yr:	SC 3764 SOUTH COAST AQMD Not reported 73 18 3 10 0 1
Year: Carbon Monoxide Emissions Tons/Yr: Air Basin: Facility ID: Air District Name: SIC Code: Air District Name: Community Health Air Pollution Info System: Consolidated Emission Reporting Rule: Total Organic Hydrocarbon Gases Tons/Yr: Reactive Organic Gases Tons/Yr: Reactive Organic Gases Tons/Yr: Carbon Monoxide Emissions Tons/Yr: NOX - Oxides of Nitrogen Tons/Yr: SOX - Oxides of Sulphur Tons/Yr: Particulate Matter Tons/Yr: Part. Matter 10 Micrometers & Smllr Tons/Yr:	1995 19 SC 800003 SC 3764 SOUTH COAST AQMD Not reported Not reported 73 18 3 10 0 1
Year: Carbon Monoxide Emissions Tons/Yr: Air Basin: Facility ID: Air District Name: SIC Code: Air District Name: Community Health Air Pollution Info System: Consolidated Emission Reporting Rule: Total Organic Hydrocarbon Gases Tons/Yr: Reactive Organic Gases Tons/Yr: Reactive Organic Gases Tons/Yr: Carbon Monoxide Emissions Tons/Yr: NOX - Oxides of Nitrogen Tons/Yr: SOX - Oxides of Sulphur Tons/Yr: Particulate Matter Tons/Yr: Part. Matter 10 Micrometers & Smllr Tons/Yr:	1996 19 SC 800003 SC 3764 SOUTH COAST AQMD Not reported Not reported 36 13 3 5 0 1
Year: Carbon Monoxide Emissions Tons/Yr: Air Basin: Facility ID: Air District Name: SIC Code: Air District Name: Community Health Air Pollution Info System: Consolidated Emission Reporting Rule: Total Organic Hydrocarbon Gases Tons/Yr:	1997 19 SC 800003 SC 3728 SOUTH COAST AQMD Not reported Not reported 76

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

HONEYWELL (Continued)	
Reactive Organic Gases Tons/Yr:	37
Carbon Monoxide Emissions Tons/Yr:	2
NOX - Oxides of Nitrogen Tons/Yr:	4
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	1
Part. Matter 10 Micrometers & Smllr Tons/Yr:	1
Year:	1998
Carbon Monoxide Emissions Tons/Yr:	19
Air Basin:	SC
Facility ID:	800003
Air District Name: SIC Code:	SC 2728
Air District Name:	3728 SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	58
Reactive Organic Gases Tons/Yr:	30
Carbon Monoxide Emissions Tons/Yr:	2
NOX - Oxides of Nitrogen Tons/Yr:	4
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	1
Part. Matter 10 Micrometers & Smllr Tons/Yr:	1
Year:	1999
Carbon Monoxide Emissions Tons/Yr:	19
Air Basin:	SC
Facility ID: Air District Name:	800003 SC
SIC Code:	3728
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	76
Reactive Organic Gases Tons/Yr:	37
Carbon Monoxide Emissions Tons/Yr:	2
NOX - Oxides of Nitrogen Tons/Yr:	4
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr: Part. Matter 10 Micrometers & Smllr Tons/Yr:	1
Part. Matter 10 Micrometers & Smill Tons/11.	I
Year:	2000
Carbon Monoxide Emissions Tons/Yr:	19
Air Basin:	SC
Facility ID:	800003
Air District Name: SIC Code:	SC 3728
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	76
Reactive Organic Gases Tons/Yr:	37
Carbon Monoxide Emissions Tons/Yr:	2
NOX - Oxides of Nitrogen Tons/Yr:	4
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	1
Part. Matter 10 Micrometers & Smllr Tons/Yr:	1

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

# HONEYWELL (Continued)

Year:	2001
Carbon Monoxide Emissions Tons/Yr:	19
Air Basin:	SC
Facility ID:	800003
Air District Name:	SC
SIC Code:	3728
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Y
Consolidated Emission Reporting Rule:	В
Total Organic Hydrocarbon Gases Tons/Yr:	55
Reactive Organic Gases Tons/Yr:	26
Carbon Monoxide Emissions Tons/Yr:	13
NOX - Oxides of Nitrogen Tons/Yr:	6
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	1
Part. Matter 10 Micrometers & Smllr Tons/Yr:	1
	•
Year:	2002
Carbon Monoxide Emissions Tons/Yr:	19
Air Basin:	SC
Facility ID:	
5	800003
Air District Name:	SC
SIC Code:	3728
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Not reported
	•
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/Yr:	30
Reactive Organic Gases Tons/Yr:	15
Carbon Monoxide Emissions Tons/Yr:	4
NOX - Oxides of Nitrogen Tons/Yr:	4
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	1
Part. Matter 10 Micrometers & Smllr Tons/Yr:	1
Fait. Matter to Micrometers & Smill Tons/ ft.	1
Year:	2003
Carbon Monoxide Emissions Tons/Yr:	19
Air Basin:	SC
	00
	000000
Facility ID:	800003
Facility ID: Air District Name:	800003 SC
Air District Name: SIC Code:	SC 3728
Air District Name: SIC Code: Air District Name:	SC 3728 SOUTH COAST AQMD
Air District Name: SIC Code: Air District Name: Community Health Air Pollution Info System:	SC 3728
Air District Name: SIC Code: Air District Name:	SC 3728 SOUTH COAST AQMD
Air District Name: SIC Code: Air District Name: Community Health Air Pollution Info System: Consolidated Emission Reporting Rule:	SC 3728 SOUTH COAST AQMD Not reported Not reported
Air District Name: SIC Code: Air District Name: Community Health Air Pollution Info System: Consolidated Emission Reporting Rule: Total Organic Hydrocarbon Gases Tons/Yr:	SC 3728 SOUTH COAST AQMD Not reported Not reported 30
Air District Name: SIC Code: Air District Name: Community Health Air Pollution Info System: Consolidated Emission Reporting Rule: Total Organic Hydrocarbon Gases Tons/Yr: Reactive Organic Gases Tons/Yr:	SC 3728 SOUTH COAST AQMD Not reported Not reported 30 15
Air District Name: SIC Code: Air District Name: Community Health Air Pollution Info System: Consolidated Emission Reporting Rule: Total Organic Hydrocarbon Gases Tons/Yr: Reactive Organic Gases Tons/Yr: Carbon Monoxide Emissions Tons/Yr:	SC 3728 SOUTH COAST AQMD Not reported Not reported 30
Air District Name: SIC Code: Air District Name: Community Health Air Pollution Info System: Consolidated Emission Reporting Rule: Total Organic Hydrocarbon Gases Tons/Yr: Reactive Organic Gases Tons/Yr:	SC 3728 SOUTH COAST AQMD Not reported Not reported 30 15
Air District Name: SIC Code: Air District Name: Community Health Air Pollution Info System: Consolidated Emission Reporting Rule: Total Organic Hydrocarbon Gases Tons/Yr: Reactive Organic Gases Tons/Yr: Carbon Monoxide Emissions Tons/Yr: NOX - Oxides of Nitrogen Tons/Yr:	SC 3728 SOUTH COAST AQMD Not reported Not reported 30 15 4
Air District Name: SIC Code: Air District Name: Community Health Air Pollution Info System: Consolidated Emission Reporting Rule: Total Organic Hydrocarbon Gases Tons/Yr: Reactive Organic Gases Tons/Yr: Carbon Monoxide Emissions Tons/Yr: NOX - Oxides of Nitrogen Tons/Yr: SOX - Oxides of Sulphur Tons/Yr:	SC 3728 SOUTH COAST AQMD Not reported Not reported 30 15 4 4 0
Air District Name: SIC Code: Air District Name: Community Health Air Pollution Info System: Consolidated Emission Reporting Rule: Total Organic Hydrocarbon Gases Tons/Yr: Reactive Organic Gases Tons/Yr: Carbon Monoxide Emissions Tons/Yr: NOX - Oxides of Nitrogen Tons/Yr: SOX - Oxides of Sulphur Tons/Yr: Particulate Matter Tons/Yr:	SC 3728 SOUTH COAST AQMD Not reported 30 15 4 4 0 1
Air District Name: SIC Code: Air District Name: Community Health Air Pollution Info System: Consolidated Emission Reporting Rule: Total Organic Hydrocarbon Gases Tons/Yr: Reactive Organic Gases Tons/Yr: Carbon Monoxide Emissions Tons/Yr: NOX - Oxides of Nitrogen Tons/Yr: SOX - Oxides of Sulphur Tons/Yr:	SC 3728 SOUTH COAST AQMD Not reported Not reported 30 15 4 4 0
Air District Name: SIC Code: Air District Name: Community Health Air Pollution Info System: Consolidated Emission Reporting Rule: Total Organic Hydrocarbon Gases Tons/Yr: Reactive Organic Gases Tons/Yr: Carbon Monoxide Emissions Tons/Yr: NOX - Oxides of Nitrogen Tons/Yr: SOX - Oxides of Sulphur Tons/Yr: Particulate Matter Tons/Yr:	SC 3728 SOUTH COAST AQMD Not reported 30 15 4 4 0 1
Air District Name: SIC Code: Air District Name: Community Health Air Pollution Info System: Consolidated Emission Reporting Rule: Total Organic Hydrocarbon Gases Tons/Yr: Reactive Organic Gases Tons/Yr: Carbon Monoxide Emissions Tons/Yr: NOX - Oxides of Nitrogen Tons/Yr: SOX - Oxides of Sulphur Tons/Yr: Particulate Matter Tons/Yr:	SC 3728 SOUTH COAST AQMD Not reported 30 15 4 4 0 1
Air District Name: SIC Code: Air District Name: Community Health Air Pollution Info System: Consolidated Emission Reporting Rule: Total Organic Hydrocarbon Gases Tons/Yr: Reactive Organic Gases Tons/Yr: Carbon Monoxide Emissions Tons/Yr: NOX - Oxides of Nitrogen Tons/Yr: SOX - Oxides of Nitrogen Tons/Yr: Particulate Matter Tons/Yr: Part. Matter 10 Micrometers & Smllr Tons/Yr: Year:	SC 3728 SOUTH COAST AQMD Not reported 30 15 4 4 0 1 1 2004
Air District Name: SIC Code: Air District Name: Community Health Air Pollution Info System: Consolidated Emission Reporting Rule: Total Organic Hydrocarbon Gases Tons/Yr: Reactive Organic Gases Tons/Yr: Carbon Monoxide Emissions Tons/Yr: NOX - Oxides of Nitrogen Tons/Yr: SOX - Oxides of Sulphur Tons/Yr: Particulate Matter Tons/Yr: Part. Matter 10 Micrometers & Smllr Tons/Yr: Year: Carbon Monoxide Emissions Tons/Yr:	SC 3728 SOUTH COAST AQMD Not reported 30 15 4 4 4 0 1 1 2004 19
Air District Name: SIC Code: Air District Name: Community Health Air Pollution Info System: Consolidated Emission Reporting Rule: Total Organic Hydrocarbon Gases Tons/Yr: Reactive Organic Gases Tons/Yr: Carbon Monoxide Emissions Tons/Yr: NOX - Oxides of Nitrogen Tons/Yr: SOX - Oxides of Sulphur Tons/Yr: Particulate Matter Tons/Yr: Part. Matter 10 Micrometers & Smllr Tons/Yr: Year: Carbon Monoxide Emissions Tons/Yr: Air Basin:	SC 3728 SOUTH COAST AQMD Not reported 30 15 4 4 4 0 1 1 2004 19 SC
Air District Name: SIC Code: Air District Name: Community Health Air Pollution Info System: Consolidated Emission Reporting Rule: Total Organic Hydrocarbon Gases Tons/Yr: Reactive Organic Gases Tons/Yr: Carbon Monoxide Emissions Tons/Yr: NOX - Oxides of Nitrogen Tons/Yr: SOX - Oxides of Sulphur Tons/Yr: Particulate Matter Tons/Yr: Part. Matter 10 Micrometers & Smllr Tons/Yr: Year: Carbon Monoxide Emissions Tons/Yr: Air Basin: Facility ID:	SC 3728 SOUTH COAST AQMD Not reported 30 15 4 4 4 0 1 1 2004 19 SC 800003
Air District Name: SIC Code: Air District Name: Community Health Air Pollution Info System: Consolidated Emission Reporting Rule: Total Organic Hydrocarbon Gases Tons/Yr: Reactive Organic Gases Tons/Yr: Carbon Monoxide Emissions Tons/Yr: NOX - Oxides of Nitrogen Tons/Yr: SOX - Oxides of Sulphur Tons/Yr: Particulate Matter Tons/Yr: Part. Matter 10 Micrometers & Smllr Tons/Yr: Year: Carbon Monoxide Emissions Tons/Yr: Air Basin:	SC 3728 SOUTH COAST AQMD Not reported 30 15 4 4 4 0 1 1 2004 19 SC
Air District Name: SIC Code: Air District Name: Community Health Air Pollution Info System: Consolidated Emission Reporting Rule: Total Organic Hydrocarbon Gases Tons/Yr: Reactive Organic Gases Tons/Yr: Carbon Monoxide Emissions Tons/Yr: NOX - Oxides of Nitrogen Tons/Yr: SOX - Oxides of Sulphur Tons/Yr: Particulate Matter Tons/Yr: Part. Matter 10 Micrometers & Smllr Tons/Yr: Year: Carbon Monoxide Emissions Tons/Yr: Air Basin: Facility ID:	SC 3728 SOUTH COAST AQMD Not reported 30 15 4 4 4 0 1 1 2004 19 SC 800003

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

1000221945

# HONEYWELL (Continued)

ONEYWELL (Continued)		
Air District Name: Community Health Air Pollutio Consolidated Emission Report Total Organic Hydrocarbon Ga Reactive Organic Gases Tons Carbon Monoxide Emissions T NOX - Oxides of Nitrogen Ton SOX - Oxides of Sulphur Tons Particulate Matter Tons/Yr: Part. Matter 10 Micrometers &	ting Rule: ases Tons/Yr: /Yr: Fons/Yr: s/Yr: s/Yr:	SOUTH COAST AQMD Y Not reported 30.2299011 15.28 4.121812 3.735981 0.04252659 1.045797 0.84
Year: Carbon Monoxide Emissions T Air Basin: Facility ID: Air District Name: SIC Code: Air District Name: Community Health Air Pollutio Consolidated Emission Report Total Organic Hydrocarbon Ga Reactive Organic Gases Tons Carbon Monoxide Emissions T NOX - Oxides of Nitrogen Ton SOX - Oxides of Sulphur Tons Particulate Matter Tons/Yr: Part. Matter 10 Micrometers &	n Info System: ting Rule: ases Tons/Yr: /Yr: Fons/Yr: s/Yr: Smllr Tons/Yr:	2005 19 SC 800003 SC 3728 SOUTH COAST AQMD Not reported 12.596043 7.5133565032 3.942918 3.258705 .041250004 .7277503 .59544335679
Document ID: Manifest Status: Trans1 State ID: Trans2 State ID: Generator Ship Date: Trans1 Recv Date: Trans2 Recv Date: TSD Site Recv Date: Part A Recv Date: Part B Recv Date: Generator EPA ID: Trans1 EPA ID: Trans2 EPA ID: TSDF ID: Waste Code: Quantity: Units: Number of Containers: Container Type: Handling Method: Specific Gravity: Year: Manifest Tracking Num: Import Ind: Export Ind: Discr Quantity Ind: Discr Type Ind: Discr Residue Ind:	00120 P - Pounds 061 CY - Cylinders	4 5

Database(s)

EDR ID Number EPA ID Number

#### HONEYWELL (Continued)

Discr Partial Reject Ind: Discr Full Reject Ind: Manifest Ref Num: Alt Fac RCRA Id: Alt Fac Sign Date: Mgmt Method Type Code: EPA ID: Facility Name: Facility Address: Facility City: Facility Address 2: Country: County: Mailing Name: Mailing Contact: Mailing Address: Mailing Address 2: Mailing City: Mailing State: Mailing Zip: Mailing Zip4: Mailing Country: Mailing Phone:

Not reported Not reported Not reported Not reported Not reported Not reported CAD071896336 HONEYWELLL 2525 190TH ST TORRANCE Not reported USA Not reported HONEYWELLL JEFFREY P ROSS 2525 19OTH ST Not reported TORRANCE CA Not reported Not reported USA N/S

# 23 CHEVRON USA SS 931 East 2623 W 190TH ST 1/8-1/4 REDONDO BEACH, CA 1046 ft.

CA FID UST:

Relative: Lower

Actual: 62 ft.	Facility ID: Regulated By: Regulated ID: Cortese Code: SIC Code: Facility Phone: Mail To: Mailing Address: Mailing Address 2: Mailing Address 2: Mailing City,St,Zip: Contact: Contact Phone: DUNs Number: NPDES Number: EPA ID: Comments:	19054866 UTNKA 00061946 Not reported 818000000 Not reported P O BOX Not reported REDONDO BEACH Not reported Not reported Not reported Not reported Not reported Not reported Not reported Not reported Not reported
	Status: SWEEPS UST: Status: Comp Number: Number: Board Of Equalization Ref Date: Act Date: Created Date: Tank Status:	Active A 9869 9 on: 44-008608 06-30-89 Not reported 06-30-89 A

CA FID UST S101587097 SWEEPS UST N/A

1000221945

TC2051883.2s Page 57

Database(s)

EDR ID Number EPA ID Number

# CHEVRON USA SS 931 (Continued)

	Sintillaca)
Owner Tank Id:	Not reported
Swrcb Tank Id:	19-000-009869-000001
Actv Date:	06-30-89
Capacity:	Not reported
Tank Use:	UNKNOWN
Stg:	W
Content:	Not reported
Number Of Tanks:	4
Status:	А
	9869
Comp Number:	
Number:	9
Board Of Equalization:	44-008608
Ref Date:	06-30-89
Act Date:	Not reported
Created Date:	06-30-89
Tank Status:	А
Owner Tank Id:	Not reported
Swrcb Tank Id:	19-000-009869-000002
Actv Date:	06-30-89
Capacity:	Not reported
Tank Use:	UNKNOWN
Stg:	W
Content:	Not reported
Number Of Tanks:	Not reported
Status:	А
Comp Number:	9869
Number:	9
Board Of Equalization:	44-008608
Ref Date:	06-30-89
Act Date:	Not reported
Created Date:	06-30-89
Tank Status:	A
Owner Tank Id:	Not reported
Swrcb Tank Id:	19-000-009869-000003
Actv Date:	06-30-89
Capacity:	Not reported
Tank Use:	UNKNOWN
Stg:	W
Content:	Not reported
Number Of Tanks:	Not reported
	•
Status:	Α
Comp Number:	9869
Number:	9
Board Of Equalization:	44-008608
Ref Date:	06-30-89
Act Date:	Not reported
Created Date:	06-30-89
Tank Status:	A
Owner Tank Id:	Not reported
Swrcb Tank Id:	19-000-009869-000004
Actv Date:	06-30-89
Capacity:	Not reported
Tank Use:	UNKNOWN
Stg:	W

Map ID Direction		MAP FINDINGS	
Distance Distance (ft Elevation	.) Site		
	CHEVRON USA SS 931 (Cont	inued)	
		ot reported ot reported	
24 East 1/4-1/2 1337 ft.	HONEYWELL SITE A 2525 W. 190TH STREET TORRANCE, CA 90504		
Relative: Lower	SLIC: Region: Global Id:	STATE SL0603795692	
Actual: 60 ft.	Assigned Name: Lead Agency Contact: Lead Agency: Lead Agency Case Numbe Responsible Party: Recent Dtw:	SLICSITE STEVE ROWE LOS ANGELES RWQCB (REGION 4)	

Г

EDR ID Number EPA ID Number

S101587097

SLIC S108245995 N/A

Database(s)

#### 25 ARCO #0154

North 3015 182ND ST W 1/4-1/2 TORRANCE, CA 90504

LUST:

1932 ft.

# **Relative:**

Higher	Region:	STATE
	Case Type:	Other ground water affected
Actual:	Cross Street:	CRENSHAW BLVD
78 ft.	Enf Type:	SI
	Funding:	Not reported
	How Discovered:	Subsurface Monitoring
	How Stopped:	Not reported
	Leak Cause:	UNK
	Leak Source:	UNK
	Global Id:	T0603701482
	Stop Date:	Not reported
	Confirm Leak:	Not reported
	Workplan:	Not reported
	Prelim Assess:	Not reported
	Pollution Char:	1998-01-14 00:00:00
	Remed Plan:	2004-05-05 00:00:00
	Remed Action:	2004-07-30 00:00:00
	Monitoring:	Not reported
	Close Date:	Not reported
	Discover Date:	1989-03-14 00:00:00
	Enforcement Dt:	2001-03-14 00:00:00
	Release Date:	1989-11-27 00:00:00
	Review Date:	Not reported
	Enter Date:	1989-12-05 00:00:00
	MTBE Date:	1965-01-01 00:00:00
	GW Qualifier:	Not reported
	Soil Qualifier:	Not reported
	Max MTBE GW ppb:	
	Max MTBE Soil ppb:	Not reported
	County:	19

LUST S101298298 Cortese N/A

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

#### ARCO #0154 (Continued)

Org Name: Not reported Los Angeles Region Reg Board: Status: Remedial action (cleanup) Underway Chemical: Gasoline Contact Person: Not reported Responsible Party: JACK OMAN RP Address: 6 CENTERPOINTE DR. Interim: Yes Oversight Prgm: LUST MTBE Class: 1 MTBE Conc: MTBE Fuel: 1 MTBE Tested: MTBE Detected. Site tested for MTBE and MTBE detected Staff: AT RVB Staff Initials: **Regional Board** Lead Agency: 19038 Local Agency: Hydr Basin #: SAN FERNANDO VALLEY Beneficial: Not reported Not reported Priority: Cleanup Fund Id: Not reported Not reported Work Suspended: Local Case #: Not reported 905040089 Case Number: Qty Leaked: Not reported Remove Free Product - remove floating product from water table Abate Method: Operator: Not reported Water System Name:Not reported Not reported Well Name: Distance To Lust: 0 Waste Discharge Global ID: Not reported Waste Disch Assigned Name: Not reported 10/13/00 3RD QTR GW MON RPT 2000; 1/15/01 4TH QTR GW MON RPT 2000; 2/8/01 SOIL Summary: SAMPLING RPT; 4/13/01 1ST QTR GW MON RPT 2001; 4/11/01 RESULTS OF PRODUCTION WELL SEARCH

# LUST:

Region:	4
Staff:	AT
County:	Los Angeles
Local Agency:	19038
Lead Agency:	Regional Board
Case Type:	Groundwater
Status:	Remediation Plan
Substance:	Gasoline
Cross Street:	CRENSHAW BLVD
Global ID:	T0603701482
Enforcement Type:	DLSEL
Date Leak Discovered:	3/14/1989
Date Leak Record Entered:	12/5/1989
How Leak Discovered:	Subsurface Monitoring
How Leak Stopped:	Not reported
Cause of Leak:	UNK
Leak Source:	UNK
Date Leak Stopped:	Not reported
Date Confirmation Began:	Not reported
Operator:	Not reported

Map ID Direction Distance Distance (ft.) Site Elevation

D26

North

1/4-1/2

1937 ft.

Database(s)

EDR ID Number EPA ID Number

# ARCO #0154 (Continued)

BIL 18-D9E 200 CRENSHAW BL RRANCE, CA 9050			HAZNET LUST Cortese	S10328 N/A
Cortese: Region: Facility Addr2:	CORTESE 3015 182ND ST W			
Local Case No: Substance Quanti Assigned Name: W Global ID: Summary:	Not reported ty: Not reported Not reported Not reported 10/13/00 3RD QT 2/8/01 SOIL SAM	R GW MON RPT 2000; 1/15/01 4TH QTR GW M IPLING RPT; 4/13/01 1ST QTR GW MON RPT 2 RODUCTION WELL SEARCH		
GW Qualifier: Soil Qualifier: Organization: Regional Board: Owner Contact: Responsible Party RP Address: Program: Lat/Long: Local Agency Stal Beneficial Use: Priority: Cleanup Fund Id: Suspended:	Not reported = Not reported 04 Not reported r: RAY VOSE PO BOX 8385 LUST 33.8656366 / -1 ff: RVB Not reported Not reported Not reported Not reported			
Abatement Metho Source of Cleanup Date Leak First Re Preliminary Site A Preliminary Site A Pollution Characte Remediation Plan Remedial Action L Post Remedial Act Date the Case wa Date Case Last C Enforcement Action Historical Max MT Hist Max MTBE C Hist Max MTBE C	eported: ssessment Workplan Submi ssessment Began: erization Began: Submitted: Jnderway: tion Monitoring Began: s Closed: hanged on Database: on Date: BE Date: onc in Groundwater:	2287.0470599889635773539459259 Remove Free Product Remove Free Product 11/27/1989 itted: Not reported 1/15/2003 1/14/1998 5/5/2004 4/15/2003 Not reported Not reported Not reported 7/15/2002 3/14/2001 1/1/1965 64000 .81 Yes		

S101298298

Relative:		
Higher	HAZNET:	
•	Gepaid:	CAL000056167
Actual:	Contact:	DALE VIATOR, ENVT'L ADVISOR
78 ft.	Telephone:	2816548470
	Facility Addr2:	Not reported
	Mailing Name:	TANKNOLOGY NDE

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

#### MOBIL 18-D9E (Continued)

Mailing Address: 16825 NORTHCHASE DRIVE RM 911 HOUSTON, TX 770600000 Mailing City, St, Zip: Gen County: Los Angeles TSD EPA ID: CAD028409019 TSD County: Los Angeles Waste Category: Unspecified oil-containing waste **Disposal Method:** Treatment, Tank Tons: 0.14 Facility County: Los Angeles Gepaid: CAL000056167 DALE VIATOR, ENVT'L ADVISOR Contact: Telephone: 2816548470 Facility Addr2: Not reported Mailing Name: TANKNOLOGY NDE Mailing Address: 16825 NORTHCHASE DRIVE RM 911 Mailing City, St, Zip: HOUSTON, TX 770600000 Gen County: Los Angeles TSD EPA ID: CAT080014079 TSD County: Los Angeles Waste Category: Other organic solids **Disposal Method:** Not reported Tons: 0.01 Facility County: Los Angeles LUST: Region: STATE Case Type: Other ground water affected Cross Street: 182ND ST. Enf Type: SI Funding: Not reported How Discovered: Not reported How Stopped: Not reported Leak Cause: UNK Leak Source: UNK T0603701494 Global Id: Stop Date: Not reported Confirm Leak: Not reported 1990-09-14 00:00:00 Workplan: Prelim Assess: Not reported 1990-12-11 00:00:00 Pollution Char: Remed Plan: 2001-03-14 00:00:00 Remed Action: 2005-04-21 00:00:00 Monitoring: Not reported Close Date: Not reported 1990-10-19 00:00:00 Discover Date: Enforcement Dt: 2001-03-14 00:00:00 Release Date: 1990-10-19 00:00:00 **Review Date:** Not reported Enter Date: 1990-11-09 00:00:00 MTBE Date: 1965-01-01 00:00:00 GW Qualifier: Not reported Soil Qualifier: Not reported Max MTBE GW ppb: 7,700 Max MTBE Soil ppb: Not reported County: 19 Org Name: Not reported

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

S103281900

#### MOBIL 18-D9E (Continued)

Reg Board: Los Angeles Region Remedial action (cleanup) Underway Status: Gasoline Chemical: Contact Person: Not reported KAREN GALE Responsible Party: **RP Address:** 8 PASTEUR, SUITE 190 Interim: Not reported Oversight Prgm: LUST MTBE Class: 1 MTBE Conc: MTBE Fuel: 1 MTBE Detected. Site tested for MTBE and MTBE detected MTBE Tested: Staff: AT RVB Staff Initials: **Regional Board** Lead Agency: 19038 Local Agency: SAN FERNANDO VALLEY Hydr Basin #: Beneficial: Not reported Priority: Not reported Cleanup Fund Id: Not reported Work Suspended: Not reported Not reported Local Case #: Case Number: 905040207 Qty Leaked: Not reported Not reported Abate Method: Operator: Not reported Water System Name:Not reported Well Name: Not reported Distance To Lust: 0 Waste Discharge Global ID: Not reported Waste Disch Assigned Name: Not reported Summary: 8/16/00 EPA UPGRADE SAMPLING REPORT AND MANIFEST; 10/13/00 3RD QTR GW MON RPT 2000; 1/15/01 4TH QTR GW MON RPT 2000; 4/5/01 1ST QTR GW MON RPT 2001

# LUST:

Region:	4
Staff:	AT
County:	Los Angeles
Local Agency:	19038
Lead Agency:	Regional Board
Case Type:	Groundwater
Status:	Remedial action (cleanup) Underway
Substance:	Gasoline
Cross Street:	182ND ST.
Global ID:	T0603701494
Enforcement Type:	DLSEL
Date Leak Discovered:	10/19/1990
Date Leak Record Entered:	11/9/1990
How Leak Discovered:	Not reported
How Leak Stopped:	Not reported
Cause of Leak:	UNK
Leak Source:	UNK
Date Leak Stopped:	Not reported
Date Confirmation Began:	Not reported
Operator:	Not reported
Water System:	Not reported
Well Name:	Not reported

Map ID Direction		MA	AP FINDINGS		
Distance Distance (fi Elevation	t.) Site			Database(s)	EDR ID Number EPA ID Number
	MOBIL 18-D9E (Continued	)			S103281900
	Approx. Dist To Produc Abatement Method Use Source of Cleanup Fun Date Leak First Reporte Preliminary Site Assess Preliminary Site Assess Pollution Characterizati Remedial Action Under Post Remedial Action Under Post Remedial Action Under Post Remedial Action In Date the Case was Cloo Date Case Last Change Enforcement Action Da Historical Max MTBE Conc ir Significant Interim Rem GW Qualifier: Soil Qualifier: Organization: Regional Board: Owner Contact: Responsible Party: RP Address: Program: Lat/Long: Local Agency Staff: Beneficial Use: Priority: Cleanup Fund Id: Suspended: Local Case No: Substance Quantity: Assigned Name: W Global ID: Summary:	tion Well (ft): d at the Site: ding: ad: ment Workplan Submit ment Began: on Began: nitted: way: Monitoring Began: sed: ad on Database: te: ate: a Groundwater: a Soil: edial Action Taken: Not reported a Not reported KAREN GALE 620 W. 16TH ST., LUST 33.8654436 / -1 RVB Not reported Not reported No	Not reported 12/11/1990 3/14/2001 1/16/2004 Not reported 7/15/2002 3/14/2001 1/1/1965 7700 48 Not reported	JIFEST; 10/13/00	9 3RD QTR GW
D27 North 1/4-1/2 1937 ft.	EXXON #7-8712 18201 CRENSHAW BLVD S TORRANCE, CA 90504	RTESE 00 CRENSHAW BLVD		LUS Cortese	
Relative: Higher Actual:	5	TATE ther ground water affec	ted		

Case Type: Cross Street: Enf Type: Actual: 78 ft. Other ground water affected 182ND ST SI Funding: Not reported How Discovered: ОМ How Stopped: Not reported

Database(s)

EDR ID Number EPA ID Number

S101298272

#### EXXON #7-8712 (Continued)

Leak Cause: UNK Leak Source: UNK T0603701484 Global Id: Stop Date: Not reported Confirm Leak: Not reported Workplan: Not reported Prelim Assess: 1992-04-30 00:00:00 Pollution Char: 1997-06-04 00:00:00 Remed Plan: 2001-03-14 00:00:00 Remed Action: 2001-09-25 00:00:00 2006-01-15 00:00:00 Monitoring: Close Date: Not reported Discover Date: 1992-04-30 00:00:00 Enforcement Dt: 2001-03-14 00:00:00 Release Date: 1992-04-17 00:00:00 **Review Date:** Not reported 1992-05-09 00:00:00 Enter Date: MTBE Date: 1965-01-01 00:00:00 GW Qualifier: Not reported Soil Qualifier: Not reported Max MTBE GW ppb: 130 Max MTBE Soil ppb: Not reported County: 19 Org Name: Not reported Reg Board: Los Angeles Region Status: Post remedial action monitoring Chemical: Gasoline Contact Person: Not reported MARIA D. GUENSLER Responsible Party: 2532 N. 4TH ST., PMB 343 **RP Address:** Interim: Not reported Oversight Prgm: LUST MTBE Class: С MTBE Conc: 1 MTBE Fuel: 1 MTBE Tested: MTBE Detected. Site tested for MTBE and MTBE detected Staff: AT Staff Initials: RVB **Regional Board** Lead Agency: 19038 Local Agency: SAN FERNANDO VALLEY Hydr Basin #: Beneficial: Not reported Priority: Not reported Cleanup Fund Id: Not reported Not reported Work Suspended: Local Case #: Not reported Case Number: 905040107 Qty Leaked: Not reported Abate Method: Not reported ABDELSAYED, ADLI Operator: Water System Name:Not reported Well Name: Not reported Distance To Lust: 0 Waste Discharge Global ID: Not reported Waste Disch Assigned Name: Not reported 1/3/00 4TH QTR GW MON RPT: 6/30/00 2ND QTR GW MON RPT: 11/15/00 3RD QTR GW MON Summarv: RPT 2000; 12/29/00 4TH QTR GW MON RPT 2000; 4/12/01 1ST QTR GW MON RPT 2001

Database(s)

EDR ID Number EPA ID Number

# EXXON #7-8712 (Continued)

LUST:		
Region:	4	
Staff:	AT	
County:	Los Angeles	
Local Agency:	19038	
Lead Agency:	Regional Board	
Case Type:	Groundwater	<b></b>
Status:	Remedial action (clea	anup) Underway
Substance:	Gasoline	
Cross Street:	182ND ST	
Global ID:	T0603701484	
Enforcement Type:	DLSEL	
Date Leak Discovered:	4/30/1992	
Date Leak Record Entered:		
How Leak Discovered:	OM	
How Leak Stopped:	Not reported	
Cause of Leak:	UNK	
Leak Source:	UNK	
Date Leak Stopped:	Not reported	
Date Confirmation Began:	Not reported	
Operator:	ABDELSAYED, ADLI	
Water System:	Not reported	
Well Name:	Not reported	
Approx. Dist To Production		2101.97755074611155303015847
Abatement Method Used at		Not reported
Source of Cleanup Funding	:	Not reported
Date Leak First Reported:		4/17/1992
Preliminary Site Assessme		
Preliminary Site Assessme		4/30/1992
Pollution Characterization E	0	6/4/1997
Remediation Plan Submitte		3/14/2001
Remedial Action Underway		9/25/2001
Post Remedial Action Moni		Not reported
Date the Case was Closed:		Not reported
Date Case Last Changed o Enforcement Action Date:	n Dalabase.	9/11/2002
Historical Max MTBE Date:		3/14/2001 1/1/1965
Hist Max MTBE Conc in Gr		130
Hist Max MTBE Conc in So		Not reported
Significant Interim Remedia		Not reported
GW Qualifier:	Not reported	Not reported
Soil Qualifier:	Not reported	
Organization:	Not reported	
Regional Board:	04	
Owner Contact:	Not reported	
Responsible Party:	MICHAEL MEDNICK	
RP Address:	2532 N. 4TH ST., PM	
Program:	LUST	
Lat/Long:	33.8654436 / -1	
Local Agency Staff:	RVB	
Beneficial Use:	Not reported	
Priority:	Not reported	
Cleanup Fund Id:	Not reported	
Suspended:	Not reported	
Local Case No:	Not reported	
Substance Quantity:	Not reported	
Assigned Name:	Not reported	

EDR ID Number Database(s) EPA ID Number

S101298272

# EXXON #7-8712 (Continued)

W Global ID: Summary:

Facility Addr2:

Not reported 1/3/00 4TH QTR GW MON RPT; 6/30/00 2ND QTR GW MON RPT; 11/15/00 3RD QTR GW MON RPT 2000; 12/29/00 4TH QTR GW MON RPT 2000; 4/12/01 1ST QTR GW MON RPT 2001

Cortese: Region:

CORTESE 18201 CRENSHAW BLVD S

D28 North 1/4-1/2	YNIGUEZ FAMILY TRUS 18145 CRENSHAW BLVI TORRANCE, CA 90504		LUST Cortese	S102441431 N/A
2079 ft.	Cite 2 of 2 in alustan D			
Relative:	Site 3 of 3 in cluster D			
Higher	LUST:			
•	Region:	STATE		
Actual:	Case Type:	Other ground water affected		
76 ft.	Cross Street:	182ND ST		
	Enf Type:	DLSEL		
	Funding:	Not reported		
	How Discovered:	Tank Closure		
	How Stopped:	Not reported		
	Leak Cause:	UNK		
	Leak Source:	UNK		
	Global Id:	T0603701488		
	Stop Date:	1995-08-15 00:00:00		
	Confirm Leak:	Not reported		
	Workplan:	Not reported		
	Prelim Assess:	2002-11-27 00:00:00		
	Pollution Char:	1997-07-01 00:00:00		
	Remed Plan:	2001-03-14 00:00:00		
	Remed Action:	2002-06-04 00:00:00		
	Monitoring:	Not reported		
	Close Date:	Not reported		
	Discover Date:	1995-12-15 00:00:00		
	Enforcement Dt:	2001-03-14 00:00:00		
	Release Date:	1993-12-30 00:00:00		
	Review Date:	2002-09-26 00:00:00		
	Enter Date: MTBE Date:	1995-07-25 00:00:00		
		1998-10-21 00:00:00		
	GW Qualifier:	Not reported		
	Soil Qualifier: Max MTBE GW ppb:	Not reported		
	Max MTBE GW ppb.			
	County:	19		
	Org Name:	Not reported		
	Reg Board:	Los Angeles Region		
	Status:	Preliminary site assessment underway		
	Chemical:	Gasoline		
	Contact Person:	Not reported		
	Responsible Party:	JOE LENTINI		
	RP Address:	8281 COMMONWEALTH AVE.		
	Interim:	No		
	Oversight Prgm:	LUST		
	MTBE Class:	*		
	MTBE Conc:	2		
		-		

Database(s)

EDR ID Number EPA ID Number

# YNIGUEZ FAMILY TRUST (Continued)

		(continuou)		0.02111.01
	MTBE Fuel:	1		
	MTBE Tested:	MTBE Detected. Site tested f	or MTBE and MTBE detected	
	Staff:	AT		
	Staff Initials:	RVB		
	Lead Agency:	Regional Board		
	Local Agency:	19038		
	Hydr Basin #:	SAN FERNANDO VALLEY		
	Beneficial:	Not reported		
	Priority:	Not reported		
	Cleanup Fund Id:	Not reported		
	Work Suspended:	Not reported		
	Local Case #:	Not reported		
	Case Number:	905040143		
	Qty Leaked:	Not reported		
	Abate Method:	Vapor Extraction		
	Operator:	Not reported		
	Water System Name Well Name:			
	Distance To Lust:	Not reported 0		
	Waste Discharge Glo			
		ed Name: Not reported		
	0	•	EMEDIATION; SPARGE TESTING REPORT DUE BY	ILINE 4 2002
	ouninary. Oc		LEMEDIATION, OF ANOL FEOTING NET ON TOOL DT	JOINE 4, 2002
LU	JST:			
	Region:	4 A T		
	Staff:			
	County:	Los Angeles		
	Local Agency: Lead Agency:	19038 Regional Board		
	Case Type:	Groundwater		
	Status:	Preliminary site asses	sment underway	
	Substance:	Gasoline	Sheri uluelway	
	Cross Street:	182ND ST		
	Global ID:	T0603701488		
	Enforcement Type:	LET		
	Date Leak Discovere			
	Date Leak Record Er			
	How Leak Discovere	d: Tank Closure		
	How Leak Stopped:	Not reported		
	Cause of Leak:	UNK		
	Leak Source:	UNK		
	Date Leak Stopped:	8/15/1995		
	Date Confirmation Be	egan: Not reported		
	Operator:	Not reported		
	Water System:	Not reported		
	Well Name:	Not reported		
	Approx. Dist To Prod		2066.1461398270175095604694715	
	Abatement Method L		VE	
	1 0		VE	
	Date Leak First Repo		12/30/1993	
	Preliminary Site Assessment Workplan Submitted:			
	Preliminary Site Asse		11/27/2002	
	Pollution Characteriz	0	7/1/1997	
	Remediation Plan Su		3/14/2001	
	Remedial Action Unc		6/4/2002 Not reported	
	Post Remedial Action Date the Case was C		Not reported Not reported	
	Date the Case was C	103 <del>0</del> 0.	Notrepoiled	

Map ID Direction	MAP FINDINGS			]	
Distance Distance (ft Elevation	.) Site			Database(s)	EDR ID Number EPA ID Number
	YNIGUEZ FAMILY TRUST (Continued)				S102441431
	Date Case Last Changed Enforcement Action Date: Historical Max MTBE Date Hist Max MTBE Conc in C Hist Max MTBE Conc in S Significant Interim Remed GW Qualifier: Organization: Regional Board: Owner Contact: Responsible Party: RP Address: Program: Lat/Long: Local Agency Staff: Beneficial Use: Priority: Cleanup Fund Id: Suspended: Local Case No: Substance Quantity: Assigned Name: W Global ID: Summary:	e: Groundwater: Soil: lial Action Taken: Not reported Not reported O4 Not reported JOE LENTINI 8281 COMMONWE LUST 33.8659446 / -1 RVB Not reported Not reported	9/26/2002 3/14/2001 10/21/1998 25000 Not reported No EALTH AVE.	E TESTING REPOR	RT DUE BY JUNE
	Region: CORTESE Facility Addr2: 18145 CRENSHAW BLVD				
E29 MOBIL, TORRANCE REFINER West 3700 W. 190TH STREET 1/2-1 TORRANCE, CA 90509 3149 ft. Site 1 of 2 in cluster E		RY		CHMIRS Toxic Pits SLIC EMI	S100676240 N/A

G

**Relative:** 

Higher

Actual:

72 ft.

CHMIRS:

OES Incident Number:

OES notification:

OES Date:

OES Time:

Incident Date:

Property Use:

Time Notified:

Time Completed:

Surrounding Area: Estimated Temperature:

Special Studies 2:

**Special Studies 3:** 

Special Studies 4:

Special Studies 5:

Property Management: Special Studies 1:

Date Completed:

Agency Id Number:

Agency Incident Number:

98-4074

Not reported

Not reported

Not reported

Not reported

Not reported

Not reported Not reported

Not reported

Not reported Not reported

Not reported Not reported

Not reported

Not reported

Not reported

Not reported

Not reported

9/5/199804:19:05 AM

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

S100676240

#### MOBIL, TORRANCE REFINERY (Continued)

**Special Studies 6:** Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Vehicle License Number: Not reported Vehicle State: Not reported Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Company Name: Not reported Reporting Officer Name/ID: Not reported Report Date: Not reported Not reported Comments: Facility Telephone: Not reported Waterway Involved: No Not reported Waterway: Spill Site: Not reported Cleanup By: Fire Dept. Containment: Not reported What Happened: Not reported Type: Not reported Measure: Not reported Other: Not reported Date/Time: Not reported 1998 Year: Mobil Refinery Agency: 9/5/199812:00:00 AM Incident Date: Admin Agency: **Torrance Fire Department** Amount: Not reported Contained: Yes Site Type: Road E Date: Not reported Gasoline Substance: Quantity Released: Not reported BBLS: 4 Cups: 0 CUFT: 0 Gallons: 0.000000 Grams: 0 Pounds: 0 Liters: 0 Ounces: 0 Pints: 0 Quarts: 0 Sheen: 0 0 Tons: Unknown: 0 Description: Not reported Evacuations: 60 Number of Injuries: 0 Number of Fatalities: 0 Description: Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway

Database(s) EPA ID

EDR ID Number EPA ID Number

#### MOBIL, TORRANCE REFINERY (Continued)

S100676240

adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes.Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit. In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials intothe atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity. caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack. Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment. Due to flaring. The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures.Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare. Flaring due to inability to sell refinery fuel gas to local power company.Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount. No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen

Database(s)

EDR ID Number EPA ID Number

### S100676240

heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost.A hydrogen header overpressured and went to flare.An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number:	98-3297	
OES notification:	7/21/199803:	47:11 AM
OES Date:	Not reported	
OES Time:	Not reported	
Incident Date:	Not reported	
Date Completed:	Not reported	1
Property Use:	Not reported	
Agency Id Number:	Not reported	
Agency Incident Number:	Not reported	
Time Notified:	Not reported	
Time Completed:	Not reported	
Surrounding Area:	Not reported	
Estimated Temperature:	Not reported	
Property Management:	Not reported	
Special Studies 1:	Not reported	
Special Studies 2:	Not reported	
Special Studies 3:	Not reported	
Special Studies 4:	Not reported	
Special Studies 5:	Not reported	
Special Studies 6:	Not reported	
More Than Two Substances Ir	nvolved?:	Not reported
Resp Agncy Personel # Of De	contaminated	Not reported
<b>Responding Agency Personel</b>	# Of Injuries:	Not reported
<b>Responding Agency Personel</b>	# Of Fatalities	Not reported
Others Number Of Decontami	nated:	Not reported
Others Number Of Injuries:		Not reported
Others Number Of Fatalities:		Not reported
Vehicle Make/year:	Not reported	
Vehicle License Number:	Not reported	
Vehicle State:	Not reported	
Vehicle Id Number:	Not reported	
CA/DOT/PUC/ICC Number:	Not reported	
Company Name:	Not reported	
Reporting Officer Name/ID:	Not reported	
Report Date:	Not reported	
Comments:	Not reported	
Facility Telephone:	Not reported	
Waterway Involved:	No	
Waterway:	Not reported	
Spill Site:	Not reported	
Cleanup By:	not feasible/v	rapor
Containment:	Not reported	
What Happened:	Not reported	
Туре:	Not reported	

Database(s)

EDR ID Number EPA ID Number

Measure: Other: Date/Time: Year: Agency: Incident Date: Admin Agency: Amount: Contained: Site Type: E Date: Substance: Quantity Released: BBLS: Cups: CUFT: Gallons: Grams: Pounds: Liters: Ounces: Pints: Quarts: Sheen: Tons: Unknown: Description: Evacuations: Number of Injuries: Number of Fatalities: Description:

Not reported Not reported Not reported 1998 Mobil Oil 7/21/199812:00:00 AM Torrance Fire Department Not reported Yes Refinery Not reported Heavy Hydrocrack feed Not reported 0 0 0 0.000000 0 0 0 0 0 0 0 0 Λ Not reported 0 0 0

Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere. Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes.Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials intothe atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the

Database(s) EPA

EDR ID Number EPA ID Number

### MOBIL, TORRANCE REFINERY (Continued)

### S100676240

release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures.Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company.Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas. Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number:	98-4
OES notification:	9/13/
OES Date:	Not r
OES Time:	Not r
Incident Date:	Not r
Date Completed:	Not
Property Use:	Not r
Agency Id Number:	Not r
Agency Incident Number:	Not r
Time Notified:	Not r
Time Completed:	Not r
Surrounding Area:	Not r

98-4198 9/13/199811:29:44 PM Not reported Not reported **Not reported** Not reported Not reported

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

### MOBIL, TORRANCE REFINERY (Continued)

Estimated Temperature: Not reported Property Management: Not reported Special Studies 1: Not reported Special Studies 2: Not reported Special Studies 3: Not reported Special Studies 4: Not reported Special Studies 5: Not reported **Special Studies 6:** Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Not reported Vehicle License Number: Vehicle State: Not reported Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Not reported Company Name: Reporting Officer Name/ID: Not reported Not reported Report Date: Comments: Not reported Facility Telephone: Not reported Waterway Involved: No Waterway: Not reported Spill Site: Not reported Cleanup By: Contractor Not reported Containment: Not reported What Happened: Type: Not reported Measure: Not reported Other: Not reported Date/Time: Not reported 1998 Year: Mobil Oil Torrance Refinery Agency: Incident Date: 9/13/199812:00:00 AM Admin Agency: **Torrance Fire Department** Not reported Amount: Contained: Yes Site Type: Refinery E Date: Not reported Coker Stabilizer off gas Substance: Quantity Released: Not reported BBLS: 0 Cups: 0 CUFT: 0 Gallons: 0.000000 Grams: 0 Pounds: 0 Liters: 0 Ounces: 0 Pints: 0 Quarts: 0 Sheen: 0 Tons: 0

MOBIL, TORRANCE REFINERY (Continued)

Database(s)

EDR ID Number EPA ID Number

EDR ID Number Database(s) EPA ID Number

### MOBIL, TORRANCE REFINERY (Continued)

Comments:

Facility Telephone:

Not reported

Not reported

#### S100676240

Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release **OES Incident Number:** 98-1332 OES notification: 3/17/199805:38:04 PM OES Date: Not reported OES Time: Not reported Incident Date: Not reported **Date Completed:** Not reported Property Use: Not reported Agency Id Number: Not reported Agency Incident Number: Not reported Time Notified: Not reported Time Completed: Not reported Surrounding Area: Not reported Estimated Temperature: Not reported Property Management: Not reported Not reported Special Studies 1: Special Studies 2: Not reported Special Studies 3: Not reported Special Studies 4: Not reported **Special Studies 5:** Not reported **Special Studies 6:** Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Vehicle License Number: Not reported Not reported Vehicle State: Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Company Name: Not reported Reporting Officer Name/ID: Not reported Report Date: Not reported

Database(s)

EDR ID Number **EPA ID Number** 

•	, ,
Waterway Involved:	No
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By:	Unknown
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	1998
Agency:	Mobile
Incident Date:	3/17/199812:00:00 AM
Admin Agency:	Torrance Fire Department
Amount:	Not reported
Contained:	Yes
Site Type:	Refinery
E Date:	Not reported
Substance:	none
Quantity Released:	Not reported
BBLS:	0
Cups:	0
CUFT:	0
Gallons:	0.000000
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	Exceeded limits between 1
	atmosphere.Piggy back of

etween 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes.Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be

EDR ID Number Database(s) EPA ID Number

### MOBIL, TORRANCE REFINERY (Continued)

S100676240

segregated and treated.per NRC: The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials intothe atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures.Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company.Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted.Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number: OES notification: OES Date: OES Time: Incident Date: 02-6091 11/10/200209:27:57 AM Not reported Not reported Not reported Map ID Direction Distance Distance (ft.) Elevation Site MAP FINDINGS

Database(s)

EDR ID Number EPA ID Number

### MOBIL, TORRANCE REFINERY (Continued)

**Date Completed:** Not reported Property Use: Not reported Not reported Agency Id Number: Agency Incident Number: Not reported Time Notified: Not reported Time Completed: Not reported Surrounding Area: Not reported Estimated Temperature: Not reported Not reported Property Management: Special Studies 1: Not reported Special Studies 2: Not reported **Special Studies 3:** Not reported Special Studies 4: Not reported **Special Studies 5:** Not reported Special Studies 6: Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Not reported Vehicle Make/year: Vehicle License Number: Not reported Vehicle State: Not reported Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Company Name: Not reported Reporting Officer Name/ID: Not reported Not reported Report Date: Comments: Not reported Facility Telephone: Not reported Waterway Involved: No Waterway: Not reported Spill Site: Not reported Cleanup By: N/A Not reported Containment: What Happened: Not reported Type: Not reported Measure: Not reported Other: Not reported Date/Time: Not reported Year: 2002 Agency: Exxon Mobil 11/10/200212:00:00 AM Incident Date: Admin Agency: **Torrance Fire Department** Amount: Not reported Contained: No Site Type: Refinery Not reported E Date: Substance: Nitrogen Oxide Quantity Released: Not reported BBLS: 0 Cups: 0 CUFT: 0 Gallons: 0.000000 Grams: 0

Database(s)

EDR ID Number EPA ID Number

# S100676240

#### MOBIL, TORRANCE REFINERY (Continued)

Pounds:	10
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	Exceeded lim

ed limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes. Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit. In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials into he atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack. Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures.Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company. Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking. High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason

Database(s) EPA I

EDR ID Number EPA ID Number

### MOBIL, TORRANCE REFINERY (Continued)

### S100676240

for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

**OES Incident Number:** 02-6717 OES notification: 12/12/200206:49:58 AM OES Date: Not reported Not reported OES Time: Incident Date: Not reported Not reported **Date Completed:** Property Use: Not reported Agency Id Number: Not reported Not reported Agency Incident Number: Time Notified: Not reported Time Completed: Not reported Surrounding Area: Not reported Estimated Temperature: Not reported Property Management: Not reported Special Studies 1: Not reported Special Studies 2: Not reported Special Studies 3: Not reported Special Studies 4: Not reported **Special Studies 5:** Not reported **Special Studies 6:** Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Vehicle License Number: Not reported Vehicle State: Not reported

Database(s)

EDR ID Number EPA ID Number

### MOBIL, TORRANCE REFINERY (Continued)

Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Not reported Company Name: Reporting Officer Name/ID: Not reported Report Date: Not reported Comments: Not reported Facility Telephone: Not reported Waterway Involved: No Waterway: Not reported Spill Site: Not reported Cleanup By: N/A Containment: Not reported What Happened: Not reported Not reported Type: Measure: Not reported Other: Not reported Date/Time: Not reported Year: 2002 Agency: Exxon Mobil Incident Date: 12/12/200212:00:00 AM **Torrance Fire Department** Admin Agency: Amount: Not reported Contained: Yes Site Type: Refinery E Date: Not reported Substance: NOX Quantity Released: Not reported BBLS: 0 Cups: 0 CUFT: 0 0.000000 Gallons: Grams: 0 Pounds: 10 Liters: 0 0 Ounces: Pints: 0 Quarts: 0 Sheen: 0 Tons: 0 Unknown: 0 Not reported Description: Evacuations: 0 Number of Injuries: 0 Number of Fatalities: 0 Description:

S100676240

Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading.Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes.Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to

EDR ID Number Database(s) EPA ID Number

MOBIL, TORRANCE REFINERY (Continued)

### S100676240

the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit. In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours. A pipe failure caused the release. Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials into he atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release. Unkown under investigation. Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release.Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures.Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare. Flaring due to inability to sell refinery fuel gas to local power company.Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking. High temperature has raised tank temp, causing PO gas to be released to the flare putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare. Release due to tank car overflow. FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a

Database(s)

EDR ID Number EPA ID Number

crack and subsequent release

OES Incident Number: 02-5827 10/29/200208:37:31 AM OES notification: OES Date: Not reported OES Time: Not reported Incident Date: Not reported Date Completed: Not reported Not reported Property Use: Agency Id Number: Not reported Not reported Agency Incident Number: Time Notified: Not reported Time Completed: Not reported Surrounding Area: Not reported Estimated Temperature: Not reported Property Management: Not reported Special Studies 1: Not reported **Special Studies 2:** Not reported **Special Studies 3:** Not reported Special Studies 4: Not reported **Special Studies 5:** Not reported **Special Studies 6:** Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Not reported Vehicle Make/year: Vehicle License Number: Not reported Vehicle State: Not reported Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Not reported Company Name: Not reported Reporting Officer Name/ID: Report Date: Not reported Comments: Not reported Facility Telephone: Not reported Waterway Involved: No Waterway: Not reported Spill Site: Not reported Cleanup By: N/A Containment: Not reported Not reported What Happened: Type: Not reported Measure: Not reported Other: Not reported Date/Time: Not reported Year: 2002 Agency: Exxon Mobil Incident Date: 10/29/200212:00:00 AM Admin Agency: Torrance Fire Department Not reported Amount: Contained: No Site Type: Refinerv E Date: Not reported

Database(s)

EDR ID Number EPA ID Number

S100676240

# MOBIL, TORRANCE REFINERY (Continued)

Substance:	NOX
Quantity Released:	Not reported
BBLS:	0
Cups:	0
CUFT:	0
Gallons:	0.000000
Grams:	0
Pounds:	10
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	Exceeded lim

ded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes. Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit. In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials into he atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures.Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare. Flaring due to inability to sell refinery fuel gas to local power company. Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank

Database(s) EP

EDR ID Number EPA ID Number

# MOBIL, TORRANCE REFINERY (Continued)

### S100676240

overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted.Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number:	02-6510
OES notification:	11/28/200204:10:10 PM
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
Date Completed:	Not reported
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances In	volved?: Not reported
Resp Agncy Personel # Of Dee	contaminated: Not reported
Deservation Assess Deservat	# Of Injurian. Not reported

Responding Agency Personel # Of Injuries: Not reported

Database(s)

EDR ID Number EPA ID Number

··, · • · · · · · • - · · - · · · · · · · ·	,	
Responding Agency Personel	# Of Fatalities:	Not reported
Others Number Of Decontami	nated:	Not reported
Others Number Of Injuries:		Not reported
Others Number Of Fatalities:		Not reported
Vehicle Make/year:	Not reported	
Vehicle License Number:	Not reported	
Vehicle State:	Not reported	
Vehicle Id Number:	Not reported	
CA/DOT/PUC/ICC Number:	Not reported	
Company Name:	Not reported	
Reporting Officer Name/ID:	Not reported	
Report Date:	Not reported	
Comments:	Not reported	
Facility Telephone:	Not reported	
Waterway Involved:	No	
Waterway:	Not reported	
Spill Site:	Not reported	
Cleanup By:	N/A	
Containment:	Not reported	
What Happened:	Not reported	
Type:	Not reported	
Measure:	Not reported	
Other:	Not reported	
Date/Time:	Not reported	
Year:	2002	
Agency:	Exxon Mobil	
Incident Date:	11/28/200212	:00:00 AM
Admin Agency:	Torrance Fire	Department
Amount:	Not reported	
Contained:	Yes	
Site Type:	Refinery	
E Date:	Not reported	
Substance:	NOX	
Quantity Released:	Not reported	
BBLS:	0	
Cups:	0	
CUFT:	0	
Gallons:	0.000000	
Grams:	0	
Pounds:	10	
Liters:	0	
Ounces:	0	
Pints:	0	
Quarts:	0	
Sheen:	0	
Tons:	0	
Unknown:	0	
Description:	Not reported	
Evacuations:	0	
Number of Injuries:	0	
Number of Fatalities:	0	
Description:	-	ts between 1542 hrs and 1619 hrs. resulting in a release to the
		iggy back of a big rig overturned during a U-turn on a roadway
	•	e refinery. Spilled to ground only. Precautionary evacuation of
		ar way's involved. Cleanup in progress. The alarm gase directly t

S100676240

area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have

EDR ID Number Database(s) EPA ID Number

### MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes. Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials into he atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release. Unkown under investigation. Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release.Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures. Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company.Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of

Database(s)

EDR ID Number EPA ID Number

### MOBIL, TORRANCE REFINERY (Continued)

Facility Telephone:

Waterway Involved:

Waterway:

Cleanup By: Containment:

What Happened:

Spill Site:

Type:

Other:

Year:

Measure:

Date/Time:

Not reported

Not reported

Not reported Reporting Party

Not reported

Not reported

Not reported

Not reported

Not reported Not reported

2002

No

### S100676240

refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release **OES Incident Number:** 02-6750 OES notification: 12/13/200211:29:45 AM OES Date: Not reported OES Time: Not reported Incident Date: Not reported **Date Completed:** Not reported Property Use: Not reported Not reported Agency Id Number: Agency Incident Number: Not reported Time Notified: Not reported Time Completed: Not reported Surrounding Area: Not reported Estimated Temperature: Not reported Property Management: Not reported Special Studies 1: Not reported Special Studies 2: Not reported **Special Studies 3:** Not reported Special Studies 4: Not reported **Special Studies 5:** Not reported Special Studies 6: Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Vehicle License Number: Not reported Vehicle State: Not reported Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Company Name: Not reported Reporting Officer Name/ID: Not reported Report Date: Not reported Comments: Not reported

Fire Department

Database(s)

EDR ID Number **EPA ID Number** 

Agency: Incident Date:	Exxon Mobil 12/13/200212:00:00 AM
	Torrance Fire Departmer
Admin Agency: Amount:	Not reported
Contained:	Yes
o o na an o an	Refinery
Site Type: F Date:	Not reported
Substance:	crude oil
Quantity Released: BBLS:	Not reported
	5
Cups:	0
CUFT:	0
Gallons:	0.000000
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	Exceeded limits between

ed limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere. Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes. Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit. In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials intothe atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment. Due to flaring. The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower,

Database(s) EPA ID I

EDR ID Number EPA ID Number

### MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures.Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare. Flaring due to inability to sell refinery fuel gas to local power company. Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring. During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas. Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare. Release due to tank car overflow. FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

**OES Incident Number: OES** notification: OES Date: OES Time: Incident Date: **Date Completed:** Property Use: Agency Id Number: Agency Incident Number: Time Notified: Time Completed: Surrounding Area: Estimated Temperature: **Property Management:** Special Studies 1: Special Studies 2:

02-6150

11/12/200209:51:13 AM Not reported Not reported

Database(s)

EDR ID Number EPA ID Number

# MOBIL, TORRANCE REFINERY (Continued)

**Special Studies 3:** Not reported Special Studies 4: Not reported Special Studies 5: Not reported Special Studies 6: Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Vehicle License Number: Not reported Vehicle State: Not reported Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Company Name: Not reported Reporting Officer Name/ID: Not reported Report Date: Not reported Comments: Not reported Facility Telephone: Not reported Waterway Involved: No Not reported Waterway: Spill Site: Not reported Cleanup By: N/A Containment: Not reported What Happened: Not reported Type: Not reported Measure: Not reported Not reported Other: Not reported Date/Time: 2002 Year: Agency: Exxon Mobil 11/12/200212:00:00 AM Incident Date: Admin Agency: **Torrance Fire Department** Not reported Amount: Contained: Yes Site Type: Refinery Not reported E Date: Substance: hydrophloric acid Quantity Released: Not reported BBLS: 0 Cups: 0 CUFT: 0 0.000000 Gallons: Grams: 0 Pounds: 1 Liters: 0 Ounces: 0 0 Pints: Quarts: 0 Sheen: 0 Tons: 0 Unknown: 0 Description: Not reported Evacuations: 0 Number of Injuries: 0

Database(s) EPA II

EDR ID Number EPA ID Number

S100676240

### MOBIL, TORRANCE REFINERY (Continued)

0

Number of Fatalities: Description:

> atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes. Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials into the atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack. Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures.Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare. Flaring due to inability to sell refinery fuel gas to local power company. Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted.Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in

Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the

Database(s) E

EDR ID Number EPA ID Number

### S100676240

pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost.A hydrogen header overpressured and went to flare.An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

		e to a breakoo
	crack and su	bsequent relea
OES Incident Number:	02-5949	
OES notification:	11/4/200210:	31:18 AM
OES Date:	Not reported	
OES Time:	Not reported	
Incident Date:	Not reported	
Date Completed:	Not reported	l
Property Use:	Not reported	
Agency Id Number:	Not reported	
Agency Incident Number:	Not reported	
Time Notified:	Not reported	
Time Completed:	Not reported	
Surrounding Area:	Not reported	
Estimated Temperature:	Not reported	
Property Management:	Not reported	
Special Studies 1:	Not reported	
Special Studies 2:	Not reported	
Special Studies 3:	Not reported	
Special Studies 4:	Not reported	
Special Studies 5:	Not reported	
Special Studies 6:	Not reported	
More Than Two Substances Ir		Not reported
Resp Agncy Personel # Of De		
Responding Agency Personel		
Responding Agency Personel		•
Others Number Of Decontamin	nated:	Not reported
Others Number Of Injuries:		Not reported
Others Number Of Fatalities:		Not reported
Vehicle Make/year:	Not reported	
Vehicle License Number:	Not reported	
Vehicle State:	Not reported	
Vehicle Id Number:	Not reported	
CA/DOT/PUC/ICC Number:	Not reported	
Company Name:	Not reported	
Reporting Officer Name/ID:	Not reported	
Report Date:	Not reported	
Comments:	Not reported	
Facility Telephone:	Not reported	
Waterway Involved:	No Not reported	
Waterway:	Not reported	
Spill Site:	Not reported N/A	
Cleanup By:	IN/A	

Database(s)

EDR ID Number EPA ID Number

### MOBIL, TORRANCE REFINERY (Continued)

Containment: Not reported What Happened: Not reported Not reported Type: Measure: Not reported Other: Not reported Date/Time: Not reported 2002 Year: Exxon Mobil-Torrance Refinery Agency: Incident Date: 11/4/200212:00:00 AM Admin Agency: **Torrance Fire Department** Not reported Amount: Contained: No Site Type: Refinery E Date: Not reported Substance: Nitrogen Oxide Quantity Released: Not reported BBLS: 0 Cups: 0 CUFT: 0 0.000000 Gallons: Grams: 0 Pounds: 10 Liters: 0 Ounces: 0 Pints: 0 Quarts: 0 Sheen: 0 Tons: 0 Unknown: 0 Description: Not reported Evacuations: 0 Number of Injuries: 0 Number of Fatalities: 0 Description:

Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes. Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials into he atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line

EDR ID Number Database(s) EPA ID Number

### MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment. Due to flaring. The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release.Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures.Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company.Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking. High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount. No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas. Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number: OES notification: OES Date: OES Time: Incident Date: **Date Completed:** Property Use: Agency Id Number: Agency Incident Number: 02-6354 11/20/200211:13:33 AM Not reported Not reported

# Map ID Direction Distance Distance (ft.) Elevation Site

MAP FINDINGS

Database(s)

EDR ID Number EPA ID Number

# MOBIL, TORRANCE REFINERY (Continued)

Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances I	
Resp Agncy Personel # Of De	•
Responding Agency Personel	
Responding Agency Personel	
Others Number Of Decontami	
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	No
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By:	N/A
Containment:	Not reported
What Happened:	Not reported
Туре:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	2002
Agency:	Exxon Mobil
Incident Date:	11/20/200212:00:00 AM
Admin Agency:	Torrance Fire Department
Amount:	Not reported
Contained:	No .
Site Type:	Refinery
E Date:	Not reported
Substance:	NOX
Quantity Released:	Not reported
BBLS:	0
Cups:	0
CUFT:	0
Gallons:	0.000000
Grams:	0
Pounds:	10
Liters:	0
Ounces:	0
Pints:	0
i into.	•

Database(s)

EDR ID Number EPA ID Number

Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Description:	Not reported
•	
•	
Evacuations: Number of Injuries: Number of Fatalities: Description:	<ul> <li>Description</li> <li>Descript</li></ul>
	flare. A check valve failed while decompressing a compressor. Equipment
	overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company.Units upset, still investigating the
	release. More gas in flare line that recovery can process.510X4 tank
	overpressured causing the release. Emission from 20F4P Stack, the mix is being
	adjusted.Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to
	the flare.putting tank back into service and flaring the gases that was in the
	tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the
	loading rack inside the refinery, no evacuations at this time.Unknown reason
	for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment

EDR ID Number Database(s) EPA ID Number

### MOBIL, TORRANCE REFINERY (Continued)

### S100676240

and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas. Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release **OES Incident Number:** 02-6359 **OES** notification: 11/20/200201:11:47 PM OES Date: Not reported OES Time: Not reported Incident Date: Not reported Date Completed: Not reported Not reported Property Use: Agency Id Number: Not reported Agency Incident Number: Not reported Time Notified: Not reported Time Completed: Not reported Surrounding Area: Not reported Not reported Estimated Temperature: **Property Management:** Not reported Special Studies 1: Not reported Special Studies 2: Not reported Special Studies 3: Not reported Special Studies 4: Not reported **Special Studies 5:** Not reported Special Studies 6: Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Vehicle License Number: Not reported Vehicle State: Not reported Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Company Name: Not reported Reporting Officer Name/ID: Not reported

Database(s)

EDR ID Number **EPA ID Number** 

# MOBIL, TORRANCE REFINERY (Continued)

Report Date: Not reported Comments: Facility Telephone: Waterway Involved: No Waterway: Spill Site: Cleanup By: N/A Containment: What Happened: Type: Measure: Other: Date/Time: 2002 Year: Agency: Incident Date: Admin Agency: Amount: Contained: No Site Type: Refinery E Date: Substance: NOX Quantity Released: BBLS: 0 Cups: 0 CUFT: 0 Gallons: 0.000000 Grams: 0 Pounds: 10 0 Liters: Ounces: 0 Pints: 0 Quarts: 0 Sheen: 0 0 Tons: Unknown: 0 Description: Evacuations: 0 Number of Injuries: 0 Number of Fatalities: 0 Description:

Not reported Exxon Mobil 11/20/200212:00:00 AM **Torrance Fire Department** Not reported Not reported Not reported Not reported

Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes.Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit. In a crude unit was upset due to water in the process. caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time

EDR ID Number Database(s) EPA ID Number

### MOBIL, TORRANCE REFINERY (Continued)

### S100676240

0015hours. A pipe failure caused the release. Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials intothe atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures.Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company.Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring. During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number: OES notification: 02-6684 12/10/200202:09:26 PM

Database(s)

EDR ID Number EPA ID Number

### MOBIL, TORRANCE REFINERY (Continued)

OES Date: Not reported OES Time: Not reported Incident Date: Not reported Not reported **Date Completed:** Property Use: Not reported Agency Id Number: Not reported Agency Incident Number: Not reported Time Notified: Not reported Time Completed: Not reported Surrounding Area: Not reported Estimated Temperature: Not reported Property Management: Not reported Special Studies 1: Not reported **Special Studies 2:** Not reported Special Studies 3: Not reported Special Studies 4: Not reported **Special Studies 5:** Not reported **Special Studies 6:** Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Not reported Vehicle Make/year: Vehicle License Number: Not reported Vehicle State: Not reported Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Company Name: Not reported Reporting Officer Name/ID: Not reported Report Date: Not reported Comments: Not reported Not reported Facility Telephone: Waterway Involved: No Not reported Waterway: Spill Site: Not reported Cleanup By: N/A Containment: Not reported What Happened: Not reported Not reported Type: Measure: Not reported Other: Not reported Date/Time: Not reported Year: 2002 Agency: Exxon Mobil Incident Date: 12/10/200212:00:00 AM Admin Agency: **Torrance Fire Department** Amount: Not reported Contained: No Site Type: Refinery E Date: Not reported Substance: NOX Quantity Released: Not reported BBLS: 0 0 Cups:

Database(s)

EDR ID Number EPA ID Number

#### MOBIL, TORRANCE REFINERY (Continued)

CUFT:	0	
Gallons:	0.000000	
Grams:	0	
Pounds:	10	
Liters:	0	
Ounces:	0	
Pints:	0	
Quarts:	0	
Sheen:	0	
Tons:	0	
Unknown:	0	
Description:	Not reported	
Evacuations:	0	
Number of Injuries:	0	
Number of Fatalities:	0	
Description:	Exceeded lim	

Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere. Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger. Pin hole leak in pipeline contained in diked area. Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes.Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials into he atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures. Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare. Flaring due to inability to sell refinery fuel gas to local power company.Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking. High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the

Database(s) EPA

EDR ID Number EPA ID Number

# MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare. Release due to tank car overflow. FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number:	02-6380	
OES notification:	11/21/20020	1:22:35 PM
OES Date:	Not reported	
OES Time:	Not reported	
Incident Date:	Not reported	
Date Completed:	Not reported	ł
Property Use:	Not reported	
Agency Id Number:	Not reported	
Agency Incident Number:	Not reported	
Time Notified:	Not reported	
Time Completed:	Not reported	
Surrounding Area:	Not reported	
Estimated Temperature:	Not reported	
Property Management:	Not reported	
Special Studies 1:	Not reported	
Special Studies 2:	Not reported	
Special Studies 3:	Not reported	
Special Studies 4:	Not reported	
Special Studies 5:	Not reported	
Special Studies 6:	Not reported	
More Than Two Substances Involved?: Not reported		
Resp Agncy Personel # Of Decontaminated: Not reported		
Responding Agency Personel	# Of Injuries:	Not reported
Responding Agency Personel # Of Fatalities:Not reported		
Others Number Of Decontaminated: Not reported		
Others Number Of Injuries:		Not reported

Not reported

Others Number Of Fatalities:

Database(s)

EDR ID Number EPA ID Number

## MOBIL, TORRANCE REFINERY (Continued)

Vehicle Make/year: Not reported Vehicle License Number: Not reported Not reported Vehicle State: Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Company Name: Not reported Reporting Officer Name/ID: Not reported Report Date: Not reported Not reported Comments: Facility Telephone: Not reported Waterway Involved: No Waterway: Not reported Spill Site: Not reported Cleanup By: N/A Containment: Not reported What Happened: Not reported Not reported Type: Measure: Not reported Other: Not reported Date/Time: Not reported 2002 Year: Agency: Exxon Mobil 11/21/200212:00:00 AM Incident Date: Admin Agency: Torrance Fire Department Amount: Not reported Contained: No Site Type: Refinery E Date: Not reported Substance: NOX Quantity Released: Not reported BBLS: 0 Cups: 0 CUFT: 0 Gallons: 0.000000 Grams: 0 Pounds: 10 Liters: 0 Ounces: 0 Pints: 0 Quarts: 0 Sheen: 0 Tons: 0 Unknown: 0 Description: Not reported Evacuations: 0 Number of Injuries: 0 Number of Fatalities: 0 Description:

Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading.Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes.Line rupture on line 24

EDR ID Number Database(s) EPA ID Number

### MOBIL, TORRANCE REFINERY (Continued)

### S100676240

F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit. In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials intothe atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred. Crude unit upset, flare was necessary of intermittent basis to control pressures. Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company. Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP

EDR ID Number Database(s) EPA ID Number

## MOBIL, TORRANCE REFINERY (Continued)

PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number:	02-5181
OES notification:	9/23/200211:30:42 AM
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
Date Completed:	Not reported
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances I	•
Resp Agncy Personel # Of De	•
Responding Agency Personel	
Responding Agency Personel	
Others Number Of Decontam	
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	No
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By:	N/A
Containment:	Not reported
What Happened:	Not reported
Туре:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	2002
Agency:	Exxon Mobil
Incident Date:	9/23/200212:00:00 AM
Admin Agency:	Torrance Fire Department
Amount:	Not reported

Database(s)

EDR ID Number EPA ID Number

	(•••••••
Contained:	No
Site Type:	Refinery
E Date:	Not reported
Substance:	NOX
Quantity Released:	Not reported
BBLS:	0
Cups:	0
CUFT:	0
Gallons:	0.000000
Grams:	0
Pounds:	10
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	Exceeded lim
	otmoonhoro I

# S100676240

ed limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes.Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials into he atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures. Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment

EDR ID Number Database(s) EPA ID Number

#### MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

overpressured and released to the flare. Flaring due to inability to sell refinery fuel gas to local power company.Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking. High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas. Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare. Release due to tank car overflow. FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

**OES Incident Number: OES** notification: OES Date: OES Time: Incident Date: **Date Completed:** Property Use: Agency Id Number: Agency Incident Number: Time Notified: Time Completed: Surrounding Area: Estimated Temperature: **Property Management:** Special Studies 1: Special Studies 2: Special Studies 3: Special Studies 4: Special Studies 5: Special Studies 6:

02-4610 8/26/200210:43:20 AM Not reported Not reported

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

#### MOBIL, TORRANCE REFINERY (Continued)

More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Vehicle License Number: Not reported Vehicle State: Not reported Vehicle Id Number: Not reported Not reported CA/DOT/PUC/ICC Number: Company Name: Not reported Reporting Officer Name/ID: Not reported Report Date: Not reported Comments: Not reported Facility Telephone: Not reported Waterway Involved: No Waterway: Not reported Spill Site: Not reported Cleanup By: N/A Containment: Not reported Not reported What Happened: Type: Not reported Measure: Not reported Other: Not reported Date/Time: Not reported Year: 2002 Agency: Exxon-Mobil corp 8/26/200212:00:00 AM Incident Date: Admin Agency: **Torrance Fire Department** Amount: Not reported Contained: No Site Type: Refinery E Date: Not reported Substance: NOX Quantity Released: Not reported BBLS: 0 Cups: 0 CUFT: 0 0.000000 Gallons: Grams: 0 Pounds: 10 0 Liters: 0 Ounces: Pints: 0 Quarts: 0 Sheen: 0 Tons: 0 0 Unknown: Description: Not reported Evacuations: 0 Number of Injuries: 0 Number of Fatalities: 0 Description: Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway

S100676240

adjacent to the refinery. Spilled to ground only. Precautionary evacuation of

Database(s) EPA

EDR ID Number EPA ID Number

### MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes.Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials intothe atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment. Due to flaring. The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures.Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare. Flaring due to inability to sell refinery fuel gas to local power company. Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount. No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring. During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas. Release due to a lot of

Type:

Measure:

Not reported Not reported

MAP FINDINGS

Database(s)

EDR ID Number EPA ID Number

#### ... MOBIL, T

BIL, TORRANCE REFINERY	(Continued)		S100676240
	soil.Release that was lost refinery caus ROOF DRAI Isolated and A BULLPLUO PROCEDUR release and emissions du	a short period of time and their sewer backed up onto due to loss of SCR to 1F1-2 due to weather. 1K3 is the ec A hydrogen header overpressured and went to flare. An up ed release to flare. Release due to tank car overflow. FAILL N CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak cleanup completed. BELIEVED TO BE AN UNDERGROUN G LEAK THAT CAUSED RELEASESMALL LEAKS DETEC ESCONTAINER FAILURE CAUSED SUBSTANCE TO EA fire. Cleanup by ACTIPotential release of higher release of te to a breakdown of equipment. Line integrity broke down of bsequent release	iset of JRE OF on transfer line. ND LEAK.APPEARS TO BE CTED DURING STARTUP IT THROUGH.Seal failed causing
OES Incident Number:	02-5362		
OES notification:	10/3/200209	:13:02 AM	
OES Date:	Not reported		
OES Time:	Not reported		
Incident Date:	Not reported		
Date Completed:	Not reported	1	
Property Use:	Not reported		
Agency Id Number:	Not reported		
Agency Incident Number:	Not reported		
Time Notified:	Not reported		
Time Completed:	Not reported		
Surrounding Area:	Not reported		
Estimated Temperature:	Not reported		
Property Management:	Not reported		
Special Studies 1: Special Studies 2:	Not reported		
Special Studies 3:	Not reported Not reported		
Special Studies 4:	Not reported		
Special Studies 5:	Not reported		
Special Studies 6:	Not reported		
More Than Two Substances		Not reported	
Resp Agncy Personel # Of De		•	
Responding Agency Persone	I # Of Injuries:	Not reported	
Responding Agency Persone	I # Of Fatalities	s:Not reported	
Others Number Of Decontam	inated:	Not reported	
Others Number Of Injuries:		Not reported	
Others Number Of Fatalities:		Not reported	
Vehicle Make/year:	Not reported		
Vehicle License Number:	Not reported		
Vehicle State:	Not reported		
Vehicle Id Number:	Not reported		
CA/DOT/PUC/ICC Number:	Not reported		
Company Name: Reporting Officer Name/ID:	Not reported Not reported		
Report Date:	Not reported		
Comments:	Not reported		
Facility Telephone:	Not reported		
Waterway Involved:	No		
Waterway:	Not reported		
Spill Site:	Not reported		
Cleanup By:	Unknown		
Containment:	Not reported		
What Happened:	Not reported		
Type:	Not reported		

Database(s)

EDR ID Number **EPA ID Number** 

#### MOBIL, TORRANCE REFINERY (Continued)

Other: Date/Time: Year: Agency: Incident Date: Admin Agency: Amount: Contained: Site Type: E Date: Substance: Quantity Released: BBLS: Cups: CUFT: Gallons: Grams: Pounds: Liters: Ounces: Pints: Quarts: Sheen: Tons: Unknown: Description: Evacuations: Number of Injuries: Number of Fatalities:

Not reported Not reported 2002 Exxon Mobil 10/3/200212:00:00 AM **Torrance Fire Department** Not reported Yes Refinery Not reported sodium hydroxide Not reported 0 0 0 0.000000 0 1000 0 0 0 0 0 0 0 Not reported 0 0

0

Description:

Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes. Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit. In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials into he atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused

EDR ID Number Database(s) EPA ID Number

#### MOBIL, TORRANCE REFINERY (Continued)

S100676240

the release. Unkown under investigation. Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release.Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures. Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company. Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare. Release due to tank car overflow. FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number:02OES notification:9/OES Date:NoOES Time:NoIncident Date:NoDate Completed:NoProperty Use:NoAgency Id Number:NoAgency Incident Number:NoTime Notified:NoTime Completed:NoSurrounding Area:NoEstimated Temperature:No

02-4880 9/9/200210:14:42 AM Not reported Not reported

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

#### MOBIL, TORRANCE REFINERY (Continued)

Property Management: Not reported Special Studies 1: Not reported Special Studies 2: Not reported Special Studies 3: Not reported Special Studies 4: Not reported Special Studies 5: Not reported Special Studies 6: Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Vehicle License Number: Not reported Not reported Vehicle State: Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Company Name: Not reported Reporting Officer Name/ID: Not reported Report Date: Not reported Not reported Comments: Facility Telephone: Not reported Waterway Involved: No Waterway: Not reported Spill Site: Not reported Cleanup By: N/A Containment: Not reported Not reported What Happened: Not reported Type: Measure: Not reported Other: Not reported Date/Time: Not reported 2002 Year: Agency: Exxon Refinery 9/9/200212:00:00 AM Incident Date: Admin Agency: **Torrance Fire Department** Amount: Not reported Contained: No Site Type: Refinery Not reported E Date: Substance: Oxides of Nitrogen(NOX) Quantity Released: Not reported BBLS: 0 Cups: 0 CUFT: 0 0.000000 Gallons: Grams: 0 Pounds: 11 Liters: 0 Ounces: 0 Pints: 0 Quarts: 0 Sheen: 0 Tons: 0 Unknown: 0

MOBIL, TORRANCE REFINERY (Continued)

Database(s)

EDR ID Number EPA ID Number

Not reported 0 0 Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to t atmosphere. Piggy back of a big rig overturned during a U-turn on a roadwa adjacent to the refinery. Spilled to ground only. Precautionary evacuation area. No water way's involved. Cleanup in progress. The alarm goes direc AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments h been made to treater and release is going downRelease caused by a leak exchanger.Pin hole leak in pipeline contained in diked area. Flow line deve a leak.Plug blew out on an exchanger (21E3C) allowing substance to esca Leak is ongoing, should be stopped within 10 minutes.Line rupture on line F1. Currently contained. Unit shut down at 0538 hrs. See also 99-3174.1 1 release valve lifted when line over pressuredBoth are ongoing. Failure in 1 in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitroger the flare.FCC Unit shut down bypassing SCR D7 causing the release to oc Release started 08/02/02 and ended 08/04/02A pocket of gas developed c maintenace on unit.In a crude unit was upset due to water in the process caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish tif 0015hours.A pipe failure caused the release. Released occurred on an inle that is used to truck acid in and pumps into the vessel. Water deluge was it to minimize the release into the air. SMALL release. Water used will be segregated and treated per NRC. The caller stated they had a compressor down on a hydrocracker unit, resulting in a release of materials intothe atmosphere.Equipment failure caused the release. Tank 400X31 pressured company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being release into the air. Unknown circumstances at a truck loading rack. Unknown circumstances caused the release. Unkown unde	ay of citly to a and it have in an loped upe. 24 inch PSA to ccur. during me t line used r shut d up and r caused o the rr, sary being ased to e
at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown rease for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was be and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was op and caused a leak.2F7 Damper 2D7 failed open causing the release.Unde Line leak caused the spill.Lost 25 K1C compressor shut down causing the release.This is a flaring event.Overfilled a rail car during loading. Spent	olowing dust pened Irground
	0 0 0 0 0 0 0 0 0 0 0 0 0 0

EDR ID Number Database(s) EPA ID Number

#### MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas. Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number: OES notification: OES Date: OES Time: Incident Date: Date Completed: Property Use: Agency Id Number: Agency Incident Number: Time Notified: Time Completed: Surrounding Area: Estimated Temperature: Property Management: Special Studies 1: Special Studies 2: Special Studies 3: Special Studies 4:	02-4233 8/5/200212:10 Not reported Not reported	):37 PM
Special Studies 5:	Not reported	
Special Studies 6: More Than Two Substances Ir	Not reported	Not reported
Resp Agncy Personel # Of De Responding Agency Personel Responding Agency Personel	contaminated: # Of Injuries:	Not reported
Others Number Of Decontami		Not reported
Others Number Of Injuries:		Not reported
Others Number Of Fatalities:		Not reported
Vehicle Make/year:	Not reported	
Vehicle License Number:	Not reported	
Vehicle State:	Not reported	
Vehicle Id Number:	Not reported	
CA/DOT/PUC/ICC Number:	Not reported	
Company Name: Reporting Officer Name/ID:	Not reported Not reported	
Report Date:	Not reported	
Comments:	Not reported	
Facility Telephone:	Not reported	
Waterway Involved:	No	

Database(s)

EDR ID Number EPA ID Number

## MOBIL, TORRANCE REFINERY (Continued)

Waterway: Not reported Spill Site: Not reported Cleanup By: N/A Containment: Not reported What Happened: Not reported Not reported Type: Measure: Not reported Other: Not reported Not reported Date/Time: Year: 2002 Agency: Exxon-Mobil Incident Date: 8/3/200212:00:00 AM Admin Agency: **Torrance Fire Department** Not reported Amount: Contained: Yes Site Type: Refinery Not reported E Date: Substance: NOX Quantity Released: Not reported BBLS: 0 Cups: 0 CUFT: 0 0.000000 Gallons: Grams: 0 Pounds: 500 Liters: 0 Ounces: 0 Pints: 0 Quarts: 0 Sheen: 0 Tons: 0 Unknown: 0 Description: Not reported Evacuations: 0 Number of Injuries: 0 Number of Fatalities: 0 Description:

S100676240

Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere. Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes.Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut

EDR ID Number Database(s) **EPA ID Number** 

#### MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

down on a hydrocracker unit, resulting in a release of materials intothe atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack. Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment. Due to flaring. The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures.Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company. Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking. High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring. During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas. Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number:
OES notification:
OES Date:
OES Time:
Incident Date:
Date Completed:

60910 Not reported 11/12/1993 07:20:00 AM Not reported Not reported

Database(s)

EDR ID Number EPA ID Number

## MOBIL, TORRANCE REFINERY (Continued)

	-
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances I	
Resp Agncy Personel # Of De	
Responding Agency Personel	# Of Injuries: Not reported
Responding Agency Personel	
Others Number Of Decontami	
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number: Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date: Comments:	Not reported
Facility Telephone:	Not reported Not reported
Waterway Involved:	NO
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By:	repairs made by mobil oil.
Containment:	Not reported
What Happened:	Not reported
Туре:	CHEMICAL
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	1993
Agency:	mobil oil
Incident Date:	11/12/93 0620
Admin Agency:	Not reported
Amount:	6.75 lbs rls to atmosphere
Contained:	NO
Site Type:	REF
E Date:	Not reported
Substance:	sulphur dioxide
Quantity Released:	Not reported
BBLS:	Not reported
Cups:	Not reported
CUFT:	Not reported
Gallons:	Not reported
Grams:	Not reported
Pounds:	Not reported

Database(s)

EDR ID Number EPA ID Number

MOBIL, TORRANCE REFINERY	(Continued)	S100676
Liters:	Not reported	
Ounces:	Not reported	
Pints:	Not reported	
Quarts:	Not reported	
Sheen:	Not reported	
Tons:	Not reported	
Unknown:	Not reported	
Description:	lost power to rational energizer and subs	ance vented out stack.
Evacuations:	NO	
Number of Injuries:	NO	
Number of Fatalities: Description:	NO	
	atmosphere.Piggy back of a big rig overti adjacent to the refinery. Spilled to groun area. No water way's involved. Cleanup AQMD. It was a false alarm of the HF set is false reading.Fuel gas treater malfunct been made to treater and release is goin exchanger.Pin hole leak in pipeline conta a leak.Plug blew out on an exchanger (2' Leak is ongoing, should be stopped withi F1. Currently contained. Unit shut down release valve lifted when line over pressu in the hydrogen unit #24.Plan Unit shutdo the flare.FCC Unit shut down bypassing 5	d only. Precautionary evacuation of in progress. The alarm goes directly to nsor, A05027. It came in at 6 ppm and it ioned at 1315 hrs. Adjustments have g downRelease caused by a leak in an ined in diked area.Flow line developed E3C) allowing substance to escape. In 10 minutes.Line rupture on line 24 at 0538 hrs See also 99-3174.1 inch iredBoth are ongoing. Failure in PSA own, purging the unit with nitrogen to SCR D7 causing the release to occur.
	Release started 08/02/02 and ended 08/0 maintenance on unit.In a crude unit was caused flaring in exceeded 1500 parts of 0015hours.A pipe failure caused the relea- that is used to truck acid in and pumps in to minimize the release into the air. SMA segregated and treated.per NRC; The ca down on a hydrocracker unit, resulting in atmosphere.Equipment failure caused the company is having to vent to reduce pres- underground.Permit allows on a stack up exceed 20 opacity. Still on going and be circumstances at a truck loading rack.Un release.Exceded capacity for more than 3	upset due to water in the process, SO2. Between 2345 and finish time ase.Released occurred on an inlet line to the vessel. Water deluge was used LL release. Water used will be ller stated they had a compressor shut a release of materials intothe e release.Tank 400X31 pressured up and sureCorrosion of a line to 20 opacity, caller stated they ing released into the air.Unknown known circumstances caused the
	the release.Unkown under investigation. If lare, due to faulty equipment.Due to flari flare.Lost compresser, causing the gas to causing a flare that caused the release.U until this morning when a flare occurred.C of intermittent basis to control pressures. flare.A check valve failed while decompre overpressured and released to the flare.F refinery fuel gas to local power company. release. More gas in flare line that recover overpressured causing the release.Emiss adjusted.Possible that a pump seal or pi leaking.High temperature has raised tank the flare.putting tank back into service an tank. 510X4 is the # of the tank.Leaking f at this time. Liquid in the tank, vapor whe loading rack inside the refinery, no evacu for the release.2F7 had a unit upset, whic	Unit was shut down, depressing to the ng.The release is due to a flare.Valve stuck closed on tower, nit is down, has been controlling Crude unit upset, flare was necessary Pilots went out on an upright essing a compressor.Equipment claring due to inability to sell Units upset, still investigating the ery can process.510X4 tank sion from 20F4P Stack, the mix is being be associated with the pump is temp, causing PO gas to be released to d flaring the gases that was in the rom a railroad car that is 1/4 full n it hits the air. The car is at the ations at this time.Unknown reason

EDR ID Number Database(s) EPA ID Number

#### MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release 0040

OES Incident Number:	99-0019	
OES notification:	1/3/199904:3	9:36 PM
OES Date:	Not reported	
OES Time:	Not reported	
Incident Date:	Not reported	
Date Completed:	Not reported	I
Property Use:	Not reported	
Agency Id Number:	Not reported	
Agency Incident Number:	Not reported	
Time Notified:	Not reported	
Time Completed:	Not reported	
Surrounding Area:	Not reported	
Estimated Temperature:	Not reported	
Property Management:	Not reported	
Special Studies 1:	Not reported	
Special Studies 2:	Not reported	
Special Studies 3:	Not reported	
Special Studies 4:	Not reported	
Special Studies 5:	Not reported	
Special Studies 6:	Not reported	
More Than Two Substances I	nvolved?:	Not reported
Resp Agncy Personel # Of De	contaminated:	Not reported
Responding Agency Personel	# Of Injuries:	Not reported
Responding Agency Personel	# Of Fatalities	Not reported
Others Number Of Decontami	inated:	Not reported
Others Number Of Injuries:		Not reported
Others Number Of Fatalities:		Not reported
Vehicle Make/year:	Not reported	
Vehicle License Number:	Not reported	
Vehicle State:	Not reported	
Vehicle Id Number:	Not reported	

Database(s)

EDR ID Number EPA ID Number

CA/DOT/PUC/ICC Number: Not reported Company Name: Reporting Officer Name/ID: Report Date: Comments: Facility Telephone: Waterway Involved: No Waterway: Spill Site: Cleanup By: None Containment: What Happened: Type: Measure: Other: Date/Time: 1999 Year: Agency: Incident Date: Admin Agency: Amount: Contained: No Site Type: Refinerv E Date: Substance: SO2 Quantity Released: BBLS: 0 Cups: 0 CUFT: 0 Gallons: 0 0 Grams: Pounds: 0 Liters: 0 Ounces: 0 Pints: 0 0 Quarts: Sheen: 0 Tons: 0 Unknown: 0 Description: 0 Evacuations: Number of Injuries: 0 Number of Fatalities: 0 Description:

Not reported Mobil Oil 1/3/199912:00:00 AM **Torrance Fire Department** Not reported Not reported Not reported Not reported

Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading.Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes.Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur.

EDR ID Number Database(s) EPA ID Number

#### MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours. A pipe failure caused the release. Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials into he atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures.Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company. Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted.Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

Database(s)

EDR ID Number **EPA ID Number** 

OES Incident Number: 03-0132 1/8/200310:33:35 AM OES notification: Not reported OES Date: Not reported OES Time: Incident Date: Not reported Not reported Date Completed: Not reported Property Use: Agency Id Number: Not reported Not reported Agency Incident Number: Time Notified: Not reported Time Completed: Not reported Surrounding Area: Not reported Estimated Temperature: Not reported Property Management: Not reported Special Studies 1: Not reported Special Studies 2: Not reported **Special Studies 3:** Not reported Special Studies 4: Not reported Special Studies 5: Not reported **Special Studies 6:** Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Vehicle License Number: Not reported Not reported Vehicle State: Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Company Name: Not reported Reporting Officer Name/ID: Not reported Report Date: Not reported Not reported Comments: Not reported Facility Telephone: Waterway Involved: No Waterway: Not reported Spill Site: Not reported Cleanup By: **Reporting Party** Containment: Not reported What Happened: Not reported Type: Not reported Measure: Not reported Other: Not reported Date/Time: Not reported Year: 2003 Agency: Exxon Mobil 1/8/200312:00:00 AM Incident Date: Admin Agency: Torrance Fire Department Amount: Not reported Contained: Yes Site Type: Refinery E Date: Not reported aasoline Substance: Quantity Released: Not reported

Database(s)

EDR ID Number EPA ID Number

S100676240

Not reported

0

BBLS:
Cups:
CUFT:
Gallons:
Grams:
Pounds:
Liters:
Ounces:
Pints:
Quarts:
Sheen:
Tons:
Unknown:
Description:
Evacuations:
Number of Injuries:
Number of Fatalities:
Description:

0 Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes. Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit. In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials intothe atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack. Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures. Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company.Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is

EDR ID Number Database(s) EPA ID Number

#### MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas. Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number:	03-0465
OES notification:	1/24/200310:55:23 AM
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
Date Completed:	Not reported
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances In	volved?: Not reported
Resp Agncy Personel # Of De	contaminated: Not reported
Responding Agency Personel	# Of Injuries: Not reported
Responding Agency Personel	# Of Fatalities:Not reported

Not reported

Others Number Of Decontaminated:

Not reported

Not reported

Database(s)

EDR ID Number **EPA ID Number** 

## MOBIL, TORRANCE REFINERY (Continued)

Others Number Of Injuries: Others Number Of Fatalities: Vehicle Make/year: Not reported Vehicle License Number: Not reported Vehicle State: Not reported Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Company Name: Not reported Reporting Officer Name/ID: Not reported Report Date: Not reported Comments: Not reported Facility Telephone: Not reported Waterway Involved: No Waterway: Not reported Spill Site: Not reported Cleanup By: N/A Containment: Not reported What Happened: Not reported Type: Not reported Measure: Not reported Other: Not reported Date/Time: Not reported 2003 Year: Agency: Exxon Mobil 1/24/200312:00:00 AM Incident Date: Admin Agency: **Torrance Fire Department** Amount: Not reported Contained: No Site Type: Refinery E Date: Not reported Substance: NOX Quantity Released: Not reported BBLS: 0 Cups: 0 CUFT: 0 0.000000 Gallons: Grams: 0 Pounds: 0 Liters: 0 Ounces: 0 Pints: 0 Quarts: 0 Sheen: 0 Tons: 0 Unknown: 0 Description: Not reported Evacuations: 0 Number of Injuries: 0 Number of Fatalities: 0 Description:

S100676240

Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere. Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed

Database(s) EPA

EDR ID Number EPA ID Number

#### MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes.Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit. In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials intothe atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment. Due to flaring. The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures.Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare. Flaring due to inability to sell refinery fuel gas to local power company. Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring. During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare. Release due to tank car overflow. FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line.

EDR ID Number Database(s) EPA ID Number

#### MOBIL, TORRANCE REFINERY (Continued)

## S100676240

Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

0 = 0 · · · · · · ·	
OES Incident Number:	03-5856
OES notification:	11/11/200306:55:12 PM
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
Date Completed:	Not reported
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Ir	volved?: Not reported
Resp Agncy Personel # Of De	
<b>Responding Agency Personel</b>	# Of Injuries: Not reported
Responding Agency Personel	# Of Fatalities:Not reported
Others Number Of Decontamin	nated: Not reported
Others Number Of Injuries:	Not reported
	Hotropolica
Others Number Of Fatalities:	Not reported
Others Number Of Fatalities: Vehicle Make/year:	•
	Not reported
Vehicle Make/year:	Not reported Not reported
Vehicle Make/year: Vehicle License Number:	Not reported Not reported Not reported
Vehicle Make/year: Vehicle License Number: Vehicle State:	Not reported Not reported Not reported Not reported
Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number:	Not reported Not reported Not reported Not reported Not reported
Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number:	Not reported Not reported Not reported Not reported Not reported Not reported
Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name:	Not reported Not reported Not reported Not reported Not reported Not reported Not reported
Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID:	Not reported Not reported Not reported Not reported Not reported Not reported Not reported Not reported
Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date: Comments:	Not reported Not reported Not reported Not reported Not reported Not reported Not reported Not reported Not reported
Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date: Comments: Facility Telephone:	Not reported Not reported
Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date: Comments: Facility Telephone: Waterway Involved:	Not reported Not reported
Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date: Comments: Facility Telephone: Waterway Involved: Waterway:	Not reported Not reported
Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date: Comments: Facility Telephone: Waterway Involved: Waterway: Spill Site:	Not reported Not reported
Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date: Comments: Facility Telephone: Waterway Involved: Waterway:	Not reported Not reported
Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date: Comments: Facility Telephone: Waterway Involved: Waterway: Spill Site: Cleanup By: Containment:	Not reported Not reported
Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date: Comments: Facility Telephone: Waterway Involved: Waterway: Spill Site: Cleanup By: Containment: What Happened:	Not reported Not reported
Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date: Comments: Facility Telephone: Waterway Involved: Waterway: Spill Site: Cleanup By: Containment: What Happened: Type:	Not reported Not reported
Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date: Comments: Facility Telephone: Waterway Involved: Waterway: Spill Site: Cleanup By: Containment: What Happened:	Not reported Not reported
Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date: Comments: Facility Telephone: Waterway Involved: Waterway: Spill Site: Cleanup By: Containment: What Happened: Type: Measure:	Not reported Not reported
Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date: Comments: Facility Telephone: Waterway Involved: Waterway: Spill Site: Cleanup By: Containment: What Happened: Type: Measure: Other:	Not reported Not reported
Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date: Comments: Facility Telephone: Waterway Involved: Waterway: Spill Site: Cleanup By: Containment: What Happened: Type: Measure: Other: Date/Time:	Not reported Not reported
Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date: Comments: Facility Telephone: Waterway Involved: Waterway Involved: Waterway: Spill Site: Cleanup By: Containment: What Happened: Type: Measure: Other: Date/Time: Year:	Not reported Not R

Database(s)

EDR ID Number EPA ID Number

## MOBIL, TORRANCE REFINERY (Continued)

Admin Agency:	Torrance Fire Department
Amount:	Not reported
Contained:	Yes
Site Type:	Refinery
E Date:	Not reported
Substance:	Light Cycle Oil
Quantity Released:	Not reported
BBLS:	15
Cups:	0
CUFT:	0
Gallons:	0.000000
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	Exceeded limits between 1
	atas a sub a sa Distant ba als of

S100676240

ed limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes. Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials into he atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred. Crude unit upset, flare was necessary

Database(s) El

EDR ID Number EPA ID Number

#### MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

of intermittent basis to control pressures. Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company. Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas. Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare. Release due to tank car overflow. FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number:	03-5514
OES notification:	10/24/20
OES Date:	Not report
OES Time:	Not report
Incident Date:	Not report
Date Completed:	Not repo
Property Use:	Not report
Agency Id Number:	Not report
Agency Incident Number:	Not report
Time Notified:	Not report
Time Completed:	Not repo
Surrounding Area:	Not repo
Estimated Temperature:	Not report
Property Management:	Not repo
Special Studies 1:	Not repo
Special Studies 2:	Not repo
Special Studies 3:	Not repo
Special Studies 4:	Not repo

4/200312:25:30 PM eported eported reported reported reported reported eported eported reported eported eported reported eported reported eported Not reported

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

#### MOBIL, TORRANCE REFINERY (Continued)

Special Studies 5: Not reported **Special Studies 6:** Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Vehicle License Number: Not reported Vehicle State: Not reported Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Company Name: Not reported Reporting Officer Name/ID: Not reported Not reported Report Date: Comments: Not reported Facility Telephone: Not reported Waterway Involved: Not reported Waterway: Not reported Spill Site: Not reported Cleanup By: N/A Containment: Not reported What Happened: Not reported Type: Not reported Measure: Not reported Other: Not reported Date/Time: Not reported 2003 Year: Agency: Exxon Mobil 10/24/200312:00:00 AM Incident Date: Admin Agency: **Torrance Fire Department** Amount: Not reported Contained: Yes Site Type: Refinery E Date: Not reported Substance: Hydro carbon Vapor Quantity Released: Not reported BBLS: 0 Cups: 0 CUFT: 0 Gallons: 0.000000 Grams: 0 Pounds: 0 Liters: 0 Ounces: 0 Pints: 0 Quarts: 0 0 Sheen: Tons: 0 Unknown: 0 Description: Not reported Evacuations: 0 Number of Injuries: 0 Number of Fatalities: 0 Description: Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the

Database(s) EPA

EDR ID Number EPA ID Number

#### MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

atmosphere. Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes. Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit. In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials intothe atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack. Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release.Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures. Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company.Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to

Database(s)

EDR ID Number EPA ID Number

## MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost.A hydrogen header overpressured and went to flare.An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number:	03-5068
OES notification:	9/30/200307:38:38 PM
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
Date Completed:	Not reported
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances In	nvolved?: Not reported
Resp Agncy Personel # Of De	econtaminated: Not reported
Responding Agency Personel	# Of Injuries: Not reported
Responding Agency Personel	# Of Fatalities:Not reported
Others Number Of Decontami	nated: Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	No
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By:	Reporting Party
Containment:	Not reported
What Happened:	Not reported
	•

Database(s)

EDR ID Number EPA ID Number

Туре:	N
Measure:	N
Other:	N
Date/Time:	N
Year:	2
Agency:	E
Incident Date:	9
Admin Agency:	Т
Amount:	N
Contained:	Y
Site Type:	R
E Date:	N
Substance:	с
Quantity Released:	N
BBLS:	4
Cups:	0
CUFT:	0
Gallons:	0
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Description:	N
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	E

Not reported Not reported Not reported Not reported 2003 Exxon Mobil 9/30/200312:00:00 AM **Forrance Fire Department** Not reported Yes Refinery Not reported crude oil Not reported n 0.000000 Not reported

Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere. Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes.Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit. In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials into he atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity. caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown

EDR ID Number Database(s)

**EPA ID Number** 

#### MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

circumstances at a truck loading rack. Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures.Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company. Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring. During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas. Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare. Release due to tank car overflow. FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number:
OES notification:
OES Date:
OES Time:
Incident Date:
Date Completed:
Property Use:
Agency Id Number:
Agency Incident Number:
Time Notified:
Time Completed:

03-0016 1/2/200312:06:51 PM Not reported Not reported

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

S100676240

#### MOBIL, TORRANCE REFINERY (Continued)

Surrounding Area: Not reported Estimated Temperature: Not reported Property Management: Not reported Special Studies 1: Not reported Special Studies 2: Not reported **Special Studies 3:** Not reported Special Studies 4: Not reported Special Studies 5: Not reported Special Studies 6: Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Vehicle License Number: Not reported Vehicle State: Not reported Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Company Name: Not reported Reporting Officer Name/ID: Not reported Report Date: Not reported Comments: Not reported Facility Telephone: Not reported Waterway Involved: No Waterway: Not reported Spill Site: Not reported Cleanup By: **Reporting Party** Not reported Containment: What Happened: Not reported Not reported Type: Measure: Not reported Other: Not reported Not reported Date/Time: 2003 Year: Agency: Exxon Mobil Incident Date: 1/2/200312:00:00 AM Admin Agency: **Torrance Fire Department** Not reported Amount: Contained: No Site Type: Refinery E Date: Not reported Substance: butane Quantity Released: Not reported BBLS: 1 Cups: 0 CUFT: 0 Gallons: 0.000000 Grams: 0 Pounds: 0 Liters: 0 0 Ounces: Pints: 0 Quarts: 0 Sheen: 0

Database(s)

EDR ID Number EPA ID Number

MOBIL, TORRANCE REFINERY	(Continued)	S100676240
Tons:	0	
Unknown:	0	
Description:	Not reported	
Evacuations:	0	
Number of Injuries:	0	
Number of Fatalities:	0	
Description:	Exceeded limits between 1542 hrs and 1619 hrs.	resulting in a release to the
·	atmosphere.Piggy back of a big rig overturned du	ring a U-turn on a roadway
	adjacent to the refinery. Spilled to ground only. F	
	area. No water way's involved. Cleanup in progre	
	AQMD. It was a false alarm of the HF sensor, A05	5027. It came in at 6 ppm and it
	is false reading. Fuel gas treater malfunctioned at	1315 hrs. Adjustments have
	been made to treater and release is going downR	elease caused by a leak in an
	exchanger.Pin hole leak in pipeline contained in d	•
	a leak.Plug blew out on an exchanger (21E3C) all	
	Leak is ongoing, should be stopped within 10 min	•
	F1. Currently contained. Unit shut down at 0538 l	•
	release valve lifted when line over pressuredBoth	
	in the hydrogen unit #24.Plan Unit shutdown, purg	0 0
	the flare.FCC Unit shut down bypassing SCR D7	
	Release started 08/02/02 and ended 08/04/02A p	0
	maintenance on unit. In a crude unit was upset du	<b>o</b> 1 <b>o</b>
	caused flaring in exceeded 1500 parts of SO2. Be	•
	0015hours.A pipe failure caused the release.Rele	
	that is used to truck acid in and pumps into the ve	
	to minimize the release into the air. SMALL release	-
	segregated and treated.per NRC; The caller state	
	down on a hydrocracker unit, resulting in a release	
	atmosphere.Equipment failure caused the release	
	company is having to vent to reduce pressureCon	
	underground.Permit allows on a stack up to 20	
	exceed 20 opacity. Still on going and being relea	
	circumstances at a truck loading rack.Unknown ci	
	release.Exceded capacity for more than 3 minutes	
	the release.Unkown under investigation.Unit was	
	flare, due to faulty equipment.Due to flaring.The re	
	flare.Lost compresser, causing the gas to flare.Va	
	causing a flare that caused the release.Unit is down	
	until this morning when a flare occurred.Crude un	
	of intermittent basis to control pressures.Pilots we	
	flare. A check valve failed while decompressing a	
	overpressured and released to the flare. Flaring du	
	refinery fuel gas to local power company.Units up	
	release. More gas in flare line that recovery can p	
	overpressured causing the release. Emission from	
	adjusted.Possible that a pump seal or pipe assoc	
	leaking.High temperature has raised tank temp, c	5 5
	the flare.putting tank back into service and flaring	
	tank. 510X4 is the # of the tank.Leaking from a ra	
	at this time. Liquid in the tank, vapor when it hits t	
	loading rack inside the refinery, no evacuations at	
	for the release.2F7 had a unit upset, which cause	•
	exceeded compliance amount.No mechanical fail	ure while company was blowing dust
	and the substance exceeded the 20 limit. Reasor	n is unknown.equipment
	failure.Pipe rupture caused the release.Bleeder or	n section of piping was opened
	and caused a leak.2F7 Damper 2D7 failed open of	
	Line leak caused the spill.Lost 25 K1C compresso	

EDR ID Number Database(s) EPA ID Number

S100676240

#### MOBIL, TORRANCE REFINERY (Continued)

## release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas. Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare. Release due to tank car overflow. FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number:	03-4481	
OES notification:	8/31/200305:	40:15 PM
OES Date:	Not reported	
OES Time:	Not reported	
Incident Date:	Not reported	
Date Completed:	Not reported	
Property Use:	Not reported	
Agency Id Number:	Not reported	
Agency Incident Number:	Not reported	
Time Notified:	Not reported	
Time Completed:	Not reported	
Surrounding Area:	Not reported	
Estimated Temperature:	Not reported	
Property Management:	Not reported	
Special Studies 1:	Not reported	
Special Studies 2:	Not reported	
Special Studies 3:	Not reported	
Special Studies 4:	Not reported	
Special Studies 5:	Not reported	
Special Studies 6:	Not reported	
More Than Two Substances In		Not reported
Resp Agncy Personel # Of De		
Responding Agency Personel		Not reported
Responding Agency Personel		
Others Number Of Decontami	nated:	Not reported
Others Number Of Injuries:		Not reported
Others Number Of Fatalities:		Not reported
Vehicle Make/year:	Not reported	
Vehicle License Number:	Not reported	
Vehicle State:	Not reported	
Vehicle Id Number:	Not reported	
CA/DOT/PUC/ICC Number:	Not reported	
Company Name:	Not reported	
Reporting Officer Name/ID:	Not reported	
Report Date:	Not reported	
Comments:	Not reported	

Database(s)

EDR ID Number EPA ID Number

### MOBIL, TORRANCE REFINERY (Continued)

Facility Telephone: Not reported Waterway Involved: No Waterway: Not reported Spill Site: Not reported Cleanup By: Reporting Party Not reported Containment: What Happened: Not reported Type: Not reported Not reported Measure: Other: Not reported Date/Time: Not reported 2003 Year: Agency: Exxon Mobil Incident Date: 8/31/200312:00:00 AM Admin Agency: **Torrance Fire Department** Amount: Not reported Contained: Unknown Site Type: Refinery E Date: Not reported Substance: Catalyst dust Quantity Released: Not reported BBLS: 0 Cups: 0 CUFT: 0 0.000000 Gallons: Grams: ٥ Pounds: 0 Liters: 0 Ounces: 0 0 Pints: Quarts: 0 Sheen: 0 Tons: 0 Unknown: 0 Not reported Description: Evacuations: 0 Number of Injuries: 0 Number of Fatalities: 0 Description:

Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes.Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours. A pipe failure caused the release. Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used

EDR ID Number Database(s) EPA ID Number

MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials intothe atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release.Unit is down, has been controlling until this morning when a flare occurred. Crude unit upset, flare was necessary of intermittent basis to control pressures.Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company. Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number: OES notification: OES Date: OES Time:

03-5285 10/12/200307:28:09 AM Not reported Not reported

Database(s)

EDR ID Number EPA ID Number

## MOBIL, TORRANCE REFINERY (Continued)

Incident Date: Not reported **Date Completed:** Not reported Not reported Property Use: Not reported Agency Id Number: Agency Incident Number: Not reported Time Notified: Not reported Time Completed: Not reported Surrounding Area: Not reported Estimated Temperature: Not reported Property Management: Not reported Special Studies 1: Not reported Not reported **Special Studies 2: Special Studies 3:** Not reported Special Studies 4: Not reported Special Studies 5: Not reported Special Studies 6: Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Vehicle License Number: Not reported Vehicle State: Not reported Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Company Name: Not reported Not reported Reporting Officer Name/ID: Report Date: Not reported Comments: Not reported Facility Telephone: Not reported Waterway Involved: No Waterway: Not reported Not reported Spill Site: Cleanup By: N/A Containment: Not reported What Happened: Not reported Type: Not reported Not reported Measure: Other: Not reported Date/Time: Not reported Year: 2003 Agency: Exxon Mobil 10/12/200312:00:00 AM Incident Date: Admin Agency: **Torrance Fire Department** Amount: Not reported Contained: Yes Refinery Site Type: E Date: Not reported Substance: catalyst dust Not reported Quantity Released: BBLS: 0 Cups: 0 CUFT: 0 Gallons: 0.000000

Database(s)

EDR ID Number EPA ID Number

Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	Exceeded lim

d limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes. Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials into he atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack. Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures. Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare. Flaring due to inability to sell refinery fuel gas to local power company. Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted.Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the

EDR ID Number Database(s) EPA ID Number

MOBIL, TORRANCE REFINERY (Continued)

### S100676240

loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas. Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare. Release due to tank car overflow. FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

**OES Incident Number:** 03-1171 OES notification: 3/1/200311:40:37 AM OES Date: Not reported OES Time: Not reported Not reported Incident Date: Date Completed: Not reported Property Use: Not reported Not reported Agency Id Number: Agency Incident Number: Not reported Time Notified: Not reported Time Completed: Not reported Surrounding Area: Not reported Estimated Temperature: Not reported Property Management: Not reported Special Studies 1: Not reported Special Studies 2: Not reported **Special Studies 3:** Not reported Special Studies 4: Not reported **Special Studies 5:** Not reported **Special Studies 6:** Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/vear: Not reported Vehicle License Number: Not reported

Database(s)

EDR ID Number EPA ID Number

## MOBIL, TORRANCE REFINERY (Continued)

Vehicle State: Not reported Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Not reported Company Name: Reporting Officer Name/ID: Not reported Report Date: Not reported Not reported Comments: Facility Telephone: Not reported Waterway Involved: No Waterway: Not reported Spill Site: Not reported **Reporting Party** Cleanup By: Not reported Containment: What Happened: Not reported Type: Not reported Measure: Not reported Not reported Other: Date/Time: Not reported Year: 2003 Exxon/Mobil Agency: Incident Date: 3/1/200312:00:00 AM Admin Agency: **Torrance Fire Department** Amount: Not reported Contained: Unknown Site Type: Refinery E Date: Not reported Substance: Catalyst Quantity Released: Not reported BBLS: 0 0 Cups: CUFT: 0 Gallons: 0.000000 Grams: 0 Pounds: 0 Liters: 0 0 Ounces: Pints: 0 Quarts: 0 Sheen: 0 Tons: 0 0 Unknown: Not reported Description: Evacuations: 0 Number of Injuries: 0 Number of Fatalities: 0 Description:

Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading.Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes.Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA

Database(s) Ef

EDR ID Number EPA ID Number

## MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit. In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials intothe atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment. Due to flaring. The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures. Pilots went out on an upright flare. A check valve failed while decompressing a compressor. Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company. Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH. Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of

Database(s) EPA I

EDR ID Number EPA ID Number

S100676240

## MOBIL, TORRANCE REFINERY (Continued)

emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number:	03-2142
OES notification:	4/23/200309:05:40 PM
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
Date Completed:	Not reported
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 1:	Not reported
	Not reported
Special Studies 3:	
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances In	
Resp Agncy Personel # Of De	
Responding Agency Personel	
Responding Agency Personel	# Of Fatalities:Not reported
Others Number Of Decontamin	
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	No
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By:	n\\a
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	2003
Agency:	Exxon Mobile
Incident Date:	4/23/200312:00:00 AM
Admin Agency:	Torrance Fire Department
Amount:	Not reported
Contained:	Yes
Site Type:	Refinery
	-

Database(s)

EDR ID Number EPA ID Number

E Data	Martine and a d
E Date:	Not reported
Substance:	Catalyst Dust
Quantity Released:	Not reported
BBLS:	0
Cups:	0
CUFT:	0
Gallons:	0.000000
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	Exceeded limit

0	
0	
Exc	eeded limits between 1542 hrs and 1619 hrs. resulting in a release to the
atm	osphere.Piggy back of a big rig overturned during a U-turn on a roadway
adja	cent to the refinery. Spilled to ground only. Precautionary evacuation of
area	a. No water way's involved. Cleanup in progress. The alarm goes directly to
AQN	ID. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it
	lse reading.Fuel gas treater malfunctioned at 1315 hrs. Adjustments have
bee	n made to treater and release is going downRelease caused by a leak in an
exch	nanger.Pin hole leak in pipeline contained in diked area.Flow line developed
	ak.Plug blew out on an exchanger (21E3C) allowing substance to escape.
Lea	k is ongoing, should be stopped within 10 minutes.Line rupture on line 24
F1.	Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch
relea	ase valve lifted when line over pressuredBoth are ongoing. Failure in PSA
in th	e hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to
the	flare.FCC Unit shut down bypassing SCR D7 causing the release to occur.
Rele	ease started 08/02/02 and ended 08/04/02A pocket of gas developed during
maiı	ntenance on unit. In a crude unit was upset due to water in the process,
caus	sed flaring in exceeded 1500 parts of SO2. Between 2345 and finish time
	5hours.A pipe failure caused the release.Released occurred on an inlet line
	is used to truck acid in and pumps into the vessel. Water deluge was used
	inimize the release into the air. SMALL release. Water used will be
•	regated and treated.per NRC; The caller stated they had a compressor shut
	n on a hydrocracker unit, resulting in a release of materials intothe
	osphere.Equipment failure caused the release.Tank 400X31 pressured up and
	pany is having to vent to reduce pressureCorrosion of a line
	erground.Permit allows on a stack up to 20 opacity, caller stated they
	eed 20 opacity. Still on going and being released into the air.Unknown
	Imstances at a truck loading rack.Unknown circumstances caused the
	ase.Exceded capacity for more than 3 minutes.A minor process upset caused
	release.Unkown under investigation.Unit was shut down, depressing to the
	e, due to faulty equipment. Due to flaring. The release is due to a
	Lost compresser, causing the gas to flare.Valve stuck closed on tower, sing a flare that caused the release.Unit is down, has been controlling
	this morning when a flare occurred.Crude unit upset, flare was necessary
	termittent basis to control pressures.Pilots went out on an upright
	A check valve failed while decompressing a compressor. Equipment
	pressured and released to the flare.Flaring due to inability to sell
	ery fuel gas to local power company.Units upset, still investigating the
1 CIII	ory new gas to local power company. Onits upset, sum investigating the

EDR ID Number Database(s) EPA ID Number

#### MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted.Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas. Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number: OES notification: OES Date: OES Time: Incident Date: Date Completed: Property Use: Agency Id Number: Agency Incident Number: Time Notified:	03-6661 12/27/200301:41:01 AM Not reported Not reported Not reported Not reported Not reported Not reported Not reported Not reported	
<b>o</b> ,	•	
Time Notified:	Not reported	
Time Completed:	Not reported	
Surrounding Area:	Not reported	
Estimated Temperature:	Not reported	
Property Management:	Not reported	
Special Studies 1:	Not reported	
Special Studies 2:	Not reported	
Special Studies 3:	Not reported	
Special Studies 4:	Not reported	
Special Studies 5:	Not reported	
Special Studies 6:	Not reported	
More Than Two Substances Involved?: Not reported		
Resp Agncy Personel # Of Decontaminated: Not reported		

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

## MOBIL, TORRANCE REFINERY (Continued)

Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Vehicle License Number: Not reported Vehicle State: Not reported Not reported Vehicle Id Number: CA/DOT/PUC/ICC Number: Not reported Not reported Company Name: Reporting Officer Name/ID: Not reported Report Date: Not reported Comments: Not reported Facility Telephone: Not reported Waterway Involved: Not reported Not reported Waterway: Spill Site: Not reported Cleanup By: N/A Containment: Not reported What Happened: Not reported Type: Not reported Measure: Not reported Other: Not reported Date/Time: Not reported 2003 Year: Agency: Exxon Mobil Incident Date: 12/27/200312:00:00 AM Admin Agency: **Torrance Fire Department** Amount: Not reported Contained: Yes Site Type: Refinery E Date: Not reported Substance: catalyst dust Not reported Quantity Released: BBLS: 0 Cups: 0 CUFT: 0 0.000000 Gallons: Grams: 0 Pounds: 0 Liters: 0 Ounces: 0 Pints: 0 Quarts: 0 Sheen: 0 Tons: 0 Unknown: 0 Description: Not reported 0 Evacuations: Number of Injuries: 0 Number of Fatalities: 0 Description:

Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it

EDR ID Number Database(s) EPA ID Number

#### MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes.Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials into he atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures. Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company.Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas. Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment

Database(s)

EDR ID Number EPA ID Number

## MOBIL, TORRANCE REFINERY (Continued)

### S100676240

that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare. Release due to tank car overflow. FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed. BELIEVED TO BE AN UNDERGROUND LEAK. APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH. Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment. Line integrity broke down causing a crack and subsequent release

	crack and subsequent release
OES Incident Number:	03-3894
OES notification:	8/3/200305:43:43 AM
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
Date Completed:	Not reported
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Ir	nvolved?: Not reported
Resp Agncy Personel # Of De	contaminated: Not reported
<b>Responding Agency Personel</b>	# Of Injuries: Not reported
<b>Responding Agency Personel</b>	# Of Fatalities:Not reported
Others Number Of Decontami	nated: Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	No
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By:	Contractor
Containment:	Not reported
What Happened:	Not reported
Туре:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported

Database(s)

EDR ID Number EPA ID Number

S100676240

#### Year: 2003 Agency: Exxon Mobil Incident Date: 8/3/200312:00:00 AM Admin Agency: **Torrance Fire Department** Amount: Not reported Contained: Yes Site Type: Refinery E Date: Not reported Substance: caustic Quantity Released: Not reported BBLS: 1 0 Cups: CUFT: 0 Gallons: 0.000000 Grams: 0 Pounds: 0 Liters: 0 Ounces: 0 Pints: 0 Quarts: 0 Sheen: 0 Tons: 0 Unknown: 0 Description: Not reported Evacuations: 0 Number of Injuries: 0 Number of Fatalities: 0 Description: Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere. Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes. Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials intothe atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a

### MOBIL, TORRANCE REFINERY (Continued)

TC2051883.2s Page 155

EDR ID Number Database(s) EPA ID Number

## MOBIL, TORRANCE REFINERY (Continued)

S100676240

flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release.Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures. Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company.Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number:SOES notification:TOES Date:IOES Time:IIncident Date:IDate Completed:IProperty Use:IAgency Id Number:IAgency Incident Number:ITime Notified:ITime Completed:ISurrounding Area:IEstimated Temperature:IProperty Management:I

99-2900 7/11/199904:34:59 AM Not reported Not reported

Database(s)

EDR ID Number EPA ID Number

## MOBIL, TORRANCE REFINERY (Continued)

Special Studies 2: Not reported **Special Studies 3:** Not reported Special Studies 4: Not reported Special Studies 5: Not reported Special Studies 6: Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Vehicle License Number: Not reported Vehicle State: Not reported Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Company Name: Not reported Reporting Officer Name/ID: Not reported Report Date: Not reported Comments: Not reported Facility Telephone: Not reported Waterway Involved: No Waterway: Not reported Spill Site: Not reported Cleanup By: **Responsible Party** Containment: Not reported What Happened: Not reported Not reported Type: Not reported Measure: Not reported Other: Date/Time: Not reported 1999 Year: Agency: Mobil Torrance 7/11/199912:00:00 AM Incident Date: Admin Agency: **Torrance Fire Department** Amount: Not reported Contained: Yes Site Type: Refinery E Date: Not reported Substance: Slop Oil and Sour Water Quantity Released: Not reported BBLS: 2 0 Cups: CUFT: 0 Gallons: 0 Grams: 0 Pounds: 0 Liters: 0 0 Ounces: Pints: 0 Quarts: 0 Sheen: 0 0 Tons: Unknown: 0 Description: Not reported Evacuations: 0

Database(s) E

EDR ID Number EPA ID Number

#### S100676240

#### MOBIL, TORRANCE REFINERY (Continued)

0

Number of Injuries: Number of Fatalities: Description:

0 Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes.Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit. In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC: The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials intothe atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures.Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare. Flaring due to inability to sell refinery fuel gas to local power company. Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it

Database(s)

EDR ID Number EPA ID Number

## MOBIL, TORRANCE REFINERY (Continued)

### S100676240

overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas. Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

	crack and sur	osequent relea
OES Incident Number:	03-4513	
OES notification:	9/2/200307:5	6:27 PM
OES Date:	Not reported	
OES Time:	Not reported	
Incident Date:	Not reported	
Date Completed:	Not reported	l i i i i i i i i i i i i i i i i i i i
Property Use:	Not reported	
Agency Id Number:	Not reported	
Agency Incident Number:	Not reported	
Time Notified:	Not reported	
Time Completed:	Not reported	
Surrounding Area:	Not reported	
Estimated Temperature:	Not reported	
Property Management:	Not reported	
Special Studies 1:	Not reported	
Special Studies 2:	Not reported	
Special Studies 3:	Not reported	
Special Studies 4:	Not reported	
Special Studies 5:	Not reported	
Special Studies 6:	Not reported	
More Than Two Substances Ir	volved?:	Not reported
Resp Agncy Personel # Of De	contaminated:	Not reported
Responding Agency Personel		Not reported
Responding Agency Personel		Not reported
Others Number Of Decontamin	nated:	Not reported
Others Number Of Injuries:		Not reported
Others Number Of Fatalities:		Not reported
Vehicle Make/year:	Not reported	
Vehicle License Number:	Not reported	
Vehicle State:	Not reported	
Vehicle Id Number:	Not reported	
CA/DOT/PUC/ICC Number:	Not reported	
Company Name:	Not reported	
Reporting Officer Name/ID:	Not reported	
Report Date:	Not reported	
Comments:	Not reported	
Facility Telephone:	Not reported	
Waterway Involved:	No	
Waterway:	Not reported	
Spill Site:	Not reported	

Database(s)

EDR ID Number EPA ID Number

## MOBIL, TORRANCE REFINERY (Continued)

Cleanup By: n∖\a Containment: Not reported Not reported What Happened: Not reported Type: Measure: Not reported Other: Not reported Date/Time: Not reported 2003 Year: Agency: Exxon Mobile Incident Date: 9/2/200312:00:00 AM Admin Agency: **Torrance Fire Department** Not reported Amount: Contained: No Site Type: Refinery E Date: Not reported Substance: Sour Hydrogen Not reported Quantity Released: BBLS: 0 Cups: 0 CUFT: 0 Gallons: 0.000000 Grams: 0 Pounds: 0 Liters: 0 Ounces: 0 Pints: 0 Quarts: 0 Sheen: 0 Tons: 0 Unknown: 0 Description: Not reported Evacuations: 0 Number of Injuries: 0 Number of Fatalities: 0 Description:

Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes. Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials into he atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and

EDR ID Number Database(s) EPA ID Number

#### MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack. Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred. Crude unit upset, flare was necessary of intermittent basis to control pressures. Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company.Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release.Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring. During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas. Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number: OES notification: OES Date: OES Time: Incident Date: **Date Completed:** Property Use: Agency Id Number: 03-3712 7/24/200302:05:46 AM Not reported Not reported Not reported Not reported Not reported Not reported

Database(s)

EDR ID Number EPA ID Number

## MOBIL, TORRANCE REFINERY (Continued)

Agency Incident Number: Not reported Time Notified: Not reported Not reported Time Completed: Surrounding Area: Not reported Estimated Temperature: Not reported Property Management: Not reported Not reported Special Studies 1: **Special Studies 2:** Not reported **Special Studies 3:** Not reported Special Studies 4: Not reported **Special Studies 5:** Not reported **Special Studies 6:** Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Not reported Others Number Of Decontaminated: Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Vehicle License Number: Not reported Vehicle State: Not reported Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Company Name: Not reported Reporting Officer Name/ID: Not reported Report Date: Not reported Comments: Not reported Facility Telephone: Not reported Waterway Involved: No Waterway: Not reported Spill Site: Not reported Cleanup By: Contractor Containment: Not reported Not reported What Happened: Not reported Type: Measure: Not reported Other: Not reported Date/Time: Not reported Year: 2003 Agency: Exoon Mobile torrance Incident Date: 7/24/200312:00:00 AM Admin Agency: Not reported Not reported Amount: Contained: Yes Site Type: Refinery E Date: Not reported Substance: Spent Caustic Quantity Released: Not reported BBLS: 2 Cups: 0 CUFT: 0 0.000000 Gallons: Grams: 0 Pounds: 0 0 Liters: Ounces: 0

MOBIL, TORRANCE REFINERY (Continued)

Database(s)

EDR ID Number EPA ID Number

Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
•	
Number of Fatalities: Description:	<sup>6</sup> Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading.Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is orgoing, should be stopped within 10 minutes.Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Mater deluge was used to minimize the release into the air. SMALL release. Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being release in to the air.Unknown circumstances at a truck loading rack.Unknown circumstances acused the release.Unkown under investigation.Unit was blue to on on upright flare.A check valve failed while decompressing a compressor.stou

Database(s) EPA

EDR ID Number EPA ID Number

## MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas. Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number:	03-6188
OES notification:	12/1/200312:14:44 PM
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
Date Completed:	Not reported
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances I	nvolved?: Not reported
Resp Agncy Personel # Of De	contaminated: Not reported
Responding Agency Personel	# Of Injuries: Not reported
Responding Agency Personel	# Of Fatalities:Not reported
Others Number Of Decontami	nated: Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported

Database(s)

EDR ID Number EPA ID Number

## MOBIL, TORRANCE REFINERY (Continued)

Reporting Officer Name/ID: Not reported Report Date: Comments: Facility Telephone: Waterway Involved: Waterway: Spill Site: Cleanup By: N/A Containment: What Happened: Type: Measure: Other: Date/Time: Year: 2003 Agency: Incident Date: Admin Agency: Amount: Contained: No Site Type: Refinery E Date: Substance: NOX Quantity Released: BBLS: 0 Cups: 0 CUFT: 0 Gallons: Grams: 0 0 Pounds: 0 Liters: Ounces: 0 Pints: 0 Quarts: 0 Sheen: 0 0 Tons: Unknown: 0 Description: Evacuations: 0 Number of Injuries: 0 Number of Fatalities: 0 Description:

Not reported Exxon Mobil 12/1/200312:00:00 AM **Torrance Fire Department** Not reported Not reported Not reported 0.000000 Not reported

Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes. Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process,

EDR ID Number Database(s) EPA ID Number

#### MOBIL, TORRANCE REFINERY (Continued)

S100676240

caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials into he atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures. Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare. Flaring due to inability to sell refinery fuel gas to local power company.Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas. Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number:

Database(s)

EDR ID Number EPA ID Number

BIL, TORRANCE REFINERY (Continued)			
OES notification:	10/1/200308:59:03 PM		
OES Date:	Not reported		
OES Time:	Not reported		
Incident Date:	Not reported		
Date Completed:	Not reported		
Property Use:	Not reported		
Agency Id Number:	Not reported		
Agency Incident Number:	Not reported		
Time Notified:	Not reported		
Time Completed:	Not reported		
Surrounding Area:	Not reported		
Estimated Temperature:	Not reported		
Property Management:	Not reported Not reported		
Special Studies 1: Special Studies 2:	Not reported		
Special Studies 3:	Not reported		
Special Studies 4:	Not reported		
Special Studies 5:	Not reported		
Special Studies 6:	Not reported		
More Than Two Substances Ir			
Resp Agncy Personel # Of De	•		
Responding Agency Personel	# Of Injuries: Not reported		
<b>Responding Agency Personel</b>	# Of Fatalities:Not reported		
Others Number Of Decontamin	nated: Not reported		
Others Number Of Injuries:	Not reported		
Others Number Of Fatalities:	Not reported		
Vehicle Make/year:	Not reported		
Vehicle License Number:	Not reported		
Vehicle State:	Not reported		
Vehicle Id Number:	Not reported		
CA/DOT/PUC/ICC Number:	Not reported		
Company Name:	Not reported		
Reporting Officer Name/ID: Report Date:	Not reported Not reported		
Comments:	Not reported		
Facility Telephone:	Not reported		
Waterway Involved:	No		
Waterway:	Not reported		
Spill Site:	Not reported		
Cleanup By:	n\\a		
Containment:	Not reported		
What Happened:	Not reported		
Туре:	Not reported		
Measure:	Not reported		
Other:	Not reported		
Date/Time:	Not reported		
Year:	2003		
Agency:	Exxon Mobile		
Incident Date:	10/1/200312:00:00 AM		
Admin Agency:	Torrance Fire Department		
Amount:	Not reported		
Contained: Site Type:	Yes Refinery		
E Date:	Not reported		
Substance:	Particulates		
Quantity Released:	Not reported		
BBLS:	0		
0.	-		

Database(s)

EDR ID Number **EPA ID Number** 

Cups:	0
CUFT:	0
Gallons:	0.000000
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	Exceeded lim

0 Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere. Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes. Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit. In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials intothe atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release. Unkown under investigation. Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures. Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company.Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to

EDR ID Number Database(s) EPA ID Number

MOBIL, TORRANCE REFINERY (Continued)

## S100676240

the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring. During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare. Release due to tank car overflow. FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number:	03-3693		
OES notification:	7/23/200307:	58:52 AM	
OES Date:	Not reported		
OES Time:	Not reported		
Incident Date:	Not reported		
Date Completed:	Not reported		
Property Use:	Not reported		
Agency Id Number:	Not reported		
Agency Incident Number:	Not reported		
Time Notified:	Not reported		
Time Completed:	Not reported		
Surrounding Area:	Not reported		
Estimated Temperature:	Not reported		
Property Management:	Not reported		
Special Studies 1:	Not reported		
Special Studies 2:	Not reported		
Special Studies 3:	Not reported		
Special Studies 4:	Not reported		
Special Studies 5:	Not reported		
Special Studies 6:	Not reported		
More Than Two Substances I	nvolved?:	Not reported	
Resp Agncy Personel # Of Decontaminated: Not reported			
Responding Agency Personel	# Of Injuries:	Not reported	
Responding Agency Personel	# Of Fatalities	Not reported	
Others Number Of Decontam	inated:	Not reported	
Others Number Of Injuries:		Not reported	

Not reported

Database(s)

EDR ID Number **EPA ID Number** 

# MOBIL, TORRANCE REFINERY (Continued)

Others Number Of Fatalities: Vehicle Make/year: Not reported Not reported Vehicle License Number: Vehicle State: Not reported Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Company Name: Not reported Reporting Officer Name/ID: Not reported Report Date: Not reported Comments: Not reported Facility Telephone: Not reported Waterway Involved: No Waterway: Not reported Spill Site: Not reported Cleanup By: N/A Containment: Not reported What Happened: Not reported Type: Not reported Measure: Not reported Other: Not reported Date/Time: Not reported Year: 2003 Agency: Exxon Mobil Incident Date: 7/23/200312:00:00 AM Admin Agency: **Torrance Fire Department** Not reported Amount: Contained: No Site Type: Refinery E Date: Not reported Oxides of Noxide (NOX) Substance: Quantity Released: Not reported BBLS: 0 Cups: 0 CUFT: 0 0.000000 Gallons: Grams: 0 10 Pounds: Liters: 0 Ounces: 0 Pints: 0 0 Quarts: Sheen: 0 Tons: 0 Unknown: 0 Description: Not reported Evacuations: 0 Number of Injuries: 0 Number of Fatalities: 0 Description: Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway

S100676240

adjacent to the refinery. Spilled to ground only. Precautionary evacuation of

Database(s) EP

EDR ID Number EPA ID Number

## MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

Leak is ongoing, should be stopped within 10 minutes. Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials into he atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred. Crude unit upset, flare was necessary of intermittent basis to control pressures. Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare. Flaring due to inability to sell refinery fuel gas to local power company. Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted.Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas. Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE

EDR ID Number Database(s) EPA ID Number

## MOBIL, TORRANCE REFINERY (Continued)

## S100676240

A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

	crack and subsequent release
OES Incident Number:	03-2498
OES notification:	5/14/200308:37:12 AM
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
Date Completed:	Not reported
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Ir	•
Resp Agncy Personel # Of De	•
Responding Agency Personel	•
Responding Agency Personel	
Others Number Of Decontamin	•
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	No
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By:	Reporting Party
Containment:	Not reported
What Happened:	Not reported
Туре:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	2003
Agency:	Exxon Mobile
Incident Date:	
	5/14/200312:00:00 AM
Admin Agency:	5/14/200312:00:00 AM Torrance Fire Department

Database(s)

EDR ID Number **EPA ID Number** 

### S100676240

### MOBIL, TORRANCE REFINERY (Continued)

Amount:
Contained:
Site Type:
E Date:
Substance:
Quantity Released:
BBLS:
Cups:
CUFT:
Gallons:
Grams:
Pounds:
Liters:
Ounces:
Pints:
Quarts: Sheen:
Tons:
Unknown:
Description:
Evacuations:
Number of Injuries:
Number of Fatalities:
Description:
Bosonption.

Not reported Yes Refinery Not reported modified hydrofluric acid Not reported 0 0 0 0.000000 0 Not reported 0 0

0

0

Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes. Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials into he atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures.Pilots went out on an upright

EDR ID Number Database(s) **EPA ID Number** 

#### MOBIL, TORRANCE REFINERY (Continued)

S100676240

flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company.Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number:	03-6519
OES notification:	12/17/200306:59:20 PM
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
Date Completed:	Not reported
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

### MOBIL, TORRANCE REFINERY (Continued)

**Special Studies 6:** Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Vehicle License Number: Not reported Vehicle State: Not reported Not reported Vehicle Id Number: CA/DOT/PUC/ICC Number: Not reported Company Name: Not reported Reporting Officer Name/ID: Not reported Report Date: Not reported Not reported Comments: Facility Telephone: Not reported Waterway Involved: Not reported Waterway: Not reported Spill Site: Not reported Cleanup By: n\\a Not reported Containment: What Happened: Not reported Type: Not reported Measure: Not reported Other: Not reported Date/Time: Not reported 2003 Year: Agency: Exxon 12/17/200312:00:00 AM Incident Date: Admin Agency: **Torrance Fire Department** Amount: Not reported Contained: No Site Type: Refinery Not reported E Date: NOX Substance: Quantity Released: Not reported BBLS: 0 Cups: 0 CUFT: 0 Gallons: 0.000000 Grams: 0 Pounds: 0 Liters: 0 Ounces: 0 Pints: 0 Quarts: 0 Sheen: 0 0 Tons: Unknown: 0 Description: Not reported Evacuations: 0 Number of Injuries: 0 Number of Fatalities: 0 Description: Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway

Database(s) EPA ID

EDR ID Number EPA ID Number

### MOBIL, TORRANCE REFINERY (Continued)

S100676240

adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes.Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit. In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials intothe atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity. caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack. Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment. Due to flaring. The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures.Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare. Flaring due to inability to sell refinery fuel gas to local power company.Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount. No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen

Database(s)

EDR ID Number EPA ID Number

#### S100676240

heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost.A hydrogen header overpressured and went to flare.An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

	Clack and Subseq	
OES Incident Number:	03-0120	
OES notification:	1/7/200304:00:44	PM
OES Date:	Not reported	
OES Time:	Not reported	
Incident Date:	Not reported	
Date Completed:	Not reported	
Property Use:	Not reported	
Agency Id Number:	Not reported	
Agency Incident Number:	Not reported	
Time Notified:	Not reported	
Time Completed:	Not reported	
Surrounding Area:	Not reported	
Estimated Temperature:	Not reported	
Property Management:	Not reported	
Special Studies 1:	Not reported	
Special Studies 2:	Not reported	
Special Studies 3:	Not reported	
Special Studies 4:	Not reported	
Special Studies 5:	Not reported	
Special Studies 6:	Not reported	
More Than Two Substances In	nvolved?: Not	reported
Resp Agncy Personel # Of De	contaminated: Not	reported
Responding Agency Personel	# Of Injuries: Not	reported
Responding Agency Personel	# Of Fatalities:Not	reported
Others Number Of Decontami	nated: Not	reported
Others Number Of Injuries:	Not	reported
Others Number Of Fatalities:	Not	reported
Vehicle Make/year:	Not reported	
Vehicle License Number:	Not reported	
Vehicle State:	Not reported	
Vehicle Id Number:	Not reported	
CA/DOT/PUC/ICC Number:	Not reported	
Company Name:	Not reported	
Reporting Officer Name/ID:	Not reported	
Report Date:	Not reported	
Comments:	Not reported	
Facility Telephone:	Not reported	
Waterway Involved:	No	
Waterway:	Not reported	
Spill Site:	Not reported	
Cleanup By:	N/A	
Containment:	Not reported	
What Happened:	Not reported	
Туре:	Not reported	

Database(s)

EDR ID Number EPA ID Number

Measure: Not reported Other: Not reported Date/Time: Not reported 2003 Year: Agency: Exxon Mobil 1/7/200312:00:00 AM Incident Date: Torrance Fire Department Admin Agency: Amount: Not reported Contained: No Site Type: Refinery Not reported E Date: Substance: NOX Quantity Released: Not reported BBLS: 0 Cups: 0 CUFT: 0 0.000000 Gallons: Grams: 0 Pounds: 10 Liters: 0 0 Ounces: Pints: 0 Quarts: 0 Sheen: 0 Tons: 0 Unknown: Λ Description: Not reported Evacuations: 0 Number of Injuries: 0 Number of Fatalities: 0 Description:

Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere. Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes.Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials intothe atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the

Database(s) EPA

EDR ID Number EPA ID Number

### MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures.Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company.Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas. Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare. Release due to tank car overflow. FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number:	03-1994
OES notification:	4/15/200312:13:11 PM
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
Date Completed:	Not reported
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

# MOBIL, TORRANCE REFINERY (Continued)

Estimated Temperature: Not reported Property Management: Not reported Special Studies 1: Not reported Special Studies 2: Not reported Special Studies 3: Not reported Special Studies 4: Not reported Special Studies 5: Not reported **Special Studies 6:** Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Not reported Vehicle License Number: Vehicle State: Not reported Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Not reported Company Name: Reporting Officer Name/ID: Not reported Not reported Report Date: Comments: Not reported Facility Telephone: Not reported Waterway Involved: No Waterway: Not reported Spill Site: Not reported Cleanup By: N/A Not reported Containment: Not reported What Happened: Type: Not reported Measure: Not reported Other: Not reported Date/Time: Not reported 2003 Year: Exxon Mobil Agency: Incident Date: 4/15/200312:00:00 AM Admin Agency: **Torrance Fire Department** Amount: Not reported Contained: Yes Site Type: Refinery E Date: Not reported Substance: NOX Quantity Released: Not reported BBLS: 0 Cups: 0 CUFT: 0 0.000000 Gallons: Grams: 0 Pounds: 10 Liters: 0 Ounces: 0 Pints: 0 Quarts: 0 Sheen: 0 Tons: 0

MOBIL, TORRANCE REFINERY (Continued)

Database(s)

EDR ID Number EPA ID Number

MODIE, TORRANCE REFINER	(continued)	5100070240
Unknown:	0	
Description:	Not reported	
Evacuations:	0	
Number of Injuries:	0	
Number of Fatalities:	0	
Description:	Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to atmosphere.Piggy back of a big rig overturned during a U-turn on a road adjacent to the refinery. Spilled to ground only. Precautionary evacuation	way on of
	area. No water way's involved. Cleanup in progress. The alarm goes dir AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 pp is false reading.Fuel gas treater malfunctioned at 1315 hrs. Adjustments	om and it s have
	been made to treater and release is going downRelease caused by a lease exchanger.Pin hole leak in pipeline contained in diked area.Flow line deva a leak.Plug blew out on an exchanger (21E3C) allowing substance to es	veloped
	Leak is ongoing, should be stopped within 10 minutes. Line rupture on lin F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.	e 24
	release valve lifted when line over pressuredBoth are ongoing. Failure in in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrog	en to
	the flare.FCC Unit shut down bypassing SCR D7 causing the release to Release started 08/02/02 and ended 08/04/02A pocket of gas developed	l during
	maintenance on unit. In a crude unit was upset due to water in the proces caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish	time
	0015hours.A pipe failure caused the release.Released occurred on an in that is used to truck acid in and pumps into the vessel. Water deluge was	
	to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compress	or shut
	down on a hydrocracker unit, resulting in a release of materials intothe atmosphere.Equipment failure caused the release.Tank 400X31 pressur	ed up and
	company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated th	ev
	exceed 20 opacity. Still on going and being released into the air.Unknow circumstances at a truck loading rack.Unknown circumstances caused the	wn
	release.Exceded capacity for more than 3 minutes.A minor process upse	et caused
	the release.Unkown under investigation.Unit was shut down, depressing flare, due to faulty equipment.Due to flaring.The release is due to a	
	flare.Lost compresser, causing the gas to flare.Valve stuck closed on tov causing a flare that caused the release.Unit is down, has been controllin	
	until this morning when a flare occurred.Crude unit upset, flare was nece of intermittent basis to control pressures.Pilots went out on an upright	ssary
	flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell	:
	refinery fuel gas to local power company.Units upset, still investigating th	Ie
	release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix	is being
	adjusted.Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be re	
	the flare.putting tank back into service and flaring the gases that was in t tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 ful	
	at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown rea	ison
	for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was and the substance exceeded the 20 limit. Reason is unknown.equipmer	blowing dust
	failure.Pipe rupture caused the release.Bleeder on section of piping was and caused a leak.2F7 Damper 2D7 failed open causing the release.Und Line leak caused the spill.Lost 25 K1C compressor shut down causing the	opened derground
	release. This is a flaring event. Overfilled a rail car during loading. Spent	

EDR ID Number Database(s) **EPA ID Number** 

# MOBIL, TORRANCE REFINERY (Continued)

OES Date:

OES Time:

#### S100676240

Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release OES Incident Number: 03-2645 OES notification: 5/22/200308:08:18 AM Not reported Not reported Incident Date: Not reported **Date Completed:** Not reported

Date Completed.	Not reported
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances I	nvolved?: Not reported
Resp Agncy Personel # Of De	econtaminated: Not reported
Responding Agency Personel	# Of Injuries: Not reported
Responding Agency Personel	# Of Fatalities:Not reported
Others Number Of Decontam	inated: Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported

Database(s)

EDR ID Number EPA ID Number

S100676240

Waterway Involved: No Waterway: Not reported Not reported Spill Site: Cleanup By: N/A Containment: Not reported What Happened: Not reported Not reported Type: Measure: Not reported Not reported Other: Date/Time: Not reported 2003 Year: Agency: Exxon Mobil Incident Date: 5/22/200312:00:00 AM **Torrance Fire Department** Admin Agency: Amount: Not reported Contained: No Site Type: Refinerv E Date: Not reported Substance: NOX Quantity Released: Not reported BBLS: 0 Cups: 0 CUFT: 0 Gallons: 0.000000 Grams: 0 Pounds: 10 Liters: 0 Ounces: 0 Pints: 0 Quarts: 0 Sheen: 0 Tons: 0 Unknown: 0 Description: Not reported Evacuations: 0 Number of Injuries: 0 Number of Fatalities: 0 Description:

Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes.Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit. In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be

# TC2051883.2s Page 183

Database(s) EPA

EDR ID Number EPA ID Number

## MOBIL, TORRANCE REFINERY (Continued)

S100676240

segregated and treated.per NRC: The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials intothe atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures.Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company.Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted.Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number: OES notification: OES Date: OES Time: Incident Date: 03-3254 6/26/200304:24:06 PM Not reported Not reported Not reported Map ID Direction Distance Distance (ft.) Elevation Site MAP FINDINGS

Database(s)

EDR ID Number EPA ID Number

# MOBIL, TORRANCE REFINERY (Continued)

**Date Completed:** Not reported Property Use: Not reported Not reported Agency Id Number: Agency Incident Number: Not reported Time Notified: Not reported Time Completed: Not reported Surrounding Area: Not reported Estimated Temperature: Not reported Property Management: Not reported Special Studies 1: Not reported Special Studies 2: Not reported Not reported **Special Studies 3:** Special Studies 4: Not reported **Special Studies 5:** Not reported Special Studies 6: Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Not reported Vehicle Make/year: Vehicle License Number: Not reported Vehicle State: Not reported Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Company Name: Not reported Reporting Officer Name/ID: Not reported Not reported Report Date: Comments: Not reported Facility Telephone: Not reported Waterway Involved: No Waterway: Not reported Spill Site: Not reported Cleanup By: N/A Not reported Containment: What Happened: Not reported Type: Not reported Measure: Not reported Other: Not reported Date/Time: Not reported Year: 2003 NRC Agency: 6/26/200312:00:00 AM Incident Date: Admin Agency: **Torrance Fire Department** Amount: Not reported Contained: Yes Site Type: Refinery Not reported E Date: Substance: nitrogen dioxide Quantity Released: Not reported BBLS: 0 Cups: 0 CUFT: 0 Gallons: 55 Grams: 0

Database(s)

EDR ID Number EPA ID Number

# S100676240

#### MOBIL, TORRANCE REFINERY (Continued)

Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	Exceeded lim

eeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes. Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit. In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials into he atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack. Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment. Due to flaring. The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures.Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company. Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking. High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason

Database(s) EPA

EDR ID Number EPA ID Number

## MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH. Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

**OES Incident Number:** 03-5857 OES notification: 11/11/200308:23:24 PM OES Date: Not reported OES Time: Not reported Incident Date: Not reported Not reported **Date Completed:** Property Use: Not reported Agency Id Number: Not reported Not reported Agency Incident Number: Time Notified: Not reported Time Completed: Not reported Surrounding Area: Not reported Estimated Temperature: Not reported Property Management: Not reported Special Studies 1: Not reported Special Studies 2: Not reported Special Studies 3: Not reported Special Studies 4: Not reported **Special Studies 5:** Not reported **Special Studies 6:** Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Vehicle License Number: Not reported Vehicle State: Not reported

Database(s)

EDR ID Number EPA ID Number

# MOBIL, TORRANCE REFINERY (Continued)

Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date: Comments: Facility Telephone: Waterway Involved: Waterway: Spill Site: Cleanup By: n\\a Containment: What Happened: Type: Measure: Other: Date/Time: Year: 2003 Agency: EXXON Incident Date: Admin Agency: Amount: Contained: Yes Site Type: Refinery E Date: Substance: NOX Quantity Released: BBLS: 0 Cups: 0 CUFT: 0 Gallons: Grams: 0 Pounds: 10 Liters: 0 0 Ounces: Pints: 0 Quarts: 0 Sheen: 0 Tons: 0 Unknown: 0 Description: Evacuations: 0 Number of Injuries: 0 Number of Fatalities: 0 Description:

Not reported 11/11/200312:00:00 AM **Torrance Fire Department** Not reported Not reported Not reported 0.000000 Not reported

Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading.Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes.Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to

EDR ID Number Database(s) EPA ID Number

MOBIL, TORRANCE REFINERY (Continued)

## S100676240

the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit. In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours. A pipe failure caused the release. Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials into he atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release. Unkown under investigation. Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures.Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare. Flaring due to inability to sell refinery fuel gas to local power company.Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking. High temperature has raised tank temp, causing PO gas to be released to the flare putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare. Release due to tank car overflow. FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a

Database(s)

EDR ID Number EPA ID Number

S100676240

crack and subsequent release

OES Incident Number: 03-5928 11/15/200309:57:45 AM OES notification: OES Date: Not reported OES Time: Not reported Incident Date: Not reported Date Completed: Not reported Not reported Property Use: Agency Id Number: Not reported Not reported Agency Incident Number: Time Notified: Not reported Time Completed: Not reported Surrounding Area: Not reported Estimated Temperature: Not reported **Property Management:** Not reported Special Studies 1: Not reported **Special Studies 2:** Not reported **Special Studies 3:** Not reported Special Studies 4: Not reported **Special Studies 5:** Not reported **Special Studies 6:** Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Not reported Vehicle Make/year: Vehicle License Number: Not reported Vehicle State: Not reported Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Company Name: Not reported Not reported Reporting Officer Name/ID: Report Date: Not reported Comments: Not reported Facility Telephone: Not reported Waterway Involved: Not reported Waterway: Not reported Spill Site: Not reported Cleanup By: N/A Containment: Not reported Not reported What Happened: Type: Not reported Measure: Not reported Other: Not reported Date/Time: Not reported Year: 2003 Agency: Exxon Mobil Incident Date: 11/15/200312:00:00 AM Admin Agency: Torrance Fire Department Not reported Amount: Contained: No Site Type: Refinerv E Date: Not reported

Database(s)

EDR ID Number EPA ID Number

•	. ,
Substance:	natural gas
Quantity Released:	Not reported
BBLS:	0
Cups:	0
CUFT:	0
Gallons:	0.000000
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	Exceeded lim
	atmosphere F

0
0
0
Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the
atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway
adjacent to the refinery. Spilled to ground only. Precautionary evacuation of
area. No water way's involved. Cleanup in progress. The alarm goes directly to
AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it
is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have
been made to treater and release is going downRelease caused by a leak in an
exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed
a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape.
Leak is ongoing, should be stopped within 10 minutes. Line rupture on line 24
F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch
release valve lifted when line over pressuredBoth are ongoing. Failure in PSA
in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to
the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur.
Release started 08/02/02 and ended 08/04/02A pocket of gas developed during
maintenance on unit. In a crude unit was upset due to water in the process,
caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time
0015hours.A pipe failure caused the release.Released occurred on an inlet line
that is used to truck acid in and pumps into the vessel. Water deluge was used
to minimize the release into the air. SMALL release. Water used will be
segregated and treated.per NRC; The caller stated they had a compressor shut
down on a hydrocracker unit, resulting in a release of materials intothe
atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and
company is having to vent to reduce pressureCorrosion of a line
underground.Permit allows on a stack up to 20 opacity, caller stated they
exceed 20 opacity. Still on going and being released into the air.Unknown
circumstances at a truck loading rack.Unknown circumstances caused the
release.Exceded capacity for more than 3 minutes.A minor process upset caused
the release.Unkown under investigation.Unit was shut down, depressing to the
flare, due to faulty equipment.Due to flaring.The release is due to a
flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower,
causing a flare that caused the release.Unit is down, has been controlling
until this morning when a flare occurred.Crude unit upset, flare was necessary
of intermittent basis to control pressures.Pilots went out on an upright
flare.A check valve failed while decompressing a compressor.Equipment
overpressured and released to the flare.Flaring due to inability to sell
refinery fuel gas to local power company.Units upset, still investigating the
release. More gas in flare line that recovery can process.510X4 tank

EDR ID Number Database(s) EPA ID Number

## MOBIL, TORRANCE REFINERY (Continued)

## S100676240

overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted.Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number:	03-3596	
OES notification:	7/17/200311:19:32 AM	
OES Date:	Not reported	
OES Time:	Not reported	
Incident Date:	Not reported	
Date Completed:	Not reported	
Property Use:	Not reported	
Agency Id Number:	Not reported	
Agency Incident Number:	Not reported	
Time Notified:	Not reported	
Time Completed:	Not reported	
Surrounding Area:	Not reported	
Estimated Temperature:	Not reported	
Property Management:	Not reported	
Special Studies 1:	Not reported	
Special Studies 2:	Not reported	
Special Studies 3:	Not reported	
Special Studies 4:	Not reported	
Special Studies 5:	Not reported	
Special Studies 6:	Not reported	
More Than Two Substances Involved?: Not reported		
Resp Agncy Personel # Of Decontaminated: Not reported		
Responding Agency Personel # Of Injuries: Not reported		

Database(s)

EDR ID Number EPA ID Number

# MOBIL, TORRANCE REFINERY (Continued)

Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Vehicle License Number: Not reported Not reported Vehicle State: Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Company Name: Not reported Reporting Officer Name/ID: Not reported Report Date: Not reported Comments: Not reported Facility Telephone: Not reported Waterway Involved: No Waterway: Not reported Not reported Spill Site: Reporting Party Cleanup By: Containment: Not reported What Happened: Not reported Not reported Type: Measure: Not reported Other: Not reported Date/Time: Not reported Year: 2003 Agency: Exxon Mobil Incident Date: 7/17/200312:00:00 AM Admin Agency: **Torrance Fire Department** Amount: Not reported Contained: No Site Type: Refinery E Date: Not reported Substance: refinery fuel gas Quantity Released: Not reported BBLS: 0 Cups: 0 CUFT: 0 Gallons: 0.000000 Grams: 0 Pounds: 0 Liters: 0 Ounces: 0 Pints: 0 Quarts: 0 Sheen: 0 Tons: 0 Unknown: 0 Description: Not reported Evacuations: 0 0 Number of Injuries: Number of Fatalities: 0 Description: Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of

S100676240

area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have

EDR ID Number Database(s) EPA ID Number

#### MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes. Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials into he atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release. Unkown under investigation. Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release.Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures. Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company.Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of

Year:

2003

MAP FINDINGS

Database(s)

EDR ID Number EPA ID Number

# MOBIL, TORRANCE REFINERY (Continued)

	refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release
OES Incident Number:	03-2691
OES notification:	5/24/200312:42:39 PM
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
Date Completed:	Not reported
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances I	nvolved?: Not reported
Resp Agncy Personel # Of De	contaminated: Not reported
Responding Agency Personel	# Of Injuries: Not reported
Responding Agency Personel	# Of Fatalities:Not reported
Others Number Of Decontami	nated: Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	No
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By:	N/A
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported

Database(s)

EDR ID Number EPA ID Number

,	(
Agency:	Exxon Mobil
Incident Date:	5/24/200312:00:00 AM
Admin Agency:	Not reported
Amount:	Not reported
Contained:	No
Site Type:	Refinery
E Date:	Not reported
Substance:	NOX
Quantity Released:	Not reported
BBLS:	0
Cups:	0
CUFT:	0
Gallons:	0.000000
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	Exceeded limits betwee
	atmaanhara Diggy haal

d limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere. Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes. Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit. In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials intothe atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment. Due to flaring. The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower,

EDR ID Number Database(s) EPA ID Number

# MOBIL, TORRANCE REFINERY (Continued)

## S100676240

causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures.Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare. Flaring due to inability to sell refinery fuel gas to local power company. Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring. During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas. Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare. Release due to tank car overflow. FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

**OES Incident Number: OES** notification: OES Date: OES Time: Incident Date: **Date Completed:** Property Use: Agency Id Number: Agency Incident Number: Time Notified: Time Completed: Surrounding Area: Estimated Temperature: **Property Management:** Special Studies 1: Special Studies 2:

03-6643

12/26/200303:33:35 AM Not reported Not reported

Database(s)

EDR ID Number EPA ID Number

# MOBIL, TORRANCE REFINERY (Continued)

**Special Studies 3:** Not reported Special Studies 4: Not reported Special Studies 5: Not reported Special Studies 6: Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Vehicle License Number: Not reported Vehicle State: Not reported Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Company Name: Not reported Reporting Officer Name/ID: Not reported Report Date: Not reported Comments: Not reported Facility Telephone: Not reported Waterway Involved: Not reported Not reported Waterway: Spill Site: Not reported Cleanup By: N/A Containment: Not reported What Happened: Not reported Type: Not reported Measure: Not reported Not reported Other: Not reported Date/Time: 2003 Year: Agency: Exxon Incident Date: 12/26/200312:00:00 AM Admin Agency: **Torrance Fire Department** Not reported Amount: Contained: Yes Site Type: Refinery E Date: Not reported Substance: Particulate Quantity Released: Not reported BBLS: 0 Cups: 0 CUFT: 0 0.000000 Gallons: Grams: 0 Pounds: 0 Liters: 0 Ounces: 0 0 Pints: Quarts: 0 Sheen: 0 Tons: 0 Unknown: 0 Description: Not reported Evacuations: 0 Number of Injuries: 0

Database(s) EPA II

EDR ID Number EPA ID Number

#### MOBIL, TORRANCE REFINERY (Continued)

0

Number of Fatalities: Description: S100676240 resulting in a release to the uring a U-turn on a roadway Precautionary evacuation of

Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes. Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials into the atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack. Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures.Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare. Flaring due to inability to sell refinery fuel gas to local power company. Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted.Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in

Database(s) E

EDR ID Number EPA ID Number

#### S100676240

pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost.A hydrogen header overpressured and went to flare.An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

	crack and sub	osequent relea
OES Incident Number:	03-1896	
OES notification:	4/9/200311:1	6:45 AM
OES Date:	Not reported	
OES Time:	Not reported	
Incident Date:	Not reported	
Date Completed:	Not reported	
Property Use:	Not reported	
Agency Id Number:	Not reported	
Agency Incident Number:	Not reported	
Time Notified:	Not reported	
Time Completed:	Not reported	
Surrounding Area:	Not reported	
Estimated Temperature:	Not reported	
Property Management:	Not reported	
Special Studies 1:	Not reported	
Special Studies 2:	Not reported	
Special Studies 3:	Not reported	
Special Studies 4:	Not reported	
Special Studies 5:	Not reported	
Special Studies 6:	Not reported	
More Than Two Substances In	volved?:	Not reported
Resp Agncy Personel # Of De	contaminated:	Not reported
Responding Agency Personel		Not reported
Responding Agency Personel	# Of Fatalities	Not reported
Others Number Of Decontamin	nated:	Not reported
Others Number Of Injuries:		Not reported
Others Number Of Fatalities:		Not reported
Vehicle Make/year:	Not reported	
Vehicle License Number:	Not reported	
Vehicle State:	Not reported	
Vehicle Id Number:	Not reported	
CA/DOT/PUC/ICC Number:	Not reported	
Company Name:	Not reported	
Reporting Officer Name/ID:	Not reported	
Report Date:	Not reported	
Comments:	Not reported	
Facility Telephone:	Not reported	
Waterway Involved:	No	
Waterway:	Not reported	
Spill Site:	Not reported	
Cleanup By:	N/A	

Database(s)

EDR ID Number EPA ID Number

# MOBIL, TORRANCE REFINERY (Continued)

Containment: Not reported What Happened: Not reported Not reported Type: Measure: Not reported Other: Not reported Date/Time: Not reported 2003 Year: Agency: Exxon Mobil Incident Date: 4/9/200312:00:00 AM Admin Agency: **Torrance Fire Department** Amount: Not reported Contained: Yes Site Type: Refinery E Date: Not reported Substance: particulate matter Quantity Released: Not reported BBLS: 0 Cups: 0 CUFT: 0 0.000000 Gallons: 0 Grams: Pounds: 0 Liters: 0 Ounces: 0 Pints: 0 Quarts: 0 Sheen: 0 Tons: 0 Unknown: 0 Description: Not reported Evacuations: 0 Number of Injuries: 0 Number of Fatalities: 0 Description:

S100676240

Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes. Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials into he atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line

EDR ID Number Database(s) EPA ID Number

MOBIL, TORRANCE REFINERY (Continued)

# S100676240

underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment. Due to flaring. The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release.Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures.Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company.Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking. High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount. No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number: OES notification: OES Date: OES Time: Incident Date: **Date Completed:** Property Use: Agency Id Number: Agency Incident Number: 03-2163 4/25/200308:16:52 AM Not reported Not reported Not reported Not reported Not reported Not reported Not reported

# Map ID Direction Distance Distance (ft.) Elevation Site

MAP FINDINGS

Database(s)

EDR ID Number EPA ID Number

# MOBIL, TORRANCE REFINERY (Continued)

Time Notified: Not reported Time Completed: Not reported Not reported Surrounding Area: Not reported Estimated Temperature: Property Management: Not reported Special Studies 1: Not reported Special Studies 2: Not reported **Special Studies 3:** Not reported Special Studies 4: Not reported Special Studies 5: Not reported **Special Studies 6:** Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Vehicle License Number: Not reported Vehicle State: Not reported Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Company Name: Not reported Reporting Officer Name/ID: Not reported Report Date: Not reported Comments: Not reported Facility Telephone: Not reported Waterway Involved: No Waterway: Not reported Spill Site: Not reported Cleanup By: Reporting Party Containment: Not reported What Happened: Not reported Not reported Type: Not reported Measure: Other: Not reported Date/Time: Not reported Year: 2003 Agency: Exxon Mobil 4/25/200312:00:00 AM Incident Date: Admin Agency: Torrance Fire Department Amount: Not reported Contained: Yes Site Type: Refinery E Date: Not reported Substance: Particulate Matter Quantity Released: Not reported BBLS: 0 0 Cups: CUFT: 0 Gallons: 0.000000 Grams: 0 0 Pounds: Liters: 0 Ounces: 0 Pints: 0

Database(s)

EDR ID Number EPA ID Number

Quarts:	0	
Sheen:	0	
Tons:	0	
Unknown:	0	
Description:	Not reported	
Evacuations:	0	
Number of Injuries:	0	
Number of Fatalities:	0	
Number of Fatalities: Description:	0 Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading.Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes.Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs. See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water duege was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials intothe atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances c	
	refinery fuel gas to local power company.Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release.Emission from 20F4P Stack, the mix is being adjusted.Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the	

EDR ID Number Database(s) EPA ID Number

## MOBIL, TORRANCE REFINERY (Continued)

# S100676240

and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas. Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release **OES Incident Number:** 03-4420 **OES** notification: 8/27/200304:06:09 PM OES Date: Not reported OES Time: Not reported Incident Date: Not reported Date Completed: Not reported Not reported Property Use: Agency Id Number: Not reported Agency Incident Number: Not reported Time Notified: Not reported Time Completed: Not reported Surrounding Area: Not reported Not reported Estimated Temperature: **Property Management:** Not reported Special Studies 1: Not reported Special Studies 2: Not reported **Special Studies 3:** Not reported Special Studies 4: Not reported **Special Studies 5:** Not reported Special Studies 6: Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Vehicle License Number: Not reported Vehicle State: Not reported Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Company Name: Not reported Reporting Officer Name/ID: Not reported

Database(s)

EDR ID Number EPA ID Number

# MOBIL, TORRANCE REFINERY (Continued)

Report Date: Not reported Not reported Comments: Facility Telephone: Not reported Waterway Involved: No Waterway: Not reported Spill Site: Not reported Cleanup By: Unknown Containment: Not reported What Happened: Not reported Type: Not reported Measure: Not reported Other: Not reported Date/Time: Not reported 2003 Year: Agency: Exxon Torrance Refinery Incident Date: 8/27/200312:00:00 AM **Torrance Fire Department** Admin Agency: Amount: Not reported Contained: Unknown Site Type: Refinery E Date: Not reported Substance: Regenerated catalyst finds from the FCC Quantity Released: Not reported BBLS: 0 Cups: 0 CUFT: 0 Gallons: 0.000000 Grams: 0 Pounds: 0 0 Liters: Ounces: 0 Pints: 0 Quarts: 0 Sheen: 0 0 Tons: Unknown: 0 Description: Not reported Evacuations: 0 Number of Injuries: 0 Number of Fatalities: 0 Description:

Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes.Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit. In a crude unit was upset due to water in the process. caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time

EDR ID Number Database(s) EPA ID Number

## MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

0015hours. A pipe failure caused the release. Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials intothe atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures. Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company.Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring. During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number: OES notification: 5823 Not reported

Database(s)

EDR ID Number EPA ID Number

# MOBIL, TORRANCE REFINERY (Continued)

OES Date: 12/23/1994 OES Time: 01:05:34 PM Incident Date: Not reported Not reported **Date Completed:** Property Use: Not reported Agency Id Number: Not reported Agency Incident Number: Not reported Time Notified: Not reported Time Completed: Not reported Surrounding Area: Not reported Estimated Temperature: Not reported Property Management: Not reported Special Studies 1: Not reported **Special Studies 2:** Not reported Special Studies 3: Not reported Special Studies 4: Not reported **Special Studies 5:** Not reported **Special Studies 6:** Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Not reported Vehicle Make/year: Vehicle License Number: Not reported Vehicle State: Not reported Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Company Name: Not reported Reporting Officer Name/ID: Not reported Report Date: Not reported Comments: Not reported Facility Telephone: Not reported Waterway Involved: YES Waterway: Not reported Spill Site: Not reported Cleanup By: dissipated Containment: Not reported What Happened: Not reported VAPOR Type: Measure: Not reported Other: Not reported Date/Time: Not reported Year: 1994 mobile oil refinery in torrance Agency: Incident Date: 1147 23 dec 94 Admin Agency: Not reported unknown Amount: Contained: NO Site Type: REF E Date: Not reported Substance: spent caustic (chemicals) Quantity Released: Not reported Not reported BBLS: Not reported Cups:

Database(s)

EDR ID Number EPA ID Number

0.157	
CUFT:	Not reported
Gallons:	Not reported
Grams:	Not reported
Pounds:	Not reported
Liters:	Not reported
Ounces:	Not reported
Pints:	Not reported
Quarts:	Not reported
Sheen:	Not reported
Tons:	Not reported
	•
Unknown:	Not reported
Description:	mobile oil loading railcar tank . tank was overpressurized causing
	leakage through pressure release valve. fire dept. contacted to
	contain situation. incident # 9400008900.
Evacuations:	NO
Number of Injuries:	NO
Number of Fatalities:	NO
Description:	Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the
	atmosphere. Piggy back of a big rig overturned during a U-turn on a roadway
	adjacent to the refinery. Spilled to ground only. Precautionary evacuation of
	area. No water way's involved. Cleanup in progress. The alarm goes directly
	AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm ar
	is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments hav
	been made to treater and release is going downRelease caused by a leak in
	exchanger.Pin hole leak in pipeline contained in diked area.Flow line develop
	a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape
	Leak is ongoing, should be stopped within 10 minutes. Line rupture on line 24
	F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 incl
	release valve lifted when line over pressuredBoth are ongoing. Failure in PS
	in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to
	the flare.FCC Unit shut down bypassing SCR D7 causing the release to occu
	Release started 08/02/02 and ended 08/04/02A pocket of gas developed duri
	maintenance on unit. In a crude unit was upset due to water in the process,
	caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time
	0015hours. A pipe failure caused the release. Released occurred on an inlet li
	that is used to truck acid in and pumps into the vessel. Water deluge was use
	to minimize the release into the air. SMALL release. Water used will be
	segregated and treated.per NRC; The caller stated they had a compressor sh
	down on a hydrocracker unit, resulting in a release of materials intothe
	atmosphere.Equipment failure caused the release.Tank 400X31 pressured up
	company is having to vent to reduce pressureCorrosion of a line
	underground.Permit allows on a stack up to 20 opacity, caller stated they
	exceed 20 opacity. Still on going and being released into the air.Unknown
	circumstances at a truck loading rack. Unknown circumstances caused the
	release.Exceded capacity for more than 3 minutes.A minor process upset cat
	the release. Unkown under investigation. Unit was shut down, depressing to the
	flare, due to faulty equipment.Due to flaring.The release is due to a
	flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower,
	causing a flare that caused the release.Unit is down, has been controlling
	until this morning when a flare occurred.Crude unit upset, flare was necessar
	of intermittent basis to control pressures. Pilots went out on an upright
	flare.A check valve failed while decompressing a compressor.Equipment
	overpressured and released to the flare. Flaring due to inability to sell
	refinery fuel gas to local power company.Units upset, still investigating the
	release. More gas in flare line that recovery can process.510X4 tank
	overpressured causing the release. Emission from 20F4P Stack, the mix is be

EDR ID Number Database(s) **EPA ID Number** 

# MOBIL, TORRANCE REFINERY (Continued)

## S100676240

leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas. Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number:	767
OES notification:	Not reported
OES Date:	2/12/1994
OES Time:	12:35:00 PM
Incident Date:	Not reported
Date Completed:	Not reported
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances In	volved?: Not
Resp Agncy Personel # Of De	contaminated: Not
Responding Agency Personel	# Of Injuries: Not
Responding Agency Personal	# Of Estalities Not

reported reported reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Map ID Direction Distance Distance (ft.) Elevation Site MAP FINDINGS

Database(s)

EDR ID Number EPA ID Number

# MOBIL, TORRANCE REFINERY (Continued)

Others Number Of Injuries: Others Number Of Fatalities: Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date: Comments: Facility Telephone: Waterway Involved: Waterway: Spill Site: Cleanup By: Containment: What Happened: Type: Measure: Other: Date/Time: Year: Agency: Incident Date: Admin Agency: Amount: Contained: Site Type: E Date: Substance: Quantity Released: BBLS: Cups: CUFT: Gallons: Grams: Pounds: Liters: Ounces: Pints: Quarts: Sheen: Tons: Unknown: Description: Evacuations: Number of Injuries: Number of Fatalities: Description:

Not reported YES Not reported Not reported . mobil oil Not reported Not reported PETROLEUM Not reported Not reported Not reported 1994 mobil oil co 2/12/94 0755 Not reported 2-5bbls NO REF Not reported gasoline Not reported section line leak NO NO NO

#### S100676240

Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading.Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed

Database(s) EPA

EDR ID Number EPA ID Number

# MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes.Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit. In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials intothe atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment. Due to flaring. The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures.Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company. Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring. During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare. Release due to tank car overflow. FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line.

EDR ID Number Database(s) EPA ID Number

# MOBIL, TORRANCE REFINERY (Continued)

# S100676240

Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number:	00-0542
OES notification:	2/4/200008:35:38 PM
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
Date Completed:	Not reported
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Ir	•
Resp Agncy Personel # Of De	•
Responding Agency Personel	
Responding Agency Personel	
Others Number Of Decontami	•
	nateur netropenteu
Others Number Of Injuries:	Not reported
Others Number Of Injuries: Others Number Of Fatalities:	Not reported Not reported
Others Number Of Fatalities:	Not reported
Others Number Of Fatalities: Vehicle Make/year:	Not reported Not reported
Others Number Of Fatalities: Vehicle Make/year: Vehicle License Number:	Not reported Not reported Not reported
Others Number Of Fatalities: Vehicle Make/year: Vehicle License Number: Vehicle State:	Not reported Not reported Not reported Not reported
Others Number Of Fatalities: Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number:	Not reported Not reported Not reported Not reported Not reported
Others Number Of Fatalities: Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number:	Not reported Not reported Not reported Not reported Not reported Not reported
Others Number Of Fatalities: Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name:	Not reported Not reported Not reported Not reported Not reported Not reported Not reported
Others Number Of Fatalities: Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID:	Not reported Not reported Not reported Not reported Not reported Not reported Not reported Not reported
Others Number Of Fatalities: Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date:	Not reported Not reported Not reported Not reported Not reported Not reported Not reported Not reported Not reported
Others Number Of Fatalities: Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date: Comments:	Not reported Not reported
Others Number Of Fatalities: Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date: Comments: Facility Telephone:	Not reported Not reported
Others Number Of Fatalities: Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date: Comments: Facility Telephone: Waterway Involved:	Not reported Not reported
Others Number Of Fatalities: Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date: Comments: Facility Telephone: Waterway Involved: Waterway:	Not reported Not reported
Others Number Of Fatalities: Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date: Comments: Facility Telephone: Waterway Involved: Waterway: Spill Site:	Not reportedNot reported
Others Number Of Fatalities: Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date: Comments: Facility Telephone: Waterway Involved: Waterway: Spill Site: Cleanup By:	Not reportedNot reported
Others Number Of Fatalities: Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date: Comments: Facility Telephone: Waterway Involved: Waterway: Spill Site: Cleanup By: Containment:	Not reportedNot reported
Others Number Of Fatalities: Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date: Comments: Facility Telephone: Waterway Involved: Waterway: Spill Site: Cleanup By: Containment: What Happened:	Not reportedNot reported
Others Number Of Fatalities: Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date: Comments: Facility Telephone: Waterway Involved: Waterway: Spill Site: Cleanup By: Containment: What Happened: Type:	Not reportedNot reported
Others Number Of Fatalities: Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date: Comments: Facility Telephone: Waterway Involved: Waterway: Spill Site: Cleanup By: Containment: What Happened: Type: Measure:	Not reportedNot reported
Others Number Of Fatalities: Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date: Comments: Facility Telephone: Waterway Involved: Waterway: Spill Site: Cleanup By: Containment: What Happened: Type: Measure: Other:	Not reportedNot reported
Others Number Of Fatalities: Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date: Comments: Facility Telephone: Waterway Involved: Waterway: Spill Site: Cleanup By: Containment: What Happened: Type: Measure: Other: Date/Time:	Not reportedNot reported
Others Number Of Fatalities: Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date: Comments: Facility Telephone: Waterway Involved: Waterway: Spill Site: Cleanup By: Containment: What Happened: Type: Measure: Other: Date/Time: Year:	Not reportedNot reported
Others Number Of Fatalities: Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date: Comments: Facility Telephone: Waterway Involved: Waterway: Spill Site: Cleanup By: Containment: What Happened: Type: Measure: Other: Date/Time:	Not reportedNot reported

Database(s)

EDR ID Number EPA ID Number

# MOBIL, TORRANCE REFINERY (Continued)

Admin Agency:	Torrance Fire Department
Amount:	Not reported
Contained:	Yes
Site Type:	Refinery
E Date:	Not reported
Substance:	kerosene
Quantity Released:	Not reported
BBLS:	2
Cups:	0
CUFT:	0
Gallons:	0.000000
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	Exceeded limits between 1
	otmoonhoro Diami hook of

S100676240

d limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes. Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials into he atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred. Crude unit upset, flare was necessary

Database(s) E

EDR ID Number EPA ID Number

#### MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

of intermittent basis to control pressures. Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare. Flaring due to inability to sell refinery fuel gas to local power company.Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas. Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

**OES Incident Number:** 99-5416 OES notification: OES Date: OES Time: Incident Date: **Date Completed:** Property Use: Agency Id Number: Agency Incident Number: Time Notified: Time Completed: Surrounding Area: Estimated Temperature: Property Management: Special Studies 1: **Special Studies 2:** Special Studies 3: Special Studies 4:

12/24/199902:08:00 PM Not reported Not reported

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

# MOBIL, TORRANCE REFINERY (Continued)

Special Studies 5: Not reported **Special Studies 6:** Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Vehicle License Number: Not reported Vehicle State: Not reported Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Company Name: Not reported Reporting Officer Name/ID: Not reported Not reported Report Date: Comments: Not reported Facility Telephone: Not reported Waterway Involved: No Waterway: Not reported Spill Site: Not reported Responsible Party Cleanup By: Containment: Not reported What Happened: Not reported Type: Not reported Measure: Not reported Other: Not reported Date/Time: Not reported 1999 Year: Mobile Torrance Refinery Agency: 12/24/199912:00:00 AM Incident Date: Admin Agency: **Torrance Fire Department** Amount: Not reported Contained: Yes Site Type: Refinery Not reported E Date: Substance: SOX Not reported Quantity Released: BBLS: 0 Cups: 0 CUFT: 0 Gallons: 0 Grams: 0 Pounds: 0 Liters: 0 Ounces: 0 Pints: 0 Quarts: 0 0 Sheen: Tons: 0 Unknown: 0 Description: Not reported Evacuations: 0 Number of Injuries: 0 Number of Fatalities: 0 Description: Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the

Database(s) EPA I

EDR ID Number EPA ID Number

# MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

atmosphere. Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes. Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials intothe atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack. Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release.Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures. Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company.Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to

Database(s)

EDR ID Number EPA ID Number

# MOBIL, TORRANCE REFINERY (Continued)

## S100676240

substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost.A hydrogen header overpressured and went to flare.An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number: OES notification: OES Date: OES Time: Incident Date: <b>Date Completed:</b> Property Use: Agency Id Number: Agency Id Number: Agency Incident Number: Time Notified: Time Completed: Surrounding Area: Estimated Temperature: Property Management: Special Studies 1: Special Studies 2: Special Studies 3: Special Studies 4: Special Studies 5: Special Studies 6: Marea Theore Two Schetzeree International Studies 1: Special Studies 5: Special Studies 6: Marea Theore Two Schetzeree International Studies 1: Special Studies 6: Marea Theore Two Schetzeree International Studies 1: Special Studies 5: Special Studies 6: Marea Theore Two Schetzeree International Studies 1: Special Studies 5: Special Studies 5	99-3498 8/20/199907:54:34 AM Not reported Not reported
More Than Two Substances In Resp Agncy Personel # Of De	contaminated: Not reported
Responding Agency Personel Responding Agency Personel	
Others Number Of Decontami Others Number Of Injuries:	nated: Not reported Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported No
Waterway Involved:	
Waterway:	Not reported
Spill Site: Cleanup By:	Not reported
Containment:	Reporting Party Not reported
	Not reported
What Happened:	Not reported

Database(s)

EDR ID Number EPA ID Number

# MOBIL, TORRANCE REFINERY (Continued)

Type: Not reported Measure: Not reported Other: Not reported Date/Time: Not reported Year: 1999 Agency: Incident Date: Admin Agency: Amount: Contained: No Site Type: E Date: Substance: Quantity Released: BBLS: 0 Cups: 0 CUFT: 0 Gallons: 0 Grams: 0 Pounds: 0 0 Liters: Ounces: 0 Pints: 0 Quarts: 0 Sheen: 0 0 Tons: Unknown: 0 Description: Evacuations: 0 0 Number of Injuries: 0 Number of Fatalities: Description:

Mobile Torrance Refinery 8/20/199912:00:00 AM **Torrance Fire Department** Not reported Refinery Not reported Vac. Gas oil Not reported Not reported Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere. Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes. Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during

maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials into the

atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and

underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown

company is having to vent to reduce pressureCorrosion of a line

EDR ID Number Database(s) EPA ID Number

#### MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

circumstances at a truck loading rack. Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures.Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company. Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring. During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas. Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare. Release due to tank car overflow. FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number:
OES notification:
OES Date:
OES Time:
Incident Date:
Date Completed:
Property Use:
Agency Id Number:
Agency Incident Number:
Time Notified:

99-3196 7/30/199901:22:26 AM Not reported Not reported

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

### MOBIL, TORRANCE REFINERY (Continued)

Surrounding Area: Not reported Estimated Temperature: Not reported Property Management: Not reported Special Studies 1: Not reported Special Studies 2: Not reported **Special Studies 3:** Not reported Special Studies 4: Not reported Special Studies 5: Not reported Special Studies 6: Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Vehicle License Number: Not reported Vehicle State: Not reported Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Company Name: Not reported Reporting Officer Name/ID: Not reported Report Date: Not reported Comments: Not reported Facility Telephone: Not reported Waterway Involved: No Waterway: Not reported Spill Site: Not reported Cleanup By: **Reporting Party** Not reported Containment: What Happened: Not reported Not reported Type: Measure: Not reported Other: Not reported Not reported Date/Time: 1999 Year: Agency: Mobile Oil Incident Date: 7/30/199912:00:00 AM Admin Agency: **Torrance Fire Department** Not reported Amount: Contained: Yes Site Type: Refinery E Date: Not reported Heavy VGO Substance: Not reported Quantity Released: BBLS: 10 Cups: 0 CUFT: 0 Gallons: 0 Grams: 0 Pounds: 0 Liters: 0 0 Ounces: Pints: 0 Quarts: 0 Sheen: 0

Database(s)

EDR ID Number EPA ID Number

MOBIL, TORRANCE REFINERY	(Continued)	S100676240
Tons:	0	
Unknown:	0	
Description:	Not reported	
Evacuations:	0	
Number of Injuries:	0	
Number of Fatalities:		
Description:	Exceeded limits between 1542 hrs and 1619 hrs. resulting in a	
	atmosphere.Piggy back of a big rig overturned during a U-turn	
	adjacent to the refinery. Spilled to ground only. Precautionary	
	area. No water way's involved. Cleanup in progress. The alar	• •
	AQMD. It was a false alarm of the HF sensor, A05027. It came	
	is false reading. Fuel gas treater malfunctioned at 1315 hrs. A	djustments have
	been made to treater and release is going downRelease cause	ed by a leak in an
	exchanger.Pin hole leak in pipeline contained in diked area.Flo	ow line developed
	a leak.Plug blew out on an exchanger (21E3C) allowing substa	ance to escape.
	Leak is ongoing, should be stopped within 10 minutes. Line rup	
	F1. Currently contained. Unit shut down at 0538 hrs See also	
	release valve lifted when line over pressuredBoth are ongoing	
	in the hydrogen unit #24.Plan Unit shutdown, purging the unit	
	the flare.FCC Unit shut down bypassing SCR D7 causing the	U U
	Release started 08/02/02 and ended 08/04/02A pocket of gas	
	maintenance on unit. In a crude unit was upset due to water in	
	caused flaring in exceeded 1500 parts of SO2. Between 2345	-
	<b>o</b>	
	0015hours. A pipe failure caused the release. Released occurre	
	that is used to truck acid in and pumps into the vessel. Water of	0
	to minimize the release into the air. SMALL release. Water us	
	segregated and treated.per NRC; The caller stated they had a	•
	down on a hydrocracker unit, resulting in a release of material	
	atmosphere.Equipment failure caused the release.Tank 400X	
	company is having to vent to reduce pressureCorrosion of a lin	
	underground.Permit allows on a stack up to 20 opacity, calle	
	exceed 20 opacity. Still on going and being released into the	
	circumstances at a truck loading rack.Unknown circumstances	
	release.Exceded capacity for more than 3 minutes.A minor pro	ocess upset caused
	the release. Unkown under investigation. Unit was shut down, o	lepressing to the
	flare, due to faulty equipment.Due to flaring.The release is due	e to a
	flare.Lost compresser, causing the gas to flare.Valve stuck clo	sed on tower,
	causing a flare that caused the release.Unit is down, has beer	n controlling
	until this morning when a flare occurred.Crude unit upset, flare	e was necessary
	of intermittent basis to control pressures.Pilots went out on an	•
	flare.A check valve failed while decompressing a compressor.	
	overpressured and released to the flare.Flaring due to inability	• •
	refinery fuel gas to local power company.Units upset, still inve	
	release. More gas in flare line that recovery can process.510X	
	overpressured causing the release.Emission from 20F4P Stac	
	adjusted.Possible that a pump seal or pipe associated with th	
	, , , , , ,	• •
	leaking.High temperature has raised tank temp, causing PO g	
	the flare.putting tank back into service and flaring the gases th	
	tank. 510X4 is the # of the tank.Leaking from a railroad car that	
	at this time. Liquid in the tank, vapor when it hits the air. The c	
	loading rack inside the refinery, no evacuations at this time.Un	known reason
	for the release.2F7 had a unit upset, which caused the release	e.The plant
	exceeded compliance amount.No mechanical failure while cor	-
	and the substance exceeded the 20 limit. Reason is unknown	
	failure.Pipe rupture caused the release.Bleeder on section of p	
	and caused a leak.2F7 Damper 2D7 failed open causing the re-	
	Line leak caused the spill.Lost 25 K1C compressor shut down	•
	Line leak caused the spill. Lost 23 K TC compressor shut down	

EDR ID Number Database(s) EPA ID Number

MOBIL, TORRANCE REFINERY (Continued)

# S100676240

release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas. Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare. Release due to tank car overflow. FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number:	99-3875	
OES notification:	9/14/199911:14:44 AM	
OES Date:	Not reported	
OES Time:	Not reported	
Incident Date:	Not reported	
Date Completed:	Not reported	
Property Use:	Not reported	
Agency Id Number:	Not reported	
Agency Incident Number:	Not reported	
Time Notified:	Not reported	
Time Completed:	Not reported	
Surrounding Area:	Not reported	
Estimated Temperature:	Not reported	
Property Management:	Not reported	
Special Studies 1:	Not reported	
Special Studies 2:	Not reported	
Special Studies 3:	Not reported	
Special Studies 4:	Not reported	
Special Studies 5:	Not reported	
Special Studies 6:	Not reported	
More Than Two Substances Ir	volved?: Not reported	
Resp Agncy Personel # Of De	contaminated: Not reported	
Responding Agency Personel	# Of Injuries: Not reported	
Responding Agency Personel	# Of Fatalities:Not reported	
Others Number Of Decontamin	nated: Not reported	
Others Number Of Injuries:	Not reported	
Others Number Of Fatalities:	Not reported	
Vehicle Make/year:	Not reported	
Vehicle License Number:	Not reported	
Vehicle State:	Not reported	
Vehicle Id Number:	Not reported	
CA/DOT/PUC/ICC Number:	Not reported	
Company Name:	Not reported	
Reporting Officer Name/ID:	Not reported	
Report Date:	Not reported	
Comments:	Not reported	

Database(s)

EDR ID Number EPA ID Number

# MOBIL, TORRANCE REFINERY (Continued)

Facility Telephone: Not reported Waterway Involved: No Waterway: Not reported Spill Site: Not reported Cleanup By: Reporting Party Not reported Containment: What Happened: Not reported Type: Not reported Measure: Not reported Other: Not reported Date/Time: Not reported 1999 Year: Agency: Mobile Oil Incident Date: 9/14/199912:00:00 AM Admin Agency: **Torrance Fire Department** Amount: Not reported Contained: Yes Site Type: Refinery E Date: Not reported Substance: hydroflorides Quantity Released: Not reported BBLS: 0 Cups: 0 CUFT: 0 Gallons: 0 Grams: 0 Pounds: 0 Liters: 0 Ounces: 0 Pints: 0 Quarts: 0 Sheen: 0 Tons: 0 Unknown: 0 Not reported Description: Evacuations: 0 Number of Injuries: 0 Number of Fatalities: 0 Description:

Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes.Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used

EDR ID Number Database(s) EPA ID Number

MOBIL, TORRANCE REFINERY (Continued)

## S100676240

to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials intothe atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release.Unit is down, has been controlling until this morning when a flare occurred. Crude unit upset, flare was necessary of intermittent basis to control pressures.Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare. Flaring due to inability to sell refinery fuel gas to local power company. Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number: OES notification: OES Date: OES Time: 99-3170 7/28/199905:46:36 AM Not reported Not reported

Database(s)

EDR ID Number EPA ID Number

# MOBIL, TORRANCE REFINERY (Continued)

Incident Date: Not reported **Date Completed:** Not reported Not reported Property Use: Not reported Agency Id Number: Agency Incident Number: Not reported Time Notified: Not reported Time Completed: Not reported Surrounding Area: Not reported Estimated Temperature: Not reported Property Management: Not reported Special Studies 1: Not reported **Special Studies 2:** Not reported **Special Studies 3:** Not reported Special Studies 4: Not reported Special Studies 5: Not reported Special Studies 6: Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Vehicle License Number: Not reported Vehicle State: Not reported Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Company Name: Not reported Not reported Reporting Officer Name/ID: Report Date: Not reported Comments: Not reported Facility Telephone: Not reported Waterway Involved: No Waterway: Not reported Not reported Spill Site: Cleanup By: N/A Containment: Not reported What Happened: Not reported Type: Not reported Not reported Measure: Other: Not reported Date/Time: Not reported 1999 Year: Mobile Oil Agency: 7/28/199912:00:00 AM Incident Date: Admin Agency: **Torrance Fire Department** Amount: Not reported Contained: Yes Refinery Site Type: E Date: Not reported Substance: Hydrogen Quantity Released: Not reported BBLS: 0 Cups: 0 CUFT: 0 Gallons: 0

Database(s)

EDR ID Number EPA ID Number

S100676240

Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	Exceeded lim

d limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes. Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials into he atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack. Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures. Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare. Flaring due to inability to sell refinery fuel gas to local power company. Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted.Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the

EDR ID Number Database(s) EPA ID Number

MOBIL, TORRANCE REFINERY (Continued)

## S100676240

loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas. Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare. Release due to tank car overflow. FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

**OES Incident Number:** 03-5553 OES notification: 10/26/200301:43:39 PM OES Date: Not reported OES Time: Not reported Not reported Incident Date: Date Completed: Not reported Property Use: Not reported Not reported Agency Id Number: Agency Incident Number: Not reported Time Notified: Not reported Time Completed: Not reported Surrounding Area: Not reported Estimated Temperature: Not reported Property Management: Not reported Special Studies 1: Not reported Special Studies 2: Not reported **Special Studies 3:** Not reported Special Studies 4: Not reported **Special Studies 5:** Not reported **Special Studies 6:** Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/vear: Not reported Vehicle License Number: Not reported

Database(s)

EDR ID Number EPA ID Number

# MOBIL, TORRANCE REFINERY (Continued)

Vehicle State: Not reported Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Not reported Company Name: Reporting Officer Name/ID: Not reported Report Date: Not reported Not reported Comments: Facility Telephone: Not reported Waterway Involved: Not reported Waterway: Not reported Spill Site: Not reported Cleanup By: **Reporting Party** Containment: Not reported What Happened: Not reported Type: Not reported Measure: Not reported Not reported Other: Date/Time: Not reported Year: 2003 Agency: Exxon Mobil Incident Date: 10/26/200312:00:00 AM Admin Agency: Torrance Fire Department Amount: Not reported Contained: Yes Site Type: Refinery E Date: Not reported Substance: waste water Quantity Released: Not reported BBLS: 2 0 Cups: CUFT: 0 Gallons: 0.000000 Grams: 0 Pounds: 0 Liters: 0 0 Ounces: Pints: 0 Quarts: 0 Sheen: 0 Tons: 0 0 Unknown: Description: Not reported Evacuations: 0 Number of Injuries: 0 Number of Fatalities: 0 Description:

Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading.Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes.Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA

Database(s) Ef

EDR ID Number EPA ID Number

# MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit. In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials intothe atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment. Due to flaring. The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures.Pilots went out on an upright flare. A check valve failed while decompressing a compressor. Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company. Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH. Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of

Database(s) EPA I

EDR ID Number EPA ID Number

S100676240

# MOBIL, TORRANCE REFINERY (Continued)

emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number:	00-4044
OES notification:	9/8/200009:38:41 AM
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
Date Completed:	Not reported
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Ir	•
Resp Agncy Personel # Of De	
Responding Agency Personel	
Responding Agency Personel	# Of Fatalities: Not reported
Others Number Of Decontami	
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
	•
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	No Not reported
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By:	none necessary
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	2000
Agency:	Exxon Mobile
Incident Date:	9/8/200012:00:00 AM
Admin Agency:	Torrance Fire Department
Amount:	Not reported
Contained:	Yes
Site Type:	
ene rype.	Refinery

Database(s)

EDR ID Number EPA ID Number

E Date:	Not reported
Substance:	None
Quantity Released:	Not reported
BBLS:	0
Cups:	0
CUFT:	0
Gallons:	0.000000
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	Exceeded lim

ed limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes.Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials into he atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures.Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare. Flaring due to inability to sell refinery fuel gas to local power company.Units upset, still investigating the

Database(s) EPA II

EDR ID Number EPA ID Number

# MOBIL, TORRANCE REFINERY (Continued)

S100676240

release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted.Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas. Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number:	05-0202	
OES notification:	1/10/200502:08:29 AM	
OES Date:	Not reported	
OES Time:	Not reported	
Incident Date:	Not reported	
Date Completed:	Not reported	
Property Use:	Not reported	
Agency Id Number:	Not reported	
Agency Incident Number:	Not reported	
Time Notified:	Not reported	
Time Completed:	Not reported	
Surrounding Area:	Not reported	
Estimated Temperature:	Not reported	
Property Management:	Not reported	
Special Studies 1:	Not reported	
Special Studies 2:	Not reported	
Special Studies 3:	Not reported	
Special Studies 4:	Not reported	
Special Studies 5:	Not reported	
Special Studies 6:	Not reported	
More Than Two Substances In	volved?: Not reported	
Doop Agency Dereanal # Of Decenterringted Net reported		

Resp Agncy Personel # Of Decontaminated: Not reported

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

# MOBIL, TORRANCE REFINERY (Continued)

Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Vehicle License Number: Not reported Vehicle State: Not reported Not reported Vehicle Id Number: CA/DOT/PUC/ICC Number: Not reported Not reported Company Name: Reporting Officer Name/ID: Not reported Report Date: Not reported Comments: Not reported Facility Telephone: Not reported Waterway Involved: Not reported Not reported Waterway: Spill Site: Not reported Cleanup By: Contractor Containment: Not reported What Happened: Not reported Type: Not reported Measure: Not reported Other: Not reported Date/Time: Not reported 2005 Year: Agency: Exxon Refinery Incident Date: 1/10/200512:00:00 AM Admin Agency: **Torrance Fire Department** Amount: Not reported Contained: Yes Site Type: Refinery E Date: Not reported Substance: Industrial Waste Water Quantity Released: Not reported BBLS: 1 Cups: 0 CUFT: 0 0.000000 Gallons: Grams: 0 Pounds: 0 Liters: 0 Ounces: 0 Pints: 0 Quarts: 0 Sheen: 0 Tons: 0 Unknown: 0 Description: Not reported 0 Evacuations: Number of Injuries: 0 Number of Fatalities: 0 Description:

Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it

EDR ID Number Database(s) EPA ID Number

#### MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes.Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials into he atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures. Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company.Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas. Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment

Database(s)

EDR ID Number EPA ID Number

# MOBIL, TORRANCE REFINERY (Continued)

# S100676240

that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare. Release due to tank car overflow. FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed. BELIEVED TO BE AN UNDERGROUND LEAK. APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH. Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment. Line integrity broke down causing a crack and subsequent release

	crack and subsequent release	
OES Incident Number:	05-0771	
OES notification:	2/2/200509:30:54 AM	
OES Date:	Not reported	
OES Time:	Not reported	
Incident Date:	Not reported	
Date Completed:	Not reported	
Property Use:	Not reported	
Agency Id Number:	Not reported	
Agency Incident Number:	Not reported	
Time Notified:	Not reported	
Time Completed:	Not reported	
Surrounding Area:	Not reported	
Estimated Temperature:	Not reported	
Property Management:	Not reported	
Special Studies 1:	Not reported	
Special Studies 2:	Not reported	
Special Studies 3:	Not reported	
Special Studies 4:	Not reported	
Special Studies 5:	Not reported	
Special Studies 6:	Not reported	
More Than Two Substances Ir	volved?: Not reported	
Resp Agncy Personel # Of De	contaminated: Not reported	
Responding Agency Personel		
Responding Agency Personel	# Of Fatalities:Not reported	
Others Number Of Decontamin	nated: Not reported	
Others Number Of Injuries:	Not reported	
Others Number Of Fatalities:	Not reported	
Vehicle Make/year:	Not reported	
Vehicle License Number:	Not reported	
Vehicle State:	Not reported	
Vehicle Id Number:	Not reported	
CA/DOT/PUC/ICC Number:	Not reported	
Company Name:	Not reported	
Reporting Officer Name/ID:	Not reported	
Report Date:	Not reported	
Comments:	Not reported	
Facility Telephone:	Not reported	
Waterway Involved:	Not reported	
Waterway:	Not reported	
Spill Site:	Not reported	
Cleanup By:	n\\a	
Containment:	Not reported	
What Happened:	Not reported	
Type:	Not reported	
Measure:	Not reported	
Other:	Not reported	
Date/Time:	Not reported	

Database(s)

EDR ID Number **EPA ID Number** 

#### Year: 2005 NRC Agency: Incident Date: 2/2/200512:00:00 AM Admin Agency: **Torrance Fire Department** Amount: Not reported Contained: Unknown Site Type: Refinery E Date: Not reported Substance: NOX Quantity Released: Not reported BBLS: 0 Cups: 0 CUFT: 0 0.000000 Gallons: Grams: 0 Pounds: 10 0 Liters: Ounces: 0 Pints: 0 Quarts: 0 Sheen: 0 Tons: 0 Unknown: 0 Description: Not reported Evacuations: 0 Number of Injuries: 0 Number of Fatalities: 0 Description: Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere. Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes. Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials intothe atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the

flare, due to faulty equipment.Due to flaring.The release is due to a

# MOBIL, TORRANCE REFINERY (Continued)

Database(s) EPA

EDR ID Number EPA ID Number

## MOBIL, TORRANCE REFINERY (Continued)

S100676240

flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release.Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures. Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company.Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number:OES notification:OES notification:OES Date:OES Date:Incident Date:Date Completed:Incident Date:Property Use:Incident Property Use:Agency Id Number:Incident Number:Agency Incident Number:Incident Number:Time Notified:Incident Number:Time Completed:Incident Number:Surrounding Area:Incident Number:Estimated Temperature:Incident:Property Management:Incident:Special Studies 1:Incident:

05-1226 2/22/200508:59:15 PM Not reported Not reported

Database(s)

EDR ID Number EPA ID Number

# MOBIL, TORRANCE REFINERY (Continued)

Special Studies 2: Not reported **Special Studies 3:** Not reported Special Studies 4: Not reported Special Studies 5: Not reported Special Studies 6: Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Vehicle License Number: Not reported Vehicle State: Not reported Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Company Name: Not reported Reporting Officer Name/ID: Not reported Report Date: Not reported Comments: Not reported Facility Telephone: Not reported Not reported Waterway Involved: Waterway: Not reported Spill Site: Not reported Cleanup By: N/A Containment: Not reported What Happened: Not reported Type: Not reported Not reported Measure: Not reported Other: Date/Time: Not reported 2005 Year: Agency: Exxon Mobil 2/22/200512:00:00 AM Incident Date: Admin Agency: **Torrance Fire Department** Amount: Not reported Contained: Unknown Site Type: Refinery E Date: Not reported Substance: NOX Quantity Released: Not reported BBLS: 0 Cups: 0 CUFT: 0 0.000000 Gallons: Grams: 0 Pounds: 0 Liters: 0 0 Ounces: Pints: 0 Quarts: 0 Sheen: 0 0 Tons: Unknown: 0 Description: Not reported Evacuations: 0

Database(s) E

EDR ID Number EPA ID Number

#### S100676240

#### MOBIL, TORRANCE REFINERY (Continued)

0

Number of Injuries: Number of Fatalities: Description:

0 Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes.Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit. In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC: The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials intothe atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures.Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare. Flaring due to inability to sell refinery fuel gas to local power company. Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it

Database(s)

EDR ID Number EPA ID Number

## S100676240

overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas. Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number:	05-0573	
OES notification:	1/24/200504:	54:44 AM
OES Date:	Not reported	
OES Time:	Not reported	
Incident Date:	Not reported	
Date Completed:	Not reported	1
Property Use:	Not reported	
Agency Id Number:	Not reported	
Agency Incident Number:	Not reported	
Time Notified:	Not reported	
Time Completed:	Not reported	
Surrounding Area:	Not reported	
Estimated Temperature:	Not reported	
Property Management:	Not reported	
Special Studies 1:	Not reported	
Special Studies 2:	Not reported	
Special Studies 3:	Not reported	
Special Studies 4:	Not reported	
Special Studies 5:	Not reported	
Special Studies 6:	Not reported	
More Than Two Substances Ir	nvolved?:	Not reported
Resp Agncy Personel # Of De	contaminated	Not reported
<b>Responding Agency Personel</b>	# Of Injuries:	Not reported
<b>Responding Agency Personel</b>	# Of Fatalities	Not reported
Others Number Of Decontami	nated:	Not reported
Others Number Of Injuries:		Not reported
Others Number Of Fatalities:		Not reported
Vehicle Make/year:	Not reported	
Vehicle License Number:	Not reported	
Vehicle State:	Not reported	
Vehicle Id Number:	Not reported	
CA/DOT/PUC/ICC Number:	Not reported	
Company Name:	Not reported	
Reporting Officer Name/ID:	Not reported	
Report Date:	Not reported	
Comments:	Not reported	
Facility Telephone:	Not reported	
Waterway Involved:	Not reported	
Waterway:	Not reported	
Spill Site:	Not reported	

Database(s)

EDR ID Number EPA ID Number

# MOBIL, TORRANCE REFINERY (Continued)

Cleanup By: N/A Containment: Not reported Not reported What Happened: Not reported Type: Measure: Not reported Other: Not reported Date/Time: Not reported Year: 2005 Agency: Exxon Mobil Incident Date: 1/24/200512:00:00 AM Admin Agency: **Torrance Fire Department** Not reported Amount: Contained: No Site Type: Refinery E Date: Not reported NOX Substance: Not reported Quantity Released: BBLS: 0 Cups: 0 CUFT: 0 Gallons: 0.000000 Grams: 0 Pounds: 0 Liters: 0 Ounces: 0 Pints: 0 Quarts: 0 Sheen: 0 Tons: 0 Unknown: 0 Description: Not reported Evacuations: 0 Number of Injuries: 0 Number of Fatalities: 0 Description:

# S100676240

Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes. Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit. In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials into he atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and

EDR ID Number Database(s) EPA ID Number

#### MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack. Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred. Crude unit upset, flare was necessary of intermittent basis to control pressures. Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company.Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release.Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring. During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas. Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number: OES notification: OES Date: OES Time: Incident Date: **Date Completed:** Property Use: Agency Id Number: 013765

Not reported 5/16/1996 11:50:43 AM Not reported Not reported Not reported Not reported

Database(s)

EDR ID Number EPA ID Number

# MOBIL, TORRANCE REFINERY (Continued)

Agency Incident Number: Not reported Time Notified: Not reported Not reported Time Completed: Surrounding Area: Not reported **Estimated Temperature:** Not reported Property Management: Not reported Not reported Special Studies 1: **Special Studies 2:** Not reported **Special Studies 3:** Not reported Special Studies 4: Not reported **Special Studies 5:** Not reported **Special Studies 6:** Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Not reported Others Number Of Decontaminated: Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Vehicle License Number: Not reported Vehicle State: Not reported Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Company Name: Not reported Reporting Officer Name/ID: Not reported Report Date: Not reported Comments: Not reported Facility Telephone: Not reported Waterway Involved: NO Waterway: Not reported Spill Site: Not reported Cleanup By: dissipated into the air Containment: Not reported Not reported What Happened: VAPOR Type: Measure: Not reported Other: Not reported Date/Time: Not reported Year: 1996 mobil torrance refinery Agency: Incident Date: 1114/5-16-96 Admin Agency: Not reported Amount: unknown Contained: NO Site Type: REF E Date: Not reported Substance: so2 Quantity Released: Not reported BBLS: Not reported Cups: Not reported CUFT: Not reported Gallons: Not reported Not reported Grams: Pounds: Not reported Liters: Not reported Ounces: Not reported

unit upset, no definite cause known.

Not reported Not reported Not reported Not reported Not reported

NO

Database(s)

EDR ID Number EPA ID Number

#### S100676240

#### MOBIL, TORRANCE REFINERY (Continued)

Pints:
Quarts:
Sheen:
Tons:
Unknown:
Description:
Evacuations:
Number of Injuries:
Number of Fatalities:
Description:

NO NO Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere. Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes.Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials intothe atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release.Unit is down, has been controlling until this morning when a flare occurred. Crude unit upset, flare was necessary of intermittent basis to control pressures.Pilots went out on an upright flare. A check valve failed while decompressing a compressor. Equipment overpressured and released to the flare. Flaring due to inability to sell refinery fuel gas to local power company.Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount. No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment

EDR ID Number Database(s) EPA ID Number

MOBIL, TORRANCE REFINERY (Continued)

# S100676240

failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas. Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number:	013744	
OES notification:	Not reported	
OES Date:	5/15/1996	
OES Time:	03:48:49 PM	
Incident Date:	Not reported	
Date Completed:	Not reported	l
Property Use:	Not reported	
Agency Id Number:	Not reported	
Agency Incident Number:	Not reported	
Time Notified:	Not reported	
Time Completed:	Not reported	
Surrounding Area:	Not reported	
Estimated Temperature:	Not reported	
Property Management:	Not reported	
Special Studies 1:	Not reported	
Special Studies 2:	Not reported	
Special Studies 3:	Not reported	
Special Studies 4:	Not reported	
Special Studies 5:	Not reported	
Special Studies 6:	Not reported	
More Than Two Substances I	nvolved?:	Not reported
Resp Agncy Personel # Of De	econtaminated:	Not reported
Responding Agency Personel		Not reported
Responding Agency Personel		Not reported
Others Number Of Decontam	inated:	Not reported
Others Number Of Injuries:		Not reported
Others Number Of Fatalities:		Not reported
Vehicle Make/year:	Not reported	
Vehicle License Number:	Not reported	
Vehicle State:	Not reported	
Vehicle Id Number:	Not reported	
CA/DOT/PUC/ICC Number:	Not reported	
Company Name:	Not reported	

Database(s)

EDR ID Number EPA ID Number

# MOBIL, TORRANCE REFINERY (Continued)

Reporting Officer Name/ID: Not reported Report Date: Not reported Comments: Not reported Not reported Facility Telephone: Waterway Involved: NO Waterway: Spill Site: Cleanup By: Containment: What Happened: VAPOR Type: Measure: Other: Date/Time: Year: 1996 Agency: Incident Date: Admin Agency: Amount: Contained: NO Site Type: REF E Date: Substance: Quantity Released: BBLS: Cups: CUFT: Gallons: Grams: Pounds: Liters: Ounces: Pints: Quarts: Sheen: Tons: Unknown: Description: Evacuations: NO Number of Injuries: NO Number of Fatalities: NO Description:

Not reported mobile refinery 1500/15 May 96 Not reported unknown over rq of 10 lbs. Not reported nitric oxide Not reported scr shut down resulting in release exceeding rg. cause of shutdown unknown at this time, investigation in process. leakage is ongoing, no estimated time of containment. Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes.Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to

the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur.

Database(s) EPA

EDR ID Number EPA ID Number

# MOBIL, TORRANCE REFINERY (Continued)

## S100676240

Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours. A pipe failure caused the release. Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials into he atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures.Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company. Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted.Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare. Release due to tank car overflow. FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

Database(s)

EDR ID Number EPA ID Number

OES Incident Number: 011995 OES notification: Not reported 1/28/1996 OES Date: 01:59:48 PM OES Time: Incident Date: Not reported Date Completed: Not reported Property Use: Not reported Agency Id Number: Not reported Not reported Agency Incident Number: Time Notified: Not reported Time Completed: Not reported Surrounding Area: Not reported Estimated Temperature: Not reported Property Management: Not reported Special Studies 1: Not reported Special Studies 2: Not reported **Special Studies 3:** Not reported Special Studies 4: Not reported Special Studies 5: Not reported **Special Studies 6:** Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Vehicle License Number: Not reported Not reported Vehicle State: Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Company Name: Not reported Reporting Officer Name/ID: Not reported Report Date: Not reported Comments: Not reported Not reported Facility Telephone: Waterway Involved: YES Waterway: Not reported Spill Site: Not reported Not reported Cleanup By: Containment: Not reported What Happened: Not reported Type: PETROLEUM Measure: Not reported Other: Not reported Date/Time: Not reported Year: 1996 Agency: mobile oil refinery Incident Date: 1330 Admin Agency: Not reported Amount: unknown Contained: NO Site Type: REF E Date: Not reported Substance: residual oil Quantity Released: Not reported

MOBIL, TORRANCE REFINERY (Continued)

MAP FINDINGS

Database(s)

EDR ID Number EPA ID Number

WOBIL, TORRAINCE REFINER	(conunded) Store
BBLS:	Not reported
Cups:	Not reported
CUFT:	Not reported
Gallons:	Not reported
Grams:	Not reported
Pounds:	Not reported
Liters:	Not reported
Ounces:	Not reported
Pints:	Not reported
Quarts:	Not reported
Sheen:	Not reported
Tons:	Not reported
Unknown:	Not reported
Description:	unknown how happened, still under investigation. situation is under
	control. immediate area where incident occurred was evacuated. no injuries or fatalities.
Evacuations:	YES
Number of Injuries:	NO
Number of Fatalities:	NO
Description:	Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the
Beschption.	atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway
	adjacent to the refinery. Spilled to ground only. Precautionary evacuation of
	area. No water way's involved. Cleanup in progress. The alarm goes directly to
	AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it
	is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have
	been made to treater and release is going downRelease caused by a leak in an
	exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed
	a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape.
	Leak is ongoing, should be stopped within 10 minutes.Line rupture on line 24
	F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch
	release valve lifted when line over pressuredBoth are ongoing. Failure in PSA
	in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to
	the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur.
	Release started 08/02/02 and ended 08/04/02A pocket of gas developed during
	maintenance on unit.In a crude unit was upset due to water in the process,
	caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time
	0015hours. A pipe failure caused the release. Released occurred on an inlet line
	that is used to truck acid in and pumps into the vessel. Water deluge was used
	to minimize the release into the air. SMALL release. Water used will be
	segregated and treated.per NRC; The caller stated they had a compressor shut
	down on a hydrocracker unit, resulting in a release of materials into the
	atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line
	underground.Permit allows on a stack up to 20 opacity, caller stated they
	exceed 20 opacity. Still on going and being released into the air.Unknown
	circumstances at a truck loading rack.Unknown circumstances caused the
	release.Exceded capacity for more than 3 minutes.A minor process upset caused
	the release.Unkown under investigation.Unit was shut down, depressing to the
	flare, due to faulty equipment.Due to flaring.The release is due to a
	flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower,
	causing a flare that caused the release.Unit is down, has been controlling
	until this morning when a flare occurred.Crude unit upset, flare was necessary
	of intermittent basis to control pressures. Pilots went out on an upright
	flare.A check valve failed while decompressing a compressor.Equipment
	overpressured and released to the flare. Flaring due to inability to sell
	refinery fuel gas to local power company.Units upset, still investigating the
	release. More gas in flare line that recovery can process.510X4 tank

Database(s) EP

EDR ID Number EPA ID Number

# MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted.Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number:	011575		
OES notification:	Not reported		
OES Date:	1/2/1996		
OES Time:	07:27:05 PM		
Incident Date:	Not reported		
Date Completed:	Not reported		
Property Use:	Not reported		
Agency Id Number:	Not reported		
Agency Incident Number:	Not reported		
Time Notified:	Not reported		
Time Completed:	Not reported		
Surrounding Area:	Not reported		
Estimated Temperature:	Not reported		
Property Management:	Not reported		
Special Studies 1:	Not reported		
Special Studies 2:	Not reported		
Special Studies 3:	Not reported		
Special Studies 4:	Not reported		
Special Studies 5:	Not reported		
Special Studies 6:	Not reported		
More Than Two Substances Involved?: Not reported			
Resp Agncy Personel # Of Decontaminated: Not reported			
Responding Agency Personel # Of Injuries: Not reported			

Database(s)

EDR ID Number EPA ID Number

S100676240

# MOBIL, TORRANCE REFINERY (Continued)

Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Vehicle License Number: Not reported Vehicle State: Not reported Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Company Name: Not reported Not reported Reporting Officer Name/ID: Report Date: Not reported Comments: Not reported Facility Telephone: Not reported Waterway Involved: YES Waterway: Not reported Not reported Spill Site: Cleanup By: Not reported Containment: Not reported What Happened: Not reported PETROLEUM Type: Measure: Not reported Other: Not reported Date/Time: Not reported Year: 1996 Agency: mobile refinery Incident Date: 1845/02 Jan 96 Admin Agency: Not reported Amount: 5 bbls. Contained: NO Site Type: REF E Date: Not reported hdt vgo hydro-treated vacuum gas oil Substance: Quantity Released: Not reported Not reported BBLS: Not reported Cups: CUFT: Not reported Gallons: Not reported Grams: Not reported Pounds: Not reported Not reported Liters: Ounces: Not reported Pints: Not reported Not reported Quarts: Sheen: Not reported Tons: Not reported Unknown: Not reported Description: a release valve lifted. spill was contained within the refinery and clean-up has been initiated. no waterways were involved. Evacuations: NO Number of Injuries: NO Number of Fatalities: NO Description: Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it

EDR ID Number Database(s) EPA ID Number

#### MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes.Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials into he atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures. Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company.Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas. Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment

Database(s)

EDR ID Number EPA ID Number

# MOBIL, TORRANCE REFINERY (Continued)

	that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare. Release due to tank car overflow. FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed. BELIEVED TO BE AN UNDERGROUND LEAK. APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH. Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment. Line integrity broke down causing a crack and subsequent release
OES Incident Number:	013083
OES notification:	Not reported
OES Date:	4/3/1996
OES Time:	04:44:41 PM
Incident Date:	Not reported
Date Completed:	Not reported
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances I	nvolved?: Not reported
Resp Agncy Personel # Of De	econtaminated: Not reported
Responding Agency Personel	# Of Injuries: Not reported
Responding Agency Personel	# Of Fatalities:Not reported
Others Number Of Decontam	inated: Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	NO
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By:	very small amount dissipated
Containment:	Not reported
What Happened:	Not reported
Type: Moosuro:	VAPOR Nat reported
Measure:	Not reported
Other: Date/Time:	Not reported Not reported
	Not reported

Database(s)

EDR ID Number EPA ID Number

#### S100676240

#### MOBIL, TORRANCE REFINERY (Continued)

Year: Agency: Incident Date: Admin Agency: Amount: Contained: Site Type: E Date: Substance: Quantity Released: BBLS: Cups: CUFT: Gallons: Grams: Pounds: Liters: Ounces: Pints: Quarts: Sheen: Tons: Unknown: Description: Evacuations: Number of Injuries: Number of Fatalities: Description:

1996 torrance fd/hazmat div. 1110/4-3-96 Not reported unknown NO REF Not reported sour desulfurizer offgas Not reported flange leak found and repaired by mobil oil. NO NO NO

Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere. Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes. Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials intothe atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release. Unkown under investigation. Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a

EDR ID Number Database(s) EPA ID Number

### MOBIL, TORRANCE REFINERY (Continued)

S100676240

flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release.Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures. Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company.Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number: OES notification: OES Date: OES Time: Incident Date: **Date Completed:** Property Use: Agency Id Number: Agency Id Number: Agency Incident Number: Time Notified: Time Completed: Surrounding Area: Estimated Temperature: Property Management: Special Studies 1:

012794 Not reported 3/15/1996 06:49:35 PM Not reported MAP FINDINGS

Database(s)

EDR ID Number EPA ID Number

	, ,
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances I	•
Resp Agncy Personel # Of De	•
Responding Agency Personel	
Responding Agency Personel	
Others Number Of Decontam	
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	YES
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By: Containment:	Not reported
What Happened:	Not reported Not reported
Туре:	PETROLEUM
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	1996
Agency:	torrance fd
Incident Date:	1449/3-15-96
Admin Agency:	Not reported
Amount:	15-20 barrels
Contained:	NO
Site Type:	REF
E Date:	Not reported
Substance:	sour heavy crude oil
Quantity Released:	Not reported
BBLS:	Not reported
Cups:	Not reported
CUFT:	Not reported
Gallons:	Not reported
Grams:	Not reported
Pounds:	Not reported
Liters:	Not reported
Ounces: Pints:	Not reported Not reported
Quarts:	Not reported
Sheen:	Not reported
Tons:	Not reported
Unknown:	Not reported
Description:	leak in a high pressure valve caused spill.
Evacuations:	NO

Database(s)

EDR ID Number EPA ID Number

#### S100676240

#### MOBIL, TORRANCE REFINERY (Continued)

NO

Number of Injuries: Number of Fatalities: Description:

NO Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes.Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit. In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC: The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials intothe atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures.Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare. Flaring due to inability to sell refinery fuel gas to local power company. Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it

Database(s)

EDR ID Number EPA ID Number

## MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas. Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

	crack and su	osequent relea
OES Incident Number: OES notification:	05-2839 5/12/200511:	50 <sup>.</sup> 41 PM
OES Date:	Not reported	00.4111
OES Time:	Not reported	
Incident Date:	Not reported	
Date Completed:	Not reported	I
Property Use:	Not reported	
Agency Id Number:	Not reported	
Agency Incident Number:	Not reported	
Time Notified:	Not reported	
Time Completed:	Not reported	
Surrounding Area:	Not reported	
Estimated Temperature:	Not reported	
Property Management:	Not reported	
Special Studies 1:	Not reported	
Special Studies 2:	Not reported	
Special Studies 3:	Not reported	
Special Studies 4:	Not reported	
Special Studies 5:	Not reported	
Special Studies 6:	Not reported	
More Than Two Substances In	volved?:	Not reported
Resp Agncy Personel # Of De		Not reported
Responding Agency Personel	# Of Injuries:	Not reported
Responding Agency Personel		
Others Number Of Decontamin	nated:	Not reported
Others Number Of Injuries:		Not reported
Others Number Of Fatalities:		Not reported
Vehicle Make/year:	Not reported	
Vehicle License Number:	Not reported	
Vehicle State:	Not reported	
Vehicle Id Number:	Not reported	
CA/DOT/PUC/ICC Number:	Not reported	
Company Name:	Not reported	
Reporting Officer Name/ID:	Not reported	
Report Date:	Not reported	
Comments:	Not reported	
Facility Telephone:	Not reported	
Waterway Involved:	Not reported	
Waterway:	Not reported	
Spill Site:	Not reported	

EDR ID Number **EPA ID Number** 

## MOBIL, TORRANCE REFINERY (Continued)

Cleanup By: Reporting Party Containment: Not reported Not reported What Happened: Not reported Type: Measure: Not reported Other: Not reported Date/Time: Not reported 2005 Year: Agency: Exxon Mobile Incident Date: 5/12/200512:00:00 AM Admin Agency: **Torrance Fire Department** Not reported Amount: Contained: Unknown Site Type: Refinery E Date: Not reported Substance: nitrogen oxide Not reported Quantity Released: BBLS: 0 Cups: 0 CUFT: 0 Gallons: 0.000000 Grams: 0 Pounds: 10 Liters: 0 Ounces: 0 Pints: 0 Quarts: 0 Sheen: 0 Tons: 0 Unknown: 0 Description: Not reported Evacuations: 0 Number of Injuries: 0 Number of Fatalities: 0 Description:

Database(s)

S100676240

Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes. Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials into he atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and

EDR ID Number Database(s) EPA ID Number

#### MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack. Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred. Crude unit upset, flare was necessary of intermittent basis to control pressures. Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company.Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release.Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring. During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas. Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number: OES notification: OES Date: OES Time: Incident Date: **Date Completed:** Property Use: Agency Id Number: 05-1850 3/24/200504:18:50 PM Not reported Not reported Not reported Not reported Not reported Not reported

Database(s)

EDR ID Number EPA ID Number

## MOBIL, TORRANCE REFINERY (Continued)

Agency Incident Number: Not reported Time Notified: Not reported Not reported Time Completed: Surrounding Area: Not reported **Estimated Temperature:** Not reported Property Management: Not reported Not reported Special Studies 1: **Special Studies 2:** Not reported **Special Studies 3:** Not reported Special Studies 4: Not reported **Special Studies 5:** Not reported **Special Studies 6:** Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Not reported Others Number Of Decontaminated: Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Vehicle License Number: Not reported Vehicle State: Not reported Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Company Name: Not reported Reporting Officer Name/ID: Not reported Report Date: Not reported Comments: Not reported Facility Telephone: Not reported Not reported Waterway Involved: Waterway: Not reported Spill Site: Not reported Reporting Party Cleanup By: Containment: Not reported Not reported What Happened: Not reported Type: Measure: Not reported Other: Not reported Date/Time: Not reported Year: 2005 Exxon Agency: 3/24/200512:00:00 AM Incident Date: Admin Agency: Torrance Fire Department Not reported Amount: Contained: Yes Site Type: Refinery E Date: Not reported Substance: NOX Quantity Released: Not reported BBLS: 0 Cups: 0 CUFT: 0 0.000000 Gallons: Grams: 0 Pounds: 0 0 Liters: Ounces: 0

MOBIL, TORRANCE REFINERY (Continued)

Database(s)

EDR ID Number EPA ID Number

Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
•	
Number of Fatalities: Description:	<sup>6</sup> Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading.Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is orgoing, should be stopped within 10 minutes.Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Mater deluge was used to minimize the release into the air. SMALL release. Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being release in to the air.Unknown circumstances at a truck loading rack.Unknown circumstances acused the release.Unkown under investigation.Unit was blue to on on upright flare.A check valve failed while decompressing a compressor.stou

Database(s) EPA

EDR ID Number EPA ID Number

# MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number:	016572	
OES notification:	Not reported	
OES Date:	11/19/1996	
OES Time:	09:08:49 PM	
Incident Date:	Not reported	
Date Completed:	Not reported	d
Property Use:	Not reported	
Agency Id Number:	Not reported	
Agency Incident Number:	Not reported	
Time Notified:	Not reported	
Time Completed:	Not reported	
Surrounding Area:	Not reported	
Estimated Temperature:	Not reported	
Property Management:	Not reported	
Special Studies 1:	Not reported	
Special Studies 2:	Not reported	
Special Studies 3:	Not reported	
Special Studies 4:	Not reported	
Special Studies 5:	Not reported	
Special Studies 6:	Not reported	
More Than Two Substances I	nvolved?:	Not reported
Resp Agncy Personel # Of De	econtaminated	: Not reported
Responding Agency Persone	I # Of Injuries:	Not reported
Responding Agency Persone		s:Not reported
Others Number Of Decontam	inated:	Not reported
Others Number Of Injuries:		Not reported
Others Number Of Fatalities:		Not reported
Vehicle Make/year:	Not reported	
Vehicle License Number:	Not reported	
Vehicle State:	Not reported	
Vehicle Id Number:	Not reported	
CA/DOT/PUC/ICC Number:	Not reported	
Company Name:	Not reported	

Database(s)

EDR ID Number EPA ID Number

### MOBIL, TORRANCE REFINERY (Continued)

Reporting Officer Name/ID: Report Date: Comments: Facility Telephone: Waterway Involved: YES Waterway: Spill Site: Cleanup By: Containment: What Happened: Type: Measure: Other: Date/Time: Year: 1996 Agency: Incident Date: Admin Agency: Amount: Contained: NO Site Type: REF E Date: Substance: so2 Quantity Released: BBLS: Cups: CUFT: Gallons: Grams: Pounds: Liters: Ounces: Pints: Quarts: Sheen: Tons: Unknown: Description: Evacuations: NO Number of Injuries: NO Number of Fatalities: NO Description:

Not reported Not reported Not reported Not reported Not reported Not reported dissipates Not reported Not reported VAPOR Not reported Not reported Not reported mobile oil refinery 2041/19, Nov 96 Not reported unknown Not reported release started at 2041 and was controlled at 2104 hrs. this release exceeded the 15 min. limit by 8 minutes.

Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading.Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes.Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during

Database(s) Ef

EDR ID Number EPA ID Number

### MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

maintenance on unit. In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC: The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials into he atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures.Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company.Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring. During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas. Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

Database(s)

EDR ID Number **EPA ID Number** 

OES Incident Number: 05-5084 8/30/200509:07:27 PM OES notification: Not reported OES Date: Not reported OES Time: Incident Date: Not reported Not reported Date Completed: Not reported Property Use: Agency Id Number: Not reported Not reported Agency Incident Number: Time Notified: Not reported Time Completed: Not reported Surrounding Area: Not reported Estimated Temperature: Not reported Property Management: Not reported Special Studies 1: Not reported Special Studies 2: Not reported **Special Studies 3:** Not reported **Special Studies 4:** Not reported Special Studies 5: Not reported **Special Studies 6:** Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Vehicle License Number: Not reported Not reported Vehicle State: Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Company Name: Not reported Reporting Officer Name/ID: Not reported Report Date: Not reported Not reported Comments: Facility Telephone: Not reported Waterway Involved: Not reported Waterway: Not reported Spill Site: Not reported Cleanup By: N/A Containment: Not reported What Happened: Not reported Type: Not reported Measure: Not reported Other: Not reported Date/Time: Not reported Year: 2005 Agency: Exxon Mobil 8/30/200512:00:00 AM Incident Date: Admin Agency: **Torrance Fire Department** Amount: Not reported Contained: No Site Type: Refinery E Date: Not reported NOX Substance: Quantity Released: Not reported

Database(s)

EDR ID Number EPA ID Number

,	· · ·
BBLS:	0
Cups:	0
CUFT:	0
Gallons:	0.000000
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	Exceeded lim

eeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes. Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit. In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours. A pipe failure caused the release. Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials intothe atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack. Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures. Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company.Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is

EDR ID Number Database(s) EPA ID Number

### MOBIL, TORRANCE REFINERY (Continued)

### S100676240

leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas. Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number:	05-5731
OES notification:	10/3/200503:16:01 PM
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
Date Completed:	Not reported
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Ir	volved?: Not reported
Resp Agncy Personel # Of De	contaminated: Not reported
Responding Agency Personel	# Of Injuries: Not reported
Responding Agency Personel	# Of Fatalities:Not reported

Not reported

Others Number Of Decontaminated:

Map ID Direction Distance Distance (ft.) Elevation Site MAP FINDINGS

Not reported

Not reported

Database(s)

EDR ID Number **EPA ID Number** 

# MOBIL, TORRANCE REFINERY (Continued)

Others Number Of Injuries: Others Number Of Fatalities: Vehicle Make/year: Not reported Vehicle License Number: Not reported Vehicle State: Not reported Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Company Name: Not reported Reporting Officer Name/ID: Not reported Report Date: Not reported Comments: Not reported Not reported Facility Telephone: Waterway Involved: Not reported Waterway: Not reported Spill Site: Not reported Cleanup By: None Containment: Not reported What Happened: Not reported Type: Not reported Measure: Not reported Other: Not reported Date/Time: Not reported 2005 Year: Agency: Exxon Mobil Incident Date: 10/3/200512:00:00 AM **Torrance Fire Department** Admin Agency: Amount: Not reported Contained: No Site Type: Refinery E Date: Not reported Nitric Oxide Substance: Quantity Released: Not reported BBLS: 0 Cups: 0 CUFT: 0 0.000000 Gallons: Grams: 0 Pounds: 10 Liters: 0 Ounces: 0 Pints: 0 Quarts: 0 Sheen: 0 Tons: 0 Unknown: 0 Description: Not reported Evacuations: 0 Number of Injuries: 0 Number of Fatalities: 0 Description:

Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere. Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed

Database(s) EPA

EDR ID Number EPA ID Number

### MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes.Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit. In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials intothe atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment. Due to flaring. The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower. causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures.Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company. Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring. During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare. Release due to tank car overflow. FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line.

EDR ID Number Database(s) EPA ID Number

S100676240

## MOBIL, TORRANCE REFINERY (Continued)

## Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number:	97-1162
OES notification:	3/21/199703:11:00 AM
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
Date Completed:	Not reported
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
, Special Studies 6:	Not reported
More Than Two Substances I	
Resp Agncy Personel # Of De	contaminated: Not reported
Responding Agency Personel	
Responding Agency Personel	
Others Number Of Decontami	
Others Number Of Injuries:	Not reported
	•
Others Number Of Injuries:	Not reported
Others Number Of Injuries: Others Number Of Fatalities:	Not reported Not reported
Others Number Of Injuries: Others Number Of Fatalities: Vehicle Make/year:	Not reported Not reported Not reported
Others Number Of Injuries: Others Number Of Fatalities: Vehicle Make/year: Vehicle License Number:	Not reported Not reported Not reported Not reported
Others Number Of Injuries: Others Number Of Fatalities: Vehicle Make/year: Vehicle License Number: Vehicle State:	Not reported Not reported Not reported Not reported Not reported
Others Number Of Injuries: Others Number Of Fatalities: Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number:	Not reported Not reported Not reported Not reported Not reported Not reported
Others Number Of Injuries: Others Number Of Fatalities: Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number:	Not reported Not reported Not reported Not reported Not reported Not reported Not reported Not reported
Others Number Of Injuries: Others Number Of Fatalities: Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name:	Not reported Not reported Not reported Not reported Not reported Not reported Not reported Not reported Not reported
Others Number Of Injuries: Others Number Of Fatalities: Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID:	Not reported Not reported Not reported Not reported Not reported Not reported Not reported Not reported Not reported Not reported
Others Number Of Injuries: Others Number Of Fatalities: Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date:	Not reported Not reported
Others Number Of Injuries: Others Number Of Fatalities: Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date: Comments:	Not reported Not reported
Others Number Of Injuries: Others Number Of Fatalities: Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date: Comments: Facility Telephone:	Not reported Not reported
Others Number Of Injuries: Others Number Of Fatalities: Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date: Comments: Facility Telephone: Waterway Involved:	Not reported Not reported
Others Number Of Injuries: Others Number Of Fatalities: Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date: Comments: Facility Telephone: Waterway Involved: Waterway:	Not reported Not reported
Others Number Of Injuries: Others Number Of Fatalities: Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date: Comments: Facility Telephone: Waterway Involved: Waterway: Spill Site:	Not reported Not reported
Others Number Of Injuries: Others Number Of Fatalities: Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date: Comments: Facility Telephone: Waterway Involved: Waterway: Spill Site: Cleanup By:	Not reported Not reported
Others Number Of Injuries: Others Number Of Fatalities: Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date: Comments: Facility Telephone: Waterway Involved: Waterway: Spill Site: Cleanup By: Containment:	Not reported Not reportedNot reported
Others Number Of Injuries: Others Number Of Fatalities: Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date: Comments: Facility Telephone: Waterway Involved: Waterway: Spill Site: Cleanup By: Containment: What Happened:	Not reported Not reportedNot reported
Others Number Of Injuries: Others Number Of Fatalities: Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date: Comments: Facility Telephone: Waterway Involved: Waterway: Spill Site: Cleanup By: Containment: What Happened: Type:	Not reported Not reportedNot reported
Others Number Of Injuries: Others Number Of Fatalities: Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date: Comments: Facility Telephone: Waterway Involved: Waterway: Spill Site: Cleanup By: Containment: What Happened: Type: Measure:	Not reported Not reportedNot reported
Others Number Of Injuries: Others Number Of Fatalities: Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date: Comments: Facility Telephone: Waterway Involved: Waterway: Spill Site: Cleanup By: Containment: What Happened: Type: Measure: Other:	Not reported Not reportedNot reported
Others Number Of Injuries: Others Number Of Fatalities: Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date: Comments: Facility Telephone: Waterway Involved: Waterway: Spill Site: Cleanup By: Containment: What Happened: Type: Measure: Other: Date/Time:	Not reported Not reportedNot
Others Number Of Injuries: Others Number Of Fatalities: Vehicle Make/year: Vehicle License Number: Vehicle State: Vehicle Id Number: CA/DOT/PUC/ICC Number: CA/DOT/PUC/ICC Number: Company Name: Reporting Officer Name/ID: Report Date: Comments: Facility Telephone: Waterway Involved: Waterway Involved: Waterway: Spill Site: Cleanup By: Containment: What Happened: Type: Measure: Other: Date/Time: Year:	Not reported Not reportedNot

Database(s)

EDR ID Number EPA ID Number

	(,
Admin Agency:	Not reported
Amount:	Not reported
Contained:	No
Site Type:	Refinery
E Date:	Not reported
Substance:	HF ACID
Quantity Released:	Not reported
BBLS:	0
Cups:	0
CUFT:	0
Gallons:	0.000000
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	Exceeded lim
	atmosphere [

S100676240

d limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes. Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials into he atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred. Crude unit upset, flare was necessary

Database(s) E

EDR ID Number EPA ID Number

### MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

of intermittent basis to control pressures. Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare. Flaring due to inability to sell refinery fuel gas to local power company.Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed. Line rupture. Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas. Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

**OES Incident Number:** OES notification: OES Date: OES Time: Incident Date: **Date Completed:** Property Use: Agency Id Number: Agency Incident Number: Time Notified: Time Completed: Surrounding Area: Estimated Temperature: Property Management: Special Studies 1: **Special Studies 2:** Special Studies 3: Special Studies 4:

97-1121 3/18/199712:15:15 AM Not reported Not reported

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

### MOBIL, TORRANCE REFINERY (Continued)

Special Studies 5: Not reported **Special Studies 6:** Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Vehicle License Number: Not reported Vehicle State: Not reported Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Company Name: Not reported Reporting Officer Name/ID: Not reported Not reported Report Date: Comments: Not reported Facility Telephone: Not reported Waterway Involved: No Waterway: Not reported Spill Site: Not reported Cleanup By: Reporting Party Containment: Not reported What Happened: Not reported Type: Not reported Measure: Not reported Other: Not reported Date/Time: Not reported 1997 Year: Agency: MOBIL OIL Incident Date: 3/18/199712:00:00 AM Admin Agency: Not reported Amount: Not reported Contained: Yes Site Type: Refinery Not reported E Date: Substance: HF ACID Quantity Released: Not reported BBLS: 0 Cups: 0 CUFT: 0 Gallons: UNK 0 Grams: Pounds: 0 Liters: 0 Ounces: 0 Pints: 0 Quarts: 0 0 Sheen: Tons: 0 Unknown: 0 Description: Not reported Evacuations: 0 Number of Injuries: 0 Number of Fatalities: 0 Description: Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the

Database(s) EPA

EDR ID Number EPA ID Number

### MOBIL, TORRANCE REFINERY (Continued)

### S100676240

atmosphere. Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes. Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials intothe atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack. Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release.Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures. Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company.Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to

Database(s)

EDR ID Number EPA ID Number

# MOBIL, TORRANCE REFINERY (Continued)

### S100676240

substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost.A hydrogen header overpressured and went to flare.An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

	07 000 4
OES Incident Number:	97-0304
OES notification:	1/22/199712:59:45 AM
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
Date Completed:	Not reported
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number: Time Notified:	Not reported
	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6: More Than Two Substances I	Not reported
Resp Agncy Personel # Of De	
Responding Agency Personel	
Responding Agency Personel Others Number Of Decontam	
Others Number Of Injuries:	inated: Not reported Not reported
Others Number Of Fatalities:	
	Not reported
Vehicle Make/year: Vehicle License Number:	Not reported Not reported
Vehicle State:	•
	Not reported
Vehicle Id Number: CA/DOT/PUC/ICC Number:	Not reported
	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported No
Waterway Involved:	
Waterway:	Not reported
Spill Site: Cleanup By:	Not reported
Cleanup By: Containment:	Not reported
	Not reported
What Happened:	Not reported

Database(s)

EDR ID Number EPA ID Number

Туре:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported
Year:	1997
Agency:	MOBIL
Incident Date:	1/21/199712:00:00 AM
Admin Agency:	Torrance Fire Department
Amount:	Not reported
Contained:	Yes
Site Type:	Refinery
E Date:	Not reported
Substance:	KEROSENE
Quantity Released:	Not reported
BBLS:	30
Cups:	0
CUFT:	0
Gallons:	0.000000
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	Exceeded limits between 1
•	

eeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere. Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes.Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit. In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials into he atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity. caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown

EDR ID Number Database(s)

**EPA ID Number** 

### MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

circumstances at a truck loading rack. Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures.Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company. Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring. During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas. Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare. Release due to tank car overflow. FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number:
OES notification:
OES Date:
OES Time:
Incident Date:
Date Completed:
Property Use:
Agency Id Number:
Agency Incident Number:
Time Notified:
Time Completed:

97-0827 2/26/199704:07:20 AM Not reported Not reported

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

#### MOBIL, TORRANCE REFINERY (Continued)

Surrounding Area: Not reported Estimated Temperature: Not reported Property Management: Not reported Special Studies 1: Not reported Special Studies 2: Not reported **Special Studies 3:** Not reported Special Studies 4: Not reported Special Studies 5: Not reported Special Studies 6: Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Vehicle License Number: Not reported Vehicle State: Not reported Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Company Name: Not reported Reporting Officer Name/ID: Not reported Report Date: Not reported Comments: Not reported Facility Telephone: Not reported Waterway Involved: No Waterway: Not reported Spill Site: Not reported Cleanup By: **Reporting Party** Not reported Containment: What Happened: Not reported Not reported Type: Measure: Not reported Other: Not reported Not reported Date/Time: 1997 Year: Agency: MOBIL OIL Incident Date: 2/26/199712:00:00 AM Admin Agency: **Torrance Fire Department** Not reported Amount: Contained: Yes Site Type: Refinery E Date: Not reported COKER HEAVY GAS OIL Substance: Quantity Released: Not reported BBLS: 10 Cups: 0 CUFT: 0 0.000000 Gallons: Grams: 0 Pounds: 0 Liters: 0 0 Ounces: Pints: 0 Quarts: 0 Sheen: 0

Database(s)

EDR ID Number EPA ID Number

IOBIL, TORRANCE REFINERY	(Continued)	S100676240
Tons:	0	
Unknown:	0	
Description:	Not reported	
Evacuations:	0	
Number of Injuries:	0	
Number of Fatalities:	0	
Description:	Exceeded limits between 1542 hrs and 1619 hrs. result	ting in a release to the
Description.	atmosphere.Piggy back of a big rig overturned during a	0
	adjacent to the refinery. Spilled to ground only. Preca	
	area. No water way's involved. Cleanup in progress. T	5
	AQMD. It was a false alarm of the HF sensor, A05027.	<b>u</b> ,
	is false reading. Fuel gas treater malfunctioned at 1315	
	been made to treater and release is going downReleas	-
		-
	exchanger.Pin hole leak in pipeline contained in diked a	•
	a leak.Plug blew out on an exchanger (21E3C) allowing	
	Leak is ongoing, should be stopped within 10 minutes.	•
	F1. Currently contained. Unit shut down at 0538 hrs S	
	release valve lifted when line over pressuredBoth are o	0 0
	in the hydrogen unit #24.Plan Unit shutdown, purging the	0
	the flare.FCC Unit shut down bypassing SCR D7 causi	5
	Release started 08/02/02 and ended 08/04/02A pocket	<b>a</b> 1 <b>a</b>
	maintenance on unit.In a crude unit was upset due to w	•
	caused flaring in exceeded 1500 parts of SO2. Betwee	
	0015hours.A pipe failure caused the release.Released	
	that is used to truck acid in and pumps into the vessel.	Water deluge was used
	to minimize the release into the air. SMALL release. W	
	segregated and treated.per NRC; The caller stated the	
	down on a hydrocracker unit, resulting in a release of n	
	atmosphere.Equipment failure caused the release.Tanl	k 400X31 pressured up and
	company is having to vent to reduce pressureCorrosior	n of a line
	underground.Permit allows on a stack up to 20 opacity	y, caller stated they
	exceed 20 opacity. Still on going and being released i	nto the air.Unknown
	circumstances at a truck loading rack.Unknown circum	stances caused the
	release.Exceded capacity for more than 3 minutes.A m	inor process upset caused
	the release. Unkown under investigation. Unit was shut of	down, depressing to the
	flare, due to faulty equipment.Due to flaring.The release	e is due to a
	flare.Lost compresser, causing the gas to flare.Valve st	tuck closed on tower,
	causing a flare that caused the release. Unit is down, ha	as been controlling
	until this morning when a flare occurred. Crude unit ups	et, flare was necessary
	of intermittent basis to control pressures.Pilots went ou	t on an upright
	flare.A check valve failed while decompressing a comp	ressor.Equipment
	overpressured and released to the flare. Flaring due to	inability to sell
	refinery fuel gas to local power company.Units upset, s	till investigating the
	release. More gas in flare line that recovery can proces	
	overpressured causing the release.Emission from 20F4	
	adjusted.Possible that a pump seal or pipe associated	
	leaking.High temperature has raised tank temp, causin	
	the flare putting tank back into service and flaring the g	
	tank. 510X4 is the # of the tank.Leaking from a railroad	
	at this time. Liquid in the tank, vapor when it hits the air	
	loading rack inside the refinery, no evacuations at this t	
	for the release.2F7 had a unit upset, which caused the	•
	exceeded compliance amount.No mechanical failure w	
	and the substance exceeded the 20 limit. Reason is ur	• •
	failure.Pipe rupture caused the release.Bleeder on sec	
	and caused a leak.2F7 Damper 2D7 failed open causir	•
	Line leak caused the spill.Lost 25 K1C compressor shu	It down causing the

EDR ID Number Database(s) EPA ID Number

S100676240

### MOBIL, TORRANCE REFINERY (Continued)

## release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare. Release due to tank car overflow. FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number:	97-0734	
OES notification:	2/19/199706:04:44 PM	
OES Date:	Not reported	
OES Time:	Not reported	
Incident Date:	Not reported	
Date Completed:	Not reported	ł
Property Use:	Not reported	
Agency Id Number:	Not reported	
Agency Incident Number:	Not reported	
Time Notified:	Not reported	
Time Completed:	Not reported	
Surrounding Area:	Not reported	
Estimated Temperature:	Not reported	
Property Management:	Not reported	
Special Studies 1:	Not reported	
Special Studies 2:	Not reported	
Special Studies 3:	Not reported	
Special Studies 4:	Not reported	
Special Studies 5:	Not reported	
Special Studies 6:	Not reported	
More Than Two Substances In		Not reported
Resp Agncy Personel # Of De	contaminated	Not reported
Responding Agency Personel	# Of Injuries:	Not reported
Responding Agency Personel		
Others Number Of Decontaminated:		Not reported
Others Number Of Injuries:		Not reported
Others Number Of Fatalities:		Not reported
Vehicle Make/year:	Not reported	
Vehicle License Number:	Not reported	
Vehicle State:	Not reported	
Vehicle Id Number:	Not reported	
CA/DOT/PUC/ICC Number:	Not reported	
Company Name:	Not reported	
Reporting Officer Name/ID:	Not reported	
Report Date:	Not reported	
Comments:	Not reported	

Database(s)

EDR ID Number EPA ID Number

## MOBIL, TORRANCE REFINERY (Continued)

Facility Telephone: Not reported Waterway Involved: No Waterway: Not reported Spill Site: Not reported Cleanup By: Reporting Party Containment: Not reported What Happened: Not reported Type: Not reported Measure: Not reported Other: Not reported Date/Time: Not reported Year: 1997 Agency: Mobile Refinery Incident Date: 2/19/199712:00:00 AM Admin Agency: Torrance Fire Department Amount: Not reported Contained: Yes Site Type: Refinery E Date: Not reported VGO (Vacuum Gas Oil) Substance: Quantity Released: Not reported BBLS: 2 Cups: 0 CUFT: 0 0.000000 Gallons: Grams: ٥ Pounds: 0 Liters: 0 Ounces: 0 Pints: 0 Quarts: 0 Sheen: 0 Tons: 0 Unknown: 0 Not reported Description: Evacuations: 0 Number of Injuries: 0 Number of Fatalities: 0 Description:

Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes.Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used

EDR ID Number Database(s) EPA ID Number

MOBIL, TORRANCE REFINERY (Continued)

### S100676240

to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials intothe atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release.Unit is down, has been controlling until this morning when a flare occurred. Crude unit upset, flare was necessary of intermittent basis to control pressures.Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare. Flaring due to inability to sell refinery fuel gas to local power company. Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number: OES notification: OES Date: OES Time: 01-7109 12/8/200112:23:18 AM Not reported Not reported

Database(s)

EDR ID Number EPA ID Number

## MOBIL, TORRANCE REFINERY (Continued)

Incident Date: Not reported **Date Completed:** Not reported Not reported Property Use: Not reported Agency Id Number: Agency Incident Number: Not reported Time Notified: Not reported Time Completed: Not reported Surrounding Area: Not reported Estimated Temperature: Not reported Property Management: Not reported Special Studies 1: Not reported **Special Studies 2:** Not reported Special Studies 3: Not reported Special Studies 4: Not reported Special Studies 5: Not reported Special Studies 6: Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Vehicle License Number: Not reported Vehicle State: Not reported Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Company Name: Not reported Not reported Reporting Officer Name/ID: Report Date: Not reported Comments: Not reported Facility Telephone: Not reported Waterway Involved: No Waterway: Not reported Not reported Spill Site: Cleanup By: N/A Containment: Not reported What Happened: Not reported Type: Not reported Not reported Measure: Other: Not reported Date/Time: Not reported 2001 Year: Agency: Exxon Mobil Incident Date: 12/7/200112:00:00 AM Admin Agency: **Torrance Fire Department** Amount: Not reported Contained: Yes Refinery Site Type: E Date: Not reported Substance: SO2;;; Quantity Released: Not reported BBLS: 0 Cups: 0 CUFT: 0 Gallons: 0

Database(s)

EDR ID Number EPA ID Number

S100676240

Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	unknown
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	Exceeded lin

ded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes. Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials into he atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack. Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures. Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare. Flaring due to inability to sell refinery fuel gas to local power company. Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted.Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the

EDR ID Number Database(s) EPA ID Number

#### MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas. Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare. Release due to tank car overflow. FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

**OES Incident Number:** 01-6648 OES notification: 11/15/200101:53:58 PM Not reported OES Date: OES Time: Not reported Not reported Incident Date: Date Completed: Not reported Property Use: Not reported Not reported Agency Id Number: Agency Incident Number: Not reported Time Notified: Not reported Time Completed: Not reported Surrounding Area: Not reported Estimated Temperature: Not reported Property Management: Not reported Special Studies 1: Not reported Special Studies 2: Not reported **Special Studies 3:** Not reported Special Studies 4: Not reported **Special Studies 5:** Not reported **Special Studies 6:** Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/vear: Not reported Vehicle License Number: Not reported

EDR ID Number **EPA ID Number** 

#### MOBIL, TORRANCE REFINERY (Continued)

Vehicle State: Not reported Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Not reported Company Name: Reporting Officer Name/ID: Not reported Report Date: Not reported Comments: Not reported Facility Telephone: Not reported Waterway Involved: No Waterway: Not reported Spill Site: Not reported **Reporting Party** Cleanup By: Containment: Not reported What Happened: Not reported Type: Not reported Measure: Not reported Not reported Other: Date/Time: Not reported Year: 2001 Agency: Exxon Mobil Incident Date: 11/15/200112:00:00 AM Admin Agency: Torrance Fire Department Amount: Not reported Contained: Yes Site Type: Refinery E Date: Not reported Hydrogen Floric;;; Substance: Quantity Released: Not reported BBLS: 0 Cups: 0 CUFT: 0 Gallons: 0 Grams: 0 Pounds: 1 Liters: 0 0 Ounces: Pints: 0 Quarts: 0 Sheen: 0 Tons: 0 0.000000 Unknown: Not reported Description: Evacuations: 0 Number of Injuries: 0 Number of Fatalities: 0 Description:

Database(s)

S100676240

Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes. Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA

Database(s) El

EDR ID Number EPA ID Number

### MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit. In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials intothe atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment. Due to flaring. The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures.Pilots went out on an upright flare. A check valve failed while decompressing a compressor. Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company. Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH. Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of

Database(s) EPA I

EDR ID Number EPA ID Number

S100676240

## MOBIL, TORRANCE REFINERY (Continued)

emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number:	05-7459
OES notification:	12/27/200508:54:08 AM
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
Date Completed:	Not reported
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances In	
Resp Agncy Personel # Of De	•
Responding Agency Personel	
Responding Agency Personel	
Others Number Of Decontamir	
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	Not reported
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By:	Reporting Party
Containment:	Not reported
What Happened:	
Туре:	Not reported
Type.	Not reported
Measure:	Not reported Not reported
	Not reported
Measure:	Not reported Not reported Not reported Not reported
Measure: Other:	Not reported Not reported Not reported
Measure: Other: Date/Time: Year:	Not reported Not reported Not reported Not reported Not reported
Measure: Other: Date/Time:	Not reported Not reported Not reported Not reported 2005
Measure: Other: Date/Time: Year: Agency: Incident Date:	Not reported Not reported Not reported Not reported 2005 Exxon Mobil Torrance
Measure: Other: Date/Time: Year: Agency:	Not reported Not reported Not reported Not reported 2005 Exxon Mobil Torrance 12/27/200512:00:00 AM
Measure: Other: Date/Time: Year: Agency: Incident Date: Admin Agency:	Not reported Not reported Not reported Not reported 2005 Exxon Mobil Torrance 12/27/200512:00:00 AM Torrance Fire Department
Measure: Other: Date/Time: Year: Agency: Incident Date: Admin Agency: Amount:	Not reported Not reported Not reported Not reported 2005 Exxon Mobil Torrance 12/27/200512:00:00 AM Torrance Fire Department Not reported

Database(s)

EDR ID Number EPA ID Number

E Date:	Not reported
Substance:	Caustic (hydrogen Sulfide)
Quantity Released:	Not reported
BBLS:	0
Cups:	0
CUFT:	0
Gallons:	10-15
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0
Description:	Exceeded limits between 1

S100676240

0	
0	
Exceeded limits between 1542 hrs and 1619 hrs. resu atmosphere.Piggy back of a big rig overturned during	5
adjacent to the refinery. Spilled to ground only. Prec	
area. No water way's involved. Cleanup in progress.	
AQMD. It was a false alarm of the HF sensor, A05027	<b>3</b>
is false reading. Fuel gas treater malfunctioned at 131	5 hrs. Adjustments have
been made to treater and release is going downRelea	se caused by a leak in an
exchanger.Pin hole leak in pipeline contained in dikec	area.Flow line developed
a leak.Plug blew out on an exchanger (21E3C) allowing	ng substance to escape.
Leak is ongoing, should be stopped within 10 minutes	Line rupture on line 24
F1. Currently contained. Unit shut down at 0538 hrs	See also 99-3174.1 inch
release valve lifted when line over pressuredBoth are	
in the hydrogen unit #24.Plan Unit shutdown, purging	
the flare.FCC Unit shut down bypassing SCR D7 cause	0
Release started 08/02/02 and ended 08/04/02A pocket	5 I S
maintenance on unit.In a crude unit was upset due to	
caused flaring in exceeded 1500 parts of SO2. Betwe	
0015hours.A pipe failure caused the release.Release	
that is used to truck acid in and pumps into the vessel	
to minimize the release into the air. SMALL release.	
segregated and treated.per NRC; The caller stated th	
down on a hydrocracker unit, resulting in a release of	
atmosphere.Equipment failure caused the release.Tai company is having to vent to reduce pressureCorrosic	
underground.Permit allows on a stack up to 20 opac	
exceed 20 opacity. Still on going and being released	
circumstances at a truck loading rack.Unknown circur	
release.Exceded capacity for more than 3 minutes.A	
the release.Unkown under investigation.Unit was shu	
flare, due to faulty equipment.Due to flaring.The relea	
flare.Lost compresser, causing the gas to flare.Valve	
causing a flare that caused the release.Unit is down, I	
until this morning when a flare occurred.Crude unit up	0
of intermittent basis to control pressures.Pilots went o	
flare.A check valve failed while decompressing a com	
overpressured and released to the flare.Flaring due to	inability to sell
refinery fuel gas to local power company.Units upset,	

Database(s) EPA II

EDR ID Number EPA ID Number

### MOBIL, TORRANCE REFINERY (Continued)

S100676240

release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted.Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas. Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

OES Incident Number:	97-3695	
OES notification:	9/20/199709:24:31 AM	
OES Date:	Not reported	
OES Time:	Not reported	
Incident Date:	Not reported	
Date Completed:	Not reported	
Property Use:	Not reported	
Agency Id Number:	Not reported	
Agency Incident Number:	Not reported	
Time Notified:	Not reported	
Time Completed:	Not reported	
Surrounding Area:	Not reported	
Estimated Temperature:	Not reported	
Property Management:	Not reported	
Special Studies 1:	Not reported	
Special Studies 2:	Not reported	
Special Studies 3:	Not reported	
Special Studies 4:	Not reported	
Special Studies 5:	Not reported	
Special Studies 6:	Not reported	
More Than Two Substances Involved?: Not reported		
Deep Agency Demond # Of Decenteminated Net reported		

Resp Agncy Personel # Of Decontaminated: Not reported

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

## MOBIL, TORRANCE REFINERY (Continued)

Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Vehicle License Number: Not reported Vehicle State: Not reported Not reported Vehicle Id Number: CA/DOT/PUC/ICC Number: Not reported Not reported Company Name: Reporting Officer Name/ID: Not reported Report Date: Not reported Comments: Not reported Facility Telephone: Not reported Waterway Involved: No Waterway: Not reported Spill Site: Not reported Cleanup By: Reporting Party Containment: Not reported What Happened: Not reported Type: Not reported Not reported Measure: Other: Not reported Date/Time: Not reported 1997 Year: Agency: MOBIL OIL Incident Date: 9/20/199712:00:00 AM Admin Agency: **Torrance Fire Department** Amount: Not reported Contained: Yes Site Type: Refinery E Date: Not reported Substance: SULFURIC ACID Not reported Quantity Released: BBLS: 0 Cups: 0 CUFT: 0 Gallons: 10 Grams: 0 Pounds: 0 Liters: 0 Ounces: 0 Pints: 0 Quarts: 0 Sheen: 0 Tons: 0 Unknown: 0 Description: Not reported 0 Evacuations: Number of Injuries: 0 Number of Fatalities: 0 Description:

Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere.Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it

EDR ID Number Database(s) EPA ID Number

#### MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes.Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials into he atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the flare, due to faulty equipment.Due to flaring.The release is due to a flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release. Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures. Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company.Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas. Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment

Database(s)

EDR ID Number EPA ID Number

## MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare. Release due to tank car overflow. FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed. BELIEVED TO BE AN UNDERGROUND LEAK. APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH. Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment. Line integrity broke down causing a crack and subsequent release

	crack and subsequent release
OES Incident Number:	02-3732
OES notification:	7/9/200205:02:18 PM
OES Date:	Not reported
OES Time:	Not reported
Incident Date:	Not reported
Date Completed:	Not reported
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances Ir	volved?: Not reported
Resp Agncy Personel # Of De	
Responding Agency Personel	
Responding Agency Personel	•
Others Number Of Decontamin	nated: Not reported
Others Number Of Injuries:	Not reported
Others Number Of Fatalities:	Not reported
Vehicle Make/year:	Not reported
Vehicle License Number:	Not reported
Vehicle State:	Not reported
Vehicle Id Number:	Not reported
CA/DOT/PUC/ICC Number:	Not reported
Company Name:	Not reported
Reporting Officer Name/ID:	Not reported
Report Date:	Not reported
Comments:	Not reported
Facility Telephone:	Not reported
Waterway Involved:	No
Waterway:	Not reported
Spill Site:	Not reported
Cleanup By:	N/A
Containment:	Not reported
What Happened:	Not reported
Type:	Not reported
Measure:	Not reported
Other:	Not reported
Date/Time:	Not reported

Database(s)

EDR ID Number EPA ID Number

S100676240

#### Year: 2002 Exxon-Mobil Agency: Incident Date: 7/9/200212:00:00 AM Admin Agency: Torrance Fire Department Amount: Not reported Contained: No Site Type: Refinery E Date: Not reported Substance: SO2 Quantity Released: Not reported BBLS: 0 Cups: 0 CUFT: 0 0.000000 Gallons: Grams: 0 Pounds: 500 Liters: 0 Ounces: 0 Pints: 0 Quarts: 0 0 Sheen: Tons: 0 Unknown: 0 Description: Not reported Evacuations: 0 Number of Injuries: 0 Number of Fatalities: 0 Description: Exceeded limits between 1542 hrs and 1619 hrs. resulting in a release to the atmosphere. Piggy back of a big rig overturned during a U-turn on a roadway adjacent to the refinery. Spilled to ground only. Precautionary evacuation of area. No water way's involved. Cleanup in progress. The alarm goes directly to AQMD. It was a false alarm of the HF sensor, A05027. It came in at 6 ppm and it is false reading. Fuel gas treater malfunctioned at 1315 hrs. Adjustments have been made to treater and release is going downRelease caused by a leak in an exchanger.Pin hole leak in pipeline contained in diked area.Flow line developed a leak.Plug blew out on an exchanger (21E3C) allowing substance to escape. Leak is ongoing, should be stopped within 10 minutes. Line rupture on line 24 F1. Currently contained. Unit shut down at 0538 hrs See also 99-3174.1 inch release valve lifted when line over pressuredBoth are ongoing. Failure in PSA in the hydrogen unit #24.Plan Unit shutdown, purging the unit with nitrogen to the flare.FCC Unit shut down bypassing SCR D7 causing the release to occur. Release started 08/02/02 and ended 08/04/02A pocket of gas developed during maintenance on unit.In a crude unit was upset due to water in the process, caused flaring in exceeded 1500 parts of SO2. Between 2345 and finish time 0015hours.A pipe failure caused the release.Released occurred on an inlet line that is used to truck acid in and pumps into the vessel. Water deluge was used to minimize the release into the air. SMALL release. Water used will be segregated and treated.per NRC; The caller stated they had a compressor shut down on a hydrocracker unit, resulting in a release of materials intothe atmosphere.Equipment failure caused the release.Tank 400X31 pressured up and company is having to vent to reduce pressureCorrosion of a line underground.Permit allows on a stack up to 20 opacity, caller stated they exceed 20 opacity. Still on going and being released into the air.Unknown circumstances at a truck loading rack.Unknown circumstances caused the release.Exceded capacity for more than 3 minutes.A minor process upset caused the release.Unkown under investigation.Unit was shut down, depressing to the

flare, due to faulty equipment.Due to flaring.The release is due to a

EDR ID Number Database(s) EPA ID Number

MOBIL, TORRANCE REFINERY (Continued)

#### S100676240

flare.Lost compresser, causing the gas to flare.Valve stuck closed on tower, causing a flare that caused the release.Unit is down, has been controlling until this morning when a flare occurred.Crude unit upset, flare was necessary of intermittent basis to control pressures. Pilots went out on an upright flare.A check valve failed while decompressing a compressor.Equipment overpressured and released to the flare.Flaring due to inability to sell refinery fuel gas to local power company.Units upset, still investigating the release. More gas in flare line that recovery can process.510X4 tank overpressured causing the release. Emission from 20F4P Stack, the mix is being adjusted. Possible that a pump seal or pipe associated with the pump is leaking.High temperature has raised tank temp, causing PO gas to be released to the flare.putting tank back into service and flaring the gases that was in the tank. 510X4 is the # of the tank.Leaking from a railroad car that is 1/4 full at this time. Liquid in the tank, vapor when it hits the air. The car is at the loading rack inside the refinery, no evacuations at this time.Unknown reason for the release.2F7 had a unit upset, which caused the release.The plant exceeded compliance amount.No mechanical failure while company was blowing dust and the substance exceeded the 20 limit. Reason is unknown.equipment failure.Pipe rupture caused the release.Bleeder on section of piping was opened and caused a leak.2F7 Damper 2D7 failed open causing the release.Underground Line leak caused the spill.Lost 25 K1C compressor shut down causing the release. This is a flaring event. Overfilled a rail car during loading. Spent Caustic release with PH of 15 spilled to ground. Area was flushed to the on site storm sewer. PH in sewer is 14.Fan trip caused the release.A leak in an 8" line has caused the release.Loader thought rail car was empty it overflowed.Line rupture.Release due to compressor shutdown due to a drop in pressure on the C-O Flush System. This resulted in a NOX release from a flare stack.Release is from equipment shut down due to unknown cause.Release due to substance going to flare, tank depressuring.During unit startup nitrogen heated up on 24c50 causing a flaring of the excess gas.Release due to a lot of rain water in a short period of time and their sewer backed up onto soil.Release due to loss of SCR to 1F1-2 due to weather. 1K3 is the equipment that was lost. A hydrogen header overpressured and went to flare. An upset of refinery caused release to flare.Release due to tank car overflow.FAILURE OF ROOF DRAIN CAUSED LIQUID TO DRAIN IN TANK FIREWALLLeak on transfer line. Isolated and cleanup completed.BELIEVED TO BE AN UNDERGROUND LEAK.APPEARS TO BE A BULLPLUG LEAK THAT CAUSED RELEASESMALL LEAKS DETECTED DURING STARTUP PROCEDURESCONTAINER FAILURE CAUSED SUBSTANCE TO EAT THROUGH.Seal failed causing release and fire. Cleanup by ACTIPotential release of higher release of emissions due to a breakdown of equipment.Line integrity broke down causing a crack and subsequent release

Toxic Pits: Region: 04 Task #: 84009 Owner: MOBIL OIL CORPORATION 1/2 Mi Limit: Num. of Pits: 1 Cease Discharge Due: 11 Cease Discharge Complete: 06/29/88 Closure Due: 06/30/91 **Closure Completed:** 08/01/91 Status: CLOSED Hydro Geological Assessment Report Due: 11 Final Hydro Geological Assessment Review Completed: 01/19/89

Database(s)

EDR ID Number EPA ID Number

## MOBIL, TORRANCE REFINERY (Continued)

SLIC:	
Region:	STATE
Global Id:	SL372452438
Assigned Name:	SLICSITE
Lead Agency Contact:	ELIZABETH ERICKSON
Lead Agency:	LOS ANGELES RWQCB (REGION 4)
Lead Agency Case Number:	0234
Responsible Party:	Mobil Oil Corporation
Recent Dtw:	Not reported
Substance Released:	PET, VOC
Facility Status:	Remedial Action Underway

## EMI:

Year: Carbon Monoxide Emissions Tons/Yr: Air Basin: Facility ID: Air District Name: SIC Code: Air District Name: Community Health Air Pollution Info System: Consolidated Emission Reporting Rule: Total Organic Hydrocarbon Gases Tons/Yr: Reactive Organic Gases Tons/Yr: Reactive Organic Gases Tons/Yr: Carbon Monoxide Emissions Tons/Yr: NOX - Oxides of Nitrogen Tons/Yr: SOX - Oxides of Sulphur Tons/Yr: Particulate Matter Tons/Yr:	1990 19 SC 59290 SC 2911 SOUTH COAST AQMD Not reported Not reported 1 1 0 0 0 0 0 0 0
Year:	2001
Carbon Monoxide Emissions Tons/Yr:	19
Air Basin:	SC
Facility ID:	800171
Air District Name:	SC
SIC Code:	5171
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info System:	Y
Consolidated Emission Reporting Rule:	B
Total Organic Hydrocarbon Gases Tons/Yr:	47
Reactive Organic Gases Tons/Yr:	24
Reactive Organic Gases Tons/Yr:	1
Carbon Monoxide Emissions Tons/Yr:	3
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0

# S100676240

Map ID Direction Distance Elevation Site

Database(s)

RCRA-TSDF

CORRACTS

CERC-NFRAP FTTS

ENVIROSTOR

**HIST FTTS** 

EDR ID Number EPA ID Number

FINDS 1000253665 HAZNET 90509MBLLC37 RCRA-LQG TRIS

Site 2 of 2 in cluster E Relative:

Higher

Actual: 72 ft.

FINDS:

Other Pertinent Environmental Activity Identified at Site

Not reported

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

California - Hazardous Waste Tracking System - Datamart

NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.

TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

NJ-NJEMS (New Jersey - New Jersey Environmental Management System). The Department of Environmental Protection (NJDEP) manages large databases of environmental information in this integrated system.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance

Database(s)

EDR ID Number EPA ID Number

#### MOBIL OIL CORP (Continued)

information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and its Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

RACT/BACT/LAER Clearinghouse (RBLC) data base contains case-specific information on the 'Best Available' air pollution technologies that have been required to reduce the emission of air pollutants from stationary sources (e.g., power plants, steel mills, chemical plants, etc.). This information has been provided by State and local permitting agencies. The Clearinghouse also contains a regulation data base that summarizes EPA emission limits required in New Source Performance Standards (NSPS), National Emission Standards for Hazardous Air Pollutants (NESHAP), and Maximum Achievable Control Technology (MACT) standards.

PCS (Permit Compliance System) is a computerized management information system that contains data on National Pollutant Discharge Elimination System (NPDES) permit holding facilities. PCS tracks the permit, compliance, and enforcement status of NPDES facilities.

## HAZNET:

Gepaid: Contact: Telephone: Facility Addr2: Mailing Name: Mailing Address: Mailing City,St,Zip: Gen County: TSD EPA ID: TSD County: Waste Category: Disposal Method: Tons: Facility County:	CAD008354052 MOBIL 2133282550 Not reported 3700 W 190TH ST TORRANCE, CA 905092929 Los Angeles AZD983473539 99 Liquids with polychlorinated biphenyls > 50 mg/l Recycler 8.29 Los Angeles
Gepaid:	CAD008354052
Contact:	MOBIL
Telephone:	2133282550
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	3700 W 190TH ST
Mailing City,St,Zip:	TORRANCE, CA 905092929
Gen County:	Los Angeles
TSD EPA ID:	CAD008302903
TSD County:	Los Angeles
Waste Category:	Not reported
Disposal Method:	Transfer Station

#### 1000253665

Database(s)

EDR ID Number EPA ID Number

### MOBIL OIL CORP (Continued)

Tons: 0 Facility County: Los Angeles Gepaid: CAD008354052 Contact: MOBIL Telephone: 2133282550 Facility Addr2: Not reported Mailing Name: Not reported Mailing Address: 3700 W 190TH ST Mailing City, St, Zip: TORRANCE, CA 905092929 Gen County: Los Angeles TSD EPA ID: CAD008302903 TSD County: Los Angeles Waste Category: Aqueous solution with less than 10% total organic residues **Disposal Method:** Not reported Tons: 4.6495 Facility County: Los Angeles CAD008354052 Gepaid: MOBIL Contact: Telephone: 2133282550 Facility Addr2: Not reported Mailing Name: Not reported Mailing Address: 3700 W 190TH ST Mailing City, St, Zip: TORRANCE, CA 905092929 Gen County: Los Angeles CAD008302903 TSD EPA ID: TSD County: Los Angeles Waste Category: Other organic solids **Disposal Method:** Recycler Tons: 0.4 Facility County: Los Angeles CAD008354052 Gepaid: MOBIL Contact: Telephone: 2133282550 Facility Addr2: Not reported Mailing Name: Not reported Mailing Address: 3700 W 190TH ST Mailing City,St,Zip: TORRANCE, CA 905092929 Gen County: Los Angeles TSD EPA ID: CAD028409019 TSD County: Los Angeles Unspecified solvent mixture Waste Waste Category: Transfer Station **Disposal Method:** Tons: 1.251 Facility County: Los Angeles

<u>Click this hyperlink</u> while viewing on your computer to access 304 additional CA\_HAZNET: record(s) in the EDR Site Report.

Database(s) E

EDR ID Number EPA ID Number

## MOBIL OIL CORP (Continued)

1000253665

Event:	ctive Action Summary: Igration of Contaminated Groundwater under Control, Yes, Migration of Contaminated Groundwater Under Control has been verified. Based on a review of information contained in the EI determination, it has been determined that migration of contaminated groundwater is under control at the facility. Specifically, this determination indicates that the migration of contaminated groundwater is under control, and that monitoring will be conducted to confirm that contaminated groundwater remains within the existing area of contaminated groundwater. This determination will be re-evaluated when the Agency becomes aware of significant changes at the facility.
Event Date:	04/07/2006
Event:	Current Human Exposures under Control, Yes, Current Human Exposures Under Control has been verified. Based on a review of information contained in the El determination, current human exposures are expected to be under control at the facility under current and reasonably expected conditions. This determination will be re-evaluated when the Agency/State becomes aware of significant changes at the facility.
Event Date:	09/26/2003
Event: Event Date:	Igration of Contaminated Groundwater under Control, Unacceptable migration of contaminated groundwater is observed or expected. 03/09/2001
Event:	Current Human Exposures under Control, Current human exposures are NOT under
Event Date:	control. 03/09/2001
Event:	CA Prioritization, Facility or area was assigned a high corrective action
Event Date:	priority. 09/21/1994
Event: Event Date:	Stabilization Measures Evaluation, This facility is amenable to stabilization activity based on the status of corrective action work at the facility, technical factors, the degree of risk, timing considerations and administrative considerations. 09/21/1994
Event:	Stabilization Construction Completed
Event Date:	06/30/1993
Event: Event Date:	Stabilization Measures Implemented, Primary measure is source removal and/or treatment (e.g., soil or waste excavation, in-situ soil treatment, off-site treatment). 09/01/1991
Event: Event Date:	RFI Approved 10/03/1990
Event:	Current Human Exposures under Control, Current human exposures are NOT under
Event Date:	control. 08/31/1990
Event:	Igration of Contaminated Groundwater under Control, Yes, Migration of Contaminated Groundwater Under Control has been verified. Based on a review of information contained in the EI determination, it has been determined that migration of contaminated groundwater is under control at the facility. Specifically, this determination indicates that the migration of contaminated groundwater is under control, and that monitoring will be conducted to confirm that contaminated groundwater remains within the existing area of contaminated groundwater. This determination will be re-evaluated when the Agency becomes aware of significant changes at the facility.

Database(s)

EDR ID Number **EPA ID Number** 

1000253665

# MOBIL OIL CORP (Continued)

IOBI	LOILCORP (C	Continued)			
E	Event Date:	08/31/1990			
E	Event:	CA Prioritization, Facility o priority.	r area was a	ssigned a	high corrective action
E	Event Date:	05/21/1990			
	Event: Event Date:	Stabilization Construction 11/30/1989	Completed		
	Event: Event Date:	RFI Workplan Approved 05/12/1988			
-	Event: Event Date:	RFI Imposition 02/25/1985			
E	Event:	Stabilization Measures Imp (e.g., to achieve groundwa			er extraction and treatment nieve MCL).
E	Event Date:	02/05/1985			
RC	RAInfo:				
(	Owner: EPA ID:	EXXONMOBIL OIL CORP CAD008354052			
(	Contact:	STEVE GIFFIN (310) 212-1991			
	Classification: TSDF Activities:	Large Quantity Generator, Not reported	TSDF		
	NNIAL REPOR Last Biennial Re	TS: porting Year: 2005			
-		uantity (Lbs)		<u>Waste</u>	Quantity (Lbs)
	D001	336638.71		D002	759517.24
	D003	27262.71		D004	153060.00
	D005	8341.00		D006	8341.00
	D007	8433.00		D008	123882.00
	D009	13853.00		D010	750.00
	D011 D039	8433.00 13258.00		D018 F001	384999.00 13258.00
	F002	4917.00		F001 F003	17779.00
	F002 F005	6472.00		F003 F037	147260.00
	K050	102761.00		K051	101765.00
	P105	7.00		U210	8341.00
١	Violation Status:	Violations exist			
	Regulation Viol	ated:	Not reported	1	
Area of Violation:				S/PREVENTION REQUIREM	

Area of Violation:

Penalty Type:

Area of Violation:

Penalty Type:

Regulation Violated:

TSD-PREPAREDNESS/PREVENTION REQUIREMENTS Date Violation Determined: 04/23/2003 Actual Date Achieved Compliance: Not reported WRITTEN INFORMAL **Enforcement Action:** 09/27/2005 Enforcement Action Date: Not reported Not reported GENERATOR-PRE-TRANSPORT REQUIREMENTS Date Violation Determined: 04/24/2001 Actual Date Achieved Compliance: 04/26/2001 Enforcement Action: WRITTEN INFORMAL

Enforcement Action Date: 04/26/2001 Not reported

Database(s)

EDR ID Number EPA ID Number

1000253665

#### MOBIL OIL CORP (Continued)

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action:

Not reported GENERATOR-OTHER REQUIREMENTS 04/24/2001 04/26/2001

WRITTEN INFORMAL 04/26/2001 Not reported

Not reported TSD-GENERAL STANDARDS 04/24/2001 04/26/2001

WRITTEN INFORMAL 04/26/2001 Not reported

Not reported TSD-GENERAL STANDARDS 04/18/2000 04/18/2000

WRITTEN INFORMAL 07/03/2000 Not reported

262.50-60 GENERATOR-ALL REQUIREMENTS (OVERSIGHT) 02/27/1996 06/02/1999

WRITTEN INFORMAL 02/15/1996 Not reported

262.20-23.B GENERATOR-ALL REQUIREMENTS (OVERSIGHT) 02/15/1996 06/02/1999

WRITTEN INFORMAL 02/15/1996 Not reported

264.10-18.B TSD-OTHER REQUIREMENTS (OVERSIGHT) 06/19/1995 12/04/1995

WRITTEN INFORMAL 06/19/1995 Not reported

FINAL 3008(A) COMPLIANCE ORDER 06/19/1995 Not reported

264.170-177.I TSD-OTHER REQUIREMENTS (OVERSIGHT) 07/09/1993 09/30/1993

WRITTEN INFORMAL

Database(s)

EDR ID Number EPA ID Number

1000253665

#### MOBIL OIL CORP (Continued)

Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: 07/09/1993 Not reported 270 TSD-OTHER REQUIREMENTS (OVERSIGHT) 07/09/1993 09/30/1993 WRITTEN INFORMAL 07/09/1993 Not reported 264.70-77.E TSD-OTHER REQUIREMENTS (OVERSIGHT) 07/09/1993 09/30/1993 WRITTEN INFORMAL 07/09/1993 Not reported 262.30-34.C **GENERATOR-ALL REQUIREMENTS (OVERSIGHT)** 07/09/1993 09/30/1993 WRITTEN INFORMAL 07/09/1993 Not reported 264.30-37.C TSD-OTHER REQUIREMENTS (OVERSIGHT) 07/09/1993 09/30/1993 WRITTEN INFORMAL 07/09/1993 Not reported 264.50-56.D TSD-OTHER REQUIREMENTS (OVERSIGHT) 07/09/1993 09/30/1993 WRITTEN INFORMAL 07/09/1993 Not reported 268 ALL **TSD-LAND BAN REQUIREMENTS** 07/09/1993 09/30/1993 WRITTEN INFORMAL 07/09/1993 Not reported 262.50-60 GENERATOR-ALL REQUIREMENTS (OVERSIGHT) 04/09/1992

WRITTEN INFORMAL 04/09/1992

07/10/1992

Database(s)

EDR ID Number EPA ID Number

1000253665

#### MOBIL OIL CORP (Continued)

Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type: Not reported

264.140-150.H TSD-FINANCIAL RESPONSIBILITY REQUIREMENTS 11/30/1989 04/25/1990

WRITTEN INFORMAL 12/07/1989 Not reported

268.7 GENERATOR-LAND BAN REQUIREMENTS 11/21/1989 10/24/1991

WRITTEN INFORMAL 01/05/1990 Not reported

268 ALL TSD-LAND BAN REQUIREMENTS 11/21/1989 04/05/1990

WRITTEN INFORMAL 01/05/1990 Not reported

270 TSD-OTHER REQUIREMENTS (OVERSIGHT) 11/21/1989 10/24/1991

WRITTEN INFORMAL 01/05/1990 Not reported

264.70-77.E TSD-OTHER REQUIREMENTS (OVERSIGHT) 11/21/1989 10/24/1991

WRITTEN INFORMAL 01/05/1990 Not reported

268.7 GENERATOR-LAND BAN REQUIREMENTS 11/15/1988 03/30/1989

WRITTEN INFORMAL 12/22/1988 Not reported

264.70-77.E TSD-OTHER REQUIREMENTS (OVERSIGHT) 11/15/1988 03/30/1989

WRITTEN INFORMAL 12/22/1988 Not reported TSD-OTHER REQUIREMENTS (OVERSIGHT)

TSD-CLOSURE/POST-CLOSURE REQUIREMENTS

TSD-FINANCIAL RESPONSIBILITY REQUIREMENTS

TSD-OTHER REQUIREMENTS (OVERSIGHT)

TSD-OTHER REQUIREMENTS (OVERSIGHT)

270

11/15/1988

03/30/1989

12/22/1988

Not reported

11/15/1988

03/30/1989

12/22/1988

Not reported

11/15/1988

03/30/1989

12/22/1988

Not reported

04/14/1988

11/07/1988

04/26/1988

Not reported

12/09/1987 03/30/1989

01/12/1988

03/18/1987 03/30/1989

06/15/1987

Not reported

Not reported

270

270

264.140-150.H

268 ALL

264.110-120.G

WRITTEN INFORMAL

WRITTEN INFORMAL

WRITTEN INFORMAL

WRITTEN INFORMAL

WRITTEN INFORMAL

WRITTEN INFORMAL

TSD-LAND BAN REQUIREMENTS

Database(s)

EDR ID Number EPA ID Number

#### MOBIL OIL CORP (Continued)

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Penalty Summary:

Penalty Description

Final Monetary Penalty Proposed Monetary Penalty Penalty Date -----8/31/1993 8/31/1993

There are 29 violation record(s) reported at this site:

**Evaluation** 

Area of Violation

Lead Agency

STATE

STATE

Penalty Amount

1300

1300

Date of Compliance

1000253665

Database(s) EPA II

EDR ID Number EPA ID Number

1000253665

## MOBIL OIL CORP (Continued)

Compliance Evaluation Inspection	TSD-PREPAREDNESS/PREVENTION REQUIREMENTS	
Compliance Evaluation Inspection	TSD-GENERAL STANDARDS	20010426
	GENERATOR-OTHER REQUIREMENTS	20010426
	GENERATOR-PRE-TRANSPORT REQUIREMENTS	20010426
Compliance Evaluation Inspection	TSD-GENERAL STANDARDS	20000418
Compliance Evaluation Inspection	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)	19990602
	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)	19990602
Compliance Evaluation Inspection	TSD-OTHER REQUIREMENTS (OVERSIGHT)	19951204
Compliance Evaluation Inspection	TSD-OTHER REQUIREMENTS (OVERSIGHT)	19930930
	TSD-OTHER REQUIREMENTS (OVERSIGHT)	19930930
	TSD-OTHER REQUIREMENTS (OVERSIGHT)	19930930
	TSD-LAND BAN REQUIREMENTS	19930930
	TSD-OTHER REQUIREMENTS (OVERSIGHT)	19930930
	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)	19930930
	TSD-OTHER REQUIREMENTS (OVERSIGHT)	19930930
Compliance Evaluation Inspection	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)	19920710
Financial Record Review	TSD-FINANCIAL RESPONSIBILITY REQUIREMENTS	19900425
Compliance Evaluation Inspection	TSD-LAND BAN REQUIREMENTS	19900405
	TSD-OTHER REQUIREMENTS (OVERSIGHT)	19911024
	TSD-OTHER REQUIREMENTS (OVERSIGHT)	19911024
	GENERATOR-LAND BAN REQUIREMENTS	19911024
Compliance Evaluation Inspection	TSD-LAND BAN REQUIREMENTS	19890330
	TSD-CLOSURE/POST-CLOSURE REQUIREMENTS	19890330
	TSD-OTHER REQUIREMENTS (OVERSIGHT)	19890330
	GENERATOR-LAND BAN REQUIREMENTS	19890330
	TSD-OTHER REQUIREMENTS (OVERSIGHT)	19890330
Financial Record Review	TSD-FINANCIAL RESPONSIBILITY REQUIREMENTS	19881107
Compliance Evaluation Inspection	TSD-OTHER REQUIREMENTS (OVERSIGHT)	19890330
Non-Financial Record Review	TSD-OTHER REQUIREMENTS (OVERSIGHT)	19890330

# CORRACTS:

EPA ID: EPA Region: Area Name: Actual Date: Action: NAICS Code(s):	CAD008354052 09 GROUNDWATER 02/05/1985 CA600GW - Stabilization Measures Implemented, Groundwater extraction and treatment 32411 Petroleum Refineries
EPA ID: EPA Region: Area Name: Actual Date: Action: NAICS Code(s):	CAD008354052 09 GROUNDWATER 02/25/1985 CA100 - RFI Imposition 32411 Petroleum Refineries
EPA ID: EPA Region: Area Name: Actual Date: Action: NAICS Code(s):	CAD008354052 09 ENTIRE FACILITY 02/25/1985 CA100 - RFI Imposition 32411 Petroleum Refineries

Database(s)

EDR ID Number EPA ID Number

# MOBIL OIL CORP (Continued)

1000253665

BIL OIL CORP (Continued)					
EPA ID: EPA Region: Area Name: Actual Date: Action:	CAD008354052 09 ENTIRE FACILITY 03/09/2001 CA750NO - Migration of Contaminated Groundwater under Control, Unacceptable migration of contaminated groundwater is observed or expected				
NAICS Code(s):	32411 Petroleum Refineries				
EPA ID: EPA Region: Area Name: Actual Date: Action: NAICS Code(s):	CAD008354052 09 ENTIRE FACILITY 03/09/2001 CA725NO - Current Human Exposures Under Control, Current human exposures are NOT under control 32411 Petroleum Refineries				
EPA ID: EPA Region: Area Name: Actual Date: Action: NAICS Code(s):	CAD008354052 09 ENTIRE FACILITY 04/07/2006 CA750YE - Migration of Contaminated Groundwater under Control, Yes, Migration of Contaminated Groundwater Under Control has been verified 32411 Petroleum Refineries				
EPA ID: EPA Region: Area Name: Actual Date: Action: NAICS Code(s):	CAD008354052 09 GROUNDWATER 05/12/1988 CA150 - RFI Workplan Approved 32411 Petroleum Refineries				
EPA ID: EPA Region: Area Name: Actual Date: Action: NAICS Code(s):	CAD008354052 09 ENTIRE FACILITY 05/21/1990 CA075HI - CA Prioritization, Facility or area was assigned a high corrective action priority 32411 Petroleum Refineries				
EPA ID: EPA Region: Area Name: Actual Date: Action: NAICS Code(s):	CAD008354052 09 ENTIRE FACILITY 06/30/1993 CA650 - Stabilization Construction Completed 32411 Petroleum Refineries				
EPA ID: EPA Region: Area Name: Actual Date:	CAD008354052 09 ENTIRE FACILITY 08/31/1990				

Database(s) EPA ID I

EDR ID Number EPA ID Number

1000253665

#### MOBIL OIL CORP (Continued) Action: CA750YE - Migration of Contaminated Groundwater under Control, Yes, Migration of Contaminated Groundwater Under Control has been verified 32411 NAICS Code(s): Petroleum Refineries CAD008354052 EPA ID: EPA Region: 09 Area Name: ENTIRE FACILITY Actual Date: 08/31/1990 Action: CA725NO - Current Human Exposures Under Control, Current human exposures are NOT under control 32411 NAICS Code(s): **Petroleum Refineries** EPA ID: CAD008354052 EPA Region: 09 ENTIRE FACILITY Area Name: Actual Date: 09/01/1991 Action: CA600SR - Stabilization Measures Implemented, Primary measure is source removal and/or treatment NAICS Code(s): 32411 **Petroleum Refineries** EPA ID: CAD008354052 EPA Region: 09 Area Name: ENTIRE FACILITY Actual Date: 09/21/1994 Action: CA225YE - Stabilization Measures Evaluation, This facility ,is amenable to stabilization activity based on the, status of corrective action work at the facility, technical factors, the degree of risk, timing considerations and administrative considerations NAICS Code(s): 32411 Petroleum Refineries EPA ID: CAD008354052 EPA Region: 09 ENTIRE FACILITY Area Name: Actual Date: 09/21/1994 Action: CA075HI - CA Prioritization, Facility or area was assigned a high corrective action priority NAICS Code(s): 32411 Petroleum Refineries EPA ID: CAD008354052 EPA Region: 09 ENTIRE FACILITY Area Name: Actual Date: 09/26/2003 Action: CA725YE - Current Human Exposures Under Control, Yes, Current Human Exposures Under Control has been verified NAICS Code(s): 32411 **Petroleum Refineries** CAD008354052 EPA ID: EPA Region: 09 GROUNDWATER Area Name: Actual Date: 10/03/1990 CA200 - RFI Approved Action:

MOBIL OIL CORP (Continued)

NAICS Code(s): 32411 **Petroleum Refineries** EPA ID: CAD008354052 EPA Region: 09 Area Name: GROUNDWATER Actual Date: 11/30/1989 Action: CA650 - Stabilization Construction Completed NAICS Code(s): 32411 **Petroleum Refineries** CERC-NFRAP: 0901077 Site ID: Federal Facility: Not a Federal Facility NPL Status: Not on the NPL NFRAP Non NPL Status: CERCLIS-NFRAP Site Contact Name(s): Matt Mitguard Contact Name: Contact Tel: (415) 972-3096 Contact Title: Site Assessment Manager (SAM) Contact Name: Jere Johnson Contact Tel: (415) 972-3094 Contact Title: Site Assessment Manager (SAM) Site Description: Not reported CERCLIS-NFRAP Assessment History: DISCOVERY Action: Date Started: Not reported Date Completed: 08/01/1980 Priority Level: Not reported PRELIMINARY ASSESSMENT Action: 04/01/1985 Date Started: Date Completed: 02/01/1986 Priority Level: Low PRELIMINARY ASSESSMENT Action: Date Started: Not reported Date Completed: 11/23/1988 Priority Level: Low ARCHIVE SITE Action: Date Started: Not reported Date Completed: 05/21/1990 Priority Level: Not reported PRELIMINARY ASSESSMENT Action: Date Started: Not reported Date Completed: 05/21/1990 Priority Level: NFRAP (No Futher Remedial Action Planned FTTS INSP: Inspection Number: 19870813CA001 1

EDR ID Number EPA ID Number

1000253665

Database(s)

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number **EPA ID Number** 

#### MOBIL OIL CORP (Continued) Region: 09 08/13/1987 Inspection Date: BERMAN Inspector: Violation occurred: Yes Section 6 PCB State Conducted Investigation Type: Investigation Reason: Neutral Scheme, State Legislation Code: TSCA Facility Function: User ENVIROSTOR: Site Type: Historical Site Type Detailed: \* Historical Acres: Not reported NPL: NO NONE SPECIFIED **Regulatory Agencies:** NONE SPECIFIED Lead Agency: Program Manager: Not reported Supervisor: Referred - Not Assigned **Division Branch:** So Cal - Cypress 19290134 Facility ID: Site Code: 400098 Assembly: 53 28 Senate: \* RCRA 3012 - Past Haz Waste Disp Inven Site Special Program: Status: Refer: RCRA 1996-09-27 00:00:00 Status Date: **Restricted Use:** NO Funding: Not reported 33.858055555556 Latitude: Longitude: -118.33694444444 Alias Name: CAD008354052 MOBIL OIL CORPORATION, TORRANCE 19290134 400098 Alias Type: **EPA Identification Number** Project Code (Site Code) Envirostor ID Number Alternate Name NONE SPECIFIED APN: **APN Description:** Not reported Comments: DECERTIFICATION. Mobil Oil, Torrance is an active facility. The site was identified as a certification due to an audit performed by the Auditor General's Office. Since the facility is still operating, the site cannot be considered remediated. TheSite is on the June 30, 1991 Chronological List of Certified Remediated and Delisted Sites as being certified in 1985.SOURCE ACT: REFINERY YR OF OPER: 1929 TO PRESENT ENF HISTORY: 9/16/80 VIO OF CA ADMINI- STRATIVE CODE-USE UNREGISTERED HAULER & FAILURE TO MANIFEST WASTE. PRELIM ASSESS DONE RCRA 3012FACILITY IDENTIFIED HMMS/ENF INSPECTION SAMPLE RESULTS

	chronological list of certified sites.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Name:	Not reported
Completed Document Type:	Removal Action Completion Report
Completed Date:	1985-12-31 00:00:00
Completed Area Name:	PROJECT WIDE

HMNS/ENF SAMPLES TAKEN RESULTS ON FILEsite has been deleted from

### 1000253665

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

1000253665

#### MOBIL OIL CORP (Continued)

Completed Sub Area Name: Not reported Preliminary Assessment Report Completed Document Type: Completed Date: 1984-04-01 00:00:00 Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported Completed Document Type: **De-Certification** Completed Date: 1996-09-27 00:00:00 Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported Completed Document Type: Certification Completed Date: 1985-12-31 00:00:00 Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported Completed Document Type: Discovery Completed Date: 1979-01-31 00:00:00 NONE SPECIFIED Confirmed: Confirmed Description: Not reported Future Area Name: Not reported Future Sub Area Name: Not reported Future Document Type: Not reported Future Due Date: Not reported Media Affected: NONE SPECIFIED Media Affected Desc: Not reported Management Required: NONE SPECIFIED Management Required Desc: Not reported 10009, 10060, 10061, 10183, 10197, 10199 Potential: Potenital Description: \* HYDROCARBON SOLVENTS Potenital Description: \* OIL/WATER SEPARATION SLUDGE \* ORGANIC LIQUIDS WITH METALS Potenital Description: \* STILL BOTTOMS WITH HALOGENATED ORGANICS Potenital Description: \* UNSPECIFIED SLUDGE WASTE Potenital Description: Potenital Description: \* WASTE OIL & MIXED OIL Schedule Area Name: Not reported Schedule Sub Area Name: Not reported Not reported Schedule Document Type: Not reported Schedule Due Date: Not reported Schedule Revised Date: PastUse: NONE SPECIFIED HIST FTTS INSP:

Inspection Number:	19870813CA001 1
Region:	09
Inspection Date:	Not reported
Inspector:	BERMAN
Violation occurred:	Yes
Investigation Type:	Section 6 PCB State Conducted
Investigation Reason:	Neutral Scheme, State
Legislation Code:	TSCA
Facility Function:	User

Database(s)

EDR ID Number EPA ID Number

HUGHES AIRCRAFT CO./SC 19300 GRAMERCY PLACE TORRANCE, CA 90503	i	ENVIROSTOR	S105954427 N/A
Site 1 of 2 in cluster F			
ENVIROSTOR: Site Type: Site Type Detailed: Acres: NPL: Regulatory Agencies: Lead Agency: Program Manager: Supervisor: Division Branch: Facility ID: Site Code: Assembly: Senate: Special Program: Status: Status Date:	Evaluation 7 NO SMBRP, US EPA US EPA Not reported Greg Holmes So Cal - Cypress 19990042 400279 53 28 Not reported No Further Action		
Restricted Use:			
Funding: Latitude: Longitude: Alias Name:	33.8551506024096 -118.315075 HUGHES AIRCRAFT CO/SPACE & COMMUN GROUP 19990042 CAX000129049		
Alias Type:	Project Code (Site Code) EPA Identification Number Envirostor ID Number		
Completed Document Ty Completed Date: Confirmed: Confirmed Description: Future Area Name: Future Sub Area Name: Future Document Type: Future Due Date: Media Affected: Media Affected Desc: Management Required D Potential: Potenital Description: Potenital Description: Potenital Description: Potenital Description: Schedule Area Name: Schedule Sub Area Name	NONE SPECIFIED Not reported PA approved by EPA. No further action required. PROJECT WIDE Not reported Preliminary Endangerment Assessment Report 2003-02-05 00:000 NONE SPECIFIED Not reported Not reported Not reported Not reported Not reported Not reported NMA Not reported NONE SPECIFIED SSC: Not reported 30013, 30160, 30407 Lead Cyanide (free) Nickel Not reported		
	19300 GRAMERCY PLACE TORRANCE, CA 90503 Site 1 of 2 in cluster F ENVIROSTOR: Site Type Detailed: Acres: NPL: Regulatory Agencies: Lead Agency: Program Manager: Supervisor: Division Branch: Facility ID: Site Code: Assembly: Senate: Special Program: Status: Status Date: Restricted Use: Funding: Latitude: Longitude: Alias Name: Alias Name: Alias Type: APN: APN Description: Completed Area Name: Completed Sub Area Name Completed Document Typ Completed Date: Confirmed: Confirmed: Confirmed: Confirmed: Confirmed: Future Area Name: Future Sub Area Name: Future Sub Area Name: Future Due Date: Media Affected: Media Affected:	TORRANCE, CA 90503         Site Type:         ENVIROSTOR:         Site Type:         Acres:         7         Not reported         Supervisor:         Greg Holmes         Division Branch:         So Cal - Cypress         Facility ID:         1990042         Stet Code:         Adsembly:         Sambly:         Sambly:         Sambly:         Sambly:         Sambly:         Sambly:         Sambly:         Sambly:         Sampe:         Not reported         Status:         Not reported         Colspan= 2         CAX000123049 <td>19300 GRAMERCY PLACE TORRANCE, CA 99503 Site 1 of 2 in cluster F ENVIROSTOR: Site Type Detailed: Evaluation Acres: Acres: NO Regulatory Agencies: NO Regulatory Agencies: SMERP, US EPA Lead Agency: US EPA Lead Agency: US EPA Lead Agency: US EPA Lead Agency: US EPA Lead Agency: US EPA Program Manage: Not reported Soc Cal - Cypress Facility ID: 1990042 Site Code: 400279 Assembly: Site 2003-02-05 00:000 Restricted Use: NO Funding: EPA Grant Latitude: 33.8551506024096 Longitude: HUGHES AIRCRAFT CO/SPACE &amp; COMMUN GROUP 19990042 Attention Number Envirosor ID Number Envirosor ID Number Attention Number Envirosor ID Number Envirosor ID Number Attention Number Envirosor ID Number E</td>	19300 GRAMERCY PLACE TORRANCE, CA 99503 Site 1 of 2 in cluster F ENVIROSTOR: Site Type Detailed: Evaluation Acres: Acres: NO Regulatory Agencies: NO Regulatory Agencies: SMERP, US EPA Lead Agency: US EPA Lead Agency: US EPA Lead Agency: US EPA Lead Agency: US EPA Lead Agency: US EPA Program Manage: Not reported Soc Cal - Cypress Facility ID: 1990042 Site Code: 400279 Assembly: Site 2003-02-05 00:000 Restricted Use: NO Funding: EPA Grant Latitude: 33.8551506024096 Longitude: HUGHES AIRCRAFT CO/SPACE & COMMUN GROUP 19990042 Attention Number Envirosor ID Number Envirosor ID Number Attention Number Envirosor ID Number Envirosor ID Number Attention Number Envirosor ID Number E

Database(s)

EDR ID Number EPA ID Number

Elevation	Site		Database(s)	EPA ID Number		
	HUGHES AIRCRAFT CO./SCG (Continued)					
	Schedule Due Schedule Revis PastUse:					
F32 ESE 1/2-1 3247 ft.	HUGHES AIRCRAF 19300 GRAMERCY TORRANCE, CA 90	PLACE	RCRA-SQG FINDS RCRA-TSDF CORRACTS	1000241007 CAD981440068		
Relative:	Site 2 of 2 in cluste	r F	CERC-NFRAP			
Higher	RCRAInfo Correct Event:	tive Action Summary: Stabilization Measures Evaluation,This facility is not amenable to				
Actual: 65 ft.		stabilization interstues Evaluation, this facility is not amenable to stabilization activity at the present time for reasons other than 1) it appears to be technically infeasible or inappropriate (NF) or 2) there is a lack of technical information (IN). Reasons for this conclusion may be the status of closure at the facility, the degree of risk, timing considerations, the status of corrective action work at the facility, or other administrative considerations.				
	Event Date:	02/12/1997				
	Event: Event Date:	CA Prioritization, Facility or area was assigned a medium corrective ac priority. 02/12/1997	tion			
	RCRAInfo: Owner: EPA ID:	NOT REQUIRED (415) 555-1212 CAD981440068				
	Contact:	Not reported				
	Classification: TSDF Activities	TSDF				
	Violation Status	s: No violations found				
	FINDS: Other Pertinent	<ul> <li>Environmental Activity Identified at Site</li> <li>TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.</li> <li>RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RC program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.</li> </ul>	g of			

CORRACTS:

CAD981440068
09
ENTIRE FACILITY
02/12/1997

TC2051883.2s Page 315

) Site		Database(s)	EDR ID Nun EPA ID Nun
HUGHES AIRCRAFT CO	IPANY SCG (Continued)		1000241007
Action:	CA225NR - Stabilization Measures Evaluation, This amenable to stabilization activity at the, present time other than (1) it appears to be technically, infeasible inappropriate (NF) or (2) there is a lack of technical, (IN). Reasons for this conclusion may be the status facility, the degree of risk, timing considerations, the corrective action work at the facility, or other, admini considerations	e for reasons or information of, closure at the status of	
NAICS Code(s):	Not reported		
EPA ID: EPA Region: Area Name: Actual Date:	CAD981440068 09 ENTIRE FACILITY 02/12/1997		
Action: NAICS Code(s):	CA075ME - CA Prioritization, Facility or area was as corrective action priority Not reported	ssigned a medium	
CERC-NFRAP:	0005131		
Site ID:	0905121		
Federal Facility:	Not a Federal Facility		
NPL Status: Non NPL Status:	Not on the NPL NFRAP		
CERCLIS-NFRAP Site			
Contact Name:	Matt Mitguard		
Contact Tel:	(415) 972-3096		
Contact Title:	Site Assessment Manager (SAM)		
Contact Name:	Jere Johnson		
Contact Tel:	(415) 972-3094		
Contact Title:	Site Assessment Manager (SAM)		
Contact Name:	Dan McMindes		
Contact Tel:	(415) 972-3401		
Contact Title:	Site Assessment Manager (SAM)		
Site Description: N	t reported		
CERCLIS-NFRAP Asse			
Action:	DISCOVERY		
Date Started: Date Completed:	Not reported		
	08/03/1994 Not reported		
Priority Level:	Not reported		
Action:	PRELIMINARY ASSESSMENT		
Date Started:	07/01/2002		
Date Completed:	02/05/2003		
Priority Level:	NFRAP (No Futher Remedial Action Planned		
Action:	ARCHIVE SITE		
Date Started:	Not reported		
Date Completed:	06/23/2003		
Priority Level:	Not reported		

Amount:

Database(s)

EDR ID Number EPA ID Number

G33 South 1/2-1 4256 ft.	305 CRENSHAW TORRANCE, CA 90503			E	CHMIRS CA WDS NVIROSTOR	S100229499 N/A
4230 n.	Site 1 of 2 in cluster G					
Relative:						
Higher	CHMIRS:	0000004				
Actual:	OES Incident Number: OES notification:	8888084 Not reported				
70 ft.	OES Date:	Not reported				
	OES Time:	Not reported				
	Incident Date:	22-MAR-88				
	Date Completed:	22-MAR-88				
	Property Use:	762				
	Agency Id Number:	19200				
	Agency Incident Number:	86607				
	Time Notified:	1139				
	Time Completed:	1225				
	Surrounding Area: Estimated Temperature:	767				
	Property Management:	75 P				
	Special Studies 1:	Not reported				
	Special Studies 2:	Not reported				
	Special Studies 3:	Not reported				
	Special Studies 4:	Not reported				
	Special Studies 5:	Not reported				
	Special Studies 6:	Not reported				
	More Than Two Substances I		N Net see astad			
	Resp Agncy Personel # Of De Responding Agency Personel		•			
	Responding Agency Personel		•			
	Others Number Of Decontami		Not reported			
	Others Number Of Injuries:		Not reported			
	Others Number Of Fatalities:		Not reported			
	Vehicle Make/year:	Not reported				
	Vehicle License Number:	Not reported				
	Vehicle State:	Not reported				
	Vehicle Id Number: CA/DOT/PUC/ICC Number:	Not reported				
	Company Name:	Not reported Not reported				
	Reporting Officer Name/ID:	DOUGLAS K	MATSON			
	Report Date:	22-MAR-88				
	Comments:	Ν				
	Facility Telephone:	213 530-2468	3			
	Waterway Involved:	Not reported				
	Waterway:	Not reported				
	Spill Site:	Not reported				
	Cleanup By: Containment:	Not reported Not reported				
	What Happened:	Not reported				
	Type:	Not reported				
	Measure:	Not reported				
	Other:	Not reported				
	Date/Time:	Not reported				
	Year:	88-92				
	Agency:	Not reported				
	Incident Date:	Not reported				
	Admin Agency: Amount	Not reported				

Not reported

Database(s)

EDR ID Number EPA ID Number

S100229499

#### (Continued)

Contained: Not reported Not reported Site Type: Not reported E Date: Substance: Not reported Quantity Released: Not reported BBLS: Not reported Not reported Cups: CUFT: Not reported Gallons: Not reported Grams: Not reported Not reported Pounds: Not reported Liters: Ounces: Not reported Pints: Not reported Quarts: Not reported Sheen: Not reported Not reported Tons: Unknown: Not reported Description: Not reported Evacuations: Not reported Number of Injuries: Not reported Number of Fatalities: Not reported Description: Tote was moved with a fork lift and it spilled itInsulated line sprung a leak causing the spill.DOW Chemical Plant: switch failed, product over flowed from tank **OES Incident Number:** 8801677 **OES** notification: Not reported OES Date: Not reported OES Time: Not reported 24-MAY-88 Incident Date: Date Completed: 24-MAY-88 Property Use: 762 Agency Id Number: 19200 Agency Incident Number: 87983 Time Notified: 1942 Time Completed: 2015 Surrounding Area: 767 Estimated Temperature: 65 Property Management: Р Not reported Special Studies 1: Special Studies 2: Not reported Special Studies 3: Not reported Special Studies 4: Not reported Special Studies 5: Not reported **Special Studies 6:** Not reported More Than Two Substances Involved?: Ν Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Vehicle License Number: Not reported Vehicle State: Not reported Vehicle Id Number: Not reported

(Continued)

MAP FINDINGS

Database(s)

EDR ID Number EPA ID Number

#### CA/DOT/PUC/ICC Number: Not reported Not reported Company Name: Reporting Officer Name/ID: DOUGLAS K MATSON (5950) Report Date: 23-MAY-88 Comments: Ν 213 618-2920 Facility Telephone: Waterway Involved: Not reported Waterway: Not reported Spill Site: Not reported Cleanup By: Not reported Containment: Not reported What Happened: Not reported Type: Not reported Measure: Not reported Other: Not reported Date/Time: Not reported 88-92 Year: Agency: Not reported Incident Date: Not reported Admin Agency: Not reported Not reported Amount: Contained: Not reported Site Type: Not reported E Date: Not reported Substance: Not reported Quantity Released: Not reported BBLS: Not reported Cups: Not reported CUFT: Not reported Gallons: Not reported Not reported Grams: Pounds: Not reported Liters: Not reported Ounces: Not reported Pints: Not reported Not reported Quarts: Sheen: Not reported Tons: Not reported Unknown: Not reported Description: Not reported Evacuations: Not reported Number of Injuries: Not reported Number of Fatalities: Not reported Description: Tote was moved with a fork lift and it spilled itInsulated line sprung a leak causing the spill.DOW Chemical Plant: switch failed, product over flowed from tank **OES Incident Number:** 99-1993 OES notification: 5/10/199909:30:29 AM OES Date: Not reported OES Time: Not reported Incident Date: Not reported Not reported **Date Completed:** Not reported Property Use: Agency Id Number: Not reported Agency Incident Number: Not reported Time Notified: Not reported

#### S100229499

Database(s)

EDR ID Number EPA ID Number

S100229499

#### (Continued)

Time Completed: Not reported Not reported Surrounding Area: Not reported Estimated Temperature: Not reported Property Management: Special Studies 1: Not reported Special Studies 2: Not reported Special Studies 3: Not reported Special Studies 4: Not reported Special Studies 5: Not reported Special Studies 6: Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Vehicle License Number: Not reported Vehicle State: Not reported Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Company Name: Not reported Reporting Officer Name/ID: Not reported Report Date: Not reported Comments: Not reported Facility Telephone: Not reported Waterway Involved: No Waterway: Not reported Not reported Spill Site: Reporting Party Cleanup By: Containment: Not reported What Happened: Not reported Type: Not reported Measure: Not reported Other: Not reported Not reported Date/Time: Year: 1999 Agency: **Dow Chemical** Incident Date: 5/10/199912:00:00 AM **Torrance Fire Department** Admin Agency: Amount: Not reported Contained: Yes Site Type: Merchant/Business E Date: Not reported Substance: Recycle (Styrine Ethyl Benzine and Water) Quantity Released: Not reported BBLS: 0 Cups: 0 CUFT: 0 Gallons: 250 Grams: 0 Pounds: 0 Liters: 0 Ounces: 0 Pints: 0 Quarts: 0

Other:

Not reported

Database(s)

EDR ID Number EPA ID Number

#### (Continued) S100229499 Sheen: 0 0 Tons: Unknown: 0 Description: Not reported Evacuations: 0 Number of Injuries: 0 Number of Fatalities: 0 Description: Tote was moved with a fork lift and it spilled itInsulated line sprung a leak causing the spill.DOW Chemical Plant: switch failed, product over flowed from tank OES Incident Number: 99-4593 10/28/199904:43:54 PM OES notification: OES Date: Not reported OES Time: Not reported Incident Date: Not reported Date Completed: Not reported Property Use: Not reported Agency Id Number: Not reported Agency Incident Number: Not reported Time Notified: Not reported Time Completed: Not reported Surrounding Area: Not reported Estimated Temperature: Not reported Property Management: Not reported Special Studies 1: Not reported **Special Studies 2:** Not reported **Special Studies 3:** Not reported Special Studies 4: Not reported Not reported Special Studies 5: Special Studies 6: Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Vehicle Make/year: Not reported Vehicle License Number: Not reported Vehicle State: Not reported Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Company Name: Not reported Reporting Officer Name/ID: Not reported Report Date: Not reported Comments: Not reported Facility Telephone: Not reported Waterway Involved: No Waterway: Not reported Spill Site: Not reported Cleanup By: Reporting Party Containment: Not reported What Happened: Not reported Type: Not reported Measure: Not reported

Database(s)

EDR ID Number EPA ID Number

(Continued)	S100229499
Date/Time:	Not reported
Year:	1999
Agency:	Torrance FD
Incident Date:	10/28/199912:00:00 AM
Admin Agency:	Torrance Fire Department
Amount:	Not reported
Contained:	Yes
Site Type:	Merchant/Business
E Date:	Not reported
Substance:	Styrene
Quantity Released:	Not reported
BBLS:	0
Cups:	0
CUFT:	0
Gallons:	100
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	
Description:	Tote was moved with a fork lift and it spilled itInsulated line sprung a leak causing the spill.DOW Chemical Plant: switch failed, product over flowed from tank
OES Incident Number:	007316
OES notification:	Not reported
OES Date:	3/14/1995
OES Time:	05:59:10 AM
Incident Date:	Not reported
Date Completed:	Not reported
Property Use:	Not reported
Agency Id Number:	Not reported
Agency Incident Number:	Not reported
Time Notified:	Not reported
Time Completed:	Not reported
Surrounding Area:	Not reported
Estimated Temperature:	Not reported
Property Management:	Not reported
Special Studies 1:	Not reported
Special Studies 2:	Not reported
Special Studies 3:	Not reported
Special Studies 4:	Not reported
Special Studies 5:	Not reported
Special Studies 6:	Not reported
More Than Two Substances I	
Resp Agncy Personel # Of De Responding Agency Persone	
Responding Agency Persone	
Others Number Of Decontam	

Database(s)

EDR ID Number EPA ID Number

## (Continued)

Others Number Of Injuries: Not reported Not reported Others Number Of Fatalities: Vehicle Make/year: Not reported Vehicle License Number: Not reported Vehicle State: Not reported Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Company Name: Not reported Reporting Officer Name/ID: Not reported Report Date: Not reported Not reported Comments: Facility Telephone: Not reported Waterway Involved: YES Waterway: Not reported Spill Site: Not reported Cleanup By: dow chemical Containment: Not reported What Happened: Not reported Type: CHEMICAL Measure: Not reported Not reported Other: Date/Time: Not reported 1995 Year: Agency: DOW CHEMICAL Incident Date: 0524 14 Mar 95 Not reported Admin Agency: Amount: 15,000 LBS (POTENTIAL) Contained: NO Site Type: PL E Date: Not reported STYRENE Substance: Quantity Released: Not reported BBLS: Not reported Cups: Not reported CUFT: Not reported Not reported Gallons: Not reported Grams: Pounds: Not reported Liters: Not reported Ounces: Not reported Pints: Not reported Not reported Quarts: Sheen: Not reported Not reported Tons: Not reported Unknown: Description: tranfer occurring between two process vessels and seal between vessels started leaking. stainless steel tote located under spill containing the leak. area itself also has concrete containment. Evacuations: NO NO Number of Injuries: Number of Fatalities: NO Description: Tote was moved with a fork lift and it spilled itInsulated line sprung a leak causing the spill.DOW Chemical Plant: switch failed, product over flowed from tank **OES Incident Number:** 02-2892 OES notification: 5/30/200203:01:49 PM

Database(s)

EDR ID Number EPA ID Number

#### (Continued)

OES Date: Not reported OES Time: Not reported Not reported Incident Date: Not reported **Date Completed:** Property Use: Not reported Agency Id Number: Not reported Agency Incident Number: Not reported Time Notified: Not reported Time Completed: Not reported Surrounding Area: Not reported Estimated Temperature: Not reported Property Management: Not reported Special Studies 1: Not reported **Special Studies 2:** Not reported **Special Studies 3:** Not reported Special Studies 4: Not reported **Special Studies 5:** Not reported **Special Studies 6:** Not reported More Than Two Substances Involved?: Not reported Resp Agncy Personel # Of Decontaminated: Not reported Responding Agency Personel # Of Injuries: Not reported Responding Agency Personel # Of Fatalities:Not reported Others Number Of Decontaminated: Not reported Others Number Of Injuries: Not reported Others Number Of Fatalities: Not reported Not reported Vehicle Make/year: Vehicle License Number: Not reported Vehicle State: Not reported Vehicle Id Number: Not reported CA/DOT/PUC/ICC Number: Not reported Company Name: Not reported Reporting Officer Name/ID: Not reported Report Date: Not reported Comments: Not reported Facility Telephone: Not reported Waterway Involved: No Waterway: Not reported Spill Site: Not reported Cleanup By: Contractor Containment: Not reported What Happened: Not reported Type: Not reported Measure: Not reported Other: Not reported Date/Time: Not reported Year: 2002 Torrance FD Agency: Incident Date: 5/30/200212:00:00 AM Admin Agency: **Torrance Fire Department** Amount: Not reported Contained: Yes Site Type: Industrial Plant E Date: Not reported Substance: Dowtherm A, heat transfer fluid Quantity Released: Not reported BBLS: 0 0 Cups:

#### S100229499

Database(s)

EDR ID Number EPA ID Number

Continued)	S100229499
CUFT:	0
Gallons:	5
Grams:	0
Pounds:	0
Liters:	0
Ounces:	0
Pints:	0
Quarts:	0
Sheen:	0
Tons:	0
Unknown:	0 National state
Description:	Not reported
Evacuations:	0
Number of Injuries:	0
Number of Fatalities:	0 Tate was moved with a fark lift and it spilled itlesulated line enruge a look
Description:	Tote was moved with a fork lift and it spilled itInsulated line sprung a leak causing the spill.DOW Chemical Plant: switch failed, product over flowed from tank
CA WDS:	
Facility ID:	4 191003192
Facility Type:	Other - Does not fall into the category of Municipal/Domestic,
	Industrial, Agricultural or Solid Waste (Class I, II or III)
Facility Status:	Active - Any facility with a continuous or seasonal discharge that is
	under Waste Discharge Requirements.
NPDES Number:	CAS000001 The 1st 2 characters designate the state. The remaining 7
	are assigned by the Regional Board
Subregion:	4
Facility Telephone:	Not reported
Facility Contact:	Not reported
Agency Name:	DOW CHEMICAL CO.
Agency Address:	Not reported
Agency City,St,Zip:	0
Agency Contact:	Not reported
Agency Telephone:	Not reported
Agency Type:	Private
SIC Code:	0
SIC Code 2:	Not reported
Primary Waste:	Not reported
Primary Waste Type:	Not reported
Secondary Waste:	Not reported
Secondary Waste Type	e: Not reported
Design Flow:	0
Baseline Flow:	0
Reclamation:	Not reported
POTW:	Not reported
Treat To Water:	Minor Threat to Water Quality. A violation of a regional board order
	should cause a relatively minor impairment of beneficial uses compared
	to a major or minor threat. Not: All nurds without a TTWQ will be
	considered a minor threat to water quality unless coded at a higher
	Level. A Zero (0) may be used to code those NURDS that are found to
<b>0 1 1</b>	represent no threat to water quality.
Complexity:	Category C - Facilities having no waste treatment systems, such as
	cooling water dischargers or thosewho must comply through best
	management practices, facilities with passive waste treatment and
	disposal systems, such as septic systems with subsurface disposal, or dischargers having waste storage systems with land disposal such as
	dischargers hoving wests storage systems with land dispessal such as

Database(s)

EDR ID Number EPA ID Number

S100229499

#### (Continued)

Media Affected Desc:

Management Required:

Management Required Desc: Not reported

dairy waste ponds. ENVIROSTOR: Site Type: Historical Site Type Detailed: \* Historical Not reported Acres: NPI · NO NONE SPECIFIED **Regulatory Agencies:** Lead Agency: NONE SPECIFIED Program Manager: Not reported Supervisor: \* MMONROY So Cal - Cypress **Division Branch:** Facility ID: 19280123 Site Code: 601125 Assembly: 53 28 Senate: Special Program: \* Site Char & Assess Grant (CERCLA 104) Status: Refer: RCRA Status Date: 1995-03-01 00:00:00 Restricted Use: NO Funding: Not reported Latitude: 33.8430555555556 Longitude: -118.328888888888 Alias Name: 19280123 CAD009547050 SANTA FE ENERGY COMPANY CHANSLOR-CANFIELD MIDWAY OIL COMPANY DOW CHEMICAL - TORRANCE (WESTERN DIV) 601125 Envirostor ID Number Alias Type: **EPA Identification Number** Project Code (Site Code) Alternate Name Alternate Name Alternate Name APN: NONE SPECIFIED **APN Description:** Not reported Comments: NFA for Site Mitigation Operations, this is a RCRA facility.Facility identified via tip; Referral by ASP (Sac) employee. PROJECT WIDE Completed Area Name: Completed Sub Area Name: Not reported Completed Document Type: Discovery Completed Date: 1981-09-04 00:00:00 Completed Area Name: PROJECT WIDE Completed Sub Area Name: Not reported Completed Document Type: Site Screening Completed Date: 1995-03-01 00:00:00 NONE SPECIFIED Confirmed: Confirmed Description: Not reported Future Area Name: Not reported Not reported Future Sub Area Name: Future Document Type: Not reported Future Due Date: Not reported NONE SPECIFIED Media Affected:

Not reported

NONE SPECIFIED

Map ID Direction			MAP FINDINGS		
Distance Distance (ft. Elevation	) Site			Database(s)	EDR ID Number EPA ID Number
	(Continued)				S100229499
	Potential: Potenital Descri Potenital Descri Potenital Descri Potenital Descri Potenital Descri Potenital Descri Potenital Descri Potenital Descri Potenital Descri Schedule Area I Schedule Sub A Schedule Docur Schedule Due D Schedule Revis PastUse:	ption: ption: ption: ption: ption: ption: ption: ption: Name: Area Name: ment Type: Date:	10009, 10067, 10097, 40001, 10183, 10198, 10199, 2000 * HYDROCARBON SOLVENTS * OXYGENATED SOLVENTS * CONTAMINATED SOIL Not reported * STILL BOTTOMS WITH HALOGENATED ORGANICS * UNSPECIFIED SOLVENT MIXTURES * WASTE OIL & MIXED OIL * LATEX WASTE * POLYMERIC RESIN WASTE Polychlorinated biphenyls (PCBs) Not reported Not reported Not reported Not reported Not reported Not reported Not reported NONE SPECIFIED	7, 20015, 30018	3
G34 South 1/2-1 4328 ft.	DOWELL DIV OF DC 301 CRENSHAW BL TORRANCE, CA 905 Site 2 of 2 in cluster	VD 510		RCRA-SQG FINDS CORRACTS CERC-NFRAP	1000204971 CAD000628271
Relative: Higher	RCRAInfo Correcti Event:	ive Action Sur	nmary: tion, Facility or area was assigned a low corrective action		
Actual: 70 ft.	priority. Event Date: 07/30/1992		,		
	Event: Event Date:	stabilization appears to b lack of techn status of clos consideration	Measures Evaluation, This facility is not amenable to activity at the present time for reasons other than 1) it e technically infeasible or inappropriate (NF) or 2) there is a ical information (IN). Reasons for this conclusion may be the sure at the facility, the degree of risk, timing ns, the status of corrective action work at the facility, or strative considerations.		
	Event:		tion, Facility or area was assigned a low corrective action		
	Event Date:	priority. 07/10/1992			
	RCRAInfo: Owner: EPA ID:	DOW CHEM (213) 320-76 CAD000628			
	Contact:	ENVIRONM (213) 320-76	ENTAL MANAGER 510		
	Classification: TSDF Activities:	Small Quant	ity Generator		

Database(s)

EDR ID Number EPA ID Number

#### DOWELL DIV OF DOW CHEMICAL (Continued)

Violation Status: Violations exist

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Enforcement Action: Enforcement Action Date: Penalty Type:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Enforcement Action: Enforcement Action Date: Penalty Type:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Not reported TSD-CONTAINERS REQUIREMENTS 02/18/2000 04/19/2002

WRITTEN INFORMAL 02/18/2000 Proposed Monetary Penalty

INITIAL 3008(A) COMPLIANCE ORDER 03/28/2001 Proposed Monetary Penalty

FINAL 3008(A) COMPLIANCE ORDER 04/19/2002 Proposed Monetary Penalty

Not reported TSD-CHEMICAL/PHYSICAL/BIOLOGICAL REQUIREMENTS 02/18/2000 04/19/2002

WRITTEN INFORMAL 02/18/2000 Proposed Monetary Penalty

INITIAL 3008(A) COMPLIANCE ORDER 03/28/2001 Proposed Monetary Penalty

FINAL 3008(A) COMPLIANCE ORDER 04/19/2002 Proposed Monetary Penalty

Not reported TSD-TANKS REQUIREMENTS 02/18/2000 02/19/2000

WRITTEN INFORMAL 02/18/2000 Not reported

Not reported GENERATOR-RECORDKEEPING REQUIREMENTS 03/12/1999 08/26/1999

WRITTEN INFORMAL 03/23/1999 Not reported

Not reported GENERATOR-OTHER REQUIREMENTS 03/12/1999 08/26/1999

WRITTEN INFORMAL 03/23/1999 Not reported

264.110-120.G TSD-CLOSURE/POST-CLOSURE REQUIREMENTS

#### 1000204971

TC2051883.2s Page 328

05/05/1993 03/23/1999

264.10-18.B

Database(s)

EDR ID Number EPA ID Number

#### DOWELL DIV OF DOW CHEMICAL (Continued)

Date Violation Determined: Actual Date Achieved Compliance:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: TSD-OTHER REQUIREMENTS (OVERSIGHT) 05/05/1993 03/23/1999 270 TSD-OTHER REQUIREMENTS (OVERSIGHT) 03/15/1990 04/30/1990 WRITTEN INFORMAL 04/27/1990 Not reported 264.110-120.G TSD-CLOSURE/POST-CLOSURE REQUIREMENTS 03/15/1990 04/30/1990

WRITTEN INFORMAL 04/27/1990 Not reported

264.140-150.H TSD-FINANCIAL RESPONSIBILITY REQUIREMENTS 04/21/1988 01/03/1989

WRITTEN INFORMAL 04/21/1988 Not reported

WRITTEN INFORMAL 05/18/1988 Not reported

268 ALL TSD-LAND BAN REQUIREMENTS 04/14/1988 07/06/1988

WRITTEN INFORMAL 09/07/1988 Not reported

270 TSD-OTHER REQUIREMENTS (OVERSIGHT) 04/14/1988 07/06/1988

WRITTEN INFORMAL 05/09/1988 Not reported

268.7 GENERATOR-LAND BAN REQUIREMENTS 04/14/1988 07/06/1988

WRITTEN INFORMAL 09/07/1988

Database(s)

EDR ID Number **EPA ID Number** 

DOWELL DIV OF DOW CHEMICAL (Continued)			1000204971
Penalty Type:	Not reported		
Penalty Summary: Penalty Description	Penalty Date	Penalty Amount	Lead Agency
Proposed Monetary Penalty	3/28/2001	45000	STATE
Final Monetary Penalty	5/5/1993	1100	STATE
Proposed Monetary Penalty	5/5/1993	1100	STATE

There are 13 violation record(s) reported at this site:

		Date of
Evaluation	Area of Violation	Compliance
Compliance Evaluation Inspection	TSD-CHEMICAL/PHYSICAL/BIOLOGICAL REQUIREMENT	S20020419
	TSD-TANKS REQUIREMENTS	20000219
	TSD-CONTAINERS REQUIREMENTS	20020419
Other Evaluation	GENERATOR-RECORDKEEPING REQUIREMENTS	19990826
	GENERATOR-OTHER REQUIREMENTS	19990826
Other Evaluation	TSD-CLOSURE/POST-CLOSURE REQUIREMENTS	19990323
	TSD-OTHER REQUIREMENTS (OVERSIGHT)	19990323
Compliance Evaluation Inspection	TSD-CLOSURE/POST-CLOSURE REQUIREMENTS	19900430
	TSD-OTHER REQUIREMENTS (OVERSIGHT)	19900430
Financial Record Review	TSD-FINANCIAL RESPONSIBILITY REQUIREMENTS	19890103
Other Evaluation	GENERATOR-LAND BAN REQUIREMENTS	19880706
	TSD-LAND BAN REQUIREMENTS	19880706
Compliance Evaluation Inspection	TSD-OTHER REQUIREMENTS (OVERSIGHT)	19880706

#### FINDS:

Other Pertinent Environmental Activity Identified at Site

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

#### CORRACTS:

EPA ID: EPA Region: Area Name: Actual Date: Action:	CAD000628271 09 ENTIRE FACILITY 07/10/1992 CA075LO - CA Prioritization, Facility or area was assigned a low corrective action priority
NAICS Code(s):	56172 81149 Janitorial Services Other Personal and Household Goods Repair and Maintenance
EPA ID: EPA Region: Area Name: Actual Date:	CAD000628271 09 ENTIRE FACILITY 07/30/1992

Distance Distance (fi Elevation	:.) Site		Database(s)	EDR ID Number EPA ID Number
	DOWELL DIV OF DO	V CHEMICAL (Continued)		1000204971
	Action:	CA075LO - CA Prioritization, Facility or area was assigned a low corrective action priority	,	
	NAICS Code(s):	56172 81149 Janitorial Services Other Personal and Household Goods Repair and Maintenance		
	CERC-NFRAP:			
	Site ID:	0900935		
	Federal Facility:	Not a Federal Facility		
	NPL Status:	Not on the NPL		
	Non NPL Status:			
	CERCLIS-NFRAP S	Site Contact Name(s):		
	Contact Name:	Matt Mitguard		
	Contact Tel:	(415) 972-3096		
	Contact Title:	Site Assessment Manager (SAM)		
	Contact Name:	Jere Johnson		
	Contact Tel:	(415) 972-3094		
	Contact Title:	Site Assessment Manager (SAM)		
	Site Description:			
	CERCLIS-NFRAP A	ssessment History:		
	Action:	DISCOVERY		
	Date Started:	Not reported		
	Date Completed:	•		
	Priority Level:	Not reported		
	Action:	PRELIMINARY ASSESSMENT		
	Date Started:	Not reported		
	Date Completed:			
	Priority Level:	Deferred to RCRA (Subtitle C)		
	Action:	ARCHIVE SITE		
	Date Started:	Not reported		
	Date Completed:	01/23/1996		
	Priority Level:	Not reported		
H35 South 1/2-1	DOW CHEMICAL CO 305 CRENSHAW BLV TORRANCE, CA 905	D	FINDS RCRA-LQG TRIS	1000106842 90503DWCHM30
4580 ft.			RCRA-TSDF	
Relative: Higher	Site 1 of 2 in cluster I		CORRACTS CERC-NFRAP	
ingrici	FINDS:			
Actual: 72 ft.	Other Pertinent E	nvironmental Activity Identified at Site		
		AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieva Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the	l of	

to comply with regulatory programs and by EPA as an input for the

Database(s)

EDR ID Number EPA ID Number

#### DOW CHEMICAL CO TORRANCE PLANT (Continued)

estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

California - Hazardous Waste Tracking System - Datamart

NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.

TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

NJ-NJEMS (New Jersey - New Jersey Environmental Management System). The Department of Environmental Protection (NJDEP) manages large databases of environmental information in this integrated system.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

#### RCRAInfo Corrective Action Summary:

Event:	RFI Workplan Approved
Event Date:	Not reported
Event:	RFI Workplan Approved
Event Date:	04/15/2004
Event:	RFI Approved
Event Date:	06/30/2003
Event:	RFI Workplan Approved
Event Date:	12/06/2000
Event:	Stabilization Measures Evaluation, This facility is not amenable to stabilization activity because of a lack of technical data. An evaluation has been completed, but further data is necessary to determine stabilization measures, feasibility or appropriateness. This status should be changed when data becomes available.
Event Date:	09/28/1994

Distance Distance (find the constance)	t.) Site			Database(s)	EDR ID Number EPA ID Number
	DOW CHEMICAL CO	O TORRANCE PLANT (	Continued)		1000106842
	Event:		ty or area was assigned a low corrective action		
	Event Date:	priority. 09/28/1994			
	RCRAInfo: Owner: EPA ID:	DOW CHEMICAL CON (213) 533-5200 CAD009547050	IPANY		
	Contact:	Not reported			
	Classification: TSDF Activities	Large Quantity Genera	tor, TSDF		
	<b>BIENNIAL REPOR</b>	·			
		<u>Quantity (Lbs)</u> 1789385.00 5280.00	WasteQuantity (Lbs)D0181795315.00K01875.00		
	Violation Status	s: Violations exist			
	Regulation Vic Area of Violati Date Violation Actual Date A	on:	Not reported TSD-FINANCIAL RESPONSIBILITY REQUIF 02/28/2006 Not reported	REMENTS	
	Enforcemen Enforcemen Penalty Type	t Action Date:	WRITTEN INFORMAL 03/03/2006 Not reported		
	Regulation Vic Area of Violati Date Violation Actual Date A	on:	Not reported TSD-FINANCIAL RESPONSIBILITY REQUIF 02/28/2006 Not reported	REMENTS	
	Enforcemen Enforcemen Penalty Type	t Action Date:	WRITTEN INFORMAL 03/03/2006 Not reported		
	Regulation Vic Area of Violati Date Violation Actual Date A	on:	Not reported TSD-OTHER REQUIREMENTS 01/24/2006 02/15/2006		
	Regulation Vic Area of Violati Date Violation Actual Date A	on:	Not reported TSD-CONTAINERS REQUIREMENTS 01/24/2006 01/25/2006		
	Enforcemen Enforcemen Penalty Type	t Action Date:	WRITTEN INFORMAL 01/25/2006 Not reported		
	Regulation Vic Area of Violati Date Violation Actual Date A	on:	Not reported TSD-FINANCIAL RESPONSIBILITY REQUIF 09/13/2004 Not reported	REMENTS	
	Enforcemen Enforcemen Penalty Type	t Action Date:	WRITTEN INFORMAL 09/14/2004 Not reported		
	Regulation Vic	plated:	Not reported		

#### Map ID Direction Distance Distance (ft.) Elevation Site

#### MAP FINDINGS

Database(s)

EDR ID Number EPA ID Number

#### DOW CHEMICAL CO TORRANCE PLANT (Continued)

Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: GENERATOR-LAND BAN REQUIREMENTS 08/13/2003 09/08/2003 WRITTEN INFORMAL 08/13/2003 Not reported

Not reported TSD-CONTAINERS REQUIREMENTS 08/13/2003 09/08/2003

WRITTEN INFORMAL 08/13/2003 Not reported

Not reported GENERATOR-GENERAL REQUIREMENTS 08/13/2003 09/08/2003

WRITTEN INFORMAL 08/13/2003 Not reported

Not reported TSD-OTHER REQUIREMENTS 11/23/1999 12/10/1999

WRITTEN INFORMAL 11/24/1999 Not reported

264.50-56.D TSD-OTHER REQUIREMENTS (OVERSIGHT) 11/22/1994 12/20/1994

WRITTEN INFORMAL 11/22/1994

Not reported

264.10-18.B TSD-OTHER REQUIREMENTS (OVERSIGHT) 11/22/1994 12/20/1994

WRITTEN INFORMAL 11/22/1994 Not reported

264.170-177.I TSD-OTHER REQUIREMENTS (OVERSIGHT) 11/22/1994 12/20/1994

WRITTEN INFORMAL 11/22/1994 Not reported

264.70-77.E TSD-OTHER REQUIREMENTS (OVERSIGHT)

Database(s)

EDR ID Number EPA ID Number

1000106842

#### DOW CHEMICAL CO TORRANCE PLANT (Continued)

Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Enforcement Action: Enforcement Action Date: Penalty Type:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Enforcement Action: Enforcement Action Date: Penalty Type:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

**Regulation Violated:** 

Not reported 268 ALL TSD-LAND E

11/22/1994

11/22/1994 01/25/1995

TSD-LAND BAN REQUIREMENTS 10/09/1992 12/29/1992

WRITTEN INFORMAL 10/16/1992 Not reported

WRITTEN INFORMAL

262.40-43.D GENERATOR-ALL REQUIREMENTS (OVERSIGHT) 10/09/1992 12/29/1992

WRITTEN INFORMAL 10/16/1992 Not reported

WRITTEN INFORMAL 10/13/1987 Not reported

WRITTEN INFORMAL 03/16/1988 Not reported

264.70-77.E TSD-OTHER REQUIREMENTS (OVERSIGHT) 10/09/1992 12/29/1992

WRITTEN INFORMAL 10/16/1992 Not reported

264.30-37.C TSD-OTHER REQUIREMENTS (OVERSIGHT) 10/09/1992 12/29/1992

WRITTEN INFORMAL 10/16/1992 Not reported

WRITTEN INFORMAL 10/13/1987 Not reported

WRITTEN INFORMAL 03/16/1988 Not reported

270

264.70-77.E TSD-OTHER REQUIREMENTS (OVERSIGHT) 04/01/1991 06/12/1991

)
Site

Database(s)

EDR ID Number EPA ID Number

1000106842

#### DOW CHEMICAL CO TORRANCE PLANT (Continued)

Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: 04/01/1991 06/12/1991 270 TSD-OTHER REQUIREMENTS (OVERSIGHT) 05/25/1990 06/12/1991 WRITTEN INFORMAL 07/09/1990 Not reported 264.110-120.G TSD-CLOSURE/POST-CLOSURE REQUIREMENTS 02/16/1989 07/10/1989 WRITTEN INFORMAL 03/31/1989 Not reported 270 TSD-OTHER REQUIREMENTS (OVERSIGHT) 02/16/1989 07/10/1989 WRITTEN INFORMAL 03/31/1989 Not reported 268.7 **GENERATOR-LAND BAN REQUIREMENTS** 02/16/1989 07/10/1989 WRITTEN INFORMAL 03/31/1989 Not reported 270 TSD-OTHER REQUIREMENTS (OVERSIGHT) 02/16/1989 07/10/1989 WRITTEN INFORMAL 03/31/1989

TSD-OTHER REQUIREMENTS (OVERSIGHT)

Proposed Monetary Penalty

INITIAL 3008(A) COMPLIANCE ORDER 06/30/1989 Proposed Monetary Penalty

268 ALL TSD-LAND BAN REQUIREMENTS 02/16/1989 07/10/1989

WRITTEN INFORMAL 03/31/1989 Not reported

268 ALL TSD-LAND BAN REQUIREMENTS 06/17/1988 07/10/1989

10/16/1992

Not reported

06/17/1988

07/10/1989

10/13/1987

02/23/1988

10/16/1992

Not reported

10/13/1987

Not reported

03/16/1988

10/13/1987

02/23/1988

10/16/1992

Not reported

10/13/1987

270

Not reported

264.110-120.G

WRITTEN INFORMAL

WRITTEN INFORMAL

WRITTEN INFORMAL

WRITTEN INFORMAL

WRITTEN INFORMAL

268.7

WRITTEN INFORMAL

GENERATOR-LAND BAN REQUIREMENTS

TSD-CLOSURE/POST-CLOSURE REQUIREMENTS

TSD-OTHER REQUIREMENTS (OVERSIGHT)

Database(s)

EDR ID Number EPA ID Number

#### DOW CHEMICAL CO TORRANCE PLANT (Continued)

Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Enforcement Action: Enforcement Action Date: Penalty Type:

Enforcement Action: Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation: Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date: Penalty Type:

Enforcement Action: Enforcement Action Date: Penalty Type:

Enforcement Action: Enforcement Action Date: Penalty Type: Not reported WRITTEN INFORMAL 03/16/1988 Not reported

There are 29 violation record(s) reported at this site:

		Date of
Evaluation	Area of Violation	Compliance
Financial Record Review	TSD-FINANCIAL RESPONSIBILITY REQUIREMENTS	
	TSD-FINANCIAL RESPONSIBILITY REQUIREMENTS	
Compliance Evaluation Inspection	TSD-OTHER REQUIREMENTS	20060215
	TSD-CONTAINERS REQUIREMENTS	20060125
Financial Record Review	TSD-FINANCIAL RESPONSIBILITY REQUIREMENTS	
Compliance Evaluation Inspection	TSD-CONTAINERS REQUIREMENTS	20030908
	GENERATOR-GENERAL REQUIREMENTS	20030908
	GENERATOR-LAND BAN REQUIREMENTS	20030908
Compliance Evaluation Inspection	TSD-OTHER REQUIREMENTS	19991210
Compliance Evaluation Inspection	TSD-OTHER REQUIREMENTS (OVERSIGHT)	19941220
	TSD-OTHER REQUIREMENTS (OVERSIGHT)	19941220
	TSD-OTHER REQUIREMENTS (OVERSIGHT)	19950125
	TSD-OTHER REQUIREMENTS (OVERSIGHT)	19941220

EDR ID Number Database(s)

## EPA ID Number

## DOW CHEMICAL CO TORRANCE PLANT (Continued)

## 1000106842

Compliance Evaluation Inspection	TSD-OTHER REQUIREMENTS (OVERSIGHT)	19921229
	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)	19921229
	TSD-LAND BAN REQUIREMENTS	19921229
	TSD-OTHER REQUIREMENTS (OVERSIGHT)	19921229
Compliance Evaluation Inspection	TSD-OTHER REQUIREMENTS (OVERSIGHT)	19910612
	TSD-OTHER REQUIREMENTS (OVERSIGHT)	19910612
Compliance Evaluation Inspection	TSD-OTHER REQUIREMENTS (OVERSIGHT)	19910612
Compliance Evaluation Inspection	GENERATOR-LAND BAN REQUIREMENTS	19890710
	TSD-CLOSURE/POST-CLOSURE REQUIREMENTS	19890710
	TSD-LAND BAN REQUIREMENTS	19890710
	TSD-OTHER REQUIREMENTS (OVERSIGHT)	19890710
	TSD-OTHER REQUIREMENTS (OVERSIGHT)	19890710
Other Evaluation	TSD-LAND BAN REQUIREMENTS	19890710
	GENERATOR-LAND BAN REQUIREMENTS	19890710
Compliance Evaluation Inspection	TSD-CLOSURE/POST-CLOSURE REQUIREMENTS	19880223
	TSD-OTHER REQUIREMENTS (OVERSIGHT)	19880223

#### CORRACTS:

EPA ID: EPA Region: Area Name: Actual Date: Action: NAICS Code(s):	CAD009547050 09 ENTIRE FACILITY 04/15/2004 CA150 - RFI Workplan Approved 325211 32614 Plastics Material and Resin Manufacturing Polystyrene Foam Product Manufacturing
EPA ID: EPA Region: Area Name: Actual Date: Action: NAICS Code(s):	CAD009547050 09 ENTIRE FACILITY 06/30/2003 CA200 - RFI Approved 325211 32614 Plastics Material and Resin Manufacturing Polystyrene Foam Product Manufacturing
EPA ID: EPA Region: Area Name: Actual Date: Action: NAICS Code(s):	CAD009547050 09 ENTIRE FACILITY 09/28/1994 CA225IN - Stabilization Measures Evaluation, This facility is not, amenable to stabilization activity because of, a lack of technical data. An evaluation has been completed, but further data is necessary to determine stabilization measures, feasibility or appropriateness. This status should be changed when data becomes available 325211 32614 Plastics Material and Resin Manufacturing Polystyrene Foam Product Manufacturing
EPA ID: EPA Region: Area Name: Actual Date: Action: NAICS Code(s):	CAD009547050 09 ENTIRE FACILITY 09/28/1994 CA075LO - CA Prioritization, Facility or area was assigned a low corrective action priority 325211 32614

Database(s)

EDR ID Number EPA ID Number

## DOW CHEMICAL CO TORRANCE PLANT (Continued)

	Plastics Material and Resin Manufacturing Polystyrene Foam Product Manufacturing
EPA ID: EPA Region: Area Name: Actual Date: Action: NAICS Code(s):	CAD009547050 09 ENTIRE SITE 12/06/2000 CA150 - RFI Workplan Approved 325211 32614 Plastics Material and Resin Manufacturing Polystyrene Foam Product Manufacturing
EPA ID: EPA Region: Area Name: Actual Date: Action: NAICS Code(s):	CAD009547050 09 ENTIRE FACILITY / / CA150 - RFI Workplan Approved 325211 32614 Plastics Material and Resin Manufacturing Polystyrene Foam Product Manufacturing
CERC-NFRAP: Site ID: Federal Facility: NPL Status: Non NPL Status:	0901223 Not a Federal Facility Not on the NPL NFRAP
CERCLIS-NFRAP Site C Contact Name: Contact Tel: Contact Title: Contact Name: Contact Tel: Contact Tel: Contact Title:	ontact Name(s): Matt Mitguard (415) 972-3096 Site Assessment Manager (SAM) Jere Johnson (415) 972-3094 Site Assessment Manager (SAM)
CERCLIS-NFRAP Site Alias Name(s): Alias Name: DOWELL DIV OF THE DOW CHEMICAL C Alias Address: 301 CRENSHAW BLVD TORRANCE, CA 90510 Site Description: Not reported	
CERCLIS-NFRAP Asses Action: Date Started: Date Completed: Priority Level:	sment History: DISCOVERY Not reported 05/01/1986 Not reported
Action: Date Started: Date Completed: Priority Level:	ARCHIVE SITE Not reported 01/01/1987 Not reported
Action: Date Started: Date Completed:	PRELIMINARY ASSESSMENT 05/01/1986 01/01/1987

Date Completed:

Priority Level:

07/22/1990

Low

MAP FINDINGS

EDR ID Number Database(s) **EPA ID Number** DOW CHEMICAL CO TORRANCE PLANT (Continued) 1000106842 Priority Level: NFRAP (No Futher Remedial Action Planned H36 **AMERICAN STANDARD INC** RCRA-SQG 1000360786 **360 CRENSHAW BLVD** South FINDS CAD008326084 TORRANCE, CA 90503 **CERC-NFRAP** 1/2-1 4623 ft. ENVIROSTOR Site 2 of 2 in cluster H Relative: RCRAInfo: Higher Owner: NOT REQUIRED Actual: (415) 555-1212 72 ft. CAD008326084 EPA ID: Contact: Not reported Classification: Small Quantity Generator **TSDF** Activities: Not reported Violation Status: No violations found FINDS: Other Pertinent Environmental Activity Identified at Site RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste, RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA. CERC-NFRAP: Site ID: 0903687 Federal Facility: Not a Federal Facility NPL Status: Not on the NPL Non NPL Status: NFRAP CERCLIS-NFRAP Site Contact Name(s): Contact Name: Matt Mitguard (415) 972-3096 Contact Tel: Contact Title: Site Assessment Manager (SAM) Contact Name: Jere Johnson Contact Tel: (415) 972-3094 Contact Title: Site Assessment Manager (SAM) Site Description: Not reported CERCLIS-NFRAP Assessment History: DISCOVERY Action: Date Started: Not reported Date Completed: 01/03/1989 Priority Level: Not reported Action: PRELIMINARY ASSESSMENT Date Started: Not reported

Database(s)

EDR ID Number EPA ID Number

Action: Date Started:	SITE INSPECTION Not reported
Date Completed: Priority Level:	10/18/1991 NFRAP (No Futher Remedial Action Planned
Action:	ARCHIVE SITE
Date Started:	Not reported
Date Completed:	10/18/1991
Priority Level:	Not reported
ENVIROSTOR:	
Site Type:	Historical
Site Type Detailed:	* Historical
Acres:	Not reported
NPL:	NO
Regulatory Agencies:	NONE SPECIFIED
Lead Agency:	NONE SPECIFIED
Program Manager:	Not reported
Supervisor:	* MMONROY
Division Branch:	So Cal - Cypress
Facility ID: Site Code:	19320195
Assembly:	Not reported 53
Senate:	28
Special Program:	Not reported
Status:	Refer: Other Agency
Status Date:	1995-04-11 00:00:00
Restricted Use:	NO
Funding:	Not reported
Latitude:	33.843611111111
Longitude:	-118.3288888888889
Alias Name:	19320195
	CAD008326084
Alias Type:	EPA Identification Number
	Envirostor ID Number
APN:	NONE SPECIFIED
APN Description: Comments:	Not reported NFA FOR DTSCFACILITY IDENTIFIED IDENTIFIED VIA FIT PA REPORT
Completed Area Name:	PROJECT WIDE
Completed Sub Area Na	
Completed Document Ty	
Completed Date:	1995-04-11 00:00:00
Completed Area Name:	PROJECT WIDE
Completed Sub Area Na	me: Not reported
Completed Document Ty	pe: Discovery
Completed Date:	1990-06-15 00:00:00
Confirmed:	NONE SPECIFIED
Confirmed Description:	Not reported
Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date: Media Affected:	Not reported
Media Affected Desc:	NONE SPECIFIED Not reported
Management Required:	NONE SPECIFIED
Management Required	
Potential:	NONE SPECIFIED

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number **EPA ID Number** 

#### 1000360786

Potenital Description: Schedule Area Name: Schedule Sub Area Name: Schedule Document Type: Schedule Due Date: Schedule Revised Date: PastUse:	Not reported Not reported Not reported Not reported Not reported NONE SPECIFIED
FRANCISCO'S CLEANERS 1830 W 182ND ST TORRANCE, CA 90504	

CAL000017120

CHA CARL

000000000

Not reported

Not reported

Los Angeles CAD981397417

Los Angeles Not reported

Los Angeles

CHA CARL

000000000

Not reported

Not reported

Los Angeles CAD981397417

Los Angeles

Los Angeles

CAL000017120

KIYONG KIM

Not reported

Not reported 1830 W 182ND ST

Los Angeles

etc.)

Recycler

.4586

0

1830 W 182ND ST

TORRANCE, CA 905040000

TORRANCE, CA 905040000

Halogenated solvents (chloroform, methyl chloride, perchloroethylene,

CAL000017120

Recycler

.0000

1830 W 182ND ST

TORRANCE, CA 905040000

AMERICAN STANDARD INC (Continued)

5015 ft. **Relative:** 

HAZNET:

Gepaid:

Contact:

Telephone: Facility Addr2:

Mailing Name:

Gen County:

TSD EPA ID: TSD County:

Tons:

Gepaid:

Contact:

Telephone:

Facility Addr2:

Mailing Name:

Gen County:

TSD EPA ID: TSD County:

Mailing Address:

Waste Category:

**Disposal Method:** 

Facility County:

Facility Addr2: Mailing Name:

Gen County:

TSD EPA ID:

TSD County:

Waste Category:

Mailing Address: Mailing City, St, Zip:

Tons:

Gepaid:

Contact: Telephone:

Mailing City, St, Zip:

Mailing Address:

Waste Category: **Disposal Method:** 

Facility County:

Mailing City, St, Zip:

37

ENE

1/2-1

Lower Actual:

55 ft.

HAZNET LA Co. Site Mitigation CLEANERS EMI ENVIROSTOR

1000308456

N/A

Database(s)

EDR ID Number EPA ID Number

#### 1000308456

## FRANCISCO'S CLEANERS (Continued)

Disposal Method:	Transfer Station
Tons:	0.12
Facility County:	Los Angeles
Gepaid: Contact: Telephone: Facility Addr2: Mailing Name: Mailing Address: Mailing City,St,Zip: Gen County: TSD EPA ID: TSD County: Waste Category:	CAL000017120 KIYONG KIM 0 Not reported 1830 W 182ND ST TORRANCE, CA 905040000 Los Angeles CAD008302903 Los Angeles Halogenated solvents (chloroform, methyl chloride, perchloroethylene,
Disposal Method: Tons: Facility County:	etc.) Recycler 0.31 Los Angeles
Gepaid:	CAL000017120
Contact:	CHA CARL
Telephone:	000000000
Facility Addr2:	Not reported
Mailing Name:	Not reported
Mailing Address:	1830 W 182ND ST
Mailing City,St,Zip:	TORRANCE, CA 905040000
Gen County:	Los Angeles
TSD EPA ID:	CAD981397417
TSD County:	Los Angeles
Waste Category:	Not reported
Disposal Method:	Recycler
Tons:	.0000
Facility County:	Los Angeles

# <u>Click this hyperlink</u> while viewing on your computer to access 5 additional CA\_HAZNET: record(s) in the EDR Site Report.

#### LA Co. Site Mitigation:

Facility ID:	RO000006
Site ID:	SD0000006
Abated:	Yes
Assigned To:	Kim Clark
Entered Date:	06/04/2003
Abated Date:	11/03/2003

#### CLEANERS:

CAL000017120
Not reported
Not reported
Not reported
11/14/1989
No
6/30/1999
Not reported
Not reported

Map ID Direction Distance Distance (ft.) Site Elevation

Database(s)

EDR ID Number EPA ID Number

#### 1000308456

FRANCISCO'S CLEANE	RS (Continued)
Mailing Address: Mailing Address 2: Mailing State: Mailing Zip: Region Code: Owner Name: Owner Address: Owner Address 2: Owner Telephone: Contact Name: Contact Addresss: Contact Addresss 2: Contact Address 2: Contact Address 2: Contact Telephone: SIC Description: G	1830 W 182ND ST Not reported CA 905040000 3 CHA CARL 25569 PINE CREEK LN Not reported 0 KIYONG KIM INACT PER PHONE-BP Not reported
EPA Id: NAICS Code: NAICS Description:	CAL000171158 81232 Drycleaning and Laundry Services (except Coin-Operated)
SIC Code: Create Date: Facility Active: Inactive Date: Facility Addr2: Mailing Name: Mailing Addresss 2: Mailing Address 2: Mailing State: Mailing Zip: Region Code: Owner Name: Owner Address 2: Owner Address 2: Owner Telephone: Contact Name: Contact Address 2: Contact Address 2: Contact Address 2: Contact Address 2: Contact Celephone: SIC Description: G	
EPA Id: NAICS Code: NAICS Description: SIC Code: Create Date: Facility Active: Inactive Date: Facility Addr2: Mailing Name: Mailing Address 1: Mailing Address 2: Mailing State: Mailing Zip: Region Code:	CAL000171158 81232 Drycleaning and Laundry Services (except Coin-Operated) 7219 9/13/1999 Yes Not reported Not reported Not reported 1830 W 182ND ST Not reported CA 905040000 3

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

#### 1000308456

## FRANCISCO'S CLEANERS (Continued)

`	NCISCO S CELANEI		
	E>	•	
	E>	7211 9/13/1999 Yes Not reported Not reported 1830 W 182ND ST Not reported CA 905040000 3 KIYONG KIM 1830 W 182ND ST Not reported Not reported Not reported Not reported Not reported KIYONG KIM-OWNER 1830 W 182ND ST Not reported	
	EPA Id: NAICS Code: NAICS Description: SIC Code: Create Date: Facility Active: Inactive Date: Facility Addr2: Mailing Name: Mailing Address: Mailing Address 2: Mailing State: Mailing Zip: Region Code: Owner Name: Owner Address 2: Owner Address 2: Owner Telephone: Contact Name:	CAL000171158 81232 Drycleaning and Laundry Services (except Coin-Operated) 7216 9/13/1999 Yes Not reported Not reported Not reported 1830 W 182ND ST Not reported CA 905040000 3 KIYONG KIM 1830 W 182ND ST Not reported Not reported KIYONG KIM	

Database(s)

EDR ID Number EPA ID Number

## FRANCISCO'S CLEANERS (Continued)

Contact Address: 1830 W 182ND ST Contact Address 2: Not reported Contact Telephone: 3105184208 SIC Description: Garment Pressing and Agents for Laundries and DrycleanersDrycleaning Plants Except Rug CleaningPower Laundries Family and CommercialLaundry and Garment Services NEC (except diaper service and clothing alteration and repair)

## EMI:

111.	
Year:	1987
Carbon Monoxide Emissions Tons/Yr:	19
Air Basin:	SC
Facility ID:	17702
Air District Name:	SC
SIC Code:	7216
Air District Name:	SOUTH COAST AQMD
Community Health Air Pollution Info Syste	em: Not reported
Consolidated Emission Reporting Rule:	Not reported
Total Organic Hydrocarbon Gases Tons/	/r: 1
Reactive Organic Gases Tons/Yr:	0
Carbon Monoxide Emissions Tons/Yr:	0
NOX - Oxides of Nitrogen Tons/Yr:	0
SOX - Oxides of Sulphur Tons/Yr:	0
Particulate Matter Tons/Yr:	0
Part. Matter 10 Micrometers & Smllr Tons	/Yr: 0
Year:	1990
Year: Carbon Monoxide Emissions Tons/Yr:	1990 19
Carbon Monoxide Emissions Tons/Yr:	19
Carbon Monoxide Emissions Tons/Yr: Air Basin:	19 SC
Carbon Monoxide Emissions Tons/Yr: Air Basin: Facility ID:	19 SC 17702
Carbon Monoxide Emissions Tons/Yr: Air Basin: Facility ID: Air District Name:	19 SC 17702 SC
Carbon Monoxide Emissions Tons/Yr: Air Basin: Facility ID: Air District Name: SIC Code:	19 SC 17702 SC 7216 SOUTH COAST AQMD
Carbon Monoxide Emissions Tons/Yr: Air Basin: Facility ID: Air District Name: SIC Code: Air District Name:	19 SC 17702 SC 7216 SOUTH COAST AQMD
Carbon Monoxide Emissions Tons/Yr: Air Basin: Facility ID: Air District Name: SIC Code: Air District Name: Community Health Air Pollution Info Syste	19 SC 17702 SC 7216 SOUTH COAST AQMD em: Not reported Not reported
Carbon Monoxide Emissions Tons/Yr: Air Basin: Facility ID: Air District Name: SIC Code: Air District Name: Community Health Air Pollution Info Syste Consolidated Emission Reporting Rule:	19 SC 17702 SC 7216 SOUTH COAST AQMD em: Not reported Not reported
Carbon Monoxide Emissions Tons/Yr: Air Basin: Facility ID: Air District Name: SIC Code: Air District Name: Community Health Air Pollution Info Syste Consolidated Emission Reporting Rule: Total Organic Hydrocarbon Gases Tons/M	19 SC 17702 SC 7216 SOUTH COAST AQMD em: Not reported Not reported (r: 1
Carbon Monoxide Emissions Tons/Yr: Air Basin: Facility ID: Air District Name: SIC Code: Air District Name: Community Health Air Pollution Info Syste Consolidated Emission Reporting Rule: Total Organic Hydrocarbon Gases Tons/Yr:	19 SC 17702 SC 7216 SOUTH COAST AQMD em: Not reported Not reported (r: 1 0
Carbon Monoxide Emissions Tons/Yr: Air Basin: Facility ID: Air District Name: SIC Code: Air District Name: Community Health Air Pollution Info Syste Consolidated Emission Reporting Rule: Total Organic Hydrocarbon Gases Tons/Yr: Reactive Organic Gases Tons/Yr: Carbon Monoxide Emissions Tons/Yr:	19 SC 17702 SC 7216 SOUTH COAST AQMD em: Not reported Not reported (fr: 1 0 0
Carbon Monoxide Emissions Tons/Yr: Air Basin: Facility ID: Air District Name: SIC Code: Air District Name: Community Health Air Pollution Info Syste Consolidated Emission Reporting Rule: Total Organic Hydrocarbon Gases Tons/Yr: Reactive Organic Gases Tons/Yr: Carbon Monoxide Emissions Tons/Yr: NOX - Oxides of Nitrogen Tons/Yr:	19 SC 17702 SC 7216 SOUTH COAST AQMD em: Not reported Not reported fr: 1 0 0 0
Carbon Monoxide Emissions Tons/Yr: Air Basin: Facility ID: Air District Name: SIC Code: Air District Name: Community Health Air Pollution Info Syste Consolidated Emission Reporting Rule: Total Organic Hydrocarbon Gases Tons/Yr Reactive Organic Gases Tons/Yr: Carbon Monoxide Emissions Tons/Yr: NOX - Oxides of Nitrogen Tons/Yr: SOX - Oxides of Sulphur Tons/Yr:	19         SC         17702         SC         7216         SOUTH COAST AQMD         em:         Not reported         Not reported         fr:         1         0
Carbon Monoxide Emissions Tons/Yr: Air Basin: Facility ID: Air District Name: SIC Code: Air District Name: Community Health Air Pollution Info Syste Consolidated Emission Reporting Rule: Total Organic Hydrocarbon Gases Tons/Yr: Reactive Organic Gases Tons/Yr: Carbon Monoxide Emissions Tons/Yr: NOX - Oxides of Nitrogen Tons/Yr: SOX - Oxides of Sulphur Tons/Yr: Particulate Matter Tons/Yr:	19         SC         17702         SC         7216         SOUTH COAST AQMD         em:         Not reported         Not reported         fr:         1         0

#### ENVIROSTOR:

Site Type:	Evaluation
Site Type Detailed:	Evaluation
Acres:	Not reported
NPL:	NO
Regulatory Agencies:	LA CNTY FIRE DEPT. (BILLING AND UST), LOS ANGELES COUNTY
Lead Agency:	NONE SPECIFIED
Program Manager:	Not reported
Supervisor:	Greg Holmes
Division Branch:	So Cal - Cypress
Facility ID:	70000171
Site Code:	Not reported
Assembly:	53
Senate:	28

Database(s)

EDR ID Number EPA ID Number

#### FRANCISCO'S CLEANERS (Continued)

Special Program: Not reported Status: Refer: 1248 Local Agency 2002-07-24 00:00:00 Status Date: Restricted Use: NO Funding: Not Applicable Latitude: 0 Longitude: 0 70000171 Alias Name: Alias Type: Envirostor ID Number APN: NONE SPECIFIED APN Description: Not reported Comments: Not reported Completed Area Name: Not reported Completed Sub Area Name: Not reported Completed Document Type: Not reported Completed Date: Not reported Confirmed: NONE SPECIFIED Confirmed Description: Not reported Future Area Name: Not reported Future Sub Area Name: Not reported Future Document Type: Not reported Future Due Date: Not reported Media Affected: NONE SPECIFIED Media Affected Desc: Not reported Management Required: NONE SPECIFIED Management Required Desc: Not reported Potential: NONE SPECIFIED Potenital Description: Not reported Schedule Area Name: Not reported Schedule Sub Area Name: Not reported Schedule Document Type: Not reported Schedule Due Date: Not reported Schedule Revised Date: Not reported PastUse: NONE SPECIFIED

# I38INTERNATIONAL LIGHT METALSESE19200 SOUTH WESTERN AVENUE1/2-1TORRANCE, CA 90501

#### Site 1 of 2 in cluster I

5043 ft.

<b>B</b> 1 <i>d</i>		
Relative: Lower	ENVIROSTOR:	
	Site Type:	Historical
Actual:	Site Type Detailed:	* Historical
59 ft.	Acres:	Not reported
	NPL:	NO
	Regulatory Agencies:	NONE SPECIFIED
	Lead Agency:	NONE SPECIFIED
	Program Manager:	Not reported
	Supervisor:	Referred - Not Assigned
	Division Branch:	So Cal - Cypress
	Facility ID:	19330238
	Site Code:	300394
	Assembly:	53
	Senate:	28
	Special Program:	Not reported
	Status:	Refer: RCRA
	Status Date:	1995-08-28 00:00:00

1000308456

ENVIROSTOR S101480757 N/A

Database(s)

EDR ID Number EPA ID Number

S101480757

#### INTERNATIONAL LIGHT METALS (Continued)

Restricted Use:	NO
Funding:	Not reported
Latitude:	33.8555555555556
Longitude:	-118.3091666666667
Alias Name:	300394
	CAD030398622
	MARTIN MARIETTA
	HARVEY ALUMINUM COMPANY
	INTEL LIGHT METALS CORP - SITE B
	19330238
Alias Type:	Project Code (Site Code)
51	EPA Identification Number
	Alternate Name
	Alternate Name
	Alternate Name
	Envirostor ID Number
APN:	NONE SPECIFIED
APN Description:	Not reported
Comments:	Facility identified from Pac Tel Classified Directory 1971. No
	current telephone listing.
Completed Area Name:	PROJECT WIDE
Completed Sub Area Na	
Completed Document Ty	•
Completed Date:	1982-10-07 00:00:00
Confirmed:	NONE SPECIFIED
Confirmed Description:	Not reported
Future Area Name:	Not reported
Future Sub Area Name:	Not reported
Future Document Type:	Not reported
Future Due Date:	Not reported
Media Affected:	NONE SPECIFIED
Media Affected Desc:	Not reported
Management Required:	NONE SPECIFIED
Management Required D	
Potential:	NONE SPECIFIED
Potenital Description:	Not reported
Schedule Area Name:	Not reported
Schedule Sub Area Nam	•
Schedule Document Typ	
Schedule Due Date:	Not reported
Schedule Revised Date:	Not reported
PastUse:	NONE SPECIFIED
1 431035.	

## 139

## ESE 19200 S WESTERN AVE 1/2-1 TORRANCE, CA 90501

INTEL LIGHT METALS CORP

5043 ft.

Site 2 of 2 in cluster I FINDS:

Relative: Lower

Other Pertinent Environmental Activity Identified at Site

Actual: 59 ft.

NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.

FINDS 1000921589 RCRA-LQG CAD030398622 RCRA-TSDF CORRACTS CERC-NFRAP

Database(s)

EDR ID Number EPA ID Number

1000921589

#### INTEL LIGHT METALS CORP (Continued)

TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CERCLIS (Comprehensive Environmental Response, Compensation, and Liability Information System) is the Superfund database that is used to support management in all phases of the Superfund program. The system contains information on all aspects of hazardous waste sites, including an inventory of sites, planned and actual site activities, and financial information.

#### RCRAInfo Corrective Action Summary:

Event: Event Date:	ve Action Summary: RFI Workplan Approved 09/26/2000
Event: Event Date:	Corrective Action Process Terminated, No Further Action 05/13/1999
Event: Event Date:	RFI Workplan Approved 06/30/1998
Event: Event Date:	RFA Completed 09/30/1996
Event: Event Date:	RFI Approved 04/29/1996
Event: Event Date:	Stabilization Measures Implemented, Primary measure is exposure control by barrier and/or institutional control (e.g., capping, fencing, deed restrictions). 05/04/1995
Event:	RFI Workplan Approved
Event Date:	02/07/1995
Event: Event Date:	RFI Imposition 01/01/1995
Event:	Stabilization Measures Evaluation, This facility is not amenable to stabilization activity at the present time for reasons other than 1) it appears to be technically infeasible or inappropriate (NF) or 2) there is a lack of technical information (IN). Reasons for this conclusion may be the status of closure at the facility, the degree of risk, timing considerations, the status of corrective action work at the facility, or other administrative considerations.
Event Date:	03/31/1992

EDR ID Number Database(s) EPA ID Number

			. ,	
EL LIGHT METALS	CORP (Continued)			100092158
		ty or area was assigned a low corrective action		100032130
	riority. 3/31/1992			
		ty or area was assigned a low corrective action		
рі	riority. 9/23/1991	,		
	5/23/1991			
CRAInfo: Owner: M	ARTIN MARIETTA A	LUMINUM		
•	13) 328-0660 AD030398622			
	ot reported			
	arge Quantity Genera	tor. TSDF		
TSDF Activities: N				
Violation Status: V	iolations exist			
Regulation Violate Area of Violation:	ed:	268 ALL TSD-LAND BAN REQUIREMENTS		
Date Violation De	termined:	01/31/1990		
Actual Date Achie	eved Compliance:	09/14/1990		
Enforcement Ac Enforcement Ac		WRITTEN INFORMAL 03/02/1990		
Penalty Type:	cion Dale.	Not reported		
Regulation Violate	ed:	268.7		
Area of Violation: Date Violation De	termined.	GENERATOR-LAND BAN REQUIREMENTS 01/31/1990		
Actual Date Achie		09/14/1990		
Enforcement Ac		WRITTEN INFORMAL		
Enforcement Ac Penalty Type:	ction Date:	03/02/1990 Not reported		
Regulation Violate	ed:	270		
Area of Violation:	to una in a di	TSD-OTHER REQUIREMENTS (OVERSIGHT)		
Date Violation De Actual Date Achie	eved Compliance:	01/31/1990 09/14/1990		
Enforcement Ac	ction:	WRITTEN INFORMAL		
Enforcement Ac	ction Date:	03/02/1990 Not reported		
Penalty Type: Regulation Violate	od	Not reported 268.7		
Area of Violation:	eu.	GENERATOR-LAND BAN REQUIREMENTS		
Date Violation De Actual Date Achie		05/24/1988 07/03/1990		
Enforcement Ac		WRITTEN INFORMAL		
Enforcement Ad		06/30/1989		
Penalty Type:		Not reported		
Regulation Violate Area of Violation:	ed:	268 ALL TSD-LAND BAN REQUIREMENTS		
Date Violation De		05/24/1988		
Actual Date Achie	·	07/03/1990		
Enforcement Ac Enforcement Ac		WRITTEN INFORMAL 06/30/1989		
Penalty Type:		Not reported		

Database(s)

EDR ID Number EPA ID Number

## INTEL LIGHT METALS CORP (Continued)

There are 5 violation record(s) reported at this site:

Evaluation Financial Record Review		Area of Violation TSD-OTHER REQUIREMENTS (OVERSIGHT)	<u>Compliance</u> 19900914
Other Evaluation		TSD-LAND BAN REQUIREMENTS GENERATOR-LAND BAN REQUIREMENTS TSD-LAND BAN REQUIREMENTS GENERATOR-LAND BAN REQUIREMENTS	19900914 19900914 19900703 19900703
CORRACTS:			
EPA ID: EPA Region: Area Name: Actual Date: Action: NAICS Code(s):	Nonferrous Forging	sition 32993 42191 d Product Manufacturing	
EPA ID: EPA Region: Area Name: Actual Date: Action: NAICS Code(s):	Nonferrous Forging	plan Approved 32993 42191 d Product Manufacturing	
EPA ID: EPA Region: Area Name: Actual Date: Action: NAICS Code(s):	amenable to stabili other than (1) it ap inappropriate (NF) (IN). Reasons for t facility, the degree corrective action w considerations 331316 332112 33 Aluminum Extrude	zation Measures Evaluation, This facility is, not ization activity at the, present time for reasons pears to be technically, infeasible or or (2) there is a lack of technical, information his conclusion may be the status of, closure at the of risk, timing considerations, the status of vork at the facility, or other, administrative 82993 42191 d Product Manufacturing	
EPA ID: EPA Region: Area Name: Actual Date: Action: NAICS Code(s):	CAD030398622 09 ENTIRE FACILITY 03/31/1992 CA075LO - CA Pri corrective action p 331316 332112 33	oritization, Facility or area was assigned a low riority 32993 42191 d Product Manufacturing	

Database(s)

EDR ID Number EPA ID Number

1000921589

## INTEL LIGHT METALS CORP (Continued)

	Ammunition (except Small Arms) Manufacturing
EPA ID: EPA Region: Area Name: Actual Date: Action: NAICS Code(s):	CAD030398622 09 ENTIRE FACILITY 04/29/1996 CA200 - RFI Approved 331316 332112 332993 42191 Aluminum Extruded Product Manufacturing Nonferrous Forging Ammunition (except Small Arms) Manufacturing
EPA ID: EPA Region: Area Name: Actual Date: Action: NAICS Code(s):	CAD030398622 09 ENTIRE FACILITY 05/04/1995 CA600EC - Stabilization Measures Implemented, Primary measure is exposure control by barrier and/or institutional control 331316 332112 332993 42191 Aluminum Extruded Product Manufacturing Nonferrous Forging Ammunition (except Small Arms) Manufacturing
EPA ID: EPA Region: Area Name: Actual Date: Action: NAICS Code(s):	CAD030398622 09 ENTIRE FACILITY 05/13/1999 CA999NF - Corrective Action Process Terminated, No Further Action 331316 332112 332993 42191 Aluminum Extruded Product Manufacturing Nonferrous Forging Ammunition (except Small Arms) Manufacturing
EPA ID: EPA Region: Area Name: Actual Date: Action: NAICS Code(s):	CAD030398622 09 OFF SITE GW CONTAMINATION INVESTIGATION 06/30/1998 CA150 - RFI Workplan Approved 331316 332112 332993 42191 Aluminum Extruded Product Manufacturing Nonferrous Forging Ammunition (except Small Arms) Manufacturing
EPA ID: EPA Region: Area Name: Actual Date: Action: NAICS Code(s):	CAD030398622 09 ENTIRE FACILITY 09/23/1991 CA075LO - CA Prioritization, Facility or area was assigned a low corrective action priority 331316 332112 332993 42191 Aluminum Extruded Product Manufacturing Nonferrous Forging Ammunition (except Small Arms) Manufacturing
EPA ID: EPA Region: Area Name:	CAD030398622 09 OFF SITE GW CONTAMINATION INVESTIGATION

Database(s)

EDR ID Number EPA ID Number

## INTEL LIGHT METALS CORP (Continued)

Actual Date: Action: NAICS Code(s):	09/26/2000 CA150 - RFI Workplan Approved 331316 332112 332993 42191 Aluminum Extruded Product Manufacturing Nonferrous Forging Ammunition (except Small Arms) Manufacturing
EPA ID: EPA Region: Area Name: Actual Date: Action: NAICS Code(s):	CAD030398622 09 ENTIRE FACILITY 09/30/1996 CA050 - RFA Completed 331316 332112 332993 42191 Aluminum Extruded Product Manufacturing Nonferrous Forging Ammunition (except Small Arms) Manufacturing
CERC-NFRAP: Site ID: Federal Facility: NPL Status: Non NPL Status:	0903401 Not a Federal Facility Not on the NPL Deferred to RCRA
CERCLIS-NFRAP Site Co Contact Name: Contact Tel: Contact Title: Contact Name: Contact Tel: Contact Tel: Contact Title: Site Description: Not re	Matt Mitguard (415) 972-3096 Site Assessment Manager (SAM) Jere Johnson (415) 972-3094 Site Assessment Manager (SAM)
CERCLIS-NFRAP Assess Action: Date Started: Date Completed: Priority Level:	
Action: Date Started: Date Completed: Priority Level:	PRELIMINARY ASSESSMENT Not reported 10/17/1991 Deferred to RCRA (Subtitle C)
Action: Date Started: Date Completed: Priority Level:	ARCHIVE SITE Not reported 01/23/1996 Not reported

Database(s)

EDR ID Number EPA ID Number

40 South 1/2-1 5096 ft.	PHENOMENEX, INC. (BLDG. 4 431 AMAPOLA AVE. TORRANCE, CA 90501		ENVIROSTOR	S108484767 N/A
South 1/2-1	431 AMAPOLA AVE. TORRANCE, CA 90501 ENVIROSTOR: Site Type: Site Type Detailed: Acres: NPL: Regulatory Agencies: Lead Agency: Program Manager: Supervisor: Division Branch: Supervisor: Division Branch: Stacility ID: Site Code: Assembly: Senate: Special Program: Status: Status Date: Status Date: Status Date: Conglude: Latitude: Latitude: Latitude: Completed Area Name: Completed Date: Completed Date: Confirmed: Confirmed: Confirmed Description: Future Area Name: Future Sub Area Name: Future Sub Area Name: Status Sub Area Name: Confirmed Description: Confirmed Date: Status Area Name: Status Area Name: Status Confirmed Date: Confirmed Description: Status Area Name: Status Area Name: Stat	Valuation Valuation 26 30 MBRP, US EPA JS EPA ONI ADAMS Greg Holmes 30 Cal - Cypress 30000589 Not reported 38 EPA - PASI Active 1007-03-01 00:00:00 NO EPA Grant 33.8442 118.3235 60000589 Envirostor ID Number NONE SPECIFIED Not reported Not repor	ENVIROSTOR	
	Future Document Type: Future Due Date: Media Affected: Media Affected Desc: Management Required:	Site Screening 2008 NONE SPECIFIED Not reported NONE SPECIFIED		
	Management Required De Potential: Potenital Description: Schedule Area Name: Schedule Sub Area Name: Schedule Document Type: Schedule Due Date: Schedule Revised Date: PastUse:	sc: Not reported NONE SPECIFIED Not reported Not reported Not reported		

Database(s)

EDR ID Number EPA ID Number

41 South 1/2-1 5165 ft. Relative:	P P G INDUSTRIES INC 465 CRENSHAW BLVD TORRANCE, CA 90509	FINDS RCRA-LQG RCRA-TSDF RAATS CORRACTS	1000119890 CAD008323438
Higher	FINDS: Other Pertinent Environmental Activity Identified at Site		
	<ul> <li>FINDS:</li> <li>Other Pertinent Environmental Activity Identified at Site</li> <li>NCDB (National Compliance Data Base) supports implementation of th Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections regions and states with cooperative agreements, enforcement actions, and settlements.</li> <li>TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.</li> <li>The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).</li> <li>NJ-NJEMS (New Jersey - New Jersey Environmental Management Sy The Department of Environmental Protection (NJDEP) manages large databases of environmental information in this integrated system.</li> <li>RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCF program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.</li> <li>ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actons. This information is maintained in ICIS by EPA in the Regional offices and its Headquarters. A future release of ICIS will replace t</li></ul>	in stem). of RA	
	Compliance System (PCS) which supports the NPDES and will integra that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring		

Database(s)

EDR ID Number EPA ID Number

1000119890

## P P G INDUSTRIES INC (Continued)

RCRAInfo Corrective Action Summary:

RCRAInfo Correct Event:	ive Action Summary: Stabilization Measures Evaluation, This facility is not amenable to stabilization activity at the present time for reasons other than 1) it appears to be technically infeasible or inappropriate (NF) or 2) there is a lack of technical information (IN). Reasons for this conclusion may be the status of closure at the facility, the degree of risk, timing considerations, the status of corrective action work at the facility, or other administrative considerations.			
Event Date:	10/06/1992			
Event:	CA Prioritization, Facility or area was assigned a low corrective action priority.			
Event Date:	10/06/1992			
RCRAInfo:				
Owner:	PPG INDUSTRIES INC (412) 434-3131			
EPA ID:	CAD008323438			
Contact:	ROEL PALANCA (310) 328-7260			
Classification: TSDF Activities	Large Quantity Generator	r, TSDF		
Violation Status	: Violations exist			
Regulation Violated:		264.10-18.B		
Area of Violation:		TSD-OTHER REQUIREMENTS (OVERSIGHT)		
Date Violation Determined:		11/29/1994		
Actual Date Achieved Compliance:		01/09/1995		
Regulation Violated:		264.30-37.C		
Area of Violation:		TSD-OTHER REQUIREMENTS (OVERSIGHT)		
Date Violation Determined:		11/29/1994		
Actual Date Achieved Compliance:		01/09/1995		
Regulation Violated:		264.50-56.D		
Area of Violation:		TSD-OTHER REQUIREMENTS (OVERSIGHT)		
Date Violation Determined:		11/29/1994		
Actual Date Achieved Compliance:		01/09/1995		
Regulation Violated:		262.40-43.D		
Area of Violation:		GENERATOR-ALL REQUIREMENTS (OVERSIGHT)		
Date Violation Determined:		11/29/1994		
Actual Date Achieved Compliance:		01/09/1995		
Regulation Violated:		262.10-12.A		
Area of Violation:		GENERATOR-ALL REQUIREMENTS (OVERSIGHT)		
Date Violation Determined:		02/03/1994		
Actual Date Achieved Compliance:		11/29/1994		
Enforcement Action:		WRITTEN INFORMAL		
Enforcement Action Date:		02/18/1988		
Penalty Type:		Not reported		
Regulation Violated:		270		
Area of Violation:		TSD-OTHER REQUIREMENTS (OVERSIGHT)		
Date Violation Determined:		01/14/1991		
Actual Date Achieved Compliance:		02/22/1991		
Enforcement Action:		WRITTEN INFORMAL		
Enforcement Action Date:		02/22/1991		

Database(s)

EDR ID Number EPA ID Number

1000119890

## P P G INDUSTRIES INC (Continued)

Penalty Type:	Not reported
Regulation Violated:	270
Area of Violation:	TSD-OTHER REQUIREMENTS (OVERSIGHT)
Date Violation Determined:	01/27/1988
Actual Date Achieved Compliance:	03/04/1988
Enforcement Action:	WRITTEN INFORMAL
Enforcement Action Date:	02/18/1988
Penalty Type:	Not reported

There are 7 violation record(s) reported at this site:

		Date of
Evaluation	Area of Violation	Compliance
Compliance Evaluation Inspection	TSD-OTHER REQUIREMENTS (OVERSIGHT)	19950109
	TSD-OTHER REQUIREMENTS (OVERSIGHT)	19950109
	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)	19950109
	TSD-OTHER REQUIREMENTS (OVERSIGHT)	19950109
Compliance Evaluation Inspection	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)	19941129
Compliance Evaluation Inspection	TSD-OTHER REQUIREMENTS (OVERSIGHT)	19910222
Compliance Evaluation Inspection	TSD-OTHER REQUIREMENTS (OVERSIGHT)	19880304

#### CORRACTS:

EPA ID:	CAD008323438
EPA Region:	09
Area Name:	ENTIRE FACILITY
Actual Date:	10/06/1992
Action:	CA075LO - CA Prioritization, Facility or area was assigned a low corrective action priority
NAICS Code(s):	Not reported

#### ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
LOS ANGELES COUNTY	S105642458	1X MCKESSON DRUG CO	2		HAZNET, LUST, CHMIRS
TORRANCE	877457	IN A VACANT LOT ON THE SW CORNER ON 190TH	IN A VACANT LOT ON THE SW CORNER ON 190TH STREET AND		ERNS
		STREET AND PACIFIC	PACIFIC		
TORRANCE	1000353590	TORRANCE LDFL	SE COR MADRONA & DEL AMO BLVD	90503	CERC-NFRAP
TORRANCE	87463940	SW COR/190TH ST & PAC GATEWY DR/VAC LOT	SW COR/190TH ST & PAC GATEWY DR/VAC LOT		ERNS
TORRANCE	1004676082	SHELL SERVICE STATION	18910 CRENSHAW	90504	HAZNET, RCRA-LQG
TORRANCE	S106716511	MOBIL	20225 VAN NESS S	90501	LUST

## **EPA Waste Codes Addendum**

- D001 IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.
- D002 A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.
- D003 A MATERIAL IS CONSIDERED TO BE A REACTIVE HAZARDOUS WASTE IF IT IS NORMALLY UNSTABLE, REACTS VIOLENTLY WITH WATER, GENERATES TOXIC GASES WHEN EXPOSED TO WATER OR CORROSIVE MATERIALS, OR IF IT IS CAPABLE OF DETONATION OR EXPLOSION WHEN EXPOSED TO HEAT OR A FLAME. ONE EXAMPLE OF SUCH WASTE WOULD BY WASTE GUNPOWDER.
- D004 ARSENIC
- D005 BARIUM
- D006 CADMIUM
- D007 CHROMIUM
- D008 LEAD
- D009 MERCURY
- D010 SELENIUM
- D011 SILVER
- D018 BENZENE
- D029 1,1-DICHLOROETHYLENE
- D035 METHYL ETHYL KETONE
- D039 TETRACHLOROETHYLENE
- D040 TRICHLOROETHYLENE
- F001 THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLOROETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE, AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE,

## **EPA Waste Codes Addendum**

## Description Code A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES. F002 THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES. THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL F003 ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL: ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES. F005 THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE: ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES. F037 PETROLEUM REFINERY PRIMARY OIL/WATER/SOLIDS SEPARATION SLUDGE-ANY SLUDGE GENERATED FROM THE GRAVITATIONAL SEPARATION OF OIL/WATER/SOLIDS DURING THE STORAGE OR TREATMENT OF PROCESS WASTEWATERS AND OILY COOLING WASTEWATERS FROM PETROLEUM REFINERIES. SUCH SLUDGES INCLUDE, BUT ARE NOT LIMITED TO, THOSE GENERATED IN: OIL/WATER/SOLIDS SEPARATORS; TANKS AND IMPOUNDMENTS; DITCHES AND OTHER CONVEYANCES; SUMPS; AND STORMWATER UNITS RECEIVING DRY WEATHER FLOW. SLUDGE GENERATED IN STORMWATER UNITS THAT DO NOT RECEIVE DRY WEATHER FLOW, SLUDGES GENERATED FROM NON-CONTACT ONCE-THROUGH COOLING WATERS SEGREGATED FOR TREATMENT FROM OTHER PROCESS OR OILY COOLING WATERS, SLUDGES GENERATED IN AGGRESSIVE BIOLOGICAL TREATMENT UNITS AS DEFINED IN SECTION 261.31(B)(2) (INCLUDING SLUDGES GENERATED IN ONE OR MORE ADDITIONAL UNITS AFTER WASTEWATERS HAVE BEEN TREATED IN AGGRESSIVE BIOLOGICAL TREATMENT UNITS) AND K051 WASTES ARE NOT INCLUDED IN THIS LISTING.

- K018 HEAVY ENDS FROM THE FRACTIONATION COLUMN IN ETHYL CHLORIDE PRODUCTION
- K050 HEAT EXCHANGER BUNDLE CLEANING SLUDGE FROM THE PETROLEUM REFINING INDUSTRY
- K051 API SEPARATOR SLUDGE FROM THE PETROLEUM REFINING INDUSTRY
- P105 SODIUM AZIDE

# **EPA Waste Codes Addendum**

- Code Description
- U134 HYDROFLUORIC ACID (C,T)
- U134 HYDROGEN FLUORIDE (C,T)
- U210 ETHENE, TETRACHLORO-
- U210 TETRACHLOROETHYLENE

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

**Number of Days to Update:** Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

#### FEDERAL RECORDS

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 07/18/2007 Date Data Arrived at EDR: 08/03/2007 Date Made Active in Reports: 08/29/2007 Number of Days to Update: 26 Source: EPA Telephone: N/A Last EDR Contact: 07/31/2007 Next Scheduled EDR Contact: 10/29/2007 Data Release Frequency: Quarterly

#### **NPL Site Boundaries**

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC) Telephone: 202-564-7333

EPA Region 1 Telephone 617-918-1143

EPA Region 3 Telephone 215-814-5418

EPA Region 4 Telephone 404-562-8033

EPA Region 5 Telephone 312-886-6686

EPA Region 10 Telephone 206-553-8665 EPA Region 7 Telephone: 913-551-7247

EPA Region 6

EPA Region 8 Telephone: 303-312-6774

Telephone: 214-655-6659

EPA Region 9 Telephone: 415-947-4246

#### Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 08/09/2007 Date Data Arrived at EDR: 09/05/2007 Date Made Active in Reports: 10/11/2007 Number of Days to Update: 36 Source: EPA Telephone: N/A Last EDR Contact: 08/31/2007 Next Scheduled EDR Contact: 10/29/2007 Data Release Frequency: Quarterly

#### **DELISTED NPL:** National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 08/27/2007 Date Data Arrived at EDR: 08/29/2007 Date Made Active in Reports: 10/11/2007 Number of Days to Update: 43 Source: EPA Telephone: N/A Last EDR Contact: 08/29/2007 Next Scheduled EDR Contact: 10/29/2007 Data Release Frequency: Quarterly

#### NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991	Source: EPA
Date Data Arrived at EDR: 02/02/1994	Telephone: 202-564-4267
Date Made Active in Reports: 03/30/1994	Last EDR Contact: 08/20/2007
Number of Days to Update: 56	Next Scheduled EDR Contact: 11/19/2007
	Data Release Frequency: No Update Planned

**CERCLIS:** Comprehensive Environmental Response, Compensation, and Liability Information System CERCLIS contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). CERCLIS contains sites which are either proposed to or on the National Priorities List (NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 04/23/2007 Date Data Arrived at EDR: 06/20/2007 Date Made Active in Reports: 08/29/2007 Number of Days to Update: 70

Source: EPA Telephone: 703-412-9810 Last EDR Contact: 09/19/2007 Next Scheduled EDR Contact: 12/17/2007 Data Release Frequency: Quarterly

### CERCLIS-NFRAP: CERCLIS No Further Remedial Action Planned

Archived sites are sites that have been removed and archived from the inventory of CERCLIS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

Date of Government Version: 06/21/2007 Date Data Arrived at EDR: 07/23/2007 Date Made Active in Reports: 08/29/2007 Number of Days to Update: 37 Source: EPA Telephone: 703-412-9810 Last EDR Contact: 09/17/2007 Next Scheduled EDR Contact: 12/17/2007 Data Release Frequency: Quarterly

### CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 06/26/2007 Date Data Arrived at EDR: 08/08/2007 Date Made Active in Reports: 08/29/2007 Number of Days to Update: 21 Source: EPA Telephone: 800-424-9346 Last EDR Contact: 09/04/2007 Next Scheduled EDR Contact: 12/03/2007 Data Release Frequency: Quarterly

RCRA: Resource Conservation and Recovery Act Information

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRAInfo replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS). The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month. Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month. Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month. Transporters are individuals or entities that move hazardous waste from the generator off-site to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 06/13/2006 Date Data Arrived at EDR: 06/28/2006 Date Made Active in Reports: 08/23/2006 Number of Days to Update: 56 Source: EPA Telephone: (415) 495-8895 Last EDR Contact: 09/04/2007 Next Scheduled EDR Contact: 10/15/2007 Data Release Frequency: Quarterly

### ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 12/31/2006	Source: National Response Center, United States Coast Guard
Date Data Arrived at EDR: 01/24/2007	Telephone: 202-267-2180
Date Made Active in Reports: 03/12/2007	Last EDR Contact: 07/23/2007
Number of Days to Update: 47	Next Scheduled EDR Contact: 10/22/2007
	Data Release Frequency: Annually

### HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 07/02/2007 Date Data Arrived at EDR: 07/18/2007 Date Made Active in Reports: 09/18/2007 Number of Days to Update: 62 Source: U.S. Department of Transportation Telephone: 202-366-4555 Last EDR Contact: 07/18/2007 Next Scheduled EDR Contact: 10/15/2007 Data Release Frequency: Annually

### US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 07/16/2007 Date Data Arrived at EDR: 08/03/2007 Date Made Active in Reports: 10/11/2007 Number of Days to Update: 69

Source: Environmental Protection Agency Telephone: 703-603-8905 Last EDR Contact: 10/01/2007 Next Scheduled EDR Contact: 12/31/2007 Data Release Frequency: Varies

#### US INST CONTROL: Sites with Institutional Controls

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 07/16/2007 Date Data Arrived at EDR: 08/03/2007 Date Made Active in Reports: 10/11/2007 Number of Days to Update: 69 Source: Environmental Protection Agency Telephone: 703-603-8905 Last EDR Contact: 10/01/2007 Next Scheduled EDR Contact: 12/31/2007 Data Release Frequency: Varies

#### DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005 Date Data Arrived at EDR: 11/10/2006 Date Made Active in Reports: 01/11/2007 Number of Days to Update: 62	Source: USGS Telephone: 703-692-8801 Last EDR Contact: 08/09/2007 Next Scheduled EDR Contact: 11/05/2007 Data Release Frequency: Semi-Annually

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 12/31/2006	Source:
Date Data Arrived at EDR: 08/31/2007	Telephor
Date Made Active in Reports: 10/11/2007	Last EDF
Number of Days to Update: 41	Next Sch

Source: U.S. Army Corps of Engineers Telephone: 202-528-4285 Last EDR Contact: 10/01/2007 Next Scheduled EDR Contact: 12/31/2007 Data Release Frequency: Varies

### US BROWNFIELDS: A Listing of Brownfields Sites

Included in the listing are brownfields properties addresses by Cooperative Agreement Recipients and brownfields properties addressed by Targeted Brownfields Assessments. Targeted Brownfields Assessments-EPA's Targeted Brownfields Assessments (TBA) program is designed to help states, tribes, and municipalities--especially those without EPA Brownfields Assessment Demonstration Pilots--minimize the uncertainties of contamination often associated with brownfields. Under the TBA program, EPA provides funding and/or technical assistance for environmental assessments at brownfields sites throughout the country. Targeted Brownfields Assessments supplement and work with other efforts under EPA's Brownfields Initiative to promote cleanup and redevelopment of brownfields. Cooperative Agreement Recipients-States, political subdivisions, territories, and Indian tribes become Brownfields Cleanup Revolving Loan Fund (BCRLF) cooperative agreement recipients when they enter into BCRLF cooperative agreements with the U.S. EPA. EPA selects BCRLF cooperative agreement recipients based on a proposal and application process. BCRLF cooperative agreement for specified brownfields-related cleanup activities.

Date of Government Version: 06/20/2007 Date Data Arrived at EDR: 07/09/2007 Date Made Active in Reports: 08/29/2007 Number of Days to Update: 51 Source: Environmental Protection Agency Telephone: 202-566-2777 Last EDR Contact: 09/10/2007 Next Scheduled EDR Contact: 12/10/2007 Data Release Frequency: Semi-Annually

### CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 04/13/2007 Date Data Arrived at EDR: 07/16/2007 Date Made Active in Reports: 08/29/2007 Number of Days to Update: 44 Source: Department of Justice, Consent Decree Library Telephone: Varies Last EDR Contact: 08/23/2007 Next Scheduled EDR Contact: 10/22/2007 Data Release Frequency: Varies

### **ROD:** Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 06/08/2007
Date Data Arrived at EDR: 07/03/2007
Date Made Active in Reports: 08/29/2007
Number of Days to Update: 57

Source: EPA Telephone: 703-416-0223 Last EDR Contact: 10/01/2007 Next Scheduled EDR Contact: 12/31/2007 Data Release Frequency: Annually

### UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Versio Date Data Arrived at EDR: Date Made Active in Report Number of Days to Update:	11/08/2006         Telephor           s: 01/29/2007         Last EDF           82         Next Sch	Department of Energy e: 505-845-0011 2 Contact: 09/19/2007 eduled EDR Contact: 12/17/2007 ease Frequency: Varies
<b>ODI:</b> Open Dump Inventory An open dump is defined as Subtitle D Criteria.	s a disposal facility that does r	ot comply with one or more of the Part 257 or Part 258
Date of Government Versio Date Data Arrived at EDR: ( Date Made Active in Report Number of Days to Update:	08/09/2004 Telephor s: 09/17/2004 Last EDF 39 Next Sch	Environmental Protection Agency e: 800-424-9346 c Contact: 06/09/2004 eduled EDR Contact: N/A ease Frequency: No Update Planned
		which release toxic chemicals to the air, water and 313.
Date of Government Versio Date Data Arrived at EDR: ( Date Made Active in Report Number of Days to Update:	04/27/2007 Telephor s: 07/05/2007 Last EDF 69 Next Sch	EPA e: 202-566-0250 c Contact: 09/18/2007 eduled EDR Contact: 12/17/2007 ease Frequency: Annually
	ct. TSCA identifies manufactu	irers and importers of chemical substances included on the on the production volume of these substances by plant
Date of Government Versio Date Data Arrived at EDR: ( Date Made Active in Report Number of Days to Update:	04/14/2006 Telephor s: 05/30/2006 Last EDF 46 Next Sch	EPA e: 202-260-5521 c Contact: 07/30/2007 eduled EDR Contact: 10/15/2007 ease Frequency: Every 4 Years
FTTS tracks administrative	cases and pesticide enforcem ency Planning and Community	icide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act) ent actions and compliance activities related to FIFRA, Right-to-Know Act). To maintain currency, EDR contacts the
Date of Government Versio Date Data Arrived at EDR: ( Date Made Active in Report Number of Days to Update:	07/20/2007         Telephor           s: 09/18/2007         Last EDF           60         Next Sch	EPA/Office of Prevention, Pesticides and Toxic Substances e: 202-566-1667 e Contact: 09/17/2007 eduled EDR Contact: 12/17/2007 ease Frequency: Quarterly
	ting System - FIFRA (Federal acking System (FTTS) inspect	Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act) ions and enforcements.
Date of Government Versio Date Data Arrived at EDR: ( Date Made Active in Report Number of Days to Update:	07/20/2007 Telephor s: 09/18/2007 Last EDF 60 Next Sch	EPA e: 202-566-1667 c Contact: 09/17/2007 eduled EDR Contact: 12/17/2007

Data Release Frequency: Quarterly

#### SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

2011.91	neurosa, ana mese naring seen preud	
Date D Date M	f Government Version: 12/31/2005 ata Arrived at EDR: 03/13/2007 lade Active in Reports: 04/27/2007 er of Days to Update: 45	Source: EPA Telephone: 202-564-4203 Last EDR Contact: 07/16/2007 Next Scheduled EDR Contact: 10/15/2007 Data Release Frequency: Annually
		ormation pertaining to the former Navy Base Realignment and Closure
Date D Date M	f Government Version: 12/09/2005 ata Arrived at EDR: 12/11/2006 lade Active in Reports: 01/11/2007 er of Days to Update: 31	Source: Department of the Navy Telephone: 843-820-7326 Last EDR Contact: 09/12/2007 Next Scheduled EDR Contact: 12/10/2007 Data Release Frequency: Varies
	Incident and Accident Data ment of Transporation, Office of Pipeline	e Safety Incident and Accident data.
Date D Date M	f Government Version: 08/14/2007 lata Arrived at EDR: 08/29/2007 lade Active in Reports: 10/11/2007 er of Days to Update: 43	Source: Department of Transporation, Office of Pipeline Safety Telephone: 202-366-4595 Last EDR Contact: 08/29/2007 Next Scheduled EDR Contact: 11/26/2007 Data Release Frequency: Varies
The In	mpliance program as well as the unique	n (ICIS) supports the information needs of the national enforcement needs of the National Pollutant Discharge Elimination System (NPDES)
Date D Date M	f Government Version: 07/27/2007 ata Arrived at EDR: 08/13/2007 lade Active in Reports: 10/11/2007 er of Days to Update: 59	Source: Environmental Protection Agency Telephone: 202-564-5088 Last EDR Contact: 10/15/2007 Next Scheduled EDR Contact: 01/14/2008 Data Release Frequency: Quarterly
A listin	<b>GION 9:</b> Torres Martinez Reservation II g of illegal dump sites location on the To and northern Imperial County, Californi	orres Martinez Indian Reservation located in eastern Riverside
Date D Date M	f Government Version: 07/25/2007 lata Arrived at EDR: 07/31/2007 lade Active in Reports: 10/11/2007 er of Days to Update: 72	Source: EPA, Region 9 Telephone: 415-972-3336 Last EDR Contact: 09/24/2007 Next Scheduled EDR Contact: 12/24/2007 Data Release Frequency: Varies

## HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006 Date Data Arrived at EDR: 03/01/2007 Date Made Active in Reports: 04/10/2007 Number of Days to Update: 40 Source: Environmental Protection Agency Telephone: 202-564-2501 Last EDR Contact: 09/17/2007 Next Scheduled EDR Contact: 12/17/2007 Data Release Frequency: No Update Planned

#### CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 12/01/2006 Date Data Arrived at EDR: 01/08/2007 Date Made Active in Reports: 01/11/2007 Number of Days to Update: 3 Source: Drug Enforcement Administration Telephone: 202-307-1000 Last EDR Contact: 10/02/2007 Next Scheduled EDR Contact: 12/24/2007 Data Release Frequency: Quarterly

### **RADINFO:** Radiation Information Database

The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 07/31/2007 Date Data Arrived at EDR: 08/01/2007 Date Made Active in Reports: 08/29/2007 Number of Days to Update: 28 Source: Environmental Protection Agency Telephone: 202-343-9775 Last EDR Contact: 08/01/2007 Next Scheduled EDR Contact: 10/29/2007 Data Release Frequency: Quarterly

#### LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 03/08/2007 Date Data Arrived at EDR: 04/12/2007 Date Made Active in Reports: 05/14/2007 Number of Days to Update: 32 Source: Environmental Protection Agency Telephone: 202-564-6023 Last EDR Contact: 08/20/2007 Next Scheduled EDR Contact: 11/19/2007 Data Release Frequency: Varies

#### PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 04/12/2007 Date Data Arrived at EDR: 06/08/2007 Date Made Active in Reports: 08/29/2007 Number of Days to Update: 82 Source: EPA Telephone: 202-566-0500 Last EDR Contact: 08/09/2007 Next Scheduled EDR Contact: 11/05/2007 Data Release Frequency: Annually

#### MLTS: Material Licensing Tracking System

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 07/09/2007 Date Data Arrived at EDR: 07/24/2007 Date Made Active in Reports: 09/18/2007 Number of Days to Update: 56 Source: Nuclear Regulatory Commission Telephone: 301-415-7169 Last EDR Contact: 10/01/2007 Next Scheduled EDR Contact: 12/31/2007 Data Release Frequency: Quarterly

#### MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 05/09/2007 Date Data Arrived at EDR: 06/28/2007 Date Made Active in Reports: 08/29/2007 Number of Days to Update: 62 Source: Department of Labor, Mine Safety and Health Administration Telephone: 303-231-5959 Last EDR Contact: 09/26/2007 Next Scheduled EDR Contact: 12/24/2007 Data Release Frequency: Semi-Annually

#### FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 07/19/2007 Date Data Arrived at EDR: 07/25/2007 Date Made Active in Reports: 09/18/2007 Number of Days to Update: 55 Source: EPA Telephone: (415) 947-8000 Last EDR Contact: 10/01/2007 Next Scheduled EDR Contact: 12/31/2007 Data Release Frequency: Quarterly

## RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995 Date Data Arrived at EDR: 07/03/1995 Date Made Active in Reports: 08/07/1995 Number of Days to Update: 35 Source: EPA Telephone: 202-564-4104 Last EDR Contact: 08/31/2007 Next Scheduled EDR Contact: 12/03/2007 Data Release Frequency: No Update Planned

#### BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2005 Date Data Arrived at EDR: 03/06/2007 Date Made Active in Reports: 04/13/2007 Number of Days to Update: 38 Source: EPA/NTIS Telephone: 800-424-9346 Last EDR Contact: 09/12/2007 Next Scheduled EDR Contact: 12/10/2007 Data Release Frequency: Biennially

## USGS WATER WELLS: National Water Information System (NWIS)

This database consists of well records in the United States. Available site descriptive information includes well location information (latitude and longitude, well depth, site use, water use, and aquifer).

Date of Government Version: 03/25/2005 Date Data Arrived at EDR: 03/25/2005 Date Made Active in Reports: N/A Number of Days to Update: 0 Source: USGS Telephone: N/A Last EDR Contact: 03/25/2005 Next Scheduled EDR Contact: N/A Data Release Frequency: N/A

### PWS: Public Water System Data

This Safe Drinking Water Information System (SDWIS) file contains public water systems name and address, population served and the primary source of water

Date of Government Version: 02/24/2000 Date Data Arrived at EDR: 04/27/2005 Date Made Active in Reports: N/A Number of Days to Update: 0

#### STATE AND LOCAL RECORDS

## HIST CAL-SITES: Calsites Database

Source: EPA Telephone: N/A Last EDR Contact: 08/20/2007 Next Scheduled EDR Contact: 11/19/2007 Data Release Frequency: N/A

The Calsites database contains potential or confirmed hazardous substance release properties. In 1996, California EPA reevaluated and significantly reduced the number of sites in the Calsites database. No longer updated by the state agency. It has been replaced by ENVIROSTOR.

Date of Government Version: 08/08/2005 Date Data Arrived at EDR: 08/03/2006 Date Made Active in Reports: 08/24/2006 Number of Days to Update: 21 Source: Department of Toxic Substance Control Telephone: 916-323-3400 Last EDR Contact: 08/27/2007 Next Scheduled EDR Contact: 11/26/2007 Data Release Frequency: No Update Planned

## CA BOND EXP. PLAN: Bond Expenditure Plan

Department of Health Services developed a site-specific expenditure plan as the basis for an appropriation of Hazardous Substance Cleanup Bond Act funds. It is not updated.

Date of Government Version: 01/01/1989	Source: Department of Health Services
Date Data Arrived at EDR: 07/27/1994	Telephone: 916-255-2118
Date Made Active in Reports: 08/02/1994	Last EDR Contact: 05/31/1994
Number of Days to Update: 6	Next Scheduled EDR Contact: N/A
	Data Release Frequency: No Update Planned

#### SCH: School Property Evaluation Program

This category contains proposed and existing school sites that are being evaluated by DTSC for possible hazardous materials contamination. In some cases, these properties may be listed in the CalSites category depending on the level of threat to public health and safety or the environment they pose.

Date of Government Version: 08/28/2007	Source: Department of Toxic Substances Control
Date Data Arrived at EDR: 08/29/2007	Telephone: 916-323-3400
Date Made Active in Reports: 09/26/2007	Last EDR Contact: 08/29/2007
Number of Days to Update: 28	Next Scheduled EDR Contact: 11/26/2007
	Data Release Frequency: Quarterly

#### TOXIC PITS: Toxic Pits Cleanup Act Sites

Toxic PITS Cleanup Act Sites. TOXIC PITS identifies sites suspected of containing hazardous substances where cleanup has not yet been completed.

Date of Government Version: 07/01/1995	Source: State Water Resources Control Board
Date Data Arrived at EDR: 08/30/1995	Telephone: 916-227-4364
Date Made Active in Reports: 09/26/1995	Last EDR Contact: 07/30/2007
Number of Days to Update: 27	Next Scheduled EDR Contact: 10/29/2007
	Data Release Frequency: No Update Planned

## SWF/LF (SWIS): Solid Waste Information System

Active, Closed and Inactive Landfills. SWF/LF records typically contain an inventory of solid waste disposal facilities or landfills. These may be active or i nactive facilities or open dumps that failed to meet RCRA Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 09/10/2007 Date Data Arrived at EDR: 09/12/2007 Date Made Active in Reports: 09/28/2007 Number of Days to Update: 16 Source: Integrated Waste Management Board Telephone: 916-341-6320 Last EDR Contact: 09/12/2007 Next Scheduled EDR Contact: 12/10/2007 Data Release Frequency: Quarterly

#### WMUDS/SWAT: Waste Management Unit Database

Waste Management Unit Database System. WMUDS is used by the State Water Resources Control Board staff and the Regional Water Quality Control Boards for program tracking and inventory of waste management units. WMUDS is composed of the following databases: Facility Information, Scheduled Inspections Information, Waste Management Unit Information, SWAT Program Information, SWAT Report Summary Information, SWAT Report Summary Data, Chapter 15 (formerly Subchapter 15) Information, Chapter 15 Monitoring Parameters, TPCA Program Information, RCRA Program Information, Closure Information, and Interested Parties Information.

Information, and Interested Parties Information	n.
Date of Government Version: 04/01/2000 Date Data Arrived at EDR: 04/10/2000 Date Made Active in Reports: 05/10/2000 Number of Days to Update: 30	Source: State Water Resources Control Board Telephone: 916-227-4448 Last EDR Contact: 09/04/2007 Next Scheduled EDR Contact: 12/03/2007 Data Release Frequency: Quarterly
CA WDS: Waste Discharge System Sites which have been issued waste discharg	e requirements.
Date of Government Version: 06/19/2007 Date Data Arrived at EDR: 06/20/2007 Date Made Active in Reports: 06/29/2007 Number of Days to Update: 9	Source: State Water Resources Control Board Telephone: 916-341-5227 Last EDR Contact: 09/17/2007 Next Scheduled EDR Contact: 12/17/2007 Data Release Frequency: Quarterly
с ,	nces Sites List te Water Resource Control Board (LUST), the Integrated Waste c Substances Control (Cal-Sites). This listing is no longer updated
Date of Government Version: 04/01/2001 Date Data Arrived at EDR: 05/29/2001 Date Made Active in Reports: 07/26/2001 Number of Days to Update: 58	Source: CAL EPA/Office of Emergency Information Telephone: 916-323-3400 Last EDR Contact: 07/23/2007 Next Scheduled EDR Contact: 10/22/2007 Data Release Frequency: No Update Planned
SWRCY: Recycler Database A listing of recycling facilities in California.	
Date of Government Version: 07/09/2007 Date Data Arrived at EDR: 07/11/2007 Date Made Active in Reports: 08/09/2007 Number of Days to Update: 29	Source: Department of Conservation Telephone: 916-323-3836 Last EDR Contact: 10/11/2007 Next Scheduled EDR Contact: 01/07/2008 Data Release Frequency: Quarterly
LUST REG 9: Leaking Underground Storage Tank Orange, Riverside, San Diego counties. For m Control Board's LUST database.	Report hore current information, please refer to the State Water Resources
Date of Government Version: 03/01/2001 Date Data Arrived at EDR: 04/23/2001 Date Made Active in Reports: 05/21/2001 Number of Days to Update: 28	Source: California Regional Water Quality Control Board San Diego Region (9) Telephone: 858-637-5595 Last EDR Contact: 10/15/2007 Next Scheduled EDR Contact: 01/14/2008 Data Release Frequency: No Update Planned
LUST REG 8: Leaking Underground Storage Tank California Regional Water Quality Control Board's to the State Water Resources Control Board's	ard Santa Ana Region (8). For more current information, please refer
Date of Government Version: 02/14/2005 Date Data Arrived at EDR: 02/15/2005 Date Made Active in Reports: 03/28/2005 Number of Days to Update: 41	Source: California Regional Water Quality Control Board Santa Ana Region (8) Telephone: 909-782-4496 Last EDR Contact: 08/06/2007 Next Scheduled EDR Contact: 11/05/2007

Date of Government Version: 06/07/2005	Source: California Regional Water Quality Control Board Victorville Branch Office (6
Date Data Arrived at EDR: 06/07/2005	Telephone: 760-241-7365
Date Made Active in Reports: 06/29/2005	Last EDR Contact: 10/01/2007
Number of Days to Update: 22	Next Scheduled EDR Contact: 12/31/2007 Data Release Frequency: No Update Planned
<b>LUST REG 6L:</b> Leaking Underground Storage Ta For more current information, please refer to	nk Case Listing the State Water Resources Control Board's LUST database.
Date of Government Version: 09/09/2003 Date Data Arrived at EDR: 09/10/2003	Source: California Regional Water Quality Control Board Lahontan Region (6) Telephone: 530-542-5572
Date Made Active in Reports: 10/07/2003	Last EDR Contact: 09/04/2007
Number of Days to Update: 27	Next Scheduled EDR Contact: 12/03/2007
	Data Release Frequency: No Update Planned
LUST REG 5: Leaking Underground Storage Tan Leaking Underground Storage Tank location	k Database s. Alameda, Alpine, Amador, Butte, Colusa, Contra Costa, Calveras, El
Dorado, Fresno, Glenn, Kern, Kings, Lake, L	assen, Madera, Mariposa, Merced, Modoc, Napa, Nevada, Placer, Plumas, Stanislaus, Sutter, Tehama, Tulare, Tuolumne, Yolo, Yuba counties.
Date of Government Version: 07/01/2007 Date Data Arrived at EDR: 08/01/2007	Source: California Regional Water Quality Control Board Central Valley Region (5) Telephone: 916-464-4834
Date Made Active in Reports: 08/09/2007	Last EDR Contact: 10/03/2007
Number of Days to Update: 8	Next Scheduled EDR Contact: 12/31/2007
	Data Release Frequency: Quarterly
	ist rrent information, please refer to the State Water Resources Control
Board's LUST database.	
Board's LUST database. Date of Government Version: 09/07/2004	Source: California Regional Water Quality Control Board Los Angeles Region (4)
Date of Government Version: 09/07/2004 Date Data Arrived at EDR: 09/07/2004	Source: California Regional Water Quality Control Board Los Angeles Region (4) Telephone: 213-576-6710
Date of Government Version: 09/07/2004 Date Data Arrived at EDR: 09/07/2004 Date Made Active in Reports: 10/12/2004	Source: California Regional Water Quality Control Board Los Angeles Region (4)
Date of Government Version: 09/07/2004 Date Data Arrived at EDR: 09/07/2004	Source: California Regional Water Quality Control Board Los Angeles Region (4) Telephone: 213-576-6710 Last EDR Contact: 09/24/2007
Date of Government Version: 09/07/2004 Date Data Arrived at EDR: 09/07/2004 Date Made Active in Reports: 10/12/2004 Number of Days to Update: 35	Source: California Regional Water Quality Control Board Los Angeles Region (4) Telephone: 213-576-6710 Last EDR Contact: 09/24/2007 Next Scheduled EDR Contact: 12/24/2007 Data Release Frequency: No Update Planned
Date of Government Version: 09/07/2004 Date Data Arrived at EDR: 09/07/2004 Date Made Active in Reports: 10/12/2004 Number of Days to Update: 35 <b>LUST REG 3:</b> Leaking Underground Storage Tan Leaking Underground Storage Tank locations Date of Government Version: 05/19/2003	Source: California Regional Water Quality Control Board Los Angeles Region (4) Telephone: 213-576-6710 Last EDR Contact: 09/24/2007 Next Scheduled EDR Contact: 12/24/2007 Data Release Frequency: No Update Planned k Database s. Monterey, San Benito, San Luis Obispo, Santa Barbara, Santa Cruz counties. Source: California Regional Water Quality Control Board Central Coast Region (3)
Date of Government Version: 09/07/2004 Date Data Arrived at EDR: 09/07/2004 Date Made Active in Reports: 10/12/2004 Number of Days to Update: 35 <b>LUST REG 3:</b> Leaking Underground Storage Tan Leaking Underground Storage Tank location: Date of Government Version: 05/19/2003 Date Data Arrived at EDR: 05/19/2003	Source: California Regional Water Quality Control Board Los Angeles Region (4) Telephone: 213-576-6710 Last EDR Contact: 09/24/2007 Next Scheduled EDR Contact: 12/24/2007 Data Release Frequency: No Update Planned k Database s. Monterey, San Benito, San Luis Obispo, Santa Barbara, Santa Cruz counties. Source: California Regional Water Quality Control Board Central Coast Region (3) Telephone: 805-542-4786
Date of Government Version: 09/07/2004 Date Data Arrived at EDR: 09/07/2004 Date Made Active in Reports: 10/12/2004 Number of Days to Update: 35 <b>LUST REG 3:</b> Leaking Underground Storage Tan Leaking Underground Storage Tank locations Date of Government Version: 05/19/2003	Source: California Regional Water Quality Control Board Los Angeles Region (4) Telephone: 213-576-6710 Last EDR Contact: 09/24/2007 Next Scheduled EDR Contact: 12/24/2007 Data Release Frequency: No Update Planned k Database s. Monterey, San Benito, San Luis Obispo, Santa Barbara, Santa Cruz counties. Source: California Regional Water Quality Control Board Central Coast Region (3)
Date of Government Version: 09/07/2004 Date Data Arrived at EDR: 09/07/2004 Date Made Active in Reports: 10/12/2004 Number of Days to Update: 35 <b>LUST REG 3:</b> Leaking Underground Storage Tan Leaking Underground Storage Tank location: Date of Government Version: 05/19/2003 Date Data Arrived at EDR: 05/19/2003 Date Made Active in Reports: 06/02/2003	Source: California Regional Water Quality Control Board Los Angeles Region (4) Telephone: 213-576-6710 Last EDR Contact: 09/24/2007 Next Scheduled EDR Contact: 12/24/2007 Data Release Frequency: No Update Planned k Database s. Monterey, San Benito, San Luis Obispo, Santa Barbara, Santa Cruz counties. Source: California Regional Water Quality Control Board Central Coast Region (3) Telephone: 805-542-4786 Last EDR Contact: 08/13/2007 Next Scheduled EDR Contact: 11/12/2007
Date of Government Version: 09/07/2004 Date Data Arrived at EDR: 09/07/2004 Date Made Active in Reports: 10/12/2004 Number of Days to Update: 35 <b>LUST REG 3:</b> Leaking Underground Storage Tan Leaking Underground Storage Tank location: Date of Government Version: 05/19/2003 Date Data Arrived at EDR: 05/19/2003 Date Made Active in Reports: 06/02/2003 Number of Days to Update: 14	Source: California Regional Water Quality Control Board Los Angeles Region (4) Telephone: 213-576-6710 Last EDR Contact: 09/24/2007 Next Scheduled EDR Contact: 12/24/2007 Data Release Frequency: No Update Planned k Database s. Monterey, San Benito, San Luis Obispo, Santa Barbara, Santa Cruz counties. Source: California Regional Water Quality Control Board Central Coast Region (3) Telephone: 805-542-4786 Last EDR Contact: 08/13/2007 Next Scheduled EDR Contact: 11/12/2007
Date of Government Version: 09/07/2004 Date Data Arrived at EDR: 09/07/2004 Date Made Active in Reports: 10/12/2004 Number of Days to Update: 35 <b>LUST REG 3:</b> Leaking Underground Storage Tan Leaking Underground Storage Tank locations Date of Government Version: 05/19/2003 Date Data Arrived at EDR: 05/19/2003 Date Made Active in Reports: 06/02/2003 Number of Days to Update: 14 <b>LUST REG 2:</b> Fuel Leak List Leaking Underground Storage Tank locations Clara, Solano, Sonoma counties. Date of Government Version: 09/30/2004	Source: California Regional Water Quality Control Board Los Angeles Region (4) Telephone: 213-576-6710 Last EDR Contact: 09/24/2007 Next Scheduled EDR Contact: 12/24/2007 Data Release Frequency: No Update Planned k Database s. Monterey, San Benito, San Luis Obispo, Santa Barbara, Santa Cruz counties. Source: California Regional Water Quality Control Board Central Coast Region (3) Telephone: 805-542-4786 Last EDR Contact: 08/13/2007 Next Scheduled EDR Contact: 11/12/2007 Data Release Frequency: No Update Planned s. Alameda, Contra Costa, Marin, Napa, San Francisco, San Mateo, Santa Source: California Regional Water Quality Control Board San Francisco Bay Region
Date of Government Version: 09/07/2004 Date Data Arrived at EDR: 09/07/2004 Date Made Active in Reports: 10/12/2004 Number of Days to Update: 35 <b>LUST REG 3:</b> Leaking Underground Storage Tan Leaking Underground Storage Tank locations Date of Government Version: 05/19/2003 Date Data Arrived at EDR: 05/19/2003 Date Made Active in Reports: 06/02/2003 Number of Days to Update: 14 <b>LUST REG 2:</b> Fuel Leak List Leaking Underground Storage Tank locations Clara, Solano, Sonoma counties. Date of Government Version: 09/30/2004 Date Data Arrived at EDR: 10/20/2004	Source: California Regional Water Quality Control Board Los Angeles Region (4) Telephone: 213-576-6710 Last EDR Contact: 09/24/2007 Next Scheduled EDR Contact: 12/24/2007 Data Release Frequency: No Update Planned k Database s. Monterey, San Benito, San Luis Obispo, Santa Barbara, Santa Cruz counties. Source: California Regional Water Quality Control Board Central Coast Region (3) Telephone: 805-542-4786 Last EDR Contact: 08/13/2007 Next Scheduled EDR Contact: 11/12/2007 Data Release Frequency: No Update Planned s. Alameda, Contra Costa, Marin, Napa, San Francisco, San Mateo, Santa Source: California Regional Water Quality Control Board San Francisco Bay Region Telephone: 510-622-2433
Date of Government Version: 09/07/2004 Date Data Arrived at EDR: 09/07/2004 Date Made Active in Reports: 10/12/2004 Number of Days to Update: 35 <b>LUST REG 3:</b> Leaking Underground Storage Tan Leaking Underground Storage Tank locations Date of Government Version: 05/19/2003 Date Data Arrived at EDR: 05/19/2003 Date Made Active in Reports: 06/02/2003 Number of Days to Update: 14 <b>LUST REG 2:</b> Fuel Leak List Leaking Underground Storage Tank locations Clara, Solano, Sonoma counties. Date of Government Version: 09/30/2004	Source: California Regional Water Quality Control Board Los Angeles Region (4) Telephone: 213-576-6710 Last EDR Contact: 09/24/2007 Next Scheduled EDR Contact: 12/24/2007 Data Release Frequency: No Update Planned k Database s. Monterey, San Benito, San Luis Obispo, Santa Barbara, Santa Cruz counties. Source: California Regional Water Quality Control Board Central Coast Region (3) Telephone: 805-542-4786 Last EDR Contact: 08/13/2007 Next Scheduled EDR Contact: 11/12/2007 Data Release Frequency: No Update Planned s. Alameda, Contra Costa, Marin, Napa, San Francisco, San Mateo, Santa Source: California Regional Water Quality Control Board San Francisco Bay Region

Date of Government Version: 02/01/2001
Date Data Arrived at EDR: 02/28/2001
Date Made Active in Reports: 03/29/2001
Number of Days to Update: 29

Source: California Regional Water Quality Control Board North Coast (1) Telephone: 707-570-3769 Last EDR Contact: 08/20/2007 Next Scheduled EDR Contact: 11/19/2007 Data Release Frequency: No Update Planned

#### LUST: Geotracker's Leaking Underground Fuel Tank Report

Leaking Underground Storage Tank Incident Reports. LUST records contain an inventory of reported leaking underground storage tank incidents. Not all states maintain these records, and the information stored varies by state. For more information on a particular leaking underground storage tank sites, please contact the appropriate regulatory agency.

Date of Government Version: 07/10/2007 Date Data Arrived at EDR: 07/11/2007 Date Made Active in Reports: 08/09/2007 Number of Days to Update: 29 Source: State Water Resources Control Board Telephone: see region list Last EDR Contact: 10/11/2007 Next Scheduled EDR Contact: 01/07/2008 Data Release Frequency: Quarterly

## LUST REG 7: Leaking Underground Storage Tank Case Listing

Leaking Underground Storage Tank locations. Imperial, Riverside, San Diego, Santa Barbara counties.

Date of Government Version: 02/26/2004	Source: California Regional Water Quality Control Board Colorado River Basin Region (7)
Date Data Arrived at EDR: 02/26/2004	Telephone: 760-776-8943
Date Made Active in Reports: 03/24/2004	Last EDR Contact: 08/20/2007
Number of Days to Update: 27	Next Scheduled EDR Contact: 11/19/2007
	Data Release Frequency: No Update Planned

## CA FID UST: Facility Inventory Database

The Facility Inventory Database (FID) contains a historical listing of active and inactive underground storage tank locations from the State Water Resource Control Board. Refer to local/county source for current data.

Date of Government Version: 10/31/1994 Date Data Arrived at EDR: 09/05/1995 Date Made Active in Reports: 09/29/1995 Number of Days to Update: 24 Source: California Environmental Protection Agency Telephone: 916-341-5851 Last EDR Contact: 12/28/1998 Next Scheduled EDR Contact: N/A Data Release Frequency: No Update Planned

#### **SLIC:** Statewide SLIC Cases

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 08/03/2007 Date Data Arrived at EDR: 08/03/2007 Date Made Active in Reports: 08/09/2007 Number of Days to Update: 6 Source: State Water Resources Control Board Telephone: 866-480-1028 Last EDR Contact: 10/11/2007 Next Scheduled EDR Contact: 01/07/2008 Data Release Frequency: Varies

#### SLIC REG 1: Active Toxic Site Investigations

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 04/03/2003
Date Data Arrived at EDR: 04/07/2003
Date Made Active in Reports: 04/25/2003
Number of Days to Update: 18

Source: California Regional Water Quality Control Board, North Coast Region (1) Telephone: 707-576-2220 Last EDR Contact: 08/20/2007 Next Scheduled EDR Contact: 11/19/2007 Data Release Frequency: No Update Planned

SLIC REG 2: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

	Date of Government Version: 09/30/2004 Date Data Arrived at EDR: 10/20/2004 Date Made Active in Reports: 11/19/2004 Number of Days to Update: 30	Source: Regional Water Quality Control Board San Francisco Bay Region (2) Telephone: 510-286-0457 Last EDR Contact: 10/09/2007 Next Scheduled EDR Contact: 01/07/2008 Data Release Frequency: Quarterly
SLIC	<b>CREG 3:</b> Spills, Leaks, Investigation & Cleanup The SLIC (Spills, Leaks, Investigations and Cle from spills, leaks, and similar discharges.	o Cost Recovery Listing eanup) program is designed to protect and restore water quality
	Date of Government Version: 05/18/2006 Date Data Arrived at EDR: 05/18/2006 Date Made Active in Reports: 06/15/2006 Number of Days to Update: 28	Source: California Regional Water Quality Control Board Central Coast Region (3) Telephone: 805-549-3147 Last EDR Contact: 08/13/2007 Next Scheduled EDR Contact: 11/12/2007 Data Release Frequency: Semi-Annually
SLIC	<b>CREG 4:</b> Spills, Leaks, Investigation & Cleanup The SLIC (Spills, Leaks, Investigations and Cle from spills, leaks, and similar discharges.	o Cost Recovery Listing eanup) program is designed to protect and restore water quality
	Date of Government Version: 11/17/2004 Date Data Arrived at EDR: 11/18/2004 Date Made Active in Reports: 01/04/2005 Number of Days to Update: 47	Source: Region Water Quality Control Board Los Angeles Region (4) Telephone: 213-576-6600 Last EDR Contact: 07/23/2007 Next Scheduled EDR Contact: 10/22/2007 Data Release Frequency: Varies
SLIC	<b>CREG 5:</b> Spills, Leaks, Investigation & Cleanup The SLIC (Spills, Leaks, Investigations and Cle from spills, leaks, and similar discharges.	o Cost Recovery Listing eanup) program is designed to protect and restore water quality
	Date of Government Version: 04/01/2005 Date Data Arrived at EDR: 04/05/2005 Date Made Active in Reports: 04/21/2005 Number of Days to Update: 16	Source: Regional Water Quality Control Board Central Valley Region (5) Telephone: 916-464-3291 Last EDR Contact: 10/01/2007 Next Scheduled EDR Contact: 12/31/2007 Data Release Frequency: Semi-Annually
SLIC	<b>CREG 6V:</b> Spills, Leaks, Investigation & Cleanu The SLIC (Spills, Leaks, Investigations and Cle from spills, leaks, and similar discharges.	up Cost Recovery Listing eanup) program is designed to protect and restore water quality
	Date of Government Version: 05/24/2005 Date Data Arrived at EDR: 05/25/2005 Date Made Active in Reports: 06/16/2005 Number of Days to Update: 22	Source: Regional Water Quality Control Board, Victorville Branch Telephone: 619-241-6583 Last EDR Contact: 10/01/2007 Next Scheduled EDR Contact: 12/31/2007 Data Release Frequency: Semi-Annually
SLIC	<b>CREG 6L:</b> SLIC Sites The SLIC (Spills, Leaks, Investigations and Cle from spills, leaks, and similar discharges.	eanup) program is designed to protect and restore water quality
	Date of Government Version: 09/07/2004 Date Data Arrived at EDR: 09/07/2004 Date Made Active in Reports: 10/12/2004 Number of Days to Update: 35	Source: California Regional Water Quality Control Board, Lahontan Region Telephone: 530-542-5574 Last EDR Contact: 09/04/2007 Next Scheduled EDR Contact: 12/03/2007 Data Release Frequency: No Update Planned
SLIC	CREG 7: SLIC List	eanun) program is designed to protect and restore water quality

The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.

Date of Government Version: 11/24/2004 Date Data Arrived at EDR: 11/29/2004 Date Made Active in Reports: 01/04/2005 Number of Days to Update: 36	Source: California Regional Quality Control Board, Colorado River Basin Region Telephone: 760-346-7491 Last EDR Contact: 08/20/2007 Next Scheduled EDR Contact: 11/19/2007 Data Release Frequency: No Update Planned		
SLIC REG 8: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.			
Date of Government Version: 07/17/2007 Date Data Arrived at EDR: 07/18/2007 Date Made Active in Reports: 08/09/2007 Number of Days to Update: 22	Source: California Region Water Quality Control Board Santa Ana Region (8) Telephone: 951-782-3298 Last EDR Contact: 10/01/2007 Next Scheduled EDR Contact: 12/31/2007 Data Release Frequency: Semi-Annually		
SLIC REG 9: Spills, Leaks, Investigation & Cleanup Cost Recovery Listing The SLIC (Spills, Leaks, Investigations and Cleanup) program is designed to protect and restore water quality from spills, leaks, and similar discharges.			
Date of Government Version: 09/10/2007 Date Data Arrived at EDR: 09/11/2007 Date Made Active in Reports: 09/28/2007 Number of Days to Update: 17	Source: California Regional Water Quality Control Board San Diego Region (9) Telephone: 858-467-2980 Last EDR Contact: 09/10/2007 Next Scheduled EDR Contact: 11/26/2007 Data Release Frequency: Annually		
UST: Active UST Facilities Active UST facilities gathered from the local regulatory agencies			
Date of Government Version: 07/10/2007 Date Data Arrived at EDR: 07/11/2007 Date Made Active in Reports: 07/25/2007 Number of Days to Update: 14	Source: SWRCB Telephone: 916-480-1028 Last EDR Contact: 10/11/2007 Next Scheduled EDR Contact: 01/07/2008 Data Release Frequency: Semi-Annually		
	UST MENDOCINO: Mendocino County UST Database A listing of underground storage tank locations in Mendocino County.		
Date of Government Version: 06/25/2007 Date Data Arrived at EDR: 06/26/2007 Date Made Active in Reports: 07/25/2007 Number of Days to Update: 29	Source: Department of Public Health Telephone: 707-463-4466 Last EDR Contact: 09/24/2007 Next Scheduled EDR Contact: 12/24/2007 Data Release Frequency: Varies		
HIST UST: Hazardous Substance Storage Container Database The Hazardous Substance Storage Container Database is a historical listing of UST sites. Refer to local/county source for current data.			
Date of Government Version: 10/15/1990 Date Data Arrived at EDR: 01/25/1991 Date Made Active in Reports: 02/12/1991 Number of Days to Update: 18	Source: State Water Resources Control Board Telephone: 916-341-5851 Last EDR Contact: 07/26/2001 Next Scheduled EDR Contact: N/A Data Release Frequency: No Update Planned		
<b>LIENS:</b> Environmental Liens Listing A listing of property locations with environmental liens for California where DTSC is a lien holder.			
Date of Government Version: 08/27/2007 Date Data Arrived at EDR: 08/28/2007 Date Made Active in Reports: 09/26/2007 Number of Days to Update: 29	Source: Department of Toxic Substances Control Telephone: 916-323-3400 Last EDR Contact: 08/20/2007 Next Scheduled EDR Contact: 11/05/2007 Data Release Frequency: Varies		

AST: Aboveground Petroleum Storage Tank Facilities Registered Aboveground Storage Tanks.

Date of Government Version: 05/01/2007 Date Data Arrived at EDR: 05/01/2007 Date Made Active in Reports: 05/25/2007 Number of Days to Update: 24 Source: State Water Resources Control Board Telephone: 916-341-5712 Last EDR Contact: 07/30/2007 Next Scheduled EDR Contact: 10/29/2007 Data Release Frequency: Quarterly

#### SWEEPS UST: SWEEPS UST Listing

Statewide Environmental Evaluation and Planning System. This underground storage tank listing was updated and maintained by a company contacted by the SWRCB in the early 1980's. The listing is no longer updated or maintained. The local agency is the contact for more information on a site on the SWEEPS list.

Date of Government Version: 06/01/1994Source: State Water Resources Control BoardDate Data Arrived at EDR: 07/07/2005Telephone: N/ADate Made Active in Reports: 08/11/2005Last EDR Contact: 06/03/2005Number of Days to Update: 35Next Scheduled EDR Contact: N/AData Release Frequency: No Update Planned

### CHMIRS: California Hazardous Material Incident Report System

California Hazardous Material Incident Reporting System. CHMIRS contains information on reported hazardous material incidents (accidental releases or spills).

Date of Government Version: 12/31/2005 Date Data Arrived at EDR: 02/23/2007 Date Made Active in Reports: 04/06/2007 Number of Days to Update: 42 Source: Office of Emergency Services Telephone: 916-845-8400 Last EDR Contact: 08/20/2007 Next Scheduled EDR Contact: 11/19/2007 Data Release Frequency: Varies

#### NOTIFY 65: Proposition 65 Records

Proposition 65 Notification Records. NOTIFY 65 contains facility notifications about any release which could impact drinking water and thereby expose the public to a potential health risk.

ource: State Water Resources Control Board
elephone: 916-445-3846
ast EDR Contact: 10/15/2007
ext Scheduled EDR Contact: 01/14/2008
ata Release Frequency: No Update Planned
2

#### DEED: Deed Restriction Listing

Site Mitigation and Brownfields Reuse Program Facility Sites with Deed Restrictions & Hazardous Waste Management Program Facility Sites with Deed / Land Use Restriction. The DTSC Site Mitigation and Brownfields Reuse Program (SMBRP) list includes sites cleaned up under the program's oversight and generally does not include current or former hazardous waste facilities that required a hazardous waste facility permit. The list represents deed restrictions that are active. Some sites have multiple deed restrictions. The DTSC Hazardous Waste Management Program (HWMP) has developed a list of current or former hazardous waste facilities that have a recorded land use restriction at the local county recorder's office. The land use restrictions on this list were required by the DTSC HWMP as a result of the presence of hazardous substances that remain on site after the facility (or part of the facility) has been closed or cleaned up. The types of land use restriction include deed notice, deed restriction, or a land use restriction that binds current and future owners.

Date of Government Version: 07/02/2007 Date Data Arrived at EDR: 07/03/2007 Date Made Active in Reports: 08/09/2007 Number of Days to Update: 37 Source: Department of Toxic Substances Control Telephone: 916-323-3400 Last EDR Contact: 10/03/2007 Next Scheduled EDR Contact: 12/31/2007 Data Release Frequency: Semi-Annually

### VCP: Voluntary Cleanup Program Properties

Contains low threat level properties with either confirmed or unconfirmed releases and the project proponents have request that DTSC oversee investigation and/or cleanup activities and have agreed to provide coverage for DTSC's costs.

Date of Government Version: 08/28/2007 Date Data Arrived at EDR: 08/29/2007 Date Made Active in Reports: 09/26/2007 Number of Days to Update: 28 Source: Department of Toxic Substances Control Telephone: 916-323-3400 Last EDR Contact: 08/29/2007 Next Scheduled EDR Contact: 11/26/2007 Data Release Frequency: Quarterly

**DRYCLEANERS:** Cleaner Facilities

A list of drycleaner related facilities that have EPA ID numbers. These are facilities with certain SIC codes: power laundries, family and commercial; garment pressing and cleaner's agents; linen supply; coin-operated laundries and cleaning; drycleaning plants, except rugs; carpet and upholster cleaning; industrial launderers; laundry and garment services.

Date of Government Version: 07/31/2007 Date Data Arrived at EDR: 07/31/2007 Date Made Active in Reports: 08/09/2007 Number of Days to Update: 9 Source: Department of Toxic Substance Control Telephone: 916-327-4498 Last EDR Contact: 10/15/2007 Next Scheduled EDR Contact: 12/31/2007 Data Release Frequency: Annually

WIP: Well Investigation Program Case List

Well Investigation Program case in the San Gabriel and San Fernando Valley area.

Date of Government Version: 03/01/2007	Source: Los Angeles Water Quality Control Board
Date Data Arrived at EDR: 03/13/2007	Telephone: 213-576-6726
Date Made Active in Reports: 04/06/2007	Last EDR Contact: 07/27/2007
Number of Days to Update: 24	Next Scheduled EDR Contact: 10/22/2007
	Data Release Frequency: Varies

#### CDL: Clandestine Drug Labs

A listing of drug lab locations. Listing of a location in this database does not indicate that any illegal drug lab materials were or were not present there, and does not constitute a determination that the location either requires or does not require additional cleanup work.

Date of Government Version: 12/31/2006SDate Data Arrived at EDR: 03/07/2007TDate Made Active in Reports: 04/06/2007LaNumber of Days to Update: 30N

Source: Department of Toxic Substances Control Telephone: 916-255-6504 Last EDR Contact: 09/04/2007 Next Scheduled EDR Contact: 10/22/2007 Data Release Frequency: Varies

#### **RESPONSE:** State Response Sites

Identifies confirmed release sites where DTSC is involved in remediation, either in a lead or oversight capacity. These confirmed release sites are generally high-priority and high potential risk.

Date of Government Version: 08/28/2007	Source: Department of Toxic Substances Control
Date Data Arrived at EDR: 08/29/2007	Telephone: 916-323-3400
Date Made Active in Reports: 09/26/2007	Last EDR Contact: 08/29/2007
Number of Days to Update: 28	Next Scheduled EDR Contact: 11/26/2007
	Data Release Frequency: Quarterly

#### HAZNET: Facility and Manifest Data

Facility and Manifest Data. The data is extracted from the copies of hazardous waste manifests received each year by the DTSC. The annual volume of manifests is typically 700,000 - 1,000,000 annually, representing approximately 350,000 - 500,000 shipments. Data are from the manifests submitted without correction, and therefore many contain some invalid values for data elements such as generator ID, TSD ID, waste category, and disposal method.

Date of Government Version: 12/31/2005 Date Data Arrived at EDR: 11/20/2006 Date Made Active in Reports: 01/03/2007 Number of Days to Update: 44 Source: California Environmental Protection Agency Telephone: 916-255-1136 Last EDR Contact: 10/04/2007 Next Scheduled EDR Contact: 11/05/2007 Data Release Frequency: Annually

#### EMI: Emissions Inventory Data

Toxics and criteria pollutant emissions data collected by the ARB and local air pollution agencies.

Date of Government Version: 12/31/2005 Date Data Arrived at EDR: 04/17/2007 Date Made Active in Reports: 05/10/2007 Number of Days to Update: 23 Source: California Air Resources Board Telephone: 916-322-2990 Last EDR Contact: 07/20/2007 Next Scheduled EDR Contact: 10/15/2007 Data Release Frequency: Varies

**HAULERS:** Registered Waste Tire Haulers Listing A listing of registered waste tire haulers.

> Date of Government Version: 09/17/2007 Date Data Arrived at EDR: 09/18/2007 Date Made Active in Reports: 09/28/2007 Number of Days to Update: 10

Source: Integrated Waste Management Board Telephone: 916-341-6422 Last EDR Contact: 09/10/2007 Next Scheduled EDR Contact: 12/10/2007 Data Release Frequency: Varies

## ENVIROSTOR: EnviroStor Database

The Department of Toxic Substances Control's (DTSC's) Site Mitigation and Brownfields Reuse Program's (SMBRP's) EnviroStor database identifes sites that have known contamination or sites for which there may be reasons to investigate further. The database includes the following site types: Federal Superfund sites (National Priorities List (NPL)); State Response, including Military Facilities and State Superfund; Voluntary Cleanup; and School sites. EnviroStor provides similar information to the information that was available in CalSites, and provides additional site information, including, but not limited to, identification of formerly-contaminated properties that have been released for reuse, properties where environmental deed restrictions have been recorded to prevent inappropriate land uses, and risk characterization information that is used to assess potential impacts to public health and the environment at contaminated sites.

Date of Government Version: 08/28/2007 Date Data Arrived at EDR: 08/29/2007 Date Made Active in Reports: 09/26/2007 Number of Days to Update: 28 Source: Department of Toxic Substances Control Telephone: 916-323-3400 Last EDR Contact: 08/29/2007 Next Scheduled EDR Contact: 11/26/2007 Data Release Frequency: Quarterly

#### TRIBAL RECORDS

#### **INDIAN RESERV:** Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2005 Date Data Arrived at EDR: 12/08/2006 Date Made Active in Reports: 01/11/2007 Number of Days to Update: 34 Source: USGS Telephone: 202-208-3710 Last EDR Contact: 08/09/2007 Next Scheduled EDR Contact: 11/05/2007 Data Release Frequency: Semi-Annually

**INDIAN LUST R7:** Leaking Underground Storage Tanks on Indian Land LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 06/01/2007	S
Date Data Arrived at EDR: 06/14/2007	Т
Date Made Active in Reports: 07/05/2007	L
Number of Days to Update: 21	N

Source: EPA Region 7 Telephone: 913-551-7003 Last EDR Contact: 08/20/2007 Next Scheduled EDR Contact: 11/19/2007 Data Release Frequency: Varies

**INDIAN LUST R6:** Leaking Underground Storage Tanks on Indian Land LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 01/04/2005 Date Data Arrived at EDR: 01/21/2005 Date Made Active in Reports: 02/28/2005 Number of Days to Update: 38 Source: EPA Region 6 Telephone: 214-665-6597 Last EDR Contact: 08/20/2007 Next Scheduled EDR Contact: 11/19/2007 Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.		
	Date of Government Version: 08/27/2007 Date Data Arrived at EDR: 09/07/2007 Date Made Active in Reports: 10/11/2007 Number of Days to Update: 34	Source: EPA Region 8 Telephone: 303-312-6271 Last EDR Contact: 08/20/2007 Next Scheduled EDR Contact: 11/19/2007 Data Release Frequency: Quarterly
IND	IAN LUST R4: Leaking Underground Storage T LUSTs on Indian land in Florida, Mississippi ar	
	Date of Government Version: 09/05/2007 Date Data Arrived at EDR: 10/02/2007 Date Made Active in Reports: 10/11/2007 Number of Days to Update: 9	Source: EPA Region 4 Telephone: 404-562-8677 Last EDR Contact: 08/20/2007 Next Scheduled EDR Contact: 11/19/2007 Data Release Frequency: Semi-Annually
INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land A listing of leaking underground storage tank locations on Indian Land.		
	Date of Government Version: 12/01/2006 Date Data Arrived at EDR: 12/01/2006 Date Made Active in Reports: 01/29/2007 Number of Days to Update: 59	Source: EPA Region 1 Telephone: 617-918-1313 Last EDR Contact: 08/20/2007 Next Scheduled EDR Contact: 11/19/2007 Data Release Frequency: Varies
INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.		
	Date of Government Version: 09/12/2007 Date Data Arrived at EDR: 09/14/2007 Date Made Active in Reports: 10/11/2007 Number of Days to Update: 27	Source: EPA Region 10 Telephone: 206-553-2857 Last EDR Contact: 08/20/2007 Next Scheduled EDR Contact: 11/19/2007 Data Release Frequency: Quarterly
INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land LUSTs on Indian land in Arizona, California, New Mexico and Nevada		
	Date of Government Version: 09/11/2007 Date Data Arrived at EDR: 09/14/2007 Date Made Active in Reports: 10/11/2007 Number of Days to Update: 27	Source: Environmental Protection Agency Telephone: 415-972-3372 Last EDR Contact: 08/20/2007 Next Scheduled EDR Contact: 11/19/2007 Data Release Frequency: Quarterly
INDIAN UST R7: Underground Storage Tanks on Indian Land		
	Date of Government Version: 06/01/2007 Date Data Arrived at EDR: 06/14/2007 Date Made Active in Reports: 07/05/2007 Number of Days to Update: 21	Source: EPA Region 7 Telephone: 913-551-7003 Last EDR Contact: 08/20/2007 Next Scheduled EDR Contact: 11/19/2007 Data Release Frequency: Varies
IND	IAN UST R6: Underground Storage Tanks on Ir	ndian Land
	Date of Government Version: 08/31/2007	Source: EPA Region 6 Telephone: 214-665-7591

Date of Government Version: 08/31/2007Source: EPA Region 6Date Data Arrived at EDR: 08/31/2007Telephone: 214-665-7591Date Made Active in Reports: 10/11/2007Last EDR Contact: 08/20/2007Number of Days to Update: 41Next Scheduled EDR Contact: 11/19/2007Data Release Frequency: Semi-Annually

#### INDIAN UST R9: Underground Storage Tanks on Indian Land

Date of Government Version: 09/11/2007	Source: EPA Region 9
Date Data Arrived at EDR: 09/14/2007	Telephone: 415-972-3368
Date Made Active in Reports: 10/11/2007 Number of Days to Update: 27	Last EDR Contact: 08/20/2007 Next Scheduled EDR Contact: 11/19/2007 Data Release Frequency: Quarterly

## INDIAN UST R1: Underground Storage Tanks on Indian Land

A listing of underground storage tank locations on Indian Land.

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 08/20/2007
Next Scheduled EDR Contact: 11/19/2007
Data Release Frequency: Varies

#### INDIAN UST R8: Underground Storage Tanks on Indian Land

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 08/20/2007
Next Scheduled EDR Contact: 11/19/2007
Data Release Frequency: Quarterly

### INDIAN UST R4: Underground Storage Tanks on Indian Land

Date of Government Version: 09/05/2007 Date Data Arrived at EDR: 10/02/2007	Source: EPA Region 4 Telephone: 404-562-9424
Date Made Active in Reports: 10/11/2007	Last EDR Contact: 08/20/2007
Number of Days to Update: 9	Next Scheduled EDR Contact: 11/19/2007
	Data Release Frequency: Semi-Annually

#### INDIAN UST R10: Underground Storage Tanks on Indian Land

Date of Government Version: 09/12/2007	Source: EPA Region 10
Date Data Arrived at EDR: 09/14/2007	Telephone: 206-553-2857
Date Made Active in Reports: 10/11/2007	Last EDR Contact: 08/20/2007
Number of Days to Update: 27	Next Scheduled EDR Contact: 11/19/2007
	Data Release Frequency: Quarterly

#### INDIAN UST R5: Underground Storage Tanks on Indian Land

Date of Government Version: 12/02/2004	Source: EPA Region 5
Date Data Arrived at EDR: 12/29/2004	Telephone: 312-886-6136
Date Made Active in Reports: 02/04/2005	Last EDR Contact: 08/20/2007
Number of Days to Update: 37	Next Scheduled EDR Contact: 11/19/2007
	Data Release Frequency: Varies

## EDR PROPRIETARY RECORDS

#### Manufactured Gas Plants: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A Date Data Arrived at EDR: N/A Date Made Active in Reports: N/A Number of Days to Update: N/A Source: EDR, Inc. Telephone: N/A Last EDR Contact: N/A Next Scheduled EDR Contact: N/A Data Release Frequency: No Update Planned

### EDR Historical Auto Stations: EDR Proprietary Historic Gas Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc.

Date of Government Version: N/A Date Data Arrived at EDR: N/A Date Made Active in Reports: N/A Number of Days to Update: N/A Source: EDR, Inc. Telephone: N/A Last EDR Contact: N/A Next Scheduled EDR Contact: N/A Data Release Frequency: Varies

## EDR Historical Cleaners: EDR Proprietary Historic Dry Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc.

Date of Government Version: N/A Date Data Arrived at EDR: N/A Date Made Active in Reports: N/A Number of Days to Update: N/A

#### Source: EDR, Inc. Telephone: N/A Last EDR Contact: N/A Next Scheduled EDR Contact: N/A Data Release Frequency: Varies

#### FEDERAL RECORDS

**COLLEGES:** Integrated Postsecondary Education Data

The National Center for Education Statistics' primary database on integrated postsecondary education in the United States.

Date of Government Version: N/A Date Data Arrived at EDR: 10/12/2005 Date Made Active in Reports: N/A Number of Days to Update: 0 Source: National Center for Education Statistics Telephone: 202-502-7300 Last EDR Contact: 09/22/2006 Next Scheduled EDR Contact: N/A Data Release Frequency: N/A

#### PUBLIC SCHOOLS: Public Schools

The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Date of Government Version: N/A Date Data Arrived at EDR: 07/13/2004 Date Made Active in Reports: N/A Number of Days to Update: 0 Source: National Center for Education statistics Telephone: 202-502-7300 Last EDR Contact: 10/10/2007 Next Scheduled EDR Contact: 01/07/2008 Data Release Frequency: N/A

## PRIVATE SCHOOLS: Private Schools of the United States

The National Center for Education Statistics' primary database on private school locations in the United States.

Date of Government Version: N/A Date Data Arrived at EDR: 10/07/2005 Date Made Active in Reports: N/A Number of Days to Update: 0 Source: National Center for Education Statistics Telephone: 202-502-7300 Last EDR Contact: 09/22/2006 Next Scheduled EDR Contact: N/A Data Release Frequency: N/A

#### NURSING HOMES: Directory of Nursing Homes

Information on Medicare and Medicaid certified nursing homes in the United States.

Date of Government Version: N/A
Date Data Arrived at EDR: 10/11/2005
Date Made Active in Reports: N/A
Number of Days to Update: 0

Source: N/A Telephone: 800-568-3282 Last EDR Contact: 09/22/2006 Next Scheduled EDR Contact: N/A Data Release Frequency: N/A

#### MEDICAL CENTERS: Provider of Services Listing

A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health & Human Services.

Date of Government Version: 06/01/1998 Date Data Arrived at EDR: 11/10/2005 Date Made Active in Reports: N/A Number of Days to Update: 0 Source: Centers for Medicare & Medicaid Services Telephone: 410-786-3000 Last EDR Contact: 01/12/2007 Next Scheduled EDR Contact: N/A Data Release Frequency: N/A

## HOSPITALS: AHA Hospital Guide

The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Date of Government Version: N/A	Source: American Hospital Association
Date Data Arrived at EDR: 10/19/1994	Telephone: 800-242-2626
Date Made Active in Reports: N/A	Last EDR Contact: 09/22/2006
Number of Days to Update: 0	Next Scheduled EDR Contact: N/A
	Data Release Frequency: N/A

#### COUNTY RECORDS

### ALAMEDA COUNTY:

#### **Contaminated Sites**

A listing of contaminated sites overseen by the Toxic Release Program (oil and groundwater contamination from chemical releases and spills) and the Leaking Underground Storage Tank Program (soil and ground water contamination from leaking petroleum USTs).

Date of Government Version: 08/03/2007 Date Data Arrived at EDR: 08/07/2007 Date Made Active in Reports: 09/26/2007 Number of Days to Update: 50 Source: Alameda County Environmental Health Services Telephone: 510-567-6700 Last EDR Contact: 07/23/2007 Next Scheduled EDR Contact: 10/22/2007 Data Release Frequency: Semi-Annually

#### **Underground Tanks**

Underground storage tank sites located in Alameda county.

Date of Government Version: 08/03/2007	Source: Alameda County Environmental Health Services
Date Data Arrived at EDR: 08/07/2007	Telephone: 510-567-6700
Date Made Active in Reports: 09/24/2007	Last EDR Contact: 07/23/2007
Number of Days to Update: 48	Next Scheduled EDR Contact: 10/22/2007
	Data Release Frequency: Semi-Annually

#### CONTRA COSTA COUNTY:

#### Site List

List includes sites from the underground tank, hazardous waste generator and business plan/2185 programs.

Date of Government Version: 09/11/2007 Date Data Arrived at EDR: 09/14/2007 Date Made Active in Reports: 09/28/2007 Number of Days to Update: 14 Source: Contra Costa Health Services Department Telephone: 925-646-2286 Last EDR Contact: 09/10/2007 Next Scheduled EDR Contact: 11/26/2007 Data Release Frequency: Semi-Annually

#### FRESNO COUNTY:

#### **CUPA Resources List**

Certified Unified Program Agency. CUPA's are responsible for implementing a unified hazardous materials and hazardous waste management regulatory program. The agency provides oversight of businesses that deal with hazardous materials, operate underground storage tanks or aboveground storage tanks.

Date of Government Version: 07/16/2007 Date Data Arrived at EDR: 07/17/2007 Date Made Active in Reports: 08/09/2007 Number of Days to Update: 23 Source: Dept. of Community Health Telephone: 559-445-3271 Last EDR Contact: 08/06/2007 Next Scheduled EDR Contact: 11/05/2007 Data Release Frequency: Semi-Annually

## KERN COUNTY:

## **Underground Storage Tank Sites & Tank Listing**

Kern County Sites and Tanks Listing.

Date of Government Version: 06/20/2007 Date Data Arrived at EDR: 06/21/2007 Date Made Active in Reports: 07/25/2007 Number of Days to Update: 34 Source: Kern County Environment Health Services Department Telephone: 661-862-8700 Last EDR Contact: 09/17/2007 Next Scheduled EDR Contact: 12/03/2007 Data Release Frequency: Quarterly

### LOS ANGELES COUNTY:

#### San Gabriel Valley Areas of Concern

San Gabriel Valley areas where VOC contamination is at or above the MCL as designated by region 9 EPA office.

Date of Government Version: 12/31/1998 Date Data Arrived at EDR: 07/07/1999 Date Made Active in Reports: N/A Number of Days to Update: 0 Source: EPA Region 9 Telephone: 415-972-3178 Last EDR Contact: 07/16/2007 Next Scheduled EDR Contact: 10/15/2007 Data Release Frequency: No Update Planned

#### **HMS: Street Number List**

Industrial Waste and Underground Storage Tank Sites.

Date of Government Version: 05/31/2007	Source: Department of Public Works
Date Data Arrived at EDR: 08/27/2007	Telephone: 626-458-3517
Date Made Active in Reports: 09/26/2007	Last EDR Contact: 08/13/2007
Number of Days to Update: 30	Next Scheduled EDR Contact: 11/12/2007
	Data Release Frequency: Semi-Annually

#### List of Solid Waste Facilities

Solid Waste Facilities in Los Angeles County.

Date of Government Version: 08/17/2007 Date Data Arrived at EDR: 09/24/2007 Date Made Active in Reports: 09/28/2007 Number of Days to Update: 4

Source: La County Department of Public Works Telephone: 818-458-5185 Last EDR Contact: 08/17/2007 Next Scheduled EDR Contact: 11/12/2007 Data Release Frequency: Varies

#### **City of Los Angeles Landfills**

Landfills owned and maintained by the City of Los Angeles.

Date of Government Version: 03/01/2007	Source: Engineering & Construction Division
Date Data Arrived at EDR: 03/27/2007	Telephone: 213-473-7869
Date Made Active in Reports: 04/27/2007	Last EDR Contact: 09/10/2007
Number of Days to Update: 31	Next Scheduled EDR Contact: 12/10/2007
	Data Release Frequency: Varies

#### Site Mitigation List

Industrial sites that have had some sort of spill or complaint.

Date of Government Version: 05/30/2007
Date Data Arrived at EDR: 07/11/2007
Date Made Active in Reports: 08/09/2007
Number of Days to Update: 29

Source: Community Health Services Telephone: 323-890-7806 Last EDR Contact: 09/20/2007 Next Scheduled EDR Contact: 11/12/2007 Data Release Frequency: Annually

### City of El Segundo Underground Storage Tank

Underground storage tank sites located in El Segundo city.

Date of Government Version: 05/14/2007	Source: City of El Segundo Fire Department
Date Data Arrived at EDR: 05/15/2007	Telephone: 310-524-2236
Date Made Active in Reports: 06/25/2007	Last EDR Contact: 08/13/2007
Number of Days to Update: 41	Next Scheduled EDR Contact: 11/12/2007
	Data Release Frequency: Semi-Annually

#### City of Long Beach Underground Storage Tank

Underground storage tank sites located in the city of Long Beach.

Date of Government Version: 03/28/2003	Source: City of Long Beach Fire Department
Date Data Arrived at EDR: 10/23/2003	Telephone: 562-570-2563
Date Made Active in Reports: 11/26/2003	Last EDR Contact: 08/23/2007
Number of Days to Update: 34	Next Scheduled EDR Contact: 11/19/2007
	Data Release Frequency: Annually

#### City of Torrance Underground Storage Tank

Underground storage tank sites located in the city of Torrance.

Date of Government Version: 05/29/2007 Date Data Arrived at EDR: 05/29/2007 Date Made Active in Reports: 06/25/2007 Number of Days to Update: 27 Source: City of Torrance Fire Department Telephone: 310-618-2973 Last EDR Contact: 09/24/2007 Next Scheduled EDR Contact: 11/12/2007 Data Release Frequency: Semi-Annually

## MARIN COUNTY:

#### Underground Storage Tank Sites

Currently permitted USTs in Marin County.

Date of Government Version: 05/08/2007 Date Data Arrived at EDR: 06/08/2007 Date Made Active in Reports: 07/25/2007 Number of Days to Update: 47 Source: Public Works Department Waste Management Telephone: 415-499-6647 Last EDR Contact: 07/30/2007 Next Scheduled EDR Contact: 10/29/2007 Data Release Frequency: Semi-Annually

### NAPA COUNTY:

#### **Sites With Reported Contamination**

A listing of leaking underground storage tank sites located in Napa county.

Date of Government Version: 09/24/2007 Date Data Arrived at EDR: 09/25/2007 Date Made Active in Reports: 09/28/2007 Number of Days to Update: 3 Source: Napa County Department of Environmental Management Telephone: 707-253-4269 Last EDR Contact: 09/24/2007 Next Scheduled EDR Contact: 12/24/2007 Data Release Frequency: Semi-Annually

## **Closed and Operating Underground Storage Tank Sites**

Underground storage tank sites located in Napa county.

Date of Government Version: 07/24/2007 Date Data Arrived at EDR: 07/27/2007 Date Made Active in Reports: 09/07/2007 Number of Days to Update: 42 Source: Napa County Department of Environmental Management Telephone: 707-253-4269 Last EDR Contact: 09/24/2007 Next Scheduled EDR Contact: 12/24/2007 Data Release Frequency: Annually

#### **ORANGE COUNTY:**

## List of Industrial Site Cleanups

Petroleum and non-petroleum spills.

Date of Government Version: 06/01/2007 Date Data Arrived at EDR: 06/19/2007 Date Made Active in Reports: 06/29/2007 Number of Days to Update: 10 Source: Health Care Agency Telephone: 714-834-3446 Last EDR Contact: 08/31/2007 Next Scheduled EDR Contact: 12/03/2007 Data Release Frequency: Annually

#### List of Underground Storage Tank Cleanups

Orange County Underground Storage Tank Cleanups (LUST).

Date of Government Version: 06/01/2007		
Date Data Arrived at EDR: 06/19/2007		
Date Made Active in Reports: 06/29/2007		
Number of Days to Update: 10		

Source: Health Care Agency Telephone: 714-834-3446 Last EDR Contact: 08/31/2007 Next Scheduled EDR Contact: 12/03/2007 Data Release Frequency: Quarterly

### List of Underground Storage Tank Facilities

Orange County Underground Storage Tank Facilities (UST).

Date of Government Version: 06/01/2007 Date Data Arrived at EDR: 06/19/2007 Date Made Active in Reports: 07/25/2007 Number of Days to Update: 36 Source: Health Care Agency Telephone: 714-834-3446 Last EDR Contact: 08/31/2007 Next Scheduled EDR Contact: 12/03/2007 Data Release Frequency: Quarterly

#### PLACER COUNTY:

#### **Master List of Facilities**

List includes aboveground tanks, underground tanks and cleanup sites.

Date of Government Version: 07/23/2007Source: Placer County Health and Human ServicesDate Data Arrived at EDR: 07/23/2007Telephone: 530-889-7312Date Made Active in Reports: 08/09/2007Last EDR Contact: 09/17/2007Number of Days to Update: 17Next Scheduled EDR Contact: 12/17/2007Data Release Frequency: Semi-Annually

#### **RIVERSIDE COUNTY:**

#### Listing of Underground Tank Cleanup Sites

Riverside County Underground Storage Tank Cleanup Sites (LUST).

Date of Government Version: 08/06/2007 Date Data Arrived at EDR: 08/07/2007 Date Made Active in Reports: 09/26/2007 Number of Days to Update: 50 Source: Department of Public Health Telephone: 951-358-5055 Last EDR Contact: 10/15/2007 Next Scheduled EDR Contact: 01/14/2008 Data Release Frequency: Quarterly

#### Underground Storage Tank Tank List

Underground storage tank sites located in Riverside county.

Date of Government Version: 08/06/2007 Date Data Arrived at EDR: 08/07/2007 Date Made Active in Reports: 09/24/2007 Number of Days to Update: 48 Source: Health Services Agency Telephone: 951-358-5055 Last EDR Contact: 10/15/2007 Next Scheduled EDR Contact: 01/14/2008 Data Release Frequency: Quarterly

#### SACRAMENTO COUNTY:

#### **Contaminated Sites**

List of sites where unauthorized releases of potentially hazardous materials have occurred.

Date of Government Version: 08/07/2007SouDate Data Arrived at EDR: 08/08/2007TeleDate Made Active in Reports: 09/26/2007LassNumber of Days to Update: 49Nex

Source: Sacramento County Environmental Management Telephone: 916-875-8406 Last EDR Contact: 07/31/2007 Next Scheduled EDR Contact: 10/29/2007 Data Release Frequency: Quarterly

#### **ML - Regulatory Compliance Master List**

Any business that has hazardous materials on site - hazardous material storage sites, underground storage tanks, waste generators.

Date of Government Version: 08/07/2007	Source: Sacramento County Environmental Management
Date Data Arrived at EDR: 08/08/2007	Telephone: 916-875-8406
Date Made Active in Reports: 09/26/2007	Last EDR Contact: 07/31/2007
Number of Days to Update: 49	Next Scheduled EDR Contact: 10/29/2007
	Data Release Frequency: Quarterly

#### SAN BERNARDINO COUNTY:

#### **Hazardous Material Permits**

This listing includes underground storage tanks, medical waste handlers/generators, hazardous materials handlers, hazardous waste generators, and waste oil generators/handlers.

Date of Government Version: 06/27/2007	Source: San Bernardino County Fire Department Hazardous Materials Division
Date Data Arrived at EDR: 06/29/2007	Telephone: 909-387-3041
Date Made Active in Reports: 08/09/2007	Last EDR Contact: 09/04/2007
Number of Days to Update: 41	Next Scheduled EDR Contact: 12/03/2007
	Data Release Frequency: Quarterly

#### SAN DIEGO COUNTY:

#### Hazardous Materials Management Division Database

The database includes: HE58 - This report contains the business name, site address, business phone number, establishment 'H' permit number, type of permit, and the business status. HE17 - In addition to providing the same information provided in the HE58 listing, HE17 provides inspection dates, violations received by the establishment, hazardous waste generated, the quantity, method of storage, treatment/disposal of waste and the hauler, and information on underground storage tanks. Unauthorized Release List - Includes a summary of environmental contamination cases in San Diego County (underground tank cases, non-tank cases, groundwater contamination, and soil contamination are included.)

Date of Government Version: 05/16/2005 Date Data Arrived at EDR: 05/18/2005 Date Made Active in Reports: 06/16/2005 Number of Days to Update: 29 Source: Hazardous Materials Management Division Telephone: 619-338-2268 Last EDR Contact: 10/05/2007 Next Scheduled EDR Contact: 12/31/2007 Data Release Frequency: Quarterly

#### **Solid Waste Facilities**

San Diego County Solid Waste Facilities.

Date of Government Version: 11/01/2006 Date Data Arrived at EDR: 01/03/2007 Date Made Active in Reports: 01/24/2007 Number of Days to Update: 21

Source: Department of Health Services Telephone: 619-338-2209 Last EDR Contact: 09/04/2007 Next Scheduled EDR Contact: 11/19/2007 Data Release Frequency: Varies

#### **Environmental Case Listing**

The listing contains all underground tank release cases and projects pertaining to properties contaminated with hazardous substances that are actively under review by the Site Assessment and Mitigation Program.

Date of Government Version: 06/27/2007 Date Data Arrived at EDR: 07/20/2007 Date Made Active in Reports: 08/09/2007 Number of Days to Update: 20

Source: San Diego County Department of Environmental Health Telephone: 619-338-2371 Last EDR Contact: 10/03/2007 Next Scheduled EDR Contact: 12/31/2007 Data Release Frequency: Varies

## SAN FRANCISCO COUNTY:

#### Local Oversite Facilities

A listing of leaking underground storage tank sites located in San Francisco county.

Date of Government Version: 09/07/2007	Source: Department Of Public Health San Francisco County
Date Data Arrived at EDR: 09/07/2007	Telephone: 415-252-3920
Date Made Active in Reports: 09/28/2007	Last EDR Contact: 09/04/2007
Number of Days to Update: 21	Next Scheduled EDR Contact: 12/03/2007
	Data Release Frequency: Quarterly

#### **Underground Storage Tank Information**

Underground storage tank sites located in San Francisco county.

Date of Government Version: 09/07/2007	Source: Department of Public Health
Date Data Arrived at EDR: 09/07/2007	Telephone: 415-252-3920
Date Made Active in Reports: 09/24/2007	Last EDR Contact: 09/04/2007
Number of Days to Update: 17	Next Scheduled EDR Contact: 12/03/2007
	Data Release Frequency: Quarterly

## SAN JOAQUIN COUNTY:

#### San Joaquin Co. UST

A listing of underground storage tank locations in San Joaquin county.

Date of Government Version: 08/21/2007 Date Data Arrived at EDR: 08/22/2007 Date Made Active in Reports: 09/24/2007 Number of Days to Update: 33

Source: Environmental Health Department Telephone: N/A Last EDR Contact: 10/15/2007 Next Scheduled EDR Contact: 01/14/2008 Data Release Frequency: Semi-Annually

## SAN MATEO COUNTY:

#### **Business Inventory**

List includes Hazardous Materials Business Plan, hazardous waste generators, and underground storage tanks.

Date of Government Version: 07/30/2007 Date Data Arrived at EDR: 07/30/2007 Date Made Active in Reports: 08/09/2007 Number of Days to Update: 10

Source: San Mateo County Environmental Health Services Division Telephone: 650-363-1921 Last EDR Contact: 10/09/2007 Next Scheduled EDR Contact: 01/07/2008 Data Release Frequency: Annually

#### **Fuel Leak List**

A listing of leaking underground storage tank sites located in San Mateo county.

Date of Government Version: 07/09/2007 Date Data Arrived at EDR: 07/10/2007 Date Made Active in Reports: 08/09/2007 Number of Days to Update: 30 Source: San Mateo County Environmental Health Services Division Telephone: 650-363-1921 Last EDR Contact: 10/09/2007 Next Scheduled EDR Contact: 01/07/2008 Data Release Frequency: Semi-Annually

#### SANTA CLARA COUNTY:

#### HIST LUST - Fuel Leak Site Activity Report

A listing of open and closed leaking underground storage tanks. This listing is no longer updated by the county. Leaking underground storage tanks are now handled by the Department of Environmental Health.

Date of Government Version: 03/29/2005 Date Data Arrived at EDR: 03/30/2005 Date Made Active in Reports: 04/21/2005 Number of Days to Update: 22 Source: Santa Clara Valley Water District Telephone: 408-265-2600 Last EDR Contact: 09/24/2007 Next Scheduled EDR Contact: 12/24/2007 Data Release Frequency: No Update Planned

## LOP Listing

A listing of leaking underground storage tanks located in Santa Clara county.

Date of Government Version: 03/26/2007	Source: Department of Environmental Health
Date Data Arrived at EDR: 03/27/2007	Telephone: 408-918-3417
Date Made Active in Reports: 04/27/2007	Last EDR Contact: 09/24/2007
Number of Days to Update: 31	Next Scheduled EDR Contact: 12/24/2007
	Data Release Frequency: Varies

#### **Hazardous Material Facilities**

Hazardous material facilities, including underground storage tank sites.

Date of Government Version: 09/17/2007	Source: City of San Jose Fire Department
Date Data Arrived at EDR: 09/17/2007	Telephone: 408-277-4659
Date Made Active in Reports: 09/28/2007	Last EDR Contact: 09/17/2007
Number of Days to Update: 11	Next Scheduled EDR Contact: 12/03/2007
	Data Release Frequency: Annually

## SOLANO COUNTY:

## Leaking Underground Storage Tanks

A listing of leaking underground storage tank sites located in Solano county.

Date of Government Version: 07/09/2007 Date Data Arrived at EDR: 08/03/2007	Source: Solano County Department of Environmental Management Telephone: 707-784-6770
Date Made Active in Reports: 08/09/2007	Last EDR Contact: 09/24/2007
Number of Days to Update: 6	Next Scheduled EDR Contact: 12/24/2007
	Data Release Frequency: Quarterly

## **Underground Storage Tanks**

Underground storage tank sites located in Solano county.

Date of Government Version: 07/09/2007 Date Data Arrived at EDR: 08/03/2007	Source: Solano County Department of Environmental Management Telephone: 707-784-6770
Date Made Active in Reports: 09/24/2007	Last EDR Contact: 09/24/2007
Number of Days to Update: 52	Next Scheduled EDR Contact: 12/24/2007
	Data Release Frequency: Quarterly

### SONOMA COUNTY:

#### Leaking Underground Storage Tank Sites

A listing of leaking underground storage tank sites located in Sonoma county.

Date of Government Version: 07/09/2007 Date Data Arrived at EDR: 07/09/2007 Date Made Active in Reports: 08/09/2007 Number of Days to Update: 31 Source: Department of Health Services Telephone: 707-565-6565 Last EDR Contact: 07/09/2007 Next Scheduled EDR Contact: 10/22/2007 Data Release Frequency: Quarterly

#### SUTTER COUNTY:

#### **Underground Storage Tanks**

Underground storage tank sites located in Sutter county.

Date of Government Version: 05/04/2007 Date Data Arrived at EDR: 05/04/2007 Date Made Active in Reports: 05/24/2007 Number of Days to Update: 20 Source: Sutter County Department of Agriculture Telephone: 530-822-7500 Last EDR Contact: 10/01/2007 Next Scheduled EDR Contact: 12/31/2007 Data Release Frequency: Semi-Annually

## **VENTURA COUNTY:**

#### Business Plan, Hazardous Waste Producers, and Operating Underground Tanks

The BWT list indicates by site address whether the Environmental Health Division has Business Plan (B), Waste Producer (W), and/or Underground Tank (T) information.

Date of Government Version: 05/30/2007 Date Data Arrived at EDR: 06/22/2007 Date Made Active in Reports: 06/29/2007 Number of Days to Update: 7 Source: Ventura County Environmental Health Division Telephone: 805-654-2813 Last EDR Contact: 09/12/2007 Next Scheduled EDR Contact: 12/10/2007 Data Release Frequency: Quarterly

#### Inventory of Illegal Abandoned and Inactive Sites

Ventura County Inventory of Closed, Illegal Abandoned, and Inactive Sites.

Date of Government Version: 08/01/2007	Source: Environmental Health Division
Date Data Arrived at EDR: 08/29/2007	Telephone: 805-654-2813
Date Made Active in Reports: 09/26/2007	Last EDR Contact: 08/21/2007
Number of Days to Update: 28	Next Scheduled EDR Contact: 11/19/2007
	Data Release Frequency: Annually

## Listing of Underground Tank Cleanup Sites

Ventura County Underground Storage Tank Cleanup Sites (LUST).

Date of Government Version: 06/05/2007	Source: Environmental Health Division
Date Data Arrived at EDR: 06/21/2007	Telephone: 805-654-2813
Date Made Active in Reports: 06/29/2007	Last EDR Contact: 09/12/2007
Number of Days to Update: 8	Next Scheduled EDR Contact: 12/10/2007
	Data Release Frequency: Quarterly

## **Underground Tank Closed Sites List**

Ventura County Operating Underground Storage Tank Sites (UST)/Underground Tank Closed Sites List.

Date of Government Version: 06/26/2007	Source: Environmental Health Division
Date Data Arrived at EDR: 07/27/2007	Telephone: 805-654-2813
Date Made Active in Reports: 09/07/2007	Last EDR Contact: 10/11/2007
Number of Days to Update: 42	Next Scheduled EDR Contact: 01/07/2008
	Data Release Frequency: Quarterly

## YOLO COUNTY:

## Underground Storage Tank Comprehensive Facility Report

Underground storage tank sites located in Yolo county.

Date of Government Version: 07/30/2007 Date Data Arrived at EDR: 09/04/2007 Date Made Active in Reports: 09/24/2007 Number of Days to Update: 20 Source: Yolo County Department of Health Telephone: 530-666-8646 Last EDR Contact: 10/15/2007 Next Scheduled EDR Contact: 01/14/2008 Data Release Frequency: Annually

#### **OTHER DATABASE(S)**

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

#### CT MANIFEST: Hazardous Waste Manifest Data

Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 12/31/2005	Source: Department of Environmental Protection
Date Data Arrived at EDR: 06/15/2007	Telephone: 860-424-3375
Date Made Active in Reports: 08/20/2007	Last EDR Contact: 09/12/2007
Number of Days to Update: 66	Next Scheduled EDR Contact: 12/10/2007
	Data Release Frequency: Annually

### NJ MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 04/01/2007 Date Data Arrived at EDR: 04/05/2007 Date Made Active in Reports: 05/08/2007 Number of Days to Update: 33 Source: Department of Environmental Protection Telephone: N/A Last EDR Contact: 10/02/2007 Next Scheduled EDR Contact: 12/31/2007 Data Release Frequency: Annually

#### NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 08/27/2007 Date Data Arrived at EDR: 08/30/2007 Date Made Active in Reports: 09/21/2007 Number of Days to Update: 22 Source: Department of Environmental Conservation Telephone: 518-402-8651 Last EDR Contact: 08/30/2007 Next Scheduled EDR Contact: 11/26/2007 Data Release Frequency: Annually

#### PA MANIFEST: Manifest Information Hazardous waste manifest information.

Date of Government Version: 12/31/2006 Date Data Arrived at EDR: 08/23/2007 Date Made Active in Reports: 09/27/2007 Number of Days to Update: 35

RI MANIFEST: Manifest information Hazardous waste manifest information

> Date of Government Version: 04/09/2007 Date Data Arrived at EDR: 04/12/2007 Date Made Active in Reports: 04/27/2007 Number of Days to Update: 15

Source: Department of Environmental Protection Telephone: N/A Last EDR Contact: 09/10/2007 Next Scheduled EDR Contact: 12/10/2007 Data Release Frequency: Annually

Source: Department of Environmental Management Telephone: 401-222-2797 Last EDR Contact: 09/17/2007 Next Scheduled EDR Contact: 12/17/2007 Data Release Frequency: Annually

#### WI MANIFEST: Manifest Information Hazardous waste manifest information.

Date of Government Version: 12/31/2006 Date Data Arrived at EDR: 04/27/2007 Date Made Active in Reports: 06/08/2007 Number of Days to Update: 42

Source: Department of Natural Resources Telephone: N/A Last EDR Contact: 10/09/2007 Next Scheduled EDR Contact: 01/07/2008 Data Release Frequency: Annually

**Oil/Gas Pipelines:** This data was obtained by EDR from the USGS in 1994. It is referred to by USGS as GeoData Digital Line Graphs from 1:100,000-Scale Maps. It was extracted from the transportation category including some oil, but primarily gas pipelines.

#### **Electric Power Transmission Line Data**

Source: PennWell Corporation

Telephone: (800) 823-6277

This map includes information copyrighted by PennWell Corporation. This information is provided on a best effort basis and PennWell Corporation does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of PennWell.

**Sensitive Receptors:** There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

#### AHA Hospitals:

Source: American Hospital Association, Inc.

Telephone: 312-280-5991

The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

#### Medical Centers: Provider of Services Listing

Source: Centers for Medicare & Medicaid Services

Telephone: 410-786-3000

A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services,

a federal agency within the U.S. Department of Health and Human Services.

#### Nursing Homes

Source: National Institutes of Health

Telephone: 301-594-6248

Information on Medicare and Medicaid certified nursing homes in the United States.

#### **Public Schools**

Source: National Center for Education Statistics

Telephone: 202-502-7300

The National Center for Education Statistics' primary database on elementary

and secondary public education in the United States. It is a comprehensive, annual, national statistical

database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

## Private Schools

Source: National Center for Education Statistics

Telephone: 202-502-7300

The National Center for Education Statistics' primary database on private school locations in the United States.

#### Daycare Centers: Licensed Facilities

Source: Department of Social Services

Telephone: 916-657-4041

**Flood Zone Data:** This data, available in select counties across the country, was obtained by EDR in 1999 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

**NWI:** National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002 and 2005 from the U.S. Fish and Wildlife Service.

## Scanned Digital USGS 7.5' Topographic Map (DRG)

Source: United States Geologic Survey

A digital raster graphic (DRG) is a scanned image of a U.S. Geological Survey topographic map. The map images are made by scanning published paper maps on high-resolution scanners. The raster image is georeferenced and fit to the Universal Transverse Mercator (UTM) projection.

## STREET AND ADDRESS INFORMATION

© 2007 Tele Atlas North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

## **GEOCHECK ®- PHYSICAL SETTING SOURCE ADDENDUM**

### TARGET PROPERTY ADDRESS

PARKING LOT (LOT 25) 2500 BLOCK W. 190TH STREET TORRANCE, CA 90504

## TARGET PROPERTY COORDINATES

Latitude (North):	33.85930 - 33° 51' 33.5"
Longitude (West):	118.3259 - 118° 19' 33.2''
Universal Tranverse Mercator:	Zone 11
UTM X (Meters):	377347.6
UTM Y (Meters):	3747152.5
Elevation:	64 ft. above sea level

#### USGS TOPOGRAPHIC MAP

Target Property Map:	33118-G3 TORRANCE, CA
Most Recent Revision:	1981
North Map:	33118-H3 INGLEWOOD, CA
Most Recent Revision:	1981

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principle investigative components:

- 1. Groundwater flow direction, and
- 2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

## **GEOCHECK<sup>®</sup> - PHYSICAL SETTING SOURCE SUMMARY**

## **GROUNDWATER FLOW DIRECTION INFORMATION**

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).


## **TOPOGRAPHIC INFORMATION**

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

## TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General South

## SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

## **GEOCHECK<sup>®</sup> - PHYSICAL SETTING SOURCE SUMMARY**

## HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

#### FEMA FLOOD ZONE

Target Property County LOS ANGELES, CA	FEMA Flood <u>Electronic Data</u> YES - refer to the Overview Map and Detail Map
Flood Plain Panel at Target Property:	0601650003B
Additional Panels in search area:	0601650001B 0601370101C
NATIONAL WETLAND INVENTORY	
NWI Quad at Target Property TORRANCE	NWI Electronic <u>Data Coverage</u> YES - refer to the Overview Map and Detail Map

## HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data*:		
Search Radius:	1.25 miles	
Status:	Not found	

## **AQUIFLOW**®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

	LOCATION	GENERAL DIRECTION
MAP ID	FROM TP	GROUNDWATER FLOW
A1	1/4 - 1/2 Mile North	S

For additional site information, refer to Physical Setting Source Map Findings.

# **GEOCHECK<sup>®</sup> - PHYSICAL SETTING SOURCE SUMMARY**

## **GROUNDWATER FLOW VELOCITY INFORMATION**

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

## **GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY**

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

## **ROCK STRATIGRAPHIC UNIT**

## **GEOLOGIC AGE IDENTIFICATION**

Era:	Cenozoic Category:	Stratifed Sequence
System:	Quaternary	
Series:	Quaternary	
Code:	Q (decoded above as Era, System & Series)	

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

## DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps. The following information is based on Soil Conservation Service STATSGO data.

a hydric soil.

Soil Component Name:	URBAN LAND
Soil Surface Texture:	variable
Hydrologic Group:	Not reported
Soil Drainage Class:	Not reported
Hydric Status: Soil does not meet the	requirements for
Corrosion Potential - Uncoated Steel:	Not Reported
Depth to Bedrock Min:	> 10 inches

Depth to Bedrock Max: > 10 inches

# **GEOCHECK<sup>®</sup> - PHYSICAL SETTING SOURCE SUMMARY**

	Soil Layer Information						
	Boundary Classification						
Layer	Upper	Lower	Soil Texture Class	AASHTO Group	Unified Soil	Permeability Rate (in/hr)	Soil Reaction (pH)
1	0 inches	6 inches	variable	Not reported	Not reported	Max: 0.00 Min: 0.00	Max: 0.00 Min: 0.00

## OTHER SOIL TYPES IN AREA

Based on Soil Conservation Service STATSGO data, the following additional subordinant soil types may appear within the general area of target property.

Soil Surface Textures:	sandy loam gravelly - sandy loam silt loam clay fine sand gravelly - sand sand fine sandy loam
Surficial Soil Types:	sandy loam gravelly - sandy loam silt loam clay fine sand gravelly - sand sand fine sandy loam
Shallow Soil Types:	fine sandy loam gravelly - loam sandy clay sandy clay loam clay silty clay sand
Deeper Soil Types:	gravelly - sandy loam sandy loam very gravelly - sandy loam stratified very fine sandy loam weathered bedrock sand gravelly - fine sandy loam silty clay loam clay loam

# **GEOCHECK<sup>®</sup> - PHYSICAL SETTING SOURCE SUMMARY**

## LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

## WELL SEARCH DISTANCE INFORMATION

DATABASE	SEARCH DISTANCE (miles)
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

## FEDERAL USGS WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
A2	USGS3156781	1/4 - 1/2 Mile North
10	USGS3156794	1/2 - 1 Mile NNW
11	USGS3156749	1/2 - 1 Mile SW

## FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

		LOCATION
MAP ID	WELL ID	FROM TP

No PWS System Found

Note: PWS System location is not always the same as well location.


## STATE DATABASE WELL INFORMATION

MAP ID	WELL ID	LOCATION FROM TP
B3	4203	1/2 - 1 Mile NW
B4	4204	1/2 - 1 Mile NW
C5	5363	1/2 - 1 Mile SW
C6	5362	1/2 - 1 Mile SW
C7	22703	1/2 - 1 Mile SW
C8	22704	1/2 - 1 Mile SW
C9	22705	1/2 - 1 Mile SW

## OTHER STATE DATABASE INFORMATION

## STATE OIL/GAS WELL INFORMATION

DISTANCE	DISTANCE
FROM TP (Miles)	<u>FROM TP (Miles</u> )
1/2 - 1 Mile NNE 1/4 - 1/2 Mile NE 1/2 - 1 Mile ENE 1/2 - 1 Mile ESE 1/2 - 1 Mile SE	1/4 - 1/2 Mile NNE 1/2 - 1 Mile WNW 1/2 - 1 Mile East 1/4 - 1/2 Mile SSW



ADDRESS:	2500 Block W. 190th Street Torrance CA 90504	CONTACT: INQUIRY #:	Golder Associates, Inc. Misty Vazquez 2051883.2s October 15, 2007 1:22 pm
		Copyrigh	t © 2007 EDR, Inc. © 2007 Tele Atlas Rel. 07/2006.

Distance Elevation					Database	EDR ID Numbe
A1 North 1/4 - 1/2 Mile Higher	Site ID: Groundwater Shallow Wate Deep Water I Average Wate Date:	Flow:Sor Depth:31Depth:34or Depth:No			AQUIFLOW	69720
A2 North 1/4 - 1/2 Mile Higher					FED USGS	USGS3156781
Agency cd: Site name: Latitude:		USGS 003S014W33E001S 335159		Site no:	335159118193001	
Longitude: Dec lon: Coor accr: Dec latlong o State:	datum:	1181930 -118.3259068 S NAD83 06		Dec lat: Coor meth: Latlong datum: District: County:	33.86640446 M NAD27 06 037	
Country: Location may Altitude: Altitude meth Altitude accu Altitude datu	nod: iracy:	US TORRANCE Not Reported Not Reported Not Reported Not Reported		Land net: Map scale:	Not Reported 24000	
Hydrologic: Topographic		Santa Monica Bay. C Not Reported	California. Ar	ea = 575 sq.mi.		
Site type: Date invento Local standa	ried:	Ground-water other t Not Reported Y	than Spring	Date construction: Mean greenwich time offset:	Not Reported PST	
	nd water site:	Single well, other that Not Reported Not Reported	an collector c	r Ranney type		
Well depth: Source of de Project numb		228 Not Reported 9479335800		Hole depth:	228	
Real time da Daily flow da Peak flow da Peak flow da Water quality	ta flag: ta end date: ta begin date: ta count: / data end date	Not Reported		Daily flow data begin date: Daily flow data count: Peak flow data end date: Water quality data begin date: Water quality data count: Ground water data end date:	Not Reported Not Reported Not Reported Not Reported Not Reported Not Reported	

Ground-water levels, Number of Measurements: 0

CA WELLS 4203

# Water System Information: Prime Station Code: 03S/14W-34B02 S

Water System Information	on:		
Prime Station Code:	03S/14W-34B02 S	User ID:	4TH
FRDS Number:	1910006008	County:	Los Angeles
District Number:			WELL/AMBNT/MUN/INTAKE/SUPPLY
Water Type:	Well/Groundwater	Well Status:	Destroyed
Source Lat/Long:	335200.0 1182000.0	Precision:	Undefined
Source Name:	FRESA WELL (INDUSTRIAL) - DES	TROYED	
System Number:	1910006		
System Name:	SO. CAL. EDISON COSANTA CAT	ALINA	
Organization That Oper			
	P O BOX 527 AVALON, CA 90704		
Pop Served:	3000	Connections:	1798
Area Served:	SANTA CATALINA ISL	Connections.	1730
	o, white o, the law to be		
B4 NW 1/2 - 1 Mile Higher			CA WELLS 4204
Water System Informatio			
Prime Station Code:	03S/14W-34C02 S	User ID:	4TH
FRDS Number:	1910213005	County:	
District Number:	07 Well/Croundwater	Station Type:	WELL/AMBNT/MUN/INTAKE/SUPPLY
Water Type: Source Lat/Long:	Well/Groundwater 335200.0 1182000.0	Well Status: Precision:	Active Raw Undefined
Source Name:	WELL 06	FIECISION.	Ondenned
System Number:	1910213		
System Name:	TORRANCE-CITY, WATER DEPT.		
Organization That Oper	-		
3	3031 TORRANCE BLVD		
	TORRANCE, CA 90503		
Pop Served:	105000	Connections:	25582
Area Served:	TORRANCE		
Sample Collected:	08/12/2004 00:00:00	Findings:	.592 PCI/L
Chemical:	RADIUM 228 COUNTING ERROR		
Sample Collected:	12/29/2004 00:00:00	Findings:	.474 PCI/L
Chemical:	RADIUM 228 COUNTING ERROR	Ū	
Sample Collected:	05/19/2005 00:00:00	Findings:	.11 NTU
Chemical:	TURBIDITY, LABORATORY	r mangs.	
Sample Collected:	05/19/2005 00:00:00	Findings:	880 US
Chemical:	SPECIFIC CONDUCTANCE		
Sample Collected:	05/19/2005 00:00:00	Findings:	7.76
Chemical:	PH, LABORATORY		
Sample Collected:	05/19/2005 00:00:00	Findings:	220 MG/L
Chemical:	ALKALINITY (TOTAL) AS CACO3	Ū	
Sample Collected:	05/19/2005 00:00:00	Findings:	220 MG/L
Chemical:	BICARBONATE ALKALINITY	Findings.	220 WB/E
Sample Collected:	05/19/2005 00:00:00	Findings:	230 MG/L
Chemical:	HARDNESS (TOTAL) AS CACO3		
Sample Collected:	05/19/2005 00:00:00	Findings:	61 MG/L
Chemical:	CALCIUM	-	
Sample Collected:	05/19/2005 00:00:00	Findings:	20 MG/L
Chemical:	MAGNESIUM	i inuniya.	ZU WUU/L
Sample Collected:	05/19/2005 00:00:00	Findings:	79 MG/L
Chemical:	SODIUM		

Sample Collected: Chemical:	05/19/2005 00:00:00 POTASSIUM
Sample Collected: Chemical:	05/19/2005 00:00:00 CHLORIDE
Sample Collected: Chemical:	05/19/2005 00:00:00 FLUORIDE (F) (NATURAL-SO
Sample Collected: Chemical:	05/19/2005 00:00:00 MANGANESE
Sample Collected: Chemical:	05/19/2005 00:00:00 TOTAL DISSOLVED SOLIDS
Sample Collected: Chemical:	05/19/2005 00:00:00 AGGRSSIVE INDEX (CORRO
Sample Collected: Chemical:	03/28/2007 00:00:00 MANGANESE
Sample Collected: Chemical:	02/01/2002 00:00:00 GROSS ALPHA COUNTING E
Sample Collected: Chemical:	06/07/2002 00:00:00 COLOR
Sample Collected: Chemical:	06/07/2002 00:00:00 ODOR THRESHOLD @ 60 C
Sample Collected: Chemical:	06/07/2002 00:00:00 SPECIFIC CONDUCTANCE
Sample Collected: Chemical:	06/07/2002 00:00:00 PH, LABORATORY
Sample Collected: Chemical:	06/07/2002 00:00:00 ALKALINITY (TOTAL) AS CAC
Sample Collected: Chemical:	06/07/2002 00:00:00 BICARBONATE ALKALINITY
Sample Collected: Chemical:	06/07/2002 00:00:00 HARDNESS (TOTAL) AS CAC
Sample Collected: Chemical:	06/07/2002 00:00:00 CALCIUM
Sample Collected: Chemical:	06/07/2002 00:00:00 MAGNESIUM
Sample Collected: Chemical:	06/07/2002 00:00:00 SODIUM
Sample Collected: Chemical:	06/07/2002 00:00:00 POTASSIUM
Sample Collected: Chemical:	06/07/2002 00:00:00 CHLORIDE
Sample Collected: Chemical:	06/07/2002 00:00:00 FLUORIDE (F) (NATURAL-SO
Sample Collected: Chemical:	06/07/2002 00:00:00 IRON
Sample Collected: Chemical:	06/07/2002 00:00:00 MANGANESE
Sample Collected: Chemical:	06/07/2002 00:00:00 ALUMINUM
Sample Collected: Chemical:	06/07/2002 00:00:00 TOTAL DISSOLVED SOLIDS

05/19/2005 00:00:00 POTASSIUM	Findings:	8 MG/L
05/19/2005 00:00:00 CHLORIDE	Findings:	130 MG/L
05/19/2005 00:00:00 FLUORIDE (F) (NATURAL-SOURCE)	Findings:	.31 MG/L
05/19/2005 00:00:00 MANGANESE	Findings:	47 UG/L
05/19/2005 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	530 MG/L
05/19/2005 00:00:00 AGGRSSIVE INDEX (CORROSIVITY)	Findings:	12
03/28/2007 00:00:00 MANGANESE	Findings:	51 UG/L
02/01/2002 00:00:00 GROSS ALPHA COUNTING ERROR	Findings:	1.21 PCI/L
06/07/2002 00:00:00 COLOR	Findings:	5 UNITS
06/07/2002 00:00:00 ODOR THRESHOLD @ 60 C	Findings:	2 TON
06/07/2002 00:00:00 SPECIFIC CONDUCTANCE	Findings:	900 US
06/07/2002 00:00:00 PH, LABORATORY	Findings:	7.89
06/07/2002 00:00:00 ALKALINITY (TOTAL) AS CACO3	Findings:	210 MG/L
06/07/2002 00:00:00 BICARBONATE ALKALINITY	Findings:	250 MG/L
06/07/2002 00:00:00 HARDNESS (TOTAL) AS CACO3	Findings:	260 MG/L
06/07/2002 00:00:00 CALCIUM	Findings:	69 MG/L
06/07/2002 00:00:00 MAGNESIUM	Findings:	22 MG/L
06/07/2002 00:00:00 SODIUM	Findings:	75 MG/L
06/07/2002 00:00:00 POTASSIUM	Findings:	8 MG/L
06/07/2002 00:00:00 CHLORIDE	Findings:	130 MG/L
06/07/2002 00:00:00 FLUORIDE (F) (NATURAL-SOURCE)	Findings:	.27 MG/L
06/07/2002 00:00:00 IRON	Findings:	310 UG/L
06/07/2002 00:00:00 MANGANESE	Findings:	52 UG/L
06/07/2002 00:00:00 ALUMINUM	Findings:	310 UG/L
06/07/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	520 MG/L

Sample Collected: Chemical:	06/07/2002 00:00:00 TURBIDITY, LABORATORY	Findings:	2.7 NTU
Sample Collected: Chemical:	06/07/2002 00:00:00 AGGRSSIVE INDEX (CORROSIVITY)	Findings:	12.45
C5 SW 1/2 - 1 Mile Higher			CA WELLS 5363
Water System Informati	on-		
Prime Station Code:	04S/14W-10D04 S	User ID:	4TH
FRDS Number:	1910033015	County:	Los Angeles
District Number:	07	Station Type:	WELL/AMBNT/MUN/INTAKE/SUPPLY
Water Type:	Well/Groundwater	Well Status:	Active Raw
Source Lat/Long:	335100.0 1182000.0	Precision:	Undefined
Source Name:	WELL 33		
System Number:			
System Name: Organization That Ope	DOMINGUEZ WATER CORP		
organization mat opt	P.O. BOX 9351		
	LONG BEACH, CA 90810		
Pop Served:	100000	Connections:	32000
Area Served:	Not Reported		
Sample Collected:	01/30/2002 00:00:00	Findings:	.18 MG/L
Chemical:	FOAMING AGENTS (MBAS)		
Sample Collected:	01/30/2002 00:00:00	Findings:	7.6
Chemical:	PH, LABORATORY		
Sample Collected: Chemical:	01/30/2002 00:00:00 ALKALINITY (TOTAL) AS CACO3	Findings:	196 MG/L
Sample Collected: Chemical:	01/30/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	1414 MG/L
Sample Collected: Chemical:	02/06/2002 00:00:00 CHLORIDE	Findings:	587 MG/L
Sample Collected: Chemical:	02/06/2002 00:00:00 IRON	Findings:	270 UG/L
Sample Collected: Chemical:	02/06/2002 00:00:00 MANGANESE	Findings:	180 UG/L
Sample Collected: Chemical:	02/06/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	1800 MG/L
Sample Collected: Chemical:	03/06/2002 00:00:00 CHLORIDE	Findings:	730 MG/L
Sample Collected: Chemical:	03/06/2002 00:00:00 IRON	Findings:	210 UG/L
Sample Collected: Chemical:	03/06/2002 00:00:00 MANGANESE	Findings:	200 UG/L
Sample Collected: Chemical:	03/06/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	2000 MG/L
Sample Collected: Chemical:	03/27/2002 00:00:00 GROSS ALPHA COUNTING ERROR	Findings:	.57 PCI/L
Sample Collected: Chemical:	04/03/2002 00:00:00 CHLORIDE	Findings:	780 MG/L

Sample Collected: Chemical:	04/03/2002 00:00:00 IRON	Findings:	110 UG/L
Sample Collected: Chemical:	04/03/2002 00:00:00 MANGANESE	Findings:	170 UG/L
Sample Collected: Chemical:	04/03/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	2100 MG/L
Sample Collected: Chemical:	04/10/2002 00:00:00 BORON	Findings:	180 UG/L
Sample Collected: Chemical:	05/01/2002 00:00:00 MANGANESE	Findings:	190 UG/L
Sample Collected: Chemical:	05/08/2002 00:00:00 GROSS ALPHA COUNTING ERROR	Findings:	.55 PCI/L
Sample Collected: Chemical:	06/05/2002 00:00:00 CHLORIDE	Findings:	770 MG/L
Sample Collected: Chemical:	06/05/2002 00:00:00 MANGANESE	Findings:	140 UG/L
Sample Collected: Chemical:	06/05/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	2200 MG/L
Sample Collected: Chemical:	07/03/2002 00:00:00 CHLORIDE	Findings:	970 MG/L
Sample Collected: Chemical:	07/03/2002 00:00:00 MANGANESE	Findings:	160 UG/L
Sample Collected: Chemical:	07/03/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	2300 MG/L
Sample Collected: Chemical:	07/31/2002 00:00:00 GROSS ALPHA COUNTING ERROR	Findings:	.76 PCI/L
Sample Collected: Chemical:	08/01/2002 00:00:00 ARSENIC	Findings:	3 UG/L
Sample Collected: Chemical:	09/04/2002 00:00:00 PH, LABORATORY	Findings:	7.7
Sample Collected: Chemical:	09/04/2002 00:00:00 BICARBONATE ALKALINITY	Findings:	240 MG/L
Sample Collected: Chemical:	09/04/2002 00:00:00 PHOSPHATE (AS PO4)	Findings:	.11 UG/L
Sample Collected: Chemical:	09/04/2002 00:00:00 CALCIUM	Findings:	320 MG/L
Sample Collected: Chemical:	09/04/2002 00:00:00 MAGNESIUM	Findings:	91 MG/L
Sample Collected: Chemical:	09/04/2002 00:00:00 SODIUM	Findings:	240 MG/L
Sample Collected: Chemical:	09/04/2002 00:00:00 POTASSIUM	Findings:	12 MG/L
Sample Collected: Chemical:	09/04/2002 00:00:00 CHLORIDE	Findings:	880 MG/L
Sample Collected: Chemical:	09/04/2002 00:00:00 FLUORIDE (F) (NATURAL-SOURCE)	Findings:	4.8 MG/L
Sample Collected: Chemical:	09/04/2002 00:00:00 SILICA	Findings:	40 MG/L
Sample Collected: Chemical:	09/04/2002 00:00:00 BARIUM	Findings:	180 UG/L

Sample Collected: Chemical:	09/04/2002 00:00:00 MANGANESE	Findings:	210 UG/L
Sample Collected: Chemical:	09/04/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	2300 MG/L
Sample Collected: Chemical:	09/04/2002 00:00:00 NITRATE (AS NO3)	Findings:	20 MG/L
Sample Collected: Chemical:	09/12/2002 00:00:00 BORON	Findings:	170 UG/L
Sample Collected: Chemical:	09/23/2002 00:00:00 CHROMIUM (TOTAL CR-CRVI SCRE	Findings: EN)	2 UG/L
Sample Collected: Chemical:	10/02/2002 00:00:00 CHLORIDE	Findings:	850 MG/L
Sample Collected: Chemical:	10/02/2002 00:00:00 MANGANESE	Findings:	170 UG/L
Sample Collected: Chemical:	10/02/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	2200 MG/L
Sample Collected: Chemical:	10/22/2002 00:00:00 ARSENIC	Findings:	4 UG/L
Sample Collected: Chemical:	11/06/2002 00:00:00 CHLORIDE	Findings:	970 MG/L
Sample Collected: Chemical:	11/06/2002 00:00:00 MANGANESE	Findings:	210 UG/L
Sample Collected: Chemical:	11/06/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	2200 MG/L
Sample Collected: Chemical:	11/18/2002 00:00:00 GROSS ALPHA COUNTING ERROR	Findings:	.66 PCI/L
Sample Collected: Chemical:	12/04/2002 00:00:00 CHLORIDE	Findings:	830 MG/L
Sample Collected: Chemical:	12/04/2002 00:00:00 MANGANESE	Findings:	130 UG/L
Sample Collected: Chemical:	12/04/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	2300 MG/L
Sample Collected: Chemical:	01/02/2003 00:00:00 CHLORIDE	Findings:	820 MG/L
Sample Collected: Chemical:	01/02/2003 00:00:00 MANGANESE	Findings:	150 UG/L
Sample Collected: Chemical:	01/02/2003 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	2300 MG/L

#### C6 SW 1/2 - 1 Mile Higher

## Water System Information:

Prime Station Code: ( FRDS Number: ) District Number: ( Water Type: ) Source Lat/Long: 3 Source Name: )

04S/14W-10D03 S 1910033014 07 Well/Groundwater 335100.0 1182000.0 WELL 32 User ID: County: Station Type: Well Status: Precision: 4TH Los Angeles WELL/AMBNT/MUN/INTAKE/SUPPLY Active Raw Undefined

CA WELLS

5362

System Number: System Name: Organization That Oper	P.O. BOX 9351		
Pop Served: Area Served:	LONG BEACH, CA 90810 100000 Not Reported	Connections:	32000
Sample Collected: Chemical:	Not Reported 01/30/2002 00:00:00 PH, LABORATORY	Findings:	7.39
Sample Collected: Chemical:	01/30/2002 00:00:00 ALKALINITY (TOTAL) AS CACO3	Findings:	166 MG/L
Sample Collected: Chemical:	01/30/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	4499 MG/L
Sample Collected: Chemical:	01/30/2002 00:00:00 FOAMING AGENTS (MBAS)	Findings:	.19 MG/L
Sample Collected: Chemical:	02/06/2002 00:00:00 PH, LABORATORY	Findings:	7.4
Sample Collected: Chemical:	02/06/2002 00:00:00 CHLORIDE	Findings:	2600 MG/L
Sample Collected: Chemical:	02/06/2002 00:00:00 MANGANESE	Findings:	210 UG/L
Sample Collected: Chemical:	02/06/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	5400 MG/L
Sample Collected: Chemical:	02/27/2002 00:00:00 GROSS ALPHA COUNTING ERROR	Findings:	.47 PCI/L
Sample Collected: Chemical:	03/06/2002 00:00:00 PH, LABORATORY	Findings:	7.6
Sample Collected: Chemical:	03/06/2002 00:00:00 CHLORIDE	Findings:	2500 MG/L
Sample Collected: Chemical:	03/06/2002 00:00:00 MANGANESE	Findings:	250 UG/L
Sample Collected: Chemical:	03/06/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	5300 MG/L
Sample Collected: Chemical:	04/03/2002 00:00:00 PH, LABORATORY	Findings:	7.5
Sample Collected: Chemical:	04/03/2002 00:00:00 CHLORIDE	Findings:	2200 MG/L
Sample Collected: Chemical:	04/03/2002 00:00:00 MANGANESE	Findings:	220 UG/L
Sample Collected: Chemical:	04/03/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	5100 MG/L
Sample Collected: Chemical:	04/10/2002 00:00:00 BORON	Findings:	160 UG/L
Sample Collected: Chemical:	04/23/2002 00:00:00 ARSENIC	Findings:	4 UG/L
Sample Collected: Chemical:	05/01/2002 00:00:00 PH, LABORATORY	Findings:	7.9
Sample Collected: Chemical:	05/01/2002 00:00:00 CHLORIDE	Findings:	2100 MG/L
Sample Collected: Chemical:	05/01/2002 00:00:00 IRON	Findings:	140 UG/L

240 UG/L

4900 MG/L

1.01 PCI/L

2000 MG/L

160 UG/L

4800 MG/L

2300 MG/L

180 UG/L

4700 MG/L

4 UG/L

5 MG/L

7.8

1.01 PCI/L

200 MG/L

1 MG/L

.11 UG/L

600 MG/L

170 MG/L

530 MG/L

18 MG/L

2000 MG/L

4.6 MG/L

37 MG/L

8

8

Sample Collected: Chemical:	05/01/2002 00:00:00 MANGANESE	Findings:
Sample Collected: Chemical:	05/01/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:
Sample Collected: Chemical:	06/03/2002 00:00:00 GROSS ALPHA COUNTING ERROR	Findings:
Sample Collected: Chemical:	06/05/2002 00:00:00 PH, LABORATORY	Findings:
Sample Collected: Chemical:	06/05/2002 00:00:00 CHLORIDE	Findings:
Sample Collected: Chemical:	06/05/2002 00:00:00 MANGANESE	Findings:
Sample Collected: Chemical:	06/05/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:
Sample Collected: Chemical:	07/03/2002 00:00:00 PH, LABORATORY	Findings:
Sample Collected: Chemical:	07/03/2002 00:00:00 CHLORIDE	Findings:
Sample Collected: Chemical:	07/03/2002 00:00:00 MANGANESE	Findings:
Sample Collected: Chemical:	07/03/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:
Sample Collected: Chemical:	07/19/2002 00:00:00 ARSENIC	Findings:
Sample Collected: Chemical:	07/22/2002 00:00:00 NITRATE (AS NO3)	Findings:
Sample Collected: Chemical:	07/31/2002 00:00:00 GROSS ALPHA COUNTING ERROR	Findings:
Sample Collected: Chemical:	09/04/2002 00:00:00 PH, LABORATORY	Findings:
Sample Collected: Chemical:	09/04/2002 00:00:00 BICARBONATE ALKALINITY	Findings:
Sample Collected: Chemical:	09/04/2002 00:00:00 AMMONIA (NH3-N)	Findings:
Sample Collected: Chemical:	09/04/2002 00:00:00 PHOSPHATE (AS PO4)	Findings:
Sample Collected: Chemical:	09/04/2002 00:00:00 CALCIUM	Findings:
Sample Collected: Chemical:	09/04/2002 00:00:00 MAGNESIUM	Findings:
Sample Collected: Chemical:	09/04/2002 00:00:00 SODIUM	Findings:
Sample Collected: Chemical:	09/04/2002 00:00:00 POTASSIUM	Findings:
Sample Collected: Chemical:	09/04/2002 00:00:00 CHLORIDE	Findings:
Sample Collected: Chemical:	09/04/2002 00:00:00 FLUORIDE (F) (NATURAL-SOURCE)	Findings:
Sample Collected:	09/04/2002 00:00:00 SILICA	Findings:

SILICA

. Chemical:

Sample Collected:
Chemical:

Sample Collected: Chemical:

Sample Collected Chemical:

Sample Collected: Chemical:

Sample Collected: Chemical:

Sample Collected: Chemical:

Sample Collected Chemical:

Sample Collected: Chemical:

Sample Collected Chemical:

Sample Collected: Chemical:

ted:	09/04/2002 00:00:00 MANGANESE	Findings:	220 UG/L
ted:	09/04/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	4500 MG/L
ted:	09/04/2002 00:00:00 NITRATE (AS NO3)	Findings:	19 MG/L
ted:	09/12/2002 00:00:00 BORON	Findings:	170 UG/L
ted:	10/02/2002 00:00:00 PH, LABORATORY	Findings:	7.7
ted:	10/02/2002 00:00:00 CHLORIDE	Findings:	1800 MG/L
ted:	10/02/2002 00:00:00 MANGANESE	Findings:	190 UG/L
ted:	10/02/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	4200 MG/L
ted:	10/22/2002 00:00:00 ARSENIC	Findings:	5 UG/L
ted:	11/06/2002 00:00:00 PH, LABORATORY	Findings:	8
ted:	11/06/2002 00:00:00 CHLORIDE	Findings:	1700 MG/L
ted:	11/06/2002 00:00:00 MANGANESE	Findings:	250 UG/L
ted:	11/06/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	4100 MG/L
ted:	11/18/2002 00:00:00 GROSS ALPHA COUNTING ERROR	Findings:	.72 PCI/L
ted:	12/04/2002 00:00:00 PH, LABORATORY	Findings:	7.9
ted:	12/04/2002 00:00:00 CHLORIDE	Findings:	1800 MG/L
ted:	12/04/2002 00:00:00 MANGANESE	Findings:	130 UG/L
ted:	12/04/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	4300 MG/L
ted:	01/02/2003 00:00:00 PH, LABORATORY	Findings:	7.7
ted:	01/02/2003 00:00:00 CHLORIDE	Findings:	1800 MG/L
ted:	01/02/2003 00:00:00 MANGANESE	Findings:	160 UG/L
ted:	01/02/2003 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	4400 MG/L

Map ID Direction				
Distance Elevation			Database	EDR ID Number
C7 SW 1/2 - 1 Mile Higher			CA WELLS	22703
Water System Informatic Prime Station Code: FRDS Number: District Number: Water Type: Source Lat/Long: Source Name: System Number: System Name: Organization That Open	G19/033-TDSBL01 1910033025 07 Well/Groundwater 335100.0 1182000.0 WELL 32 & 33 AND RO EFF - BLEND 1910033 DOMINGUEZ WATER CORP	User ID: County: Station Type: Well Status: Precision:	4TH Los Angeles WELL/AMBNT/MUN/INTAK Combined Treated 1 Mile (One Minute)	E
Pop Served: Area Served: Sample Collected:	100000 Not Reported 01/30/2002 00:00:00	Connections: Findings:	32000 7.1	
Chemical: Sample Collected: Chemical:	PH, LABORATORY 01/30/2002 00:00:00 CHLORIDE	Findings:	180 MG/L	
Sample Collected: Chemical:	01/30/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	420 MG/L	
Sample Collected: Chemical:	02/06/2002 00:00:00 PH, LABORATORY	Findings:	7.7	
Sample Collected: Chemical:	02/06/2002 00:00:00 CHLORIDE	Findings:	220 MG/L	
Sample Collected: Chemical:	02/06/2002 00:00:00 MANGANESE	Findings:	25 UG/L	
Sample Collected: Chemical:	02/06/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	500 MG/L	
Sample Collected: Chemical:	02/13/2002 00:00:00 PH, LABORATORY	Findings:	7.6	
Sample Collected: Chemical:	02/13/2002 00:00:00 CHLORIDE	Findings:	190 MG/L	
Sample Collected: Chemical:	02/13/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	470 MG/L	
Sample Collected: Chemical:	02/20/2002 00:00:00 PH, LABORATORY	Findings:	7.4	
Sample Collected: Chemical:	02/20/2002 00:00:00 CHLORIDE	Findings:	200 MG/L	
Sample Collected: Chemical:	02/20/2002 00:00:00 MANGANESE	Findings:	27 UG/L	
Sample Collected: Chemical:	02/20/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	450 MG/L	
Sample Collected: Chemical:	02/27/2002 00:00:00 PH, LABORATORY	Findings:	7.7	
Sample Collected: Chemical:	02/27/2002 00:00:00 CHLORIDE	Findings:	56 MG/L	

Sample Collected: Chemical:	02/27/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	440 MG/L
Sample Collected: Chemical:	03/06/2002 00:00:00 PH, LABORATORY	Findings:	7.6
Sample Collected: Chemical:	03/06/2002 00:00:00 CHLORIDE	Findings:	200 MG/L
Sample Collected: Chemical:	03/06/2002 00:00:00 MANGANESE	Findings:	26 UG/L
Sample Collected: Chemical:	03/06/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	450 MG/L
Sample Collected: Chemical:	03/13/2002 00:00:00 PH, LABORATORY	Findings:	7.6
Sample Collected: Chemical:	03/13/2002 00:00:00 CHLORIDE	Findings:	180 MG/L
Sample Collected: Chemical:	03/13/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	410 MG/L
Sample Collected: Chemical:	03/20/2002 00:00:00 PH, LABORATORY	Findings:	7.6
Sample Collected: Chemical:	03/20/2002 00:00:00 CHLORIDE	Findings:	160 MG/L
Sample Collected: Chemical:	03/20/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	360 MG/L
Sample Collected: Chemical:	03/27/2002 00:00:00 PH, LABORATORY	Findings:	7.5
Sample Collected: Chemical:	03/27/2002 00:00:00 CHLORIDE	Findings:	180 MG/L
Sample Collected: Chemical:	03/27/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	400 MG/L
Sample Collected: Chemical:	04/03/2002 00:00:00 PH, LABORATORY	Findings:	7.3
Sample Collected: Chemical:	04/03/2002 00:00:00 CHLORIDE	Findings:	160 MG/L
Sample Collected: Chemical:	04/03/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	370 MG/L
Sample Collected: Chemical:	04/10/2002 00:00:00 PH, LABORATORY	Findings:	7.1
Sample Collected: Chemical:	04/10/2002 00:00:00 CHLORIDE	Findings:	170 MG/L
Sample Collected: Chemical:	04/10/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	380 MG/L
Sample Collected: Chemical:	04/17/2002 00:00:00 PH, LABORATORY	Findings:	7.5
Sample Collected: Chemical:	04/17/2002 00:00:00 CHLORIDE	Findings:	170 MG/L
Sample Collected: Chemical:	04/17/2002 00:00:00 MANGANESE	Findings:	21 UG/L
Sample Collected: Chemical:	04/17/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	380 MG/L
Sample Collected: Chemical:	04/24/2002 00:00:00 PH, LABORATORY	Findings:	7.5

Sample Collected:
Chemical:

Sample Collected: Chemical:

l:	04/24/2002 00:00:00 CHLORIDE	Findings:	180 MG/L
1:	04/24/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	410 MG/L
1:	05/08/2002 00:00:00 PH, LABORATORY	Findings:	7.1
l:	05/08/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	380 MG/L
l:	05/15/2002 00:00:00 PH, LABORATORY	Findings:	7.7
l:	05/15/2002 00:00:00 CHLORIDE	Findings:	170 MG/L
l:	05/15/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	380 MG/L
l:	05/22/2002 00:00:00 PH, LABORATORY	Findings:	7.5
1:	05/22/2002 00:00:00 CHLORIDE	Findings:	180 MG/L
l:	05/22/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	390 MG/L
l:	05/29/2002 00:00:00 PH, LABORATORY	Findings:	7.3
1:	05/29/2002 00:00:00 CHLORIDE	Findings:	180 MG/L
1:	05/29/2002 00:00:00 MANGANESE	Findings:	21 UG/L
l:	05/29/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	410 MG/L
l:	06/05/2002 00:00:00 PH, LABORATORY	Findings:	7.8
l:	06/05/2002 00:00:00 CHLORIDE	Findings:	180 MG/L
1:	06/05/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	450 MG/L
1:	06/19/2002 00:00:00 PH, LABORATORY	Findings:	7.8
1:	06/19/2002 00:00:00 CHLORIDE	Findings:	190 MG/L
1:	06/19/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	440 MG/L
1:	06/26/2002 00:00:00 PH, LABORATORY	Findings:	7.5
l:	06/26/2002 00:00:00 CHLORIDE	Findings:	180 MG/L
l:	06/26/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	410 MG/L
l:	07/03/2002 00:00:00 PH, LABORATORY	Findings:	7.8
l:	07/03/2002 00:00:00 CHLORIDE	Findings:	200 MG/L

66 UG/L

410 MG/L

190 MG/L

410 MG/L

170 MG/L

390 MG/L

180 MG/L

410 MG/L

180 MG/L

420 MG/L

170 MG/L

400 MG/L

170 MG/L

390 MG/L

170 MG/L

21 UG/L

400 MG/L

7.4

7.5

7.8

7.4

7

7.7

7.7

7.3

07/03/2002 00:00:00 MANGANESE	Findings:
07/03/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:
07/10/2002 00:00:00 PH, LABORATORY	Findings:
07/10/2002 00:00:00 CHLORIDE	Findings:
07/10/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:
07/17/2002 00:00:00 PH, LABORATORY	Findings:
07/17/2002 00:00:00 CHLORIDE	Findings:
07/17/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:
07/24/2002 00:00:00 PH, LABORATORY	Findings:
07/24/2002 00:00:00 CHLORIDE	Findings:
07/24/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:
07/31/2002 00:00:00 PH, LABORATORY	Findings:
07/31/2002 00:00:00 CHLORIDE	Findings:
07/31/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:
08/14/2002 00:00:00 PH, LABORATORY	Findings:
08/14/2002 00:00:00 CHLORIDE	Findings:
08/14/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:
08/21/2002 00:00:00 PH, LABORATORY	Findings:
08/21/2002 00:00:00 CHLORIDE	Findings:
08/21/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:
08/28/2002 00:00:00 PH, LABORATORY	Findings:
08/28/2002 00:00:00 CHLORIDE	Findings:
08/28/2002 00:00:00 MANGANESE	Findings:
08/28/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:
09/04/2002 00:00:00 PH, LABORATORY	Findings:
	MANGANESE         07/03/2002 00:00:00         TOTAL DISSOLVED SOLIDS         07/10/2002 00:00:00         PH, LABORATORY         07/10/2002 00:00:00         CHLORIDE         07/11/2002 00:00:00         PH, LABORATORY         07/17/2002 00:00:00         PH, LABORATORY         07/17/2002 00:00:00         PH, LABORATORY         07/17/2002 00:00:00         CHLORIDE         07/17/2002 00:00:00         PH, LABORATORY         07/24/2002 00:00:00         PH, LABORATORY         07/24/2002 00:00:00         CHLORIDE         07/31/2002 00:00:00         PH, LABORATORY         07/31/2002 00:00:00         PH, LABORATORY         08/14/2002 00:00:00         PH, LABORATORY         08/14/2002 00:00:00         PH, LABORATORY         08/14/2002 00:00:00         PH, LABORATORY         08/21/2002 00:00:00         PH, LABORATORY         08/21/2002 00:00:00         PH, LABORATORY         08/21/2002 00:00:00         PH, LABORATORY         08/221/2002 00:00:00         PH, LABORATORY         08/221/2002 00:00:00

Sample Collected: Chemical:	09/04/2002 00:00:00 CHLORIDE	Findings:	180 MG/L
Sample Collected: Chemical:	09/04/2002 00:00:00 MANGANESE	Findings:	21 UG/L
Sample Collected: Chemical:	09/04/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	420 MG/L
Sample Collected: Chemical:	09/11/2002 00:00:00 PH, LABORATORY	Findings:	7.5
Sample Collected: Chemical:	09/11/2002 00:00:00 CHLORIDE	Findings:	200 MG/L
Sample Collected: Chemical:	09/11/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	450 MG/L
Sample Collected: Chemical:	09/18/2002 00:00:00 PH, LABORATORY	Findings:	7.7
Sample Collected: Chemical:	09/18/2002 00:00:00 CHLORIDE	Findings:	190 MG/L
Sample Collected: Chemical:	09/18/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	440 MG/L
Sample Collected: Chemical:	09/25/2002 00:00:00 PH, LABORATORY	Findings:	7.5
Sample Collected: Chemical:	09/25/2002 00:00:00 CHLORIDE	Findings:	180 MG/L
Sample Collected: Chemical:	09/25/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	420 MG/L
Sample Collected: Chemical:	10/02/2002 00:00:00 PH, LABORATORY	Findings:	7.5
Sample Collected: Chemical:	10/02/2002 00:00:00 CHLORIDE	Findings:	180 MG/L
Sample Collected: Chemical:	10/02/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	410 MG/L
Sample Collected: Chemical:	10/09/2002 00:00:00 PH, LABORATORY	Findings:	7.5
Sample Collected: Chemical:	10/09/2002 00:00:00 CHLORIDE	Findings:	210 MG/L
Sample Collected: Chemical:	10/09/2002 00:00:00 MANGANESE	Findings:	24 UG/L
Sample Collected: Chemical:	10/09/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	450 MG/L
Sample Collected: Chemical:	10/16/2002 00:00:00 PH, LABORATORY	Findings:	7.8
Sample Collected: Chemical:	10/16/2002 00:00:00 CHLORIDE	Findings:	210 MG/L
Sample Collected: Chemical:	10/16/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	460 MG/L
Sample Collected: Chemical:	10/23/2002 00:00:00 PH, LABORATORY	Findings:	7.8
Sample Collected: Chemical:	10/23/2002 00:00:00 CHLORIDE	Findings:	200 MG/L
Sample Collected: Chemical:	10/23/2002 00:00:00 MANGANESE	Findings:	30 UG/L

Sample Collected: Chemical:	10/23/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	440 MG/L
Sample Collected: Chemical:	10/30/2002 00:00:00 PH, LABORATORY	Findings:	7.6
Sample Collected: Chemical:	10/30/2002 00:00:00 CHLORIDE	Findings:	200 MG/L
Sample Collected: Chemical:	10/30/2002 00:00:00 MANGANESE	Findings:	23 UG/L
Sample Collected: Chemical:	10/30/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	430 MG/L
Sample Collected: Chemical:	11/06/2002 00:00:00 PH, LABORATORY	Findings:	7.8
Sample Collected: Chemical:	11/06/2002 00:00:00 CHLORIDE	Findings:	200 MG/L
Sample Collected: Chemical:	11/06/2002 00:00:00 MANGANESE	Findings:	33 UG/L
Sample Collected: Chemical:	11/06/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	440 MG/L
Sample Collected: Chemical:	11/13/2002 00:00:00 PH, LABORATORY	Findings:	7.8
Sample Collected: Chemical:	11/13/2002 00:00:00 CHLORIDE	Findings:	210 MG/L
Sample Collected: Chemical:	11/13/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	450 MG/L
Sample Collected: Chemical:	11/20/2002 00:00:00 PH, LABORATORY	Findings:	7.5
Sample Collected: Chemical:	11/20/2002 00:00:00 CHLORIDE	Findings:	220 MG/L
Sample Collected: Chemical:	11/20/2002 00:00:00 MANGANESE	Findings:	24 UG/L
Sample Collected: Chemical:	11/20/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	480 MG/L
Sample Collected: Chemical:	11/27/2002 00:00:00 PH, LABORATORY	Findings:	7.8
Sample Collected: Chemical:	11/27/2002 00:00:00 CHLORIDE	Findings:	220 MG/L
Sample Collected: Chemical:	11/27/2002 00:00:00 MANGANESE	Findings:	23 UG/L
Sample Collected: Chemical:	11/27/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	480 MG/L
Sample Collected: Chemical:	12/04/2002 00:00:00 PH, LABORATORY	Findings:	7.9
Sample Collected: Chemical:	12/04/2002 00:00:00 CHLORIDE	Findings:	210 MG/L
Sample Collected: Chemical:	12/04/2002 00:00:00 MANGANESE	Findings:	22 UG/L
Sample Collected: Chemical:	12/04/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	480 MG/L
Sample Collected: Chemical:	12/11/2002 00:00:00 PH, LABORATORY	Findings:	7.7

Sample Collected: Chemical:	12/11/2002 00:00:00 CHLORIDE	Findings:	210 MG/L
Sample Collected: Chemical:	12/11/2002 00:00:00 MANGANESE	Findings:	25 UG/L
Sample Collected: Chemical:	12/11/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	480 MG/L
Sample Collected: Chemical:	12/18/2002 00:00:00 PH, LABORATORY	Findings:	6.7
Sample Collected: Chemical:	12/18/2002 00:00:00 CHLORIDE	Findings:	210 MG/L
Sample Collected: Chemical:	12/18/2002 00:00:00 MANGANESE	Findings:	23 UG/L
Sample Collected: Chemical:	12/18/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	470 MG/L
Sample Collected: Chemical:	01/02/2003 00:00:00 PH, LABORATORY	Findings:	7.2
Sample Collected: Chemical:	01/02/2003 00:00:00 CHLORIDE	Findings:	210 MG/L
Sample Collected: Chemical:	01/02/2003 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	460 MG/L
Sample Collected: Chemical:	01/08/2003 00:00:00 PH, LABORATORY	Findings:	7.3
Sample Collected: Chemical:	01/08/2003 00:00:00 CHLORIDE	Findings:	210 MG/L
Sample Collected: Chemical:	01/08/2003 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	470 MG/L
Sample Collected: Chemical:	01/15/2003 00:00:00 PH, LABORATORY	Findings:	7.5
Sample Collected: Chemical:	01/15/2003 00:00:00 CHLORIDE	Findings:	170 MG/L
Sample Collected: Chemical:	01/15/2003 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	390 MG/L

C8 SW 1/2 - 1 Mile Higher

## Water System Information:

waler Sys		II.		
Prime St	tation Code:	G19/033-TDSROEF	User ID:	4TH
FRDS N	umber:	1910033026	County:	Los Angeles
District N	lumber:	07	Station Type:	WELL/AMBNT/MUN/INTAKE
Water Ty	ype:	Well/Groundwater	Well Status:	Active Treated
Source L	_at/Long:	335100.0 1182000.0	Precision:	1 Mile (One Minute)
Source N	Name:	WELLS 32 & 33 - RO PLANT EFF (TD	S REDUC)	
System	Number:	1910033		
System	Name:	DOMINGUEZ WATER CORP		
Organiza	ation That Opera	ates System:		
		P.O. BOX 9351		
		LONG BEACH, CA 90810		
Pop Ser	ved:	100000	Connections:	32000
Area Se	rved:	Not Reported		

## CA WELLS 22704

Sample Collected: Chemical:	05/15/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	86 MG/L
Sample Collected: Chemical:	05/22/2002 00:00:00 CHLORIDE	Findings:	39 MG/L
Sample Collected: Chemical:	05/22/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	84 MG/L
Sample Collected: Chemical:	05/29/2002 00:00:00 CHLORIDE	Findings:	39 MG/L
Sample Collected: Chemical:	05/29/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	83 MG/L
Sample Collected: Chemical:	06/05/2002 00:00:00 CHLORIDE	Findings:	39 MG/L
Sample Collected: Chemical:	06/05/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	83 MG/L
Sample Collected: Chemical:	06/19/2002 00:00:00 CHLORIDE	Findings:	45 MG/L
Sample Collected: Chemical:	06/19/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	99 MG/L
Sample Collected: Chemical:	06/26/2002 00:00:00 CHLORIDE	Findings:	44 MG/L
Sample Collected: Chemical:	06/26/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	96 MG/L
Sample Collected: Chemical:	07/03/2002 00:00:00 CHLORIDE	Findings:	47 MG/L
Sample Collected: Chemical:	07/03/2002 00:00:00 MANGANESE	Findings:	52 UG/L
Sample Collected: Chemical:	07/03/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	88 MG/L
Sample Collected: Chemical:	07/10/2002 00:00:00 CHLORIDE	Findings:	46 MG/L
Sample Collected: Chemical:	07/10/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	97 MG/L
Sample Collected: Chemical:	07/17/2002 00:00:00 CHLORIDE	Findings:	44 MG/L
Sample Collected: Chemical:	07/17/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	95 MG/L
Sample Collected: Chemical:	07/24/2002 00:00:00 CHLORIDE	Findings:	43 MG/L
Sample Collected: Chemical:	07/24/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	94 MG/L
Sample Collected: Chemical:	07/31/2002 00:00:00 CHLORIDE	Findings:	180 MG/L
Sample Collected: Chemical:	07/31/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	410 MG/L
Sample Collected: Chemical:	08/14/2002 00:00:00 CHLORIDE	Findings:	39 MG/L
Sample Collected: Chemical:	08/14/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	86 MG/L
Sample Collected: Chemical:	08/21/2002 00:00:00 CHLORIDE	Findings:	39 MG/L

Sample Collected: Chemical:	08/21/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	85 MG/L
Sample Collected: Chemical:	08/28/2002 00:00:00 CHLORIDE	Findings:	39 MG/L
Sample Collected: Chemical:	08/28/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	87 MG/L
Sample Collected: Chemical:	09/04/2002 00:00:00 CHLORIDE	Findings:	43 MG/L
Sample Collected: Chemical:	09/04/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	94 MG/L
Sample Collected: Chemical:	09/11/2002 00:00:00 CHLORIDE	Findings:	44 MG/L
Sample Collected: Chemical:	09/11/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	96 MG/L
Sample Collected: Chemical:	09/18/2002 00:00:00 CHLORIDE	Findings:	43 MG/L
Sample Collected: Chemical:	09/18/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	96 MG/L
Sample Collected: Chemical:	09/25/2002 00:00:00 CHLORIDE	Findings:	43 MG/L
Sample Collected: Chemical:	09/25/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	94 MG/L
Sample Collected: Chemical:	10/02/2002 00:00:00 CHLORIDE	Findings:	43 MG/L
Sample Collected: Chemical:	10/02/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	88 MG/L
Sample Collected: Chemical:	10/09/2002 00:00:00 CHLORIDE	Findings:	42 MG/L
Sample Collected: Chemical:	10/09/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	87 MG/L
Sample Collected: Chemical:	10/16/2002 00:00:00 CHLORIDE	Findings:	41 MG/L
Sample Collected: Chemical:	10/16/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	86 MG/L
Sample Collected: Chemical:	10/23/2002 00:00:00 CHLORIDE	Findings:	41 MG/L
Sample Collected: Chemical:	10/23/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	84 MG/L
Sample Collected: Chemical:	10/30/2002 00:00:00 CHLORIDE	Findings:	43 MG/L
Sample Collected: Chemical:	10/30/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	86 MG/L
Sample Collected: Chemical:	11/06/2002 00:00:00 CHLORIDE	Findings:	42 MG/L
Sample Collected: Chemical:	11/06/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	86 MG/L
Sample Collected: Chemical:	11/13/2002 00:00:00 CHLORIDE	Findings:	46 MG/L
Sample Collected: Chemical:	11/13/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	93 MG/L

Sample Collected: Chemical:

:	11/20/2002 00:00:00 CHLORIDE	Findings:	47 MG/L
:	11/20/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	97 MG/L
:	11/27/2002 00:00:00 CHLORIDE	Findings:	47 MG/L
:	11/27/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	95 MG/L
:	12/04/2002 00:00:00 CHLORIDE	Findings:	48 MG/L
:	12/04/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	100 MG/L
:	12/11/2002 00:00:00 CHLORIDE	Findings:	48 MG/L
:	12/11/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	100 MG/L
:	12/18/2002 00:00:00 CHLORIDE	Findings:	47 MG/L
:	12/18/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	100 MG/L
:	01/02/2003 00:00:00 CHLORIDE	Findings:	47 MG/L
:	01/02/2003 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	170 MG/L
:	01/08/2003 00:00:00 CHLORIDE	Findings:	47 MG/L
:	01/08/2003 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	99 MG/L
:	01/15/2003 00:00:00 CHLORIDE	Findings:	47 MG/L
:	01/15/2003 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	100 MG/L
:	06/11/2007 00:00:00 PH, LABORATORY	Findings:	7.18
	07/25/2007 00:00:00 PH, LABORATORY	Findings:	6.87
	07/25/2007 00:00:00 CHLORIDE	Findings:	43.8 MG/L
:	07/25/2007 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	86.7 MG/L
:	01/30/2002 00:00:00 CHLORIDE	Findings:	56 MG/L
:	01/30/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	120 MG/L
:	02/06/2002 00:00:00 CHLORIDE	Findings:	57 MG/L
:	02/06/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	120 MG/L
:	02/13/2002 00:00:00 CHLORIDE	Findings:	57 MG/L

Sample Collected: Chemical:	02/13/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	130 MG/L
Sample Collected: Chemical:	02/20/2002 00:00:00 CHLORIDE	Findings:	56 MG/L
Sample Collected: Chemical:	02/20/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	120 MG/L
Sample Collected: Chemical:	02/27/2002 00:00:00 CHLORIDE	Findings:	11 MG/L
Sample Collected: Chemical:	02/27/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	120 MG/L
Sample Collected: Chemical:	03/06/2002 00:00:00 CHLORIDE	Findings:	56 MG/L
Sample Collected: Chemical:	03/06/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	120 MG/L
Sample Collected: Chemical:	03/13/2002 00:00:00 CHLORIDE	Findings:	47 MG/L
Sample Collected: Chemical:	03/13/2002 00:00:00 MANGANESE	Findings:	25 UG/L
Sample Collected: Chemical:	03/13/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	98 MG/L
Sample Collected: Chemical:	03/20/2002 00:00:00 CHLORIDE	Findings:	46 MG/L
Sample Collected: Chemical:	03/20/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	99 MG/L
Sample Collected: Chemical:	03/27/2002 00:00:00 CHLORIDE	Findings:	44 MG/L
Sample Collected: Chemical:	03/27/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	95 MG/L
Sample Collected: Chemical:	04/03/2002 00:00:00 CHLORIDE	Findings:	44 MG/L
Sample Collected: Chemical:	04/03/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	94 MG/L
Sample Collected: Chemical:	04/10/2002 00:00:00 CHLORIDE	Findings:	43 MG/L
Sample Collected: Chemical:	04/10/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	93 MG/L
Sample Collected: Chemical:	04/17/2002 00:00:00 CHLORIDE	Findings:	43 MG/L
Sample Collected: Chemical:	04/17/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	91 MG/L
Sample Collected: Chemical:	04/24/2002 00:00:00 CHLORIDE	Findings:	41 MG/L
Sample Collected: Chemical:	04/24/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	88 MG/L
Sample Collected: Chemical:	05/01/2002 00:00:00 CHLORIDE	Findings:	41 MG/L
Sample Collected: Chemical:	05/01/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	88 MG/L
Sample Collected: Chemical:	05/15/2002 00:00:00 CHLORIDE	Findings:	40 MG/L

Map ID Direction Distance				
Elevation			Database	EDR ID Number
C9 SW 1/2 - 1 Mile Higher			CA WELLS	22705
Water System Informatic Prime Station Code: FRDS Number: District Number: Water Type: Source Lat/Long: Source Name: System Number: System Name: Organization That Open	G19/033-TDSROIN 1910033027 07 Well/Groundwater 335100.0 1182000.0 WELLS 32 & 33 - RO PLANT INF. 1910033 DOMINGUEZ WATER CORP rates System: P.O. BOX 9351	User ID: County: Station Type: Well Status: Precision:	4TH Los Angeles WELL/AMBNT/MUN/INTAKE Active Treated 1 Mile (One Minute)	Ξ
Pop Served: Area Served:	LONG BEACH, CA 90810 100000 Not Reported	Connections:	32000	
Sample Collected: Chemical:	01/30/2002 00:00:00 ARSENIC	Findings:	6 UG/L	
Sample Collected: Chemical:	02/06/2002 00:00:00 CHLORIDE	Findings:	1500 MG/L	
Sample Collected: Chemical:	02/06/2002 00:00:00 IRON	Findings:	140 UG/L	
Sample Collected: Chemical:	02/06/2002 00:00:00 MANGANESE	Findings:	190 UG/L	
Sample Collected: Chemical:	02/06/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	3700 MG/L	
Sample Collected: Chemical:	03/06/2002 00:00:00 CHLORIDE	Findings:	1500 MG/L	
Sample Collected: Chemical:	03/06/2002 00:00:00 IRON	Findings:	120 UG/L	
Sample Collected: Chemical:	03/06/2002 00:00:00 MANGANESE	Findings:	230 UG/L	
Sample Collected: Chemical:	03/06/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	3700 MG/L	
Sample Collected: Chemical:	04/03/2002 00:00:00 CHLORIDE	Findings:	1500 MG/L	
Sample Collected: Chemical:	04/03/2002 00:00:00 MANGANESE	Findings:	200 UG/L	
Sample Collected: Chemical:	04/03/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	3600 MG/L	
Sample Collected: Chemical:	04/23/2002 00:00:00 ARSENIC	Findings:	3 UG/L	
Sample Collected: Chemical:	05/01/2002 00:00:00 CHLORIDE	Findings:	1400 MG/L	
Sample Collected: Chemical:	05/01/2002 00:00:00 MANGANESE	Findings:	220 UG/L	
Sample Collected: Chemical:	05/01/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	3600 MG/L	

Sample Collected: Chemical:	06/05/2002 00:00:00 CHLORIDE	Findings:	1400 MG/L
Sample Collected: Chemical:	06/05/2002 00:00:00 MANGANESE	Findings:	160 UG/L
Sample Collected: Chemical:	06/05/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	3500 MG/L
Sample Collected: Chemical:	07/03/2002 00:00:00 CHLORIDE	Findings:	1600 MG/L
Sample Collected: Chemical:	07/03/2002 00:00:00 MANGANESE	Findings:	180 UG/L
Sample Collected: Chemical:	07/03/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	3500 MG/L
Sample Collected: Chemical:	08/01/2002 00:00:00 ARSENIC	Findings:	4 UG/L
Sample Collected: Chemical:	09/04/2002 00:00:00 CHLORIDE	Findings:	1400 MG/L
Sample Collected: Chemical:	09/04/2002 00:00:00 MANGANESE	Findings:	200 UG/L
Sample Collected: Chemical:	09/04/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	3400 MG/L
Sample Collected: Chemical:	10/02/2002 00:00:00 CHLORIDE	Findings:	1400 MG/L
Sample Collected: Chemical:	10/02/2002 00:00:00 MANGANESE	Findings:	180 UG/L
Sample Collected: Chemical:	10/02/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	3200 MG/L
Sample Collected: Chemical:	10/22/2002 00:00:00 ARSENIC	Findings:	6 UG/L
Sample Collected: Chemical:	11/06/2002 00:00:00 CHLORIDE	Findings:	1400 MG/L
Sample Collected: Chemical:	11/06/2002 00:00:00 MANGANESE	Findings:	200 UG/L
Sample Collected: Chemical:	11/06/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	3200 MG/L
Sample Collected: Chemical:	12/04/2002 00:00:00 CHLORIDE	Findings:	1300 MG/L
Sample Collected: Chemical:	12/04/2002 00:00:00 MANGANESE	Findings:	130 UG/L
Sample Collected: Chemical:	12/04/2002 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	3300 MG/L
Sample Collected: Chemical:	01/02/2003 00:00:00 CHLORIDE	Findings:	1300 MG/L
Sample Collected: Chemical:	01/02/2003 00:00:00 MANGANESE	Findings:	150 UG/L
Sample Collected: Chemical:	01/02/2003 00:00:00 TOTAL DISSOLVED SOLIDS	Findings:	3300 MG/L

Map ID				
Direction Distance Elevation			Database	EDR ID Number
10				
NNW 1/2 - 1 Mile			FED USGS	USGS3156794
Higher				
Agency cd:	USGS	Site no:	335210118195901	
Site name:	003S014W34B002S			
Latitude:	335210			
Longitude:	1181959	Dec lat:	33.86945984	
Dec lon:	-118.33396257	Coor meth:	M	
Coor accr:	S	Latlong datum:	NAD27	
Dec latlong datum:	NAD83	District:	06	
State:	06	County:	037	
Country:	US	Land net:	Not Reported	
Location map: Altitude:	TORRANCE	Map scale:	24000	
Altitude method:	Not Reported			
Altitude accuracy:	Not Reported Not Reported			
Altitude datum:	Not Reported			
Hydrologic:	Santa Monica Bay. California. Ar	ea = 575 sg.mi.		
Topographic:	Not Reported			
Site type:	Ground-water other than Spring	Date construction:	Not Reported	
Date inventoried:	Not Reported	Mean greenwich time offset:	PST	
Local standard time flag:	Y	-		
Type of ground water site:	Single well, other than collector c	or Ranney type		
Aquifer Type:	Not Reported			
Aquifer:	Not Reported			
Well depth:	337	Hole depth:	485	
Source of depth data:	Not Reported			
Project number:	9479335800			
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported	
Daily flow data end date:	Not Reported	Daily flow data count: Peak flow data end date:	Not Reported	
Peak flow data begin date: Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported	
Water quality data end date	•	Water quality data count:	Not Reported	
Ground water data begin da	•	Ground water data end date:	Not Reported	
Ground water data count:			Not Reported	
Ground-water levels, Numb	er of Measurements: 0			
11				
SW			FED USGS	USGS3156749
1/2 - 1 Mile Higher				
Agency cd:	USGS	Site no:	335104118201701	
Site name:	004S014W03L003S			
Latitude:	335104			
Longitude:	1182017	Dec lat:	33.85112675	
Dec Ion:	-118.3389624	Coor meth:	Μ	
Coor accr:	S	Latlong datum:	NAD27	
Dec latlong datum:	NAD83	District:	06	
State:	06	County:	037	
Country:	US	Land net:	Not Reported	
Location map:	TORRANCE	Map scale:	24000	

Altitude:	Not Reported		
Altitude method:	Not Reported		
Altitude accuracy:	Not Reported		
Altitude datum:	Not Reported		
Hydrologic:	Santa Monica Bay. California. Ar	ea = 575 sq.mi.	
Topographic:	Not Reported		
Site type:	Ground-water other than Spring	Date construction:	Not Reported
Date inventoried:	Not Reported	Mean greenwich time offset:	PST
Local standard time flag:	Y		
Type of ground water site:	Single well, other than collector c	or Ranney type	
Aquifer Type:	Not Reported		
Aquifer:	Not Reported		
Well depth:	450	Hole depth:	450
Source of depth data:	Not Reported		
Project number:	9479335800		
Real time data flag:	Not Reported	Daily flow data begin date:	Not Reported
Daily flow data end date:	Not Reported	Daily flow data count:	Not Reported
Peak flow data begin date:	Not Reported	Peak flow data end date:	Not Reported
Peak flow data count:	Not Reported	Water quality data begin date:	Not Reported
Water quality data end date	Not Reported	Water quality data count:	Not Reported
Ground water data begin da	ate: Not Reported	Ground water data end date:	Not Reported
Ground water data count:	Not Reported		

Ground-water levels, Number of Measurements: 0

## Direction

Distance

Database EDR ID Number

#### NNE 1/2 - 1 Mile OIL\_GAS CA200000017120 Apinumber: 03705615 Operator: Marathon Oil Co. Lease: R. H. Fish Well no: 1 LOS ANGELES COUNTY Not Reported Field: Area: Map: 126 006 Status cod: Source: hud Latitude: 33.867816 Longitude: -118.322074 Td: 7418 35 Sec: 3S 14W Twn: Rge: Bm: SB 0 X coord: Y coord: 0 12/12/1968 00:00:00 Zone: Not Reported Spuddate: Abanddate: 12/30/1899 00:00:00 Comments: Not Reported District: 1 Site id: CA200000017120

#### NNE 1/4 - 1/2 Mile

#### OIL\_GAS CA200000016924 Apinumber: 03706012 Operator: L. F. Stephenson Lease: Not Reported Well no: 1 LOS ANGELES COUNTY Field: Area: Not Reported 126 Status cod: 006 Map: Source: hud Latitude: 33.864945 Longitude: -118.321904 600 Td: Sec: 35 3S 14W Twn: Rge: Bm: SB X coord: 0 0 Y coord: 12/12/1968 00:00:00 Not Reported Spuddate: Zone: 12/30/1899 00:00:00 Comments: Not Reported Abanddate: District: Site id: CA200000016924 1

#### NE 1/4 - 1/2 Mile

Apinumber: Lease: Field: Map: Source: Latitude: Longitude: Td:	03705513 Mcdowell Community LOS ANGELES COUNTY 126 hud 33.862852 -118.321995 7209	Operator: Well no: Area: Status cod:	Imperial Gypsum & Oil Corp. 1 Not Reported 006
Sec: Twn:	35 3S	Rge:	14W

OIL GAS

CA200000016843

Bm: X coord: Y coord: Zone: Abanddate: District:	SB 0 0 Not Reported 12/30/1899 00:00:00 1	Spuddate: Comments: Site id:	12/12/1968 00:00:00 Not Reported CA2000000016843	
WNW 1/2 - 1 Mile			OIL_GAS	CA2000000016837
Apinumber:	03706090	Operator:	Chevron U.S.A. Inc.	
Lease:		Well no:	1	
Field:	LOS ANGELES COUNTY	Area:	Not Reported	
Map:	126	Status cod:	006	
Source: Latitude:	hud			
	33.862697 -118.333024			
Longitude: Td:	5251			
Sec:	34			
Twn:	35	Rge:	14W	
Bm:	SB	rigo.	1-7.00	
X coord:	0			
Y coord:	õ			
Zone:	Not Reported	Spuddate:	12/12/1968 00:00:00	
Abanddate:	12/30/1899 00:00:00	Comments:	Not Reported	
District:	1	Site id:	CA200000016837	

# ENE 1/2 - 1 Mile

Apinumber:	03705809	Operator:	Barnett Rosenburg
Lease:	Not Reported	Well no:	2
Field:	LOS ANGELES COUNTY	Area:	Not Reported
Map:	126	Status cod:	006
Source:	hud		
Latitude:	33.862458		
Longitude:	-118.310036		
Td:	4184		
Sec:	35		
Twn:	3S	Rge:	14W
Bm:	SB		
X coord:	0		
Y coord:	0		
Zone:	Not Reported	Spuddate:	12/12/1968 00:00:00
Abanddate:	12/30/1899 00:00:00	Comments:	Not Reported
District:	1	Site id:	CA200000016826

OIL\_GAS CA200000016798

OIL\_GAS CA200000016826

Apinumber: Lease: Field: Map: Source: Latitude: Longitude: Td: Soci	03705808 Not Reported LOS ANGELES COUNTY 126 hud 33.861351 -118.309943 3505	Operator: Well no: Area: Status cod:	Barnett Rosenburg 1 Not Reported 006
Sec: Twn: Bm:	35 3S SB	Rge:	14W
X coord: Y coord: Zone: Abanddate: District:	0 0 Not Reported 12/30/1899 00:00:00 1	Spuddate: Comments: Site id:	12/12/1968 00:00:00 Not Reported CA2000000016798

## ESE 1/2 - 1 Mile

Apinumber:	03705279	Operator:	Chevron U.S.A. Inc.	
Lease:	Francis	Well no:	1	
Field:	LOS ANGELES COUNTY	Area:	Not Reported	
Map:	126	Status cod:	006	
Source:	hud			
Latitude:	33.854132			
Longitude:	-118.309554			
Td:	6536			
Sec:	2			
Twn:	4S	Rge:	14W	
Bm:	SB	C		
X coord:	0			
Y coord:	0			
Zone:	Not Reported	Spuddate:	12/12/1968 00:00:00	
Abanddate:	12/30/1899 00:00:00	Comments:	Not Reported	
District:	1	Site id:	CA200000016667	

SSW 1/4 - 1/2 Mile

Apinumber:	03706329	Operator:	Chevron U.S.A. Inc.
Lease:	North Torrance Corehole	Well no:	1
Field:	LOS ANGELES COUNTY	Area:	Not Reported
Map:	126	Status cod:	006
Source:	hud		
Latitude:	33.853629		
Longitude:	-118.326752		
Td:	7005		
Sec:	3		
Twn:	4S	Rge:	14W

OIL\_GAS

OIL\_GAS

CA200000016667

CA200000016659

Bm: X coord: Y coord: Zone: Abanddate: District:

SB Not Reported 12/30/1899 00:00:00

0 0

1

Spuddate: Comments: Site id:

12/12/1968 00:00:00 Not Reported CA200000016659

OIL\_GAS

CA200000016621

# SE 1/2 - 1 Mile

Apinumber: Lease: Field: Map: Source: Latitude: Longitude: Td:	03705358 Fee LOS ANGELES COUNTY 126 hud 33.850265 -118.314248 7168	Operator: Well no: Area: Status cod:	Dominguez Estate Co. 1 Not Reported 006
Sec: Twn: Bm: X coord: Y coord: Zone: Abanddate: District:	2 4S SB 0 0 Not Reported 12/30/1899 00:00:00 1	Rge: Spuddate: Comments: Site id:	14W 12/12/1968 00:00:00 Not Reported CA2000000016621

## AREA RADON INFORMATION

## State Database: CA Radon

Radon Test Results

Zip	Total Sites	> 4 Pci/L	Pct. > 4 Pci/L
90504	6	0	0.00

Federal EPA Radon Zone for LOS ANGELES County: 2

Note: Zone 1 indoor average level > 4 pCi/L.

: Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L. : Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for Zip Code: 90504

Number of sites tested: 2

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area - 1st Floor	1.850 pCi/L	100%	0%	0%
Living Area - 2nd Floor	Not Reported	Not Reported	Not Reported	Not Reported
Basement	Not Reported	Not Reported	Not Reported	Not Reported

## **TOPOGRAPHIC INFORMATION**

## USGS 7.5' Digital Elevation Model (DEM)

Source: United States Geologic Survey

EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

## Scanned Digital USGS 7.5' Topographic Map (DRG)

Source: United States Geologic Survey

A digital raster graphic (DRG) is a scanned image of a U.S. Geological Survey topographic map. The map images are made by scanning published paper maps on high-resolution scanners. The raster image is georeferenced and fit to the Universal Transverse Mercator (UTM) projection.

### HYDROLOGIC INFORMATION

**Flood Zone Data:** This data, available in select counties across the country, was obtained by EDR in 1999 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

**NWI:** National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002 and 2005 from the U.S. Fish and Wildlife Service.

## HYDROGEOLOGIC INFORMATION

## AQUIFLOW<sup>R</sup> Information System

Source: EDR proprietary database of groundwater flow information

EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

## **GEOLOGIC INFORMATION**

### Geologic Age and Rock Stratigraphic Unit

Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

## **STATSGO:** State Soil Geographic Database

Source: Department of Agriculture, Natural Resources Conservation Services

The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

## SSURGO: Soil Survey Geographic Database

Source: Department of Agriculture, Natural Resources Conservation Services (NRCS) Telephone: 800-672-5559

SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Services, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

## LOCAL / REGIONAL WATER AGENCY RECORDS

## FEDERAL WATER WELLS

## PWS: Public Water Systems

Source: EPA/Office of Drinking Water

Telephone: 202-564-3750

Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data

Source: EPA/Office of Drinking Water

Telephone: 202-564-3750

Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

### USGS Water Wells: USGS National Water Inventory System (NWIS)

This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

## STATE RECORDS

## Water Well Database

Source: Department of Water Resources Telephone: 916-651-9648

## California Drinking Water Quality Database

Source: Department of Health Services

Telephone: 916-324-2319

The database includes all drinking water compliance and special studies monitoring for the state of California since 1984. It consists of over 3,200,000 individual analyses along with well and water system information.

### OTHER STATE DATABASE INFORMATION

### **California Oil and Gas Well Locations**

Source: Department of Conservation Telephone: 916-323-1779

## RADON

## State Database: CA Radon

Source: Department of Health Services Telephone: 916-324-2208 Radon Database for California

## Area Radon Information

Source: USGS Telephone: 703-356-4020 The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

## **EPA Radon Zones**

Source: EPA Telephone: 703-356-4020 Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

# PHYSICAL SETTING SOURCE RECORDS SEARCHED

## OTHER

Airport Landing Facilities: Private and public use landing facilities Source: Federal Aviation Administration, 800-457-6656

**Epicenters:** World earthquake epicenters, Richter 5 or greater Source: Department of Commerce, National Oceanic and Atmospheric Administration

**California Earthquake Fault Lines:** The fault lines displayed on EDR's Topographic map are digitized quaternary fault lines, prepared in 1975 by the United State Geological Survey. Additional information (also from 1975) regarding activity at specific fault lines comes from California's Preliminary Fault Activity Map prepared by the California Division of Mines and Geology.

## STREET AND ADDRESS INFORMATION

© 2007 Tele Atlas North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

APPENDIX C

#### HISTORICAL DOCUMENTATION

# The EDR Aerial Photo Decade Package

Parking Lot (Lot 25) 2500 Block W. 190th Street Torrance, CA 90504

Inquiry Number: 2051883.5

October 15, 2007

# The Standard in Environmental Risk Information

**EDR**<sup>®</sup> Environmental

Data Resources Inc

440 Wheelers Farms Road Milford, Connecticut 06461

## **Nationwide Customer Service**

Telephone:1-Fax:1-Internet:w

1-800-352-0050 1-800-231-6802 www.edrnet.com

## **EDR Aerial Photo Decade Package**

Environmental Data Resources, Inc. (EDR) Aerial Photo Decade Package is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDRs professional researchers provide digitally reproduced historical aerial photographs, and when available, provide one photo per decade.

When delivered electronically by EDR, the aerial photo images included with this report are for ONE TIME USE ONLY. Further reproduction of these aerial photo images is prohibited without permission from EDR. For more information contact your EDR Account Executive.

*Thank you for your business.* Please contact EDR at 1-800-352-0050 with any questions or comments.

#### **Disclaimer - Copyright and Trademark Notice**

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report AS IS. Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2007 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

#### **Date EDR Searched Historical Sources:**

Aerial Photography October 15, 2007


#### **Target Property:**

2500 Block W. 190th Street Torrance, CA 90504

<u>Year</u>	<u>Scale</u>	<u>Details</u>	<u>Source</u>
1928	Aerial Photograph. Scale: 1"=500'	Flight Year: 1928	Fairchild
1938	Aerial Photograph. Scale: 1"=555'	Flight Year: 1938	Laval
1947	Aerial Photograph. Scale: 1"=666'	Flight Year: 1947	Fairchild
1956	Aerial Photograph. Scale: 1"=400'	Flight Year: 1956	Fairchild
1965	Aerial Photograph. Scale: 1"=666'	Flight Year: 1965	Fairchild
1976	Aerial Photograph. Scale: 1"=666'	Flight Year: 1976	Teledyne
1990	Aerial Photograph. Scale: 1"=666'	Flight Year: 1990	USGS
1994	Aerial Photograph. Scale: 1"=666'	Flight Year: 1994	USGS
2002	Aerial Photograph. Scale: 1"=666'	Flight Year: 2002	USGS
























# **Certified Sanborn® Map Report**



Sanborn® Library search results Certification # 4DF5-4F50-AEAC

Parking Lot (Lot 25) 2500 Block W. 190th Street Torrance, CA 90504

Inquiry Number 2051883.3

October 15, 2007

# The Standard in Environmental Risk Information

440 Wheelers Farms Rd Milford, Connecticut 06461

Nationwide Customer Service

 Telephone:
 1-800-352-0050

 Fax:
 1-800-231-6802

 Internet:
 www.edrnet.com

### **Certified Sanborn® Map Report**

#### Site Name:

Parking Lot (Lot 25) 2500 Block W. 190th Street Torrance, CA 90504

EDR Inquiry # 2051883.3

#### **Client Name:** Golder Associates, Inc. 230 Commerce Irvine, CA 92602

Contact: Misty Vazquez

EDR° Environmental Data Resources Inc

The complete Sanborn Library collection has been searched by EDR, and fire insurance maps covering the target property location provided by Golder Associates, Inc. were identified for the years listed below. The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by Sanborn Library LLC, the copyright holder for the collection.

#### Certified Sanborn Results:

Site Name:	Parking Lot (Lot 25)
Address:	2500 Block W. 190th Street
City, State, Zip:	Torrance, CA 90504
Cross Street:	
P.O. #	073-91953
Project:	073-91953
Certification #	4DF5-4F50-AEAC

#### UNMAPPED PROPERTY

This report certifies that the complete holdings of the Sanborn Library, LLC collection have been searched based on client supplied target property information, and fire insurance maps covering the target property were not found.



Sanborn® Library search results Certification # 4DF5-4F50-AEAC

The Sanborn Library includes more than 1.2 million Sanborn fire insurance maps, which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

Library of Congress
 University Publications of America
 EDR Private Collection

Total Maps: 0

#### Limited Permission To Make Copies

Golder Associates, Inc. (the client) is permitted to make up to THREE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

#### **Disclaimer - Copyright and Trademark notice**

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2007 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

10/15/07



# EDR Historical Topographic Map Report

Parking Lot (Lot 25) 2500 Block W. 190th Street Torrance, CA 90504

Inquiry Number: 2051883.4

October 15, 2007

# The Standard in Environmental Risk Information

440 Wheelers Farms Rd Milford, Connecticut 06461

## **Nationwide Customer Service**

Telephone:1-Fax:1-Internet:w

1-800-352-0050 1-800-231-6802 www.edrnet.com

## **EDR Historical Topographic Map Report**

Environmental Data Resources, Inc.s (EDR) Historical Topographic Map Report is designed to assist professionals in evaluating potential liability on a target property resulting from past activities. EDRs Historical Topographic Map Report includes a search of a collection of public and private color historical topographic maps, dating back to the early 1900s.


*Thank you for your business.* Please contact EDR at 1-800-352-0050 with any questions or comments.

#### **Disclaimer - Copyright and Trademark Notice**


This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report AS IS. Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2007 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.


EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.



N 🛧	TARGET QU NAME: MAP YEAR:	REDONDO	ADDRESS:	Parking Lot (Lot 25) 2500 Block W. 190th Street Torrance, CA 90504 33.8593 / 118.3259	CLIENT: CONTACT: INQUIRY#: RESEARCH	Golder Associates, Inc. Misty Vazquez 2051883.4 DATE: 10/15/2007
Ι	SERIES: SCALE:	15 1:62500	LAT/LONG.	33.63937 116.3239	RESEARCH	DATE. 10/15/2007




	TARGET QUAD NAME: SOUTHERN CA SHEET 1 MAP YEAR: 1901 SERIES: 60 SCALE: 1:250000	SITE NAME: ADDRESS: LAT/LONG:	Parking Lot (Lot 25) 2500 Block W. 190th Street Torrance, CA 90504 33.8593 / 118.3259	CLIENT: CONTACT: INQUIRY#: RESEARCH	Golder Associates, Inc. Misty Vazquez 2051883.4 DATE: 10/15/2007
--	---	-------------------------------------	--	--	---



NAME: TORRANCE MAP YEAR: 1924 SERIES: 6

SERIES: 6 SCALE: 1:24000 SITE NAME: Parking Lot (Lot 25) ADDRESS: 2500 Block W. 190th Street Torrance, CA 90504 LAT/LONG: 33.8593 / 118.3259

CLIENT: Golder Associates, Inc. CONTACT: Misty Vazquez INQUIRY#: 2051883.4 RESEARCH DATE: 10/15/2007




TARGET QUAD NAME: TORRANCE MAP YEAR: 1934 SERIES: 6

SCALE:


Ν

6 1:24000 SITE NAME: Parking Lot (Lot 25) ADDRESS: 2500 Block W. 190th Street Torrance, CA 90504 LAT/LONG: 33.8593 / 118.3259

CLIENT:Golder Associates, Inc.CONTACT:Misty VazquezINQUIRY#:2051883.4RESEARCH DATE:10/15/2007




z 🔶	TARGET QU NAME: MAP YEAR: SERIES: SCALE:	REDONDO	SITE NAME: ADDRESS: LAT/LONG:	Parking Lot (Lot 25) 2500 Block W. 190th Street Torrance, CA 90504 33.8593 / 118.3259	CLIENT: CONTACT: INQUIRY#: RESEARCH	Golder Associates, Inc. Misty Vazquez 2051883.4 DATE: 10/15/2007
	SCALE:	1:50000				



	TARGET QU	IAD	SITE NAME:	Parking Lot (Lot 25)	CLIENT:	Go
N ▲	NAME:	LONGBEACH VICINITY 30F3	ADDRESS:	2500 Block W. 190th Street Torrance, CA 90504	CONTACT: INQUIRY#:	Mis 20
	MAP YEAR:	1951	LAT/LONG:	33.8593 / 118.3259	RESEARCH	
	SERIES: SCALE:	7.5 1:24000				

LIENT: Golder Associates, Inc. ONTACT: Misty Vazquez IQUIRY#: 2051883.4 ESEARCH DATE: 10/15/2007




TARGET QUAD NAME: TORRANCE MAP YEAR: 1951 SERIES: 7.5

Ν

SCALE: 1:24000 ADDRESS: LAT/LONG:

SITE NAME: Parking Lot (Lot 25) 2500 Block W. 190th Street Torrance, CA 90504 33.8593 / 118.3259

CLIENT: Golder Associates, Inc. CONTACT: Misty Vazquez INQUIRY#: 2051883.4 **RESEARCH DATE: 10/15/2007** 



TARGET QUAD NAME: TORRANCE MAP YEAR: 1964 SERIES:


Ν

SCALE:

7.5 1:24000

SITE NAME: Parking Lot (Lot 25) ADDRESS: 2500 Block W. 190th Street Torrance, CA 90504 LAT/LONG: 33.8593 / 118.3259

CLIENT: Golder Associates, Inc. CONTACT: Misty Vazquez INQUIRY#: 2051883.4 **RESEARCH DATE: 10/15/2007** 




TARGET QUAD NAME: TORRANCE MAP YEAR: 1972 PHOTOREVISED FROM:1964 SERIES: 7.5 SCALE: 1:24000

Ν

SITE NAME: Parking Lot (Lot 25) ADDRESS: 2500 Block W. 190th Street Torrance, CA 90504 LAT/LONG: 33.8593 / 118.3259

CLIENT: Golder Associates, Inc. CONTACT: Misty Vazquez INQUIRY#: 2051883.4 RESEARCH DATE: 10/15/2007



TARGET QUAD NAME: TORRANCE MAP YEAR: 1981 PHOTOREVISED FROM:1964 SERIES: 7.5 SCALE: 1:24000

Ν

SITE NAME: Parking Lot (Lot 25) ADDRESS: 2500 Block W. 190th Street Torrance, CA 90504 LAT/LONG: 33.8593 / 118.3259

CLIENT: Golder Associates, Inc. CONTACT: Misty Vazquez INQUIRY#: 2051883.4 RESEARCH DATE: 10/15/2007



# The EDR-City Directory Abstract

Parking Lot (Lot 25) 2500 Block W. 190th Street Torrance, CA 90504

Inquiry Number: 2051883.6

Monday, October 15, 2007

# The Standard in Environmental Risk Information

440 Wheelers Farms Road Milford, Connecticut 06461

## Nationwide Customer Service

 Telephone:
 1-800-352-0050

 Fax:
 1-800-231-6802

 Internet:
 www.edrnet.com

## **EDR City Directory Abstract**

Environmental Data Resources, Inc.'s (EDR) City Directory Abstract is a screening report designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Abstract includes a search and abstract of available city directory data. For each address, the directory lists the name of the corresponding occupant at five year intervals.

> *Thank you for your business.* Please contact EDR at 1-800-352-0050 with any questions or comments.

#### **Disclaimer - Copyright and Trademark Notice**

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provide in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as provided in this Report are provided for illustrative purposes only, and are environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2007 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

#### SUMMARY

#### • City Directories:

Business directories including city, cross reference and telephone directories were reviewed, if available, at approximately five year intervals for the years spanning 1920 through 2006. (These years are not necessarily inclusive.) A summary of the information obtained is provided in the text of this report.

This report compiles information by geocoding the subject properties (that is, plotting the latitude and longitude for such subject properties and obtaining data concerning properties within 1/8th of a mile of the subject properties). There is no warranty or guarantee that geocoding will report or list all properties within the specified radius of the subject properties and any such warranty or guarantee is expressly disclaimed. Accordingly, some properties within the aforementioned radius and the information concerning those properties may not be referenced in this report.

Date EDR Searched Historical Sources: October 15, 2007

Target Property:

2500 Block W. 190th Street Torrance, CA 90504

<u>Year</u>	<u>Uses</u>	Source
1920	Address Not Listed in Research Source	Los Angeles Directory Co.
1921	Address Not Listed in Research Source	Los Angeles Directory Co.
1923	Address Not Listed in Research Source	Los Angeles Directory Co.
1924	Address Not Listed in Research Source	Los Angeles Directory Co.
1925	Address Not Listed in Research Source	Los Angeles Directory Co.
1926	Address Not Listed in Research Source	Los Angeles Directory Co.
1927	Address Not Listed in Research Source	Kaasen Directory Company Publishers
1928	Address Not Listed in Research Source	Los Angeles Directory Co.
1929	Address Not Listed in Research Source	Los Angeles Directory Co.
1930	Address Not Listed in Research Source	Los Angeles Directory Co.
1931	Address Not Listed in Research Source	Los Angeles Directory Company Publishers
1932	Address Not Listed in Research Source	Los Angeles Directory Co.
1933	Address Not Listed in Research Source	Los Angeles Directory Co.
1934	Address Not Listed in Research Source	Los Angeles Directory Co.
1935	Address Not Listed in Research Source	Los Angeles Directory Co.
1936	Address Not Listed in Research Source	Los Angeles Directory Co.

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1937	Address Not Listed in Research Source	Los Angeles Directory Co.
1938	Address Not Listed in Research Source	Los Angeles Directory Company Publishers
1939	Address Not Listed in Research Source	Los Angeles Directory Co.
1940	Address Not Listed in Research Source	Los Angeles Directory Co.
1942	Address Not Listed in Research Source	Los Angeles Directory Co.
1944	Address Not Listed in Research Source	R. L. Polk & Co.
1945	Address Not Listed in Research Source	R. L. Polk & Co.
1946	Address Not Listed in Research Source	Los Angeles Directory Co.
1947	Address Not Listed in Research Source	Pacific Directory Co.
1948	Address Not Listed in Research Source	Los Angeles Directory Co.
1949	Address Not Listed in Research Source	Los Angeles Directory Co.
1950	Address Not Listed in Research Source	Pacific Telephone
1951	Address Not Listed in Research Source	Los Angeles Directory Co Publishers
1952	Address Not Listed in Research Source	Los Angeles Directory Co.
1954	Address Not Listed in Research Source	R. L. Polk & Co.
1955	Address Not Listed in Research Source	R. L. Polk & Co.
1956	Address Not Listed in Research Source	Pacific Telephone
1957	Address Not Listed in Research Source	Pacific Telephone
1958	Address Not Listed in Research Source	Pacific Telephone
1960	Address Not Listed in Research Source	Pacific Telephone

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1961	Address Not Listed in Research Source	Luskey Brothers & Co
1962	Address Not Listed in Research Source	Pacific Telephone
1963	Address Not Listed in Research Source	Pacific Telephone
1964	Address Not Listed in Research Source	Pacific Telephone
1965	Address Not Listed in Research Source	GTE
1966	Address Not Listed in Research Source	Pacific Telephone
1967	Address Not Listed in Research Source	R. L. Polk & Co.
1969	Address Not Listed in Research Source	Pacific Telephone
1970	Address Not Listed in Research Source	R. L. Polk & Co.
1971	Address Not Listed in Research Source	B&G Publications
1972	Address Not Listed in Research Source	R. L. Polk & Co.
1975	Address Not Listed in Research Source	Pacific Telephone
1976	Address Not Listed in Research Source	R.L. Polk & co Publishers
1980	Address Not Listed in Research Source	Pacific Telephone
1981	Address Not Listed in Research Source	Pacific Telephone
1985	Address Not Listed in Research Source	Pacific Bell
1986	Address Not Listed in Research Source	Pacific Bell
1990	Address Not Listed in Research Source	Pacific Bell
1991	Address Not Listed in Research Source	Pacific Bell
1995	Address Not Listed in Research Source	Pacific Bell Telephone

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1996	Address Not Listed in Research Source	GTE
1999	Address Not Listed in Research Source	Haines Company
2000	Address Not Listed in Research Source	Pacific Bell Telephone
2001	Address Not Listed in Research Source	Haines & Company, Inc.
2003	Address Not Listed in Research Source	Haines & Company
2004	Address Not Listed in Research Source	Haines Company
2006	Address Not Listed in Research Source	Haines Company

## **Adjoining Properties**

#### SURROUNDING

Multiple Addresses Torrance, CA 90504

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1920	Address Not Listed in Research Source	Los Angeles Directory Co.
1921	Address Not Listed in Research Source	Los Angeles Directory Co.
1923	Address Not Listed in Research Source	Los Angeles Directory Co.
1924	Address Not Listed in Research Source	Los Angeles Directory Co.
1925	Address Not Listed in Research Source	Los Angeles Directory Co.
1926	Address Not Listed in Research Source	Los Angeles Directory Co.
1927	Address Not Listed in Research Source	Kaasen Directory Company Publishers
1928	Address Not Listed in Research Source	Los Angeles Directory Co.
1929	Address Not Listed in Research Source	Los Angeles Directory Co.
1930	Address Not Listed in Research Source	Los Angeles Directory Co.

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1931	Address Not Listed in Research Source	Los Angeles Directory Company Publishers
1932	Address Not Listed in Research Source	Los Angeles Directory Co.
1933	Address Not Listed in Research Source	Los Angeles Directory Co.
1934	Address Not Listed in Research Source	Los Angeles Directory Co.
1935	Address Not Listed in Research Source	Los Angeles Directory Co.
1936	Address Not Listed in Research Source	Los Angeles Directory Co.
1937	Address Not Listed in Research Source	Los Angeles Directory Co.
1938	Address Not Listed in Research Source	Los Angeles Directory Company Publishers
1939	Address Not Listed in Research Source	Los Angeles Directory Co.
1940	Address Not Listed in Research Source	Los Angeles Directory Co.
1942	Address Not Listed in Research Source	Los Angeles Directory Co.
1944	Address Not Listed in Research Source	R. L. Polk & Co.
1945	Address Not Listed in Research Source	R. L. Polk & Co.
1946	<u>**190TH ST**</u> 0 S OREENAN (2890)	Los Angeles Directory Co.
1947	Address Not Listed in Research Source	Pacific Directory Co.
1948	Address Not Listed in Research Source	Los Angeles Directory Co.
1949	Address Not Listed in Research Source	Los Angeles Directory Co.
1950	Address Not Listed in Research Source	Pacific Telephone
1951	Address Not Listed in Research Source	Los Angeles Directory Co Publishers
1952	Address Not Listed in Research Source	Los Angeles Directory Co.

<u>Year</u>	<u>Uses</u>		<u>Source</u>
1954	**S CRENSHAW BLVD**		R. L. Polk & Co.
	SAGE HELEN DARLENE (18909)		
	**W 187TH PL**		R. L. Polk & Co.
	WARD MELVIN R (3112)		
	ENGLAND C T (3113)		
	MCMULLIN LA VINA BLACK (3119)		
	BISHOP VIVIAN (3120)		
	KELLEY IDOS S (3122)		
	KINDER VERNON (3126)		
	BROOKES EARL E (3127) WEAVER J H (3131)		
	ESTRIVO E MOSES (3134)		
	**W 189TH ST**		R. L. Polk & Co.
	BLACKWELL ROY HOGAN (3205)		
	BLACKWELL ROY HOGAN (3205)		
	MYRE MARY M (3210)		
	BILLINGSLEY CHAS M (3215)		
	FRANKLIN J L (3216)		
	WILLIAMS LENA R (3219)		
	JACOBSEN C J (3223)		
	<u>**187TH PL**</u>		R. L. Polk & Co.
	JONES WALTER B (3123)		
	HEFFLER STEVE (3124)		
	LOGSDON MARY JO (3133)		R. L. Polk & Co.
			R. L. FUIK & CO.
	DOOLING C R (18703) U S MALL ORDER CO (18721)		
	MIDWAY MKTS (18727)		
	TONY S LIQUOR STORE (18825)		
	**CRENSHAW PL**		R. L. Polk & Co.
	BASKOVICH ANTE (18803)		
	DAVIS J G (18809)		
1955	Address Not Listed in Research Source		R. L. Polk & Co.
1956	Address Not Listed in Research Source		Pacific Telephone
1957	**S CRENSHAW BLVD**		Pacific Telephone
	SAGE HELEN DARLENE (18909)		
	<u>**W 187TH PL**</u>		Pacific Telephone
	WARD MELVIN R (3112)		
	ENGLAND C T (3113)		
		2051883-6	

### Year Uses

1957 (continued)

JONES MILFORD U (3115) EVESLAGE EUGENE D (3116) FOURNIER ALICE MRS (3118) **BUCHANAN PAUL (3119) GREEN CLAMON MRS (3119) BISHOP VIVIAN (3120) GUENGERICH DEL P (3120)** CLONTZ A E (3123) WESEVICH WM J (3123) KINDER VERNON (3126) CARPENTER LEONARD (3127) EDDY THEO R (3127) **BEISHONGS-HAN RACHAEL (3128)** EMIAW DONALD L (3128) JEFFERS STANLEY L (3130) MARR SHARON LA MOTTE (3133) DU RAE E HARRY (3134) ESTRIVO MOSES E (3134) LARSON JOHN E (3136) LUNDSTROM FRANK E (3140) ROBERTS ROBT J (3142)

#### \*\*W 189TH ST\*\*

BLACKWELL ROY HOGAN (3205) BILLINGSLEY CHAS M (3215) WILLIAMS LENA R (3219) SILLS M0-DAVI (3220) 4ACOBSEN C J (3223)

### \*\*W 190TH ST\*\*

NATALIE S PLACE BEER (2895)

### \*\*CRENSHAW DR\*\*

WILLIAMS NAT MRS (18709) BERTONI C E (18715) SHEPHERD M D REALTOR (18721) MIDWAY MKTS (18727) CRENSHAW BAPTIST CHURCH (18749) PAT S CAFE (18801) RASH R C (18803) WLLDBLOOD THEO (18903) MOHAWK SELF SERVSERVICE STATIONS (18910) TONY S LIQUOR STORE (18915)

1958 Address Not Listed in Research Source

Pacific Telephone

Pacific Telephone

Pacific Telephone

Pacific Telephone

### <u>Source</u>

<u>Year</u>	<u>Uses</u>
-------------	-------------

1960 **\*\*S CRENSHAW BLVD\*\*** 

HAMM W R (18809)

### \*\*W 187TH PL\*\*

TALLEY WM H (3110) OWEN BILLY J (3113) NEUBAUER DELBERT (3115) EVESLAGE EUGENE D (3116) GREEN MILDRED A (3119) **BISHOP VIVIAN (3120)** GUENGERICH DEL P (3120) SCHLOEDER ROBT W (3121) KAPPEN JAS D (3123) DE YOUNG ROBT J (3124) MCCUE RAYMOND G (3124) PATTON ROBT W (3126) EDDY THEO R (3127) EMLAW DONALD L (3128) SCHWARTZ ARTHUR J (3131) WOOD G R (3132) MARR SHARON LA MOTTE (3133) ESTRADA JUVENTINO (3134) LARSON JOHN E (3136) SIBLEY EDW J (3137) SCHIRMAN EVERETTE O (3141) ROBERTS ROBT J (3142) DAVIS GLADYS P TORRANCE (3146) DAVIS L J TORRANCE (3146) KAISER ROBT L (3150) MITCHELL EARL J (3154)

### \*\*W 189TH ST\*\*

KNIGHTEN JAS W (3209) BILLINGSLEY CHAS M (3215) FRESQUEZ LEON (3216) JACOBSEN C J (3223)

### \*\*187TH PL\*\*

JONES WALTER B (3123)

#### \*\*CRENSHAW DR\*\*

WILLIAMS NAT MRS (18709) JEFFERS STANLEY L (18715) RICHTER CHAS N (18721) MIDWAY MKTS (18727) VAN PATTEN FRANK JR (18737)

### <u>Source</u>

Pacific Telephone

Pacific Telephone

Pacific Telephone

Pacific Telephone

Pacific Telephone

<u>Year</u>	<u>Uses</u>		<u>Source</u>
1960 (0	continued)		
	CRENSHAW BAPTIST CHURCH (18749)		
	SAMPLES HENRY R REV (18749)		
	SAYRE NAOMI E (18815)		
	KEEN VINCENT BARBER SHOP (18825)		
	FITCH PAUL V FITCH REALTY (18901)		
	FITCH REALTY (18901)		
	STROUP RICHARD M (18903)		
	LONGACRE ED (18909)		
	LONGACRE RUTH MISS (18909)		
	MOHAWK SELF SERV SERVICE STATIO	NS (18910)	
	TONYS LIQUOR STORE (18915)		
1961	Address Not Listed in Research Source		Luskey Brothers & Co
1962	Address Not Listed in Research Source		Pacific Telephone
1963	Address Not Listed in Research Source		Pacific Telephone
1964	**S CRENSHAW BLVD**		Pacific Telephone
	FRIESTAD REALTY TORRANCE (18750)		
	<u>**W 109TH ST**</u>		Pacific Telephone
	ROSE ROBT M (3024)		
	<u>**W 187TH PL**</u>		Pacific Telephone
	TALLEY WM H TORRANCE (3110)		
	LUEDKE DUANE (3111)		
	OWEN BILLY J (3113)		
	SMITH J HOWARD (3115)		
	AYRES JACK D (3119)		
	BISHOP VIVIAN (3120)		
	GUENGERICH DEL P (3120)		
	LUGAR ALFRED L (3121)		
	ALDEN JOHN (3124)		
	RINCON ALFRED (3124)		
	PATTON ROBT W (3126)		
	EMLAW DONALD L (3128)		
	WOOD MARIE (3132)		
	GINEVAN RICHARD (3134)		
	GINEVAN TAMARA (3134)		
	LARSON JOHN E TORRANCE (3136)		
	SIBLEY EDW J TORRANCE (3137)		
	FRIED SIDNEY (3141)		
	ROBERTS ROBT J (3142)		
	DEFOE S H (3146)		
	( /	2051883-6	
		2051003-0	

<u>Year</u>	Uses	<u>Source</u>
1004 (0	STEWARD KENNETH A (3150)	
	MITCHELL EARL J (3154)	
	<u>**W 189TH ST**</u>	Pacific Telephone
	KNIGHTEN JAS W (3209)	
	POSEY RICHARD TORRANCE (3210)	
	STROUP RICHARD M (3210)	
	BILLINGSLEY CHAS M (3215)	
	FRESQUEZ LEON (3216)	
	DOYLE DON E (3220)	
	HOWELL DONALD T (3223)	
	<u>**187TH PL**</u>	Pacific Telephone
	JONES WALTER B (3123)	
	**CRENSHAW DR**	Pacific Telephone
	GENDRE RUSSEL (18703)	
	MIDWAY MKT (18727)	
	CRENSHAW BAPTIST CHURCH (18749)	
	HENDRICKS HAROLD W REV (18749)	
	YOUNG J W YOUNG PRODUCTS (18752)	
	YOUNG PRODUCTS (18752)	
	MOMS CHAR BROIL (18801)	
	KELLY GREG R (18815)	
	BROWN S BARBER SHOP (18825)	
	BAY HOMES REALTY (18901)	
	PELICAN (18905)	
	MOHAWK SELF SERV SERVICE STATIONS (18910)	
	TONY S LIQUOR STORE (18915)	
	**CRENSHAW PL**	Pacific Telephone
	LITERARY CORP OF AMERICA (18801)	
1965	Address Not Listed in Research Source	GTE
1966	Address Not Listed in Research Source	Pacific Telephone
1967	**CRENSHAW PL**	R. L. Polk & Co.
	LITERARY CORP OF AMERICA (18801)	
	ZAMIOCH ARCHER ATTY (18801)	
	BLACHFORD H L INC (18811)	
1969	Address Not Listed in Research Source	Pacific Telephone
1970	<u>**W 187TH PL**</u>	R. L. Polk & Co.
	TALLEY WM H (3110)	
	CARNEY WELLS (3111)	
	2051883-6 11	

### <u>Year</u><u>Uses</u>

1970 (continued)

KINGSMILL HOWARD (3111) PAXTON ROBT (3116) STEBBIN CHAS E (3119) **BISHOP VIVIAN (3120)** BUOSCIO RICHARD R (3123) RINCON ALFRED (3124) EMLAW DONALD L (3128) KLOPP KARIA (3131) BUCHMAN ANDREW C (3132) SHRYOCK JAS F (3133) **GREENBERG ALLEN R (3134)** ALLEN M C (3136) SIBLEY EDW J (3137) NIXT GARY E (3141) ROBERTS ROBT J (3142) **DEFOE S H (3146)** STEWARD KENNETH A (3150) **BEEDY DUANE (3154)** \*\*W 187TH ST\*\* JULIAN MARCEL J (3115) \*\*W 189TH ST\*\*

PREECE IRA D (3209) STROUP RICHARD M SR (3210) BILLINGSLEY CHAS M (3215) FRESQUEZ LEON (3216) ANDERSON JOE K (3220) OBUSZEWSKI EDW (3224) RIVERA PETE R (3227) LITTLETON DEEN (3232)

### \*\*W 190TH ST\*\*

PHILLIPS BIKE & MOWER SHOP (2899) DOLL HOUSE THE (3103) DOLL HOUSE THE (3103)

### \*\*187TH PL\*\*

JONES WALTER B (3123)

### \*\*CRENSHAW BLVD\*\*

ALLSTATE BAIL BOND AGCY (18750) PERSONS & GERMAN BAIL BONDS (18750)

### \*\*CRENSHAW PL\*\*

GENDRE RUSSEL (18703) CHARTER REAL ESTATE & INSURANCE (18721) DOT REALTY (18721)

### <u>Source</u>

R. L. Polk & Co.

### Year Uses

### 1970 (continued)

### <u>Source</u>

MIDWAY MKT (18727)

HARRIS LAWRENCE (18737)

CRENSHAW BAPTIST CHURCH (18749)

HENDRICKS HAROLD W REV (18749)

ISAACSON INS AGCY (18760)

ISAACSON JOHN A INSURANCE AGENCY (18760)

PATTON DEYOUNG ISAACSON INSURANCE AGENCY (18760)

COLOR DETAIL (18764)

STEWART JANE (18764)

DON RAMON BEAUTY SALON (18766)

DON RAMON BEAUTY SALON (18766)

BLUE CHIP PLUMBING & HEATING (18801)

BOULE INC (18801)

THOMAS EARL ATTY (18801)

SEHY NANCY (18803)

PHILLIPS LARRY (18809)

EDWARDS J H CLVII ENGNRS (18811)

EDWARDS J H CO (18811)

HOWCO CONSTRUCTION CO (18811)

SOUTH BAY UNDERGROUND CONSTRUCTION CO (18811)

TABER ELECTRIC CO (18811)

TABER ELECTRIC CO (18811)

CARPET INDUSTRIES (18814)

CAPPS JAS C (18815)

RAY S CUT-RITE BARBER SHOP (18825)

SEYMOUR REAL ESTATE (18901)

**PELICAN (18905)** 

LITTLE BAR NONE RANCH (18909)

MOHAWK SELF SERV SERVICE STATIONS (18910)

CORNER LIQUOR STORE (18915)

### 1971 **\*\*CRENSHAW BLVD\*\***

**B&G** Publications

PATTON DE YOUNG ISAACSON INSURANCE AGENCY (18760) COLOR DETAIL (18764) STEWART JANE (18764) CUTLASS ELECTRONICS (18811) EDWARDS J H CO (18811)

### \*\*CRENSHAW PL\*\*

THOMAS EARL ATTY (18801) ZAMLOCH ARCHER ATTY (18801) CONSTRUCTION INTEGRITY TESTING (18811) MONTOUR PROPERTIES (18811)

### \*\*CRENSHAW TER\*\*

**B&G** Publications

**B&G** Publications

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1971 (c	xontinued) SEYMOUR REAL ESTATE (18901)	
1972	Address Not Listed in Research Source	R. L. Polk & Co.
1975	**W 187TH PL**	Pacific Telephone
	PAXTON ROBT (3116)	
	FORD J MICHAEL (3119)	
	BISHOP VIVIAN (3120)	
	GUENGERICH DEL P (3120)	
	JONES WALTER B (3123)	
	COFFER CALVIN (3124)	
	EMLAW DONALD L (3128)	
	MARTY GERALD (3132)	
	NIXT GARY E (3141)	
	GOMEZ ALFRED P A (3146)	
	BEEDY DUANE (3154)	
	**W 189TH ST**	Pacific Telephone
	HINOJOSA CHRIS (3209)	
	PASLOSKY PAUL J JR (3215)	
	FRESQUEZ LEON (3216)	
	FRESQUEZ LEON H (3216)	
	CRAWLEY ANTHONY (3220)	
	**CRENSHAW BLVD**	Pacific Telephone
	FULTS KURT (18703)	
	MONTGOMERY JOE (18715)	
	KANE WEST DISTRIBUTORS (18720)	
	MIDWAY MKT (18727)	
	DALLAS CERAMIC CO (18740)	
	CRENSHAW BAPTIST CHURCH (18749)	
	ALLSTATE BAIL BONDS (18750)	
	PERSONS & GORMAN BALL BONDS (18750)	
	ISAACSON INS AGCY (18760)	
	ISAACSON JOHN A INSURANCE AGENCY (18760)	
	PATTON-DE YOUNG INSURANCE (18760)	
	PATTON-DE YOUNG-ISAACSON INSURANCE AGENCY (18760)	
	COLOR DETAIL (18764)	
	OTTO JON & ASSOCIATES (18766)	
	CAL-FED MORTGAGE CO (18809)	
	BANNER CARPETS & DRAPES (18814)	
	AMES D M (18815)	
	DICKSON ROBT G (18821)	
	DICKSON S THEATRICAL MAKE-UP & SUPPLIES (18825)	
	CRENSHAW CHILDREN S CENTER (18909)	

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1975 (	continued) MOHAWK SELF SERVICE STNS (18910)	
	CORNER LIQUOR STORE (18915)	
	**CRENSHAW PL**	Pacific Telephone
	DE WITT LOUIS ATTY (18801)	
	ELLIOTT PROPERTY MANAGEMENT (18801)	
	EDWARDS J H COMPANY (18811)	
	HOWCO CONSTRUCTION CO (18811)	
	LOWELL CONSTRUCTION GENL ENGINEERING CONTRACTOR (18811)	
	PELICAN (18905)	
1976	<u>**W 190TH ST**</u>	R.L. Polk & co Publishers
	TORRANCE (3109)	
	**CRENSHAW BLVD**	R.L. Polk & co Publishers
	PATTON DE YOUNG ISAACSON INSURANCE AGENCY (18760)	
	COLOR DETAIL (18764)	
	STEWART JANE (18764)	
	CAL FED MORTGAGE CO (18809)	
	SEYMOUR REAL ESTATE (18901)	
	**CRENSHAW PL**	R.L. Polk & co Publishers
	DE WITT LOUIS ATTY (18801)	
	ZAMLOCH ARCHER ATTY (18801)	
	EDWARDS J H CO (18811)	
1980	**CRENSHAW BLVD**	Pacific Telephone
	GARRETT CORPORATION THE DIVISIONS (18700)	
	GARRETT CORPORATION THE DIVISIONS (18700)	
	<u>**W 187TH PL**</u>	Pacific Telephone
	MONTANDON S L (3115)	
	PAXTON ROBT (3116)	
	BISHOP VIVIAN (3120)	
	PITTMAN WM R (3120)	
	JONES WALTER B (3123)	
	MCKEE CLAUDE (3123)	
	EMLAW DONALD L (3128)	
	HUSSON BETTY J (3132)	
	ITO WAYNE A (3136)	
	NIXT GARY E (3141)	
	HORN HANK (3146)	
	BEEDY DUANE (3154)	
	<u>**W 189TH ST**</u>	Pacific Telephone
	HINOJOSA CHRIS (3209)	
	MAY MICHAEL TORRANCE (3215)	

### <u>Year</u> <u>Uses</u>

### 1980 (continued)

30 (0		
	<u>**190TH ST**</u>	Pacific T
	MARGIE S LOUNGE TORRANCE (3103)	
	**CRENSHAW BLVD**	Pacific T
	MIDWAY MKT (18727)	
	FASHION RUG (18731)	
	DALLAS CERAMIC COMPANY (18740)	
	CRENSHAW BAPTIST CHURCH (18749)	
	ALLSTATE BAIL BONDS (18750)	
	PERSONS & GORMAN BAIL BONDS (18750)	
	LA SALLE PLUMBING & HEATING (18760)	
	MIDWAY ESCROW CORP (18766)	
	JENSEN GRAPHICS & PRINTING (18801)	
	BORGES JOSE (18803)	
	D M D DATA SYSTEMS (18807)	
	CAL WEST FUNDING (18809)	
	CALWEST FUNDING (18809)	
	BANNER CARPETS & DRAPES (18814)	
	FEDERICOS TAILOR SHOP (18825)	
	MURDICK STEVEN (18903)	
	CRENSHAW CHILDREN S CENTER (18909)	
	MOHAWK PETROLEUM CORP INC (18910)	
	CORNER LIQUOR STORE TORRANCE (18915)	
	**CRENSHAW PL**	Pacific T
	KROL VERNON C ATTY (18801)	
	LOVEJOY RICHARD D (18801)	
	LUXURY CO OF AMERICA TORRANCE (18801)	
	COONEY CONSTRUCTION CO (18807)	
	GOLDEN WEST LOAN SERVICES (18807)	
	INTERNATIONAL MARRIAGE BUREAU (18807)	
	LOWELL CONSTRUCTION GENL ENGNRNG (18807)	
	LOWELL CONSTRUCTION GENL ENGNRNG (18807)	
	DELTA REALTY TORRANCE (18811)	
	EDWARDS J H COMPANY (18811)	
	GILES C & ASSOCIATES INC (18811)	

### 1981 <u>\*\*W 190TH\*\*</u>

TUNEUP MASTERS (3109)

### \*\*CRENSHAW BLVD\*\*

PELICAN (18905)

MIDWAY ESCROW CORP TORRANCE (18766) CAL WEST FUNDING TORRANCE (18809) SEYMOUR REAL ESTATE TORRNACE (18901)

LINDEMAN ROGER H BUILDING DESIGNER (18811)

<u>Source</u>

Pacific Telephone

Pacific Telephone

### Pacific Telephone

Pacific Telephone

Pacific Telephone

<u>Year</u>	<u>Uses</u>	Source
1981 (	continued) <u>**CRENSHAW PL**</u>	Pacific Telephone
	KROL VERNON C ATTY TORRANCE (18801)	
	ZAMIOCH ARCHER ATTY TORRANCE (18801)	
	EDWARDS J H CO TORRANCE (18811)	
1985	**CRENSHAW BLVD**	Pacific Bell
	GARRETT CORPORATION THE DIVISIONS (18700)	
	GARRETT CORPORATION THE AIRSUPPLY CO (18700)	
	**W 187TH PL**	Pacific Bell
	HIGGINS DAVID T (3110)	
	SIBLEY GLENN & DANIELLE (3111)	
	WRIGHT M V (3113) BISHOP VIVIAN (3120)	
	PITTMAN WM R (3120)	
	SMYTHE STEPHEN E (3121)	
	JONES WALTER B (3123)	
	PAINTER PAUL & DEBORAH (3123)	
	URBAN CLEMENT F (3124)	
	LOSS D (3127)	
	EMLAW DONALD L (3128)	
	NIXT GARY E (3141)	
	ROBERTS ROBT J (3142)	
	STEWARD KENNETH A (3150)	
	BEADY DUANE (3154)	
	<u>**W 189TH ST**</u>	Pacific Bell
	FRESQUEZ DIANE (3205)	
	HINOJOSA CHRIS (3209)	
	BYHOWER LENNA (3210)	
	WEISBROT MIKE (3215)	
	FRESQUEZ LEON (3216)	
	THOMPSON DAVID R (3219)	
	SHELLMAN ROBT M (3223)	
	<u>**W 190TH ST**</u>	Pacific Bell
	MARGIE S LOUNGE (3103)	
	TUNEUP MASTERS (3109)	
	**CRENSHAW BLVD**	Pacific Bell
	MIDWAY MKT (18727)	
	CONTROL DATA (18730)	
	CONTROL DATA BUSINESS CENTERS INC (18730)	
	CONTROL DATA BUSINESS CENTERS INC (18730)	
	SERVICE BUREAU CO THE (18730)	
	SERVICE BUREAU CO THE (18730)	
	SERVICE BUREAU CO THE (18730)	
	2051883-6 17	

### <u>Year</u> Uses

### 1985 (continued)

LY KEV (18737)

<u>Source</u>

DALTILE CORPORATION (18740) CRENSHAW BAPTIST CHURCH (18749)

ALLSTATE BAIL BONDS (18750)

BILLY PERSONS BAIL BONDS (18750)

PERSONS BILLY BAIL BONDS (18750)

PERSONS SURETY INSURANCE AGENCY (18750)

L T D INVESTMENTS (18760)

LA SALLE AIR CONDITIONING PLUMBING & HEATING (18760)

LA SALLE PLUMBING & HEATING (18760)

LA SALLE PLUMBING HEATING & AIR CONDITIONING (18760)

JENSEN GRAPHICS & PRINTING (18801)

BORGES JOSE (18803)

ARMSTRONG DOUG HERBALIFE DISTR (18807)

CAL WEST FUNDING (18809)

CALWEST FUNDING (18809)

BANNER CARPETS & DRAPES (18814)

JORDAN F F (18821)

FEDERICOS TAILOR SHOP (18825)

SEYMOUR REAL ESTATE (18901)

VOLLMER ENGINEERING & GRADING CONTRACTORS (18901)

CRENSHAW CHILDRENS CENTER (18909)

KIM S TEXACO SERVICE STATION (18910)

CORNER LIQUOR STORE (18915)

### \*\*CRENSHAW PL\*\*

Pacific Bell

HERBALIFE ANTHONY TOM DISTRIBUTORS (18807) HERBALIFE DISTRIBUTOR (18807) HERBALIFE DISTRIBUTOR ARMSTRONG DOUG & LORI (18807) HERBALIFE DOSTRIBUTOR ARMSTRONG DOUG & LORI (18807) HERBALIFE PRODUCTS DISTRIBUTORS (18807) LOWELL CONSTRUCTION GENALENGNARG (18807) MC GOLDRICK DENNIS E ATTY (18807) MCGOLDRICK ELLEN D ATTY (18807) AMERICAN REHABILITATION MANAGEMENT (18811) ATKINS LANDSCAPE CORP (18811) D M D DATA SYSTEMS (18811) GARLAND R G CO (18811) LINDEMAN ROGER H BUILDING DESIGNER (18811) PELICAN (18905) \*\*W 190TH\*\*

### 1986 <u>\*\*W 190TH\*\*</u>

TUNEUP MASTERS TORRANCE TORRANCE (3109)

### \*\*CRENSHAW BLVD\*\*

Pacific Bell

<u>Year</u> 1986 (	Uses continued)	<u>Source</u>
1000 (	AIRSUPY COMPANY DIVISION OF TORRANCE (18700) GARRETT CORPORATION THE (18700)	
1990	<u>**W 190TH**</u>	Pacific Bell
	TUNEUP MASTERS (3109)	
	**CRENSHAW BLVD**	Pacific Bell
	DAL TILE CORPORATION B PK (18740)	
	<u>**187TH PL W**</u>	Pacific Bell
	BISHOP VIVIAN (3120)	
	JONES E M (3123)	
	EMLAW DONALD L (3128)	
	<u>**188TH W**</u>	Pacific Bell
	HAGGARD DAVID (3133)	
	ZELADA ROSA (3134)	Pacific Bell
	<u>**189TH_W**</u> BYHOWER LENNA (3210)	
	OSTLER WILLARD H (3215)	
	WEISBROT MIKE (3215)	
	FRESQUEZ LEON (3216)	
	THOMPSON DAVID R (3219)	
	R M SHELLMAN INC (3223)	
	SHELLMAN ROBT M (3223)	
	<u>**190TH W**</u>	Pacific Bell
	JULI (3103)	
	JULI (3103)	
	TUNEUP MASTERS (3109)	
1991	**CRENSHAW BLVD**	Pacific Bell
	DAL TILE CORPORATION (18740)	
1995	<u>**W 187TH PL**</u>	Pacific Bell Telephone
	NEEDELMAN DAVID & MARTHA TORRANCE (3119)	
	BISHOP VIVIAN TORRANCE (3120)	
	JONES E M TORRANCE (3123)	Desifie Dell Telephone
	<u>**W 187TH**</u>	Pacific Bell Telephone
	SWANSON GARY M TORRANCE (3118) SCHREIBER SAML H TORRANCE (3122)	
	<u>**W 190TH**</u>	Pacific Bell Telephone
	SMOG CHECK STATIONS (3109)	
	**CRENSHAW BLVD**	Pacific Bell Telephone
	BRUSH WELLMAN INC TORRANCE (18720)	
	SWISHER RESTROOM HYGIENE TORRANCE (18729)	
	CERIDIAN EMPLOYER SERVICES TORRANCE (18730)	

Year <u>Uses</u> 1995 (continued)	<u>Source</u>
DAL-TILE CORPORATION TORRANCE (18740)	
ALLSTATE BALI BONDS TORRANCE (18750)	
ALLSTATE BONDS AGENCY TORRANCE (18750)	
BILLY PERSONS BAIL BONDS TORRANCE (18750)	
CARPETCO TORRANCE (18760)	
BAUER MARTIN J III CPA TORRANCE (18815)	
STILLION CONSTRUCTION TORRANCE (18901)	
STILLION PAULA TORRANCE (18901)	
**CRENSHAW PL**	Pacific Bell Telephone
D M D DATA SYSTEMS TORRANCE (18811)	
H C G HOMEOPATHIC CONSULTATATION GROUP TORRANCE (18811)	
<u>**W 187TH PL**</u>	Pacific Bell Telephone
NEEDELMAN DAVID & MARTHA (3119)	
BISHOP VIVIAN (3120)	
JONES E M (3123)	
EMLAW DONALD L (3128)	
<u>**W 188TH ST**</u>	Pacific Bell Telephone
LIMA ISRAEL (3127)	
<u>**W 189TH ST**</u>	Pacific Bell Telephone
FRESQUEZ LEON (3216)	
THOMPSON DAVID R (3219)	
R M SHELLMAN INC (3223)	
SHELLMAN ROBT M (3223)	
<u>**W 190TH**</u>	Pacific Bell Telephone
JULI (3103)	
JULI (3103)	
SOUTH GATE TUNEUP MASTERS (3109)	
TORRANCE (3109)	
TORRANCE TUNEUP MASTERS (3109)	
**CRENSHAW BLVD**	Pacific Bell Telephone
BRUSH WELLMAN INC (18720)	
MIDWAY MKT (18727)	
SWISHER RESTROOM HYGIENE (18729)	
CERIDIAN EMPLOYER SERVICES (18730)	
SANTORO DAN (18731)	
MIYAZONO GLENN (18737)	
DAL TILE CORPORATION (18740)	
CRENSHAW BAPTIST CHURCH (18749)	
ALLSTATE BALI BONDS (18750)	
ALLSTATE BONDS AGENCY (18750)	
BILLY PERSONS BAIL BONDS (18750)	

<u>Year</u> <u>Uses</u>	<u>Source</u>
1995 (continued) PERSONS BILLY BAIL BONDS (18750)	
PERSONS SURETY INSURANCE AGENCY (18750)	
CARPETCO (18760)	
CAL WEST FUNDING (18809)	
CALWEST FUNDING (18809)	
BANNER CARPETS & DRAPES (18814)	
BAUER MARTIN J III CPA (18815)	
KING DAVID F CPA (18815)	
FEDERICOS TAILOR SHOP (18825)	
STILLION CONSTRUCTION (18901)	
AZEVEDO LOUIE (18903)	
CRENSHAW CHILDRENS CENTER (18909)	
**CRENSHAW PL**	Pacific Bell Telephone
LA SALLE AIR CONDITIONING PLUMBING & HEATING (18801)	
LA SALLE ELECTRIC (18801)	
LA SALLE PLUMBING & HEATING (18801)	
LA SALLE PLUMBING HEATING & AIR CONDITIONING (18801)	
D M D DATA SYSTEMS (18811)	
H C G HOMEOPATHIC CONSULTATATION GROUP (18811)	
CLASSIC STAR (18905)	
<u>**W 190TH**</u>	Pacific Bell Telephone
TUNEUP MASTERS LOS ANGELES (3109)	
**CRENSHAW BLVD**	Pacific Bell Telephone
DAL-TILE CORPORATION B PK (18740)	
<u>**187TH PL W**</u>	Pacific Bell Telephone
NEEDELMAN DAVID & MARTHA (3119)	
BISHOP VIVIAN (3120)	
LEDBETTER DALE (3123)	
EMLAW DONALD L (3128)	
<u>**188TH W**</u>	Pacific Bell Telephone
LIMA ISRAEL (3127)	
<u>**189TH W**</u>	Pacific Bell Telephone
FRESQUEZ LEON (3216)	
THOMPSON DAVID R (3219)	
R M SHELLMAN INC (3223)	
SHELLMAN ROBT M (3223)	
<u>**190TH W**</u>	Pacific Bell Telephone
JULI (3103)	
JULI (3103)	
TUNEUP MASTERS (3109)	
**CRENSHAW BLVD**	Pacific Bell Telephone

### Year Uses

#### 1995 (continued)

Source

**MISAINE TRADE INC (18710) BRUSH WELLMAN INC (18720) B KORTCAMP RICHARD (18721)** (18721) MIDWAY MKT (18727) LIFEGUARD SECURITY & GATE (18729) CAPARROS CORP (18730) SANTORO DAN (18731) OCEANBRIDGE SHIPPING INTERNATL INC (18732) TRIPLE ALLIANCE CO INC WESTERN REGION (18732) MIYAZONO GLENN (18737) **DAL-TILE CORPORATION (18740) CRENSHAW BAPTIST CHURCH (18749)** WRIGHT GROUP (18749) ALL STATE BAIL BONDS (18750) PERSONS SURETY INSURANCE AGENCY (18750) **CARPETCO (18760)** CALWEST FUNDING (18809) BANNER CARPETS & DRAPES (18814) A INDUSTRIAL TECHNOLOGY MGMT INC (18815) B KING DAVID F CPA (18815) BAUER MARTIN J III CPA (18815) (18815) FEDERICOS TAILOR SHOP (18825) **STILLION CONSTRUCTION (18901)** AZEVEDO LOUIE (18903) **CRENSHAW CHILDRENS CENTER (18909)** Pacific Bell Telephone **\*\*CRENSHAW PL\*\*** LA SALLE PLUMBING HEATING & AIR CONDITIONING (18801) 104 D M D DATA SYSTEMS (18811) HAGUE QUALITY WATER (18811) (18811) C CLASSIC STAR (18905) (18905)1996 GTE Address Not Listed in Research Source 1999 Haines Company Address Not Listed in Research Source 2000 Pacific Bell Telephone Address Not Listed in Research Source 2001 Haines & Company, Inc. \*\*W 187TH PL\*\* **ONEEDELMAN DAVID (3119)** 2051883-6

### Source <u>Year</u> <u>Uses</u> 2001 (continued) FARLEY RANDY (3120) SLEDBETTER DALE (3123) SOROZCOSTEVEN (3124) OLOSSDEBRA (3127) EMLAWDONALD L (3128) MARSHALLLESL IE (3133) OAGUIRREJUAN (3134) \*\*W 188TH ST\*\* Haines & Company, Inc. XXXX (3116) XXXX (3120) XXXX (3123) ROBB MONICA (3127) **OOUINNMAUREEN (3130)** HAGGARDJAMES (3133) SROMEROOSVALDO (3134) Haines & Company, Inc. \*\*W 189TH ST\*\* WAHLERSKARL (3205) XXXX (3209) **BRADFORDRICK (3210)** HENSELMANJOHN (3215) FRESOOEZMA IRA (3216) THOMPSON DAVID R (3219) SALEROYSIDERO (3220) **RMSHELLMANINC (3223)** 2003 Haines & Company Address Not Listed in Research Source 2004 Haines Company Address Not Listed in Research Source 2006 Address Not Listed in Research Source Haines Company

### **APPENDIX D**

### PHOTOGRAPHS RECORDED DURING THE SUBJECT PROPERTY INSPECTION



**Photograph 1**: View of subject property looking northwest from southeastern corner of subject property.



Photograph 2: View along northern boundary of subject property looking east.

### SITE PHOTOGRAPHS

PARKING LOT NORTHEAST CORNER OF WEST 190<sup>TH</sup> STREET AND CRENSHAW PLACE TORRANCE, CALIFORNIA



Photograph 3: View looking southeast from northwestern corner of subject property.



Photograph 4: View along western boundary of subject property looking south.

SITE PHOTOGRAPHS PARKING LOT

NORTHEAST CORNER OF WEST 190<sup>TH</sup> STREET AND CRENSHAW PLACE TORRANCE, CALIFORNIA



Photograph 5: View of looking northeast from eastern boundary of subject property.



Photograph 6: View along southern boundary of subject property looking east.

### SITE PHOTOGRAPHS

PARKING LOT NORTHEAST CORNER OF WEST 190<sup>TH</sup> STREET AND CRENSHAW PLACE TORRANCE, CALIFORNIA



Photograph 7: View along southern boundary of subject property looking west.



Photograph 8: View along eastern boundary of subject property looking north.

### SITE PHOTOGRAPHS

PARKING LOT NORTHEAST CORNER OF WEST 190<sup>TH</sup> STREET AND CRENSHAW PLACE TORRANCE, CALIFORNIA



Photograph 9: View looking southwest from northeast corner of subject property.



Photograph 10: View along northern boundary of subject property looking west.

### SITE PHOTOGRAPHS

PARKING LOT NORTHEAST CORNER OF WEST 190<sup>TH</sup> STREET AND CRENSHAW PLACE TORRANCE, CALIFORNIA



Photograph 11: View from northwestern corner of subject property looking north.



Photograph 12: View along western boundary of subject property looking south.

SITE PHOTOGRAPHS PARKING LOT NORTHEAST CORNER OF WEST 190<sup>TH</sup> STREET AND CRENSHAW PLACE TORRANCE, CALIFORNIA



Photograph 13: View looking east along the southern boundary and adjacent 190<sup>th</sup> Street.



**Photograph 14**: View of concrete strip and patches.

### SITE PHOTOGRAPHS PARKING LOT

NORTHEAST CORNER OF WEST 190<sup>TH</sup> STREET AND CRENSHAW PLACE TORRANCE, CALIFORNIA

**APPENDIX E** 

USER QUESTIONNAIRE

### ASTM International Standard E 1527 – 05

### **User Questionnaire**

(Parking Lot – NE Corner W. 190th Street and Crenshaw Place, Torrance, CA)

The ASTM Standard requires the person commissioning a Phase I Environmental Site Assessment (the user) to provide the following information (if available) to the environmental professional. Failure to provide this information could result in a determination that "all appropriate inquiry" is not complete.

### 1. Environmental cleanup liens that are filed or recorded against the site (40 CFR 312.25).

Are you aware of any environmental cleanup liens against the subject property that are filed or recorded under federal, tribal, state or local law? No.

# 2. Activity and land use limitations that are in place on the site or have that been filed or recorded in a registry (40 CFR 312.26).

Are you aware of any AULs, such as *engineering controls*, land use restrictions or *institutional controls* that are in place at the site and/or have been filed or recorded in a registry under federal, tribal, state or local law? No.

### 3. Specialized knowledge or experience of the user (40 CFR 312.28).

As the user of this ESA do you have any specialized knowledge or experience related to the subject property or nearby properties? For example, are you involved in the same line of business as the current or former *occupants* of the property or an adjoining property so that you would have specialized knowledge of the chemicals and processes used by this type of business? We are not in the same line of business as the former owners of this parcel of land. We have owned the adjacent office building since late 1997 and received a Phase I Environmental Assessment from the owner at that time.

# 4. Relationship of the purchase price to the fair market value of the property if it were not contaminated (40 CFR 312.29).

Does the purchase price being paid for this property reasonably reflect the fair market value of the property? If you conclude that there is a difference have you considered whether the lower purchase price is because contamination is know or believed to be present at the property? The purchase price for the land was set in an option agreement ten years ago. I believe most experienced real estate professionals would consider the purchase price to be below its fair market value. The lower price is the result of the option agreement and not because of any known or potential contamination at the property.

# 5. Commonly known or reasonably ascertainable information about the property (40 CFR 312.30).

Are you aware of commonly known or reasonably ascertainable information about the property that would help the environmental professional to identify conditions indicative of releases or threatened releases? For example, as user,

- a) Do you know the past uses of the property?
- b) Do you know of specific chemicals that are present or once were present at the property?
- c) Do you know of spills or other chemical releases that have taken place at the property?

d) Do you know of any environmental cleanups that have taken place at the property? Any knowledge meeting this standard would be contained in the 1997 Phase I mentioned in Paragraph 3 or in current regulatory databases. The site is adjacent to a former manufacturing plant now owned by Honeywell. Honeywell has an environmental specialist on site, so I assume both chemical releases and clean ups have occurred in the past.

# 6. The degree of obviousness or the presence or likely presence of contamination at the *property*, and the ability to detect the contamination by appropriate investigation (40 CFR 312.31).

As the *user* of this *ESA*, based on your knowledge and experience related to the *property* are there any *obvious* indicators that point to the presence or likely presence of contamination at the *property*? No. The property is currently utilized as a parking lot.

**APPENDIX F** 

**RESUMES OF ENVIRONMENTAL PROFESSIONALS** 



### Kristina Byrne, EIT – Environmental Engineer

Ms. Byrne has a Bachelor of Science Degree in Environmental Engineering and is an Engineer in Training. Ms. Byrne has experience in conducting Phase I and Phase II Environmental Site Assessments (ESAs) and projects involving water quality, soil quality, and regulatory compliance.

### Misty Vazquez, EIT, REA – Senior Project Environmental Engineer

Ms. Vazquez has a Bachelor of Science Degree in Environmental Engineering and is an Engineer in Training, California Registered Environmental Assessor, and AHERA Certified Building Inspector. Ms. Vazquez has considerable experience in conducting Phase I and Phase II Environmental Site Assessments (ESAs) and projects involving water quality, soil quality, and regulatory compliance. Ms. Vazquez has conducted over 200 Phase I and Phase II ESA investigations and has both managed and supported soil and groundwater remediation projects and underground storage tank removal projects. Additionally, Ms. Vazquez routinely prepares storm water pollution prevention plans, spill prevention control and countermeasures plans, site assessment work plans, and landfill permitting documents.

### Jane P. Mills, CSP, CHMM - Associate & Senior Environmental Consultant

Ms. Mills has a B.S. in Civil Engineering and an M.S. in Occupational Safety and Health. She has worked for over 20 years providing health and safety services in conjunction with environmental evaluation, measurement, analysis, and corrective action design consulting services. Ms. Mills is experienced in performing environmental compliance audits, indoor air quality investigations for mold, industrial emissions and other worker exposure parameters, and environmental remediation design and implementation. She has worked with clients during the acquisition and disposition of industrial, commercial, multi-family residential and publicly-owned properties. Ms. Mills is experienced in performing multi-site evaluations, and understands environmental and safety issues from the view of the client. Assessing project objectives and developing strategies to insure appropriate, economical responses to meet business and regulatory requirements are priorities. Her recent projects include: environmental permit-related studies for new power generating facilities in the Northwest, a multi-media environmental audit of a waste-to-energy power plant, environmental audits of over 100 industrial business parks throughout the west coast, and exposure monitoring during the mass excavation of a state-listed contaminated development site.

**APPENDIX G** 

AGENCY DOCUMENTATION

To: Request for Records	<b>Fax Number</b> : (626) 458-3569	
<b>Company</b> : LADPW Environmental Programs	<b>Date</b> : 10/12/07	
From: Kristina Byrne	e-mail: kbyrne@golder.com	
Our Ref:	Voice Mail:	
<b>RE</b> : Availability of files		
Total pages (including cover): 1	Hard copy to follow: Yes	
	<u>    X    </u> No	
MESSAGE		

Can you please let me know whether there are available UST or Industrial Waste files for the following addresses:

### PARKING LOT LOCATED AT NORTHEAST CORNER OF WEST 190TH STREET AND CRENSHAW PLACE TORRANCE, CALIFORNIA 90504

Please let me know the availability of files. Thank you for your assistance.





230 Commerce, Suite 200 Irvine, CA USA 92602 Telephone (714) 508-4400 Fax (714) 508-4401

Comprehensive Global Consulting Services in Geotechnical Engineering, Waste Management, and Environmental Services

### Industries Served:

Agriculture

Finance, Insurance, Real Estate and Legal

Forestry

Land Development

Manufacturing

Mining

Oil and Gas

Power

Solid Waste

Transportation

Water Resources

Offices across Asia, Australasia, Europe, North America, South America

The document(s) included with this transmission are only for the recipient named above and contain privileged/confidential information. Unauthorized disclosure, dissemination, or copying of this transmission is strictly prohibited. If received in error, please destroy. Questions or problems with this transmission should be referred to the receptionist at the number provided above.

To: Request for Records	Fax Number: (626) 458-3569	Golder
Company: LADPW Environmental Programs	Date: 10/12/07	<b>V</b> ASSOCIATES
From: Kristina Byrne	e-mail: kbyme@golder.com	230 Commerce, Suite 200 Irvine, CA USA 92602
Our Ref:	Voice Mail:	Telephone (714) 508-4400 Fax (714) 508-4401
RE: Availability of files		
Total pages (including cover): 1	Hard copy to follow: Yes	
	X No	Comprehensive Global Consulting Services in Geotechnical Engineering,
MESSAGE		Waste Management, and Environmental Services

Can you please let me know whether there are available UST or Industrial Waste files for the following addresses:

PARKING LOT LOCATED AT NORTHEAST CORNER OF WEST 190TH STREET AND CRENSHAW PLACE TORRANCE, CALIFORNIA 90504

Please let me know the availability of files. Thank you for your assistance.

NO FILES FOUND

The document(s) included with this transmission are only for the recipient named above and contain privileged/confidential information. Unauthorized disclosure, dissemination, or copying of this transmission is strictly prohibited. If received in error, please destroy, Questions or problems with this transmission should be referred to the receptionist at the number provided above.

Transportation

Water Resources

Industries Served:

Land Development

Manufacturing

Finance, Insurance, Real Estate

Agriculture

and Legal

Forestry

Mining

Offices across Asia, Australasia, Europe, North America, South America

To: Gary Chiang	<b>Fax Number</b> : (213) 576-1323
Company: Los Angeles RWQCB	<b>Date</b> : 10-12-07
From: Kristina Byrne	e-mail: kbyrne@golder.com
Our Ref:	Voice Mail:
<b>RE</b> : Availability of WDR files	
Total pages (including cover): 1	Hard copy to follow: Yes
	X No

Golder

230 Commerce, Suite 200 Irvine, CA USA 92602 Telephone (714) 508-4400 Fax (714) 508-4401

Comprehensive Global Consulting Services in Geotechnical Engineering, Waste Management, and Environmental Services

MESSAGE

Do you have any WDR files for the following subject property address?

### PARKING LOT LOCATED AT NORTHEAST CORNER OF WEST 190TH STREET AND CRENSHAW PLACE TORRANCE, CALIFORNIA 90504

This information is being requested for a Phase I Environmental Site Assessment. Please contact me regarding the availability of files at 714-508-4400. Thank you for your assistance.

Industries Served:

Agriculture Finance, Insurance, Real Estate and Legal Forestry Land Development Manufacturing Mining Oil and Gas

Power

Solid Waste

Transportation

Water Resources

Offices across Asia, Australasia, Europe, North America, South America

The document(s) included with this transmission are only for the recipient named above and contain privileged/confidential information. Unauthorized disclosure, dissemination, or copying of this transmission is strictly prohibited. If received in error, please destroy. Questions or problems with this transmission should be referred to the receptionist at the number provided above.

### Byrne, Kristina

From:	Sussan Magana [smagana@waterboards.ca.gov]
Sent:	Wednesday, October 17, 2007 3:56 PM
То:	Byrne, Kristina
Subject:	RE: Availability of WDR files

Mrs. Byrne,

I am writing in response to the file review request made on October 12, 2007 regarding:

Parking lot located at northeast corner of west 190th street and crenshaw place Torrance, CA 90504

I have researched the location(s) and have found no landfills in close proximity. If you have any further questions, please feel free to contact me. Have a good day.

Sussan Magana email: smagana@waterboards.ca.gov phone: (213)620-2271

To: SLIC File Review Request	Fax Number: 213-576-6717
Company: Los Angeles RWQCB	<b>Date</b> : 10-12-07
From: Kristina Byrne	e-mail: kbyrne@golder.com
Our Ref:	Voice Mail:
<b>RE</b> : Availability of SLIC files	

<u>X</u> No

MESSAGE

Do you have any SLIC files for the following subject property address?

### PARKING LOT LOCATED AT NORTHEAST CORNER OF WEST 190TH STREET AND CRENSHAW PLACE TORRANCE, CALIFORNIA 90504

This information is being requested for a Phase I Environmental Site Assessment. Please contact me regarding the availability of files at 714-508-4400. Thank you for your assistance.



230 Commerce, Suite 200 Irvine, CA USA 92602 Telephone (714) 508-4400 Fax (714) 508-4401

Comprehensive Global Consulting Services in Geotechnical Engineering, Waste Management, and Environmental Services

### Industries Served:

Agriculture

Finance, Insurance, Real Estate and Legal

Forestry

Land Development

Manufacturing

Mining

Oil and Gas

Power

Solid Waste

Transportation

Water Resources

Offices across Asia, Australasia, Europe, North America, South America

### Byrne, Kristina

From:	Andrew Veloz [asveloz@waterboards.ca.gov]
Sent:	Tuesday, October 16, 2007 10:12 AM
То:	Byrne, Kristina
Subject:	The SLIC 1 Unit has received your faxed request

The SLIC 1 Unit has received your faxed request for information regarding the property(ies) located at:

190th Street and crenshaw place, Torrance, CA

Currently, the SLIC 1 Unit does not have any record of investigation for the above property(ies). We also recommend that you contact the the SLIC 2 Unit--213-576-6749 and/or the UST Unit at 213-576-6748 for any other records that they may have on the above property(ies)

If you have any questions you may reply to this email or call (213)576-6663 or (213)576-6749.

Thank You for your request.

Andrew Veloz Student Intern

To: UST File Review Request	<b>Fax Number</b> : 213-576-6707
Company: Los Angeles RWQCB	Date: 10-12-07
From: Kristina Byrne	e-mail: kbyrne@golder.com
Our Ref:	Voice Mail:
Our Ref: RE: Availability of UST files	Voice Mail:

<u>X</u> No

Yes

MESSAGE

Do you have any UST files for the following subject property address?

### PARKING LOT LOCATED AT NORTHEAST CORNER OF WEST 190TH STREET AND CRENSHAW PLACE TORRANCE, CALIFORNIA 90504

This information is being requested for a Phase I Environmental Site Assessment. Please contact me regarding the availability of files at 714-508-4400. Thank you for your assistance.

## Industries Served:

Agriculture

Finance, Insurance, Real Estate and Legal

Forestry

Land Development

Manufacturing

Mining

Oil and Gas

Power

Solid Waste

Transportation

Water Resources

Offices across Asia, Australasia, Europe, North America, South America





230 Commerce, Suite 200 Irvine, CA USA 92602 Telephone (714) 508-4400

Fax (714) 508-4401

Comprehensive Global Consulting Services in Geotechnical Engineering, Waste Management, and

**Environmental Services** 

## **TELEPHONE MEMORANDUM**

	Incoming	Outgoing _	C	onference Call
Job/Project:	nes en general de la companya de la	99999999999999999999999999999999999999	Route to:	Project #:
Person:		al i george a botta e rop te geo materia i me e vita a "Constructivos monto terra a constructor		Phase #:
Firm:		en normalise and an an Anno Cran Marina de Anno II de Cante Constantin's Marina de Cant		Date:
Phone No:	92/1911/991/1919/991/991/991/991/991/991	n far fan		Time:
Email Address:	ан улуналар жалан каларан жаларан каларын каларын каларын каларын каларын каларын каларын каларын каларын калар Каларын каларын	98125.44551107824472578956399699967897897897897897897897897897897897897897		By:
	na na manda na manana da manana na manana na manana na manana na manana na manana na manana kao any kao any kao Na manana manda na manana da manana na manana na manana na manana na manana na manana na manana kao any kao any			
Remarks:		· .		
	Henry Jone	25		-10/0/0,
				~ ~ ~
·	RWOLD	-455		
	- Fax			
			. ^.	- Annum
i	can't fi	nd it sp	zcifically_	WT
· · · · · · · · · · · · · · · · · · ·	HC Dr	ding 30	GOGO MIC	her nothing
······································	C ve 012	-576-67	· 入っ	V
· · · · · · · · · · · · · · · · · · ·		016-61	07	
			<u> </u>	
·····				
			Manunialiniin antonia	
- - -				
	1			
Action Required:				
	4534000005000015005000000000000000000000	2007-01-2007-01-20-20-20-20-20-20-20-20-20-20-20-20-20-		



To: Efehi Ogbebor	<b>Fax Number</b> : (213) 576-6660
Company: Los Angeles RWQCB	Date: 10-12-07
From: Kristina Byrne	e-mail: kbyrne@golder.com
Our Ref:	Voice Mail:
Our Ref: RE: Availability of NPDES files	Voice Mail:

<u> X No</u>

Yes

MESSAGE

Do you have any NPDES files for the following subject property address?

### PARKING LOT LOCATED AT NORTHEAST CORNER OF WEST 190TH STREET AND CRENSHAW PLACE TORRANCE, CALIFORNIA 90504

This information is being requested for a Phase I Environmental Site Assessment. Please contact me regarding the availability of files at 714-508-4400. Thank you for your assistance.



230 Commerce, Suite 200 Irvine, CA USA 92602 Telephone (714) 508-4400 Fax (714) 508-4401

Comprehensive Global Consulting Services in Geotechnical Engineering, Waste Management, and Environmental Services

#### Industries Served:

Agriculture

Finance, Insurance, Real Estate and Legal

Forestry

Land Development

Manufacturing

Mining

Oil and Gas

Power

Solid Waste

Transportation

Water Resources

Offices across Asia, Australasia, Europe, North America, South America

The document(s) included with this transmission are only for the recipient named above and contain privileged/confidential information. Unauthorized disclosure, dissemination, or copying of this transmission is strictly prohibited. If received in error, please destroy. Questions or problems with this transmission should be referred to the receptionist at the number provided above.

## Byrne, Kristina

From:	Efehi Ogbebor [eogbebor@waterboards.ca.gov]
Sent:	Wednesday, October 17, 2007 10:31 AM
То:	Byrne, Kristina
Subject:	File Review Request

This e-mail is in response to your file review request for:

PARKING LOT LOCATED AT NORTHEAST CORNER OF WEST 190TH STREET AND CRENSHAW PLACE TORRENCE, CA 90504

We did not have any records for this site in the NPDES unit. If you have any questions you may reply or call me at the number listed below

Efehi Ogbebor California Regional Water Quality Control Board Specialized Student Assistant, NPDES (213) 576 6752

To: WIP File Review Request	Fax Number: (213) 576-6717
Company: Los Angeles RWQCB	Date: 10-12-07
From: Kristina Byrne	e-mail: kbyrne@golder.com
Our Ref:	Voice Mail:
<b>RE</b> : Availability of Well Investigation F	Program files
Total pages (including cover): 1	Hard copy to follow: Yes
	X No

MESSAGE

Do you have any WIP files for the following subject property address?

## PARKING LOT LOCATED AT NORTHEAST CORNER OF WEST 190TH STREET AND CRENSHAW PLACE **TORRANCE, CALIFORNIA 90504**

This information is being requested for a Phase I Environmental Site Assessment. Please contact me regarding the availability of files at 714-508-4400. Thank you for your assistance.



Industries Served:

Agriculture

Finance, Insurance, Real Estate and Legal

Forestry

Land Development

Manufacturing

Mining

Oil and Gas

Power

Solid Waste

Transportation

Water Resources

Offices across Asia, Australasia, Europe, North America. South America

Golder

Telephone (714) 508-4400 Fax (714) 508-4401

**Comprehensive Global Consulting Services in** Geotechnical Engineering, Waste Management, and

**Environmental Services** 

230 Commerce, Suite 200 Irvine, CA USA 92602

## Byrne, Kristina

From:	Raul Lima [rlima@waterboards.ca.gov]
Sent:	Tuesday, October 23, 2007 8:01 AM
То:	Byrne, Kristina
Subject:	SLIC 2 FILE REV

The SLIC 2 (Former Well Investigation Program) Unit has received your faxed request for information regarding the property(ies) located at:

190TH AND CRENSHAW OR ANY SITE IN TORRANCE.

Currently, the SLIC 2/ WIP Unit does not have any record of investigation for the above property(ies). We also recommend that you contact the SLIC 1 Unit at 213-576-6749 or the Underground Storage Tanks Unit at 213-576-6748 for any other records that they may have on the above property(ies)

If you have any questions you may reply to this email or call (213)576-6727.

Thank You for your request.

Raul Lima

SLIC 2/ (Former WIP) Unit Student Intern

**Golder Associates Inc.** 230 Commerce, Suite 200 Irvine, CA USA 92602 Telephone: (714) 508-4400 Fax: (714) 508-4401



October 15, 2007

Custodian of Records (Fax: 323-728-0217) Public Health Investigation (PHI) 5555 Ferguson Drive, Suite 120-04 Commerce, California 90022

SUBJECT: Request for Public Records

To Whom It May Concern:

Do you have any files regarding Hazardous Material Plans/Inventory, Waste Generator Permits, California ARP, spills, and site remediation information for the following assessor parcel numbers:

### PARKING LOT LOCATED AT NORTHEAST CORNER OF WEST 190TH STREET AND CRENSHAW PLACE TORRANCE, CALIFORNIA 90504

This information is being requested for an environmental site assessment. Please call me at (714) 508-4400 if you have any questions or require additional information to process this request. Thank you for your assistance.

Sincerely,

GOLDER ASSOCIATES, INC.

Kristina Byrne Environmental Engineer **Golder Associates Inc.** 230 Commerce, Suite 200 Irvine, CA USA 92602 Telephone: (714) 508-4400 Fax: (714) 508-4401



October 15, 2007

ストロートアンテキーやます いっていたい アインス ひとうしき 単純ない アイクタカイド ひとう しょうきゅう かいしょう かいきょう

Ŷ

Custodian of Records (Fax: 323-728-0217) Public Health Investigation (PHI) 5555 Ferguson Drive, Suite 120-04 Commerce, California 90022



SUBJECT: Request for Public Records

Public Health Investigation Administrative Headquarters

To Whom it May Concern:

Do you have any files regarding Hazardous Material Plans/Inventory, Waste Generator Permits, California ARP, spills, and site remediation information for the following assessor parcel numbers:

## PARKING LOT LOCATED AT NORTHEAST CORNER OF WEST 190TH STREET AND CRENSHAW PLACE TORRANCE, CALIFORNIA 90504

This information is being requested for an environmental site assessment. Please call me at (714) 508-4400 if you have any questions or require additional information to process this request. Thank you for your assistance.

Sincerely,

GOLDER ASSOCIATES, INC.

Kristina Byrne Environmental Engineer

Att Kristing address We nerd a physical address

To: File Review Section	<b>Fax Number</b> : 714 484 5318
Company: DTSC- Cypress	<b>Date</b> : 10-12-07
From: Kristina Byrne	e-mail: kbyrne@golder.com
Our Ref:	Voice Mail:
<b>RE</b> : Availability of DTSC files	

<u>X</u> No

MESSAGE

Do you have any DTSC files for the following subject property address?

### PARKING LOT LOCATED AT NORTHEAST CORNER OF WEST 190TH STREET AND CRENSHAW PLACE TORRANCE, CALIFORNIA 90504

This information is being requested for a Phase I Environmental Site Assessment. Please contact me regarding the availability of files at 714-508-4400. Thank you for your assistance.

FASSIFIC



230 Commerce, Suite 200 Irvine, CA USA 92602 Telephone (714) 508-4400 Fax (714) 508-4401

Comprehensive Global Consulting Services in Geotechnical Engineering, Waste Management, and Environmental Services

## Industries Served:

Agriculture

Finance, Insurance, Real Estate and Legal

Forestry

Land Development

Manufacturing

Mining

Oil and Gas

Power

Solid Waste

Transportation

Water Resources

Offices across Asia, Australasia, Europe, North America, South America **Department of Toxic Substances Control** 

Alan C. Lloyd, Ph.D. Agency Secretary Cal/EPA

5796 Corporate Avenue Cypress, California 90630

October 16, 2007

Ms. Kristina Byrne Golder Associates Inc. 230 Commerce, Suite 200 Irvine, California 92602

PARKING LOT LOCATED AT NE CORNER OF WEST 190<sup>TH</sup> STREET AND CRENSHAW PLACE, TORRANCE, CA 90504 PR#41015075

Dear Ms. Byrne:

The Department of Toxic Substances Control has received your request to review records under the Public Records Act.

After a thorough review of our files we have found that no such records exist at this office pertaining to the sites/facilities referenced above.

We would like to inform you about Envirostor, a database that provides information and documents on over 5,000 DTSC cleanup sites. EnviroStor can be accessed at: <u>http://www.envirostor.dtsc.ca.gov/public</u>. Also, a computer is available at each DTSC Regional File Room for use by community members to view EnviroStor.

If you have any questions or would like further information regarding your request, please contact our Regional Records Coordinators at (714) 484-5337.

Sincerely,

Centry Du

Julie Johnson Regional Records Coordinator

brm



Arnold Schwarzenegge

Governor



To: File Review Section	<b>Fax Number</b> : 818-551-2976
Company: DTSC- Glendale	Date: 10-12-07
From: Kristina Byrne	e-mail: kbyrne@golder.com
Our Ref:	Voice Mail:
Our Ref: RE: Availability of DTSC files	Voice Mail:
	Voice Mail: Hard copy to follow:

<u> X No</u>

Yes

MESSAGE

Do you have any DTSC files for the following subject property address?

## PARKING LOT LOCATED AT NORTHEAST CORNER OF WEST 190TH STREET AND CRENSHAW PLACE TORRANCE, CALIFORNIA 90504

This information is being requested for a Phase I Environmental Site Assessment. Please contact me regarding the availability of files at 714-508-4400. Thank you for your assistance.

SAX SE



230 Commerce, Suite 200 Irvine, CA USA 92602 Telephone (714) 508-4400 Fax (714) 508-4401

Comprehensive Global Consulting Services in Geotechnical Engineering, Waste Management, and Environmental Services

#### Industries Served:

Agriculture

Finance, Insurance, Real Estate and Legal

Forestry

Land Development

Manufacturing

Mining

Oil and Gas

Power

Solid Waste

Transportation

Water Resources

Offices across Asia, Australasia, Europe, North America, South America

The document(s) included with this transmission are only for the recipient named above and contain privileged/confidential information. Unauthorized disclosure, dissemination, or copying of this transmission is strictly prohibited. If received in error, please destroy. Questions or problems with this transmission should be referred to the receptionist at the number provided above. Department of Toxic Substances Control

Linda S. Adams Secretary for Environmental Protection

Maureen F. Gorsen, Director 1011 North Grandview Avenue Glendale, California 91201-2205

October 19, 2007

Ms. Kristina Byrne Golder Associates Inc. 230 Commerce, Suite 200 Irvine, California 92602

Parking Lot located at Northeast corner of West 190<sup>th</sup> Street and Crenshaw Place, Torrance, CA 90504 PR310160710

Dear Ms. Byrne:

We have received your Public Records Act Request for records from the Department of Toxic Substances Control.

After a thorough review of our files we have found that no such records exist at this office pertaining to the site/facility referenced above.

We would like to inform you about Envirostor, a database that provides information and documents on over 5,000 DTSC cleanup sites. EnviroStor can be accessed at: http://www.envirostor.dtsc.ca.gov/public. Also, a computer is available in the Central Files of each DTSC Regional Office for use by community members to view EnviroStor.

If you have any questions, would like further information regarding your request or would like an appointment to visit Glendale's Central Files, please contact me at (818) 551-2886.

Sincerely,

C. C. A. C. C. C. March & C. C. C. Jone Barrio Regional Records Coordinator



Arnold Schwarzenegger

Governor



