APPENDIX D

LIGHTING PERFORMANCE SUMMARY RESULTS



IDA Community Friendly Outdoor Sports Lighting

Lighting Performance Summary

Project: Carmel High School Football

Location: Carmel,CA **Curfew:** 10:30pm

Submitted: 27 October 21 - 10:36 AM PDT

Field: Football Field type: Football - Class IV Environmental Zone: E2							
Applicable Lighting Standard							
	Standard	Measured	Result				
Meets IES or HS Standard	_	Yes	PASS				
Applied BUG Analysis							
	Standard	Measured	Result				
Total Fixture Lumens	_	5,446,744 lumens	_				
Backlight: Lumens	15% or less	1.95%	PASS				
Backlight: Spill	2.0 lux or less	0.17 lux	PASS				
Uplight: Lumens	8% or less	7.7%	PASS				
Glare: Max Candela	1000 candela or less	789 candela	PASS				
Glare: 80° - 90°	250 lumens	0 lumens	PASS				
Application Efficiency							
	Standard	Measured	Result				
Total Fixture Watts	_	46,160 watts	_				
Applied Lumens	_	4,776,326 lumens	_				
Application Efficiency	70+ (lumens per watt)	103	PASS				

Lighting Performance Result

PASS



IDA Community Friendly Outdoor Sports Lighting

Lighting Performance Summary

Project: Carmel Pool Retrofit

Location: Carmel,CA **Curfew:** 10:30pm

Submitted: 15 July 22 - 3:10 PM PDT

Field: Pool Field type: Unknown - Class IV Environmental Zone: E2							
Applicable Lighting Standard							
	Standard	Measured	Result				
Meets IES or HS Standard	_	Yes	PASS				
Applied BUG Analysis							
	Standard	Measured	Result				
Total Fixture Lumens	_	962,008 lumens	_				
Backlight: Lumens	15% or less	0%	PASS				
Backlight: Spill	2.0 lux or less	0 lux	PASS				
Uplight: Lumens	8% or less	0%	PASS				
Glare: Max Candela	1000 candela or less	22 candela	PASS				
Glare: 80° - 90°	250 lumens	0 lumens	PASS				

Lighting Performance Result

PASS