

HRC Unique SLIDE_ID	Photo Year	Subbasin	Landuse Association	Volume Displaced (yd ³)	Volume Delivered (yd ³)	Reactivation Status	Status
3865	2006	Bridge Creek	R	73	0	1	Requires Assessment
3866	2006	Bridge Creek	OS	121	12	1	Requires Assessment
3893	2006	Browns Gulch	R	126	101	1	Requires Assessment
3903	2006	Lake Creek	R	61	15	1	Requires Assessment
3876	2006	Lake Creek	R	73	0	0	Requires Assessment
3878	2006	Lake Creek	R	61	15	0	Requires Assessment
3894	2006	Lake Creek	SK	121	0	0	Requires Assessment
3906	2006	Lake Creek	SK	61	0	0	Requires Assessment
3867	2006	Lower NF	R	182	136	1	Requires Assessment
3895	2006	Lower NF	R	485	121	1	Requires Assessment
3871	2006	Lower NF	OS	121	0	0	Requires Assessment
3875	2006	Lower NF	R	121	0	0	Requires Assessment
3877	2006	Lower NF	R	61	0	0	Requires Assessment
3883	2006	Lower NF	R	606	0	0	Requires Assessment
3920	2010	Lower SF	OS	121	61	1	Requires Assessment
3909	2006	North Fork Elk	OS	182	73	0	Requires Assessment
3869	2006	North Branch NF	R	364	0	1	Requires Assessment
3915	2006	North Branch NF	OS	121	30	0	Requires Assessment
3916	2006	North Branch NF	R	61	61	0	Requires Assessment
3879	2006	North Fork Elk	OS	61	30	1	Requires Assessment
3881	2006	North Fork Elk	R	73	18	1	Requires Assessment
3880	2006	North Fork Elk	R	61	6	0	Requires Assessment
3912	2006	North Fork Elk	R	485	485	0	Requires Assessment
3914	2006	North Fork Elk	R	61	0	0	Requires Assessment
3917	2006	North Fork Elk	R	121	0	0	Requires Assessment
3918	2006	North Fork Elk	R	61	45	0	Requires Assessment
3870	2006	South Branch NF	R	121	0	0	Requires Assessment
3911	2006	South Branch NF	OS	121	91	0	Requires Assessment
3913	2006	South Branch NF	R	61	0	0	Requires Assessment
3885	2006	Upper NF	R	182	0	1	Requires Assessment
3882	2006	Upper NF	R	364	91	0	Requires Assessment
3907	2006	Upper NF	R	182	0	0	Requires Assessment
3908	2006	Upper NF	R	121	30	0	Requires Assessment
3910	2006	Upper NF	OS	121	91	0	Requires Assessment
3922	2010	Upper NF	R	121	0	1	Requires Assessment