Alexandra Owens

From: Sent: To: Cc:	Zachariasen, Judith@DOC <judith.zachariasen@co Wednesday, June 7, 2023 12:33 PM Cort.Hitchens@sanjoseca.gov OLRA@DOC; OPR State Clearinghouse</judith.zachariasen@co 	J
Subject:	Kaiser Permanente San Jose Medical Center Project	t - SCH Number 2023050424
Follow Up Flag:	Follow up	soft.
Flag Status:	Flagged	DON ES
Categories:	Comments	Han 07 2023 Fa

Dear Cort Hitchens,

The California Geological Survey (CGS) has received the Notice of Preparation of a Draft Environmental Impact Report (DEIR) for the Kaiser Permanente San Jose Medical Center Project. This email conveys the following recommendations from CGS concerning geologic issues related to the project area:

STATE OF CALIFORN

1. Liquefaction Hazards

The project site is located within an earthquake zone of required investigation (ZORI) for liquefaction mapped by CGS. The DEIR and supporting documents should address this hazard as it relates to the design of the proposed structures. Additional information is available at the links below:

https://maps.conservation.ca.gov/cgs/EQZApp/app/

https://maps.conservation.ca.gov/cgs/informationwarehouse/index.html?map=regulatorymaps

2. Ground Shaking Hazards

The project area is not located in an Earthquake Fault Zone mapped by CGS. However, several active faults are nearby, and the site could be subject to significant ground shaking. The DEIR and supporting documents should address this hazard as it relates to the design of the proposed structures. Additional information about ground shaking hazard can be obtained at the following sites:

https://usgs.maps.arcgis.com/apps/webappviewer/index.html?id=14d2f75c7c4f4619936dac0d14e1e468 https://earthquake.usgs.gov/scenarios/catalog/bssc2014/

3. Surface Fault Rupture Hazard

The project area is not located in an Earthquake Fault Zone mapped by CGS. However, the Quaternary-age San Jose Fault has been mapped as inferred through the hospital campus. The DEIR and supporting documents should address this hazard as it relates to the design of the proposed structures. Additional information about surface faults can be obtained at the following sites:

https://usgs.maps.arcgis.com/apps/webappviewer/index.html?id=5a6038b3a1684561a9b0aadf88412fcf

If you have any additional comments or questions, please feel free to call or email.

Thank you, Judy Zachariasen



Judith Zachariasen, PhD, PG, CEG

Senior Engineering Geologist Fault Zoning Unit Supervisor Seismic Hazards Program California Geological Survey

California Department of Conservation 715 P Street, MS 1900, Sacramento, CA 95814 T: (916) 879-2844

E: judith.zachariasen@conservation.ca.gov