

FILE: I:\ST11501\GIS\MXDs\Noise\ExistingVibrationLocs - Appx.mxd (11/14/2019)

PRELIMINARY DRAFT/SUBJECT TO CHANGE - HSR ALIGNMENT IS NOT DETERMINED
SOURCE: National Geographic (2018); CHSRA (11/2019)




Figure A-2
Page 1 of 2

Existing Vibration Measurement Locations





Figure A-2
Page 2 of 2

Existing Vibration Measurement Locations