

Site Photos – County Road 200A Bridge Replacement Project



Photo 1 –

Overview of the upstream side of the bridge.

- Standing near the southwest corner of the bridge looking north.



Photo 2 –

Overview of the northern end on the downstream side of the bridge.

- Standing near the northeast corner of the bridge looking south.

Site Photos – County Road 200A Bridge Replacement Project



Photo 3 –

Approach on to the northern end of the bridge.

- Standing in County Road 200A looking south.



Photo 4 –

Bridge Deck approximately half way across the bridge.

- Standing on the bridge looking north.

Site Photos – County Road 200A Bridge Replacement Project



Photo 5 –

Approach coming into the bridge on the southern end.

- Standing near the southern end of the bridge looking south.



Photo 6 –

Downstream portion of the bridge with piers within Stony Creek. Debris visible on left of second pier.

- Standing near the southeastern corner of the bridge looking north.

Site Photos – County Road 200A Bridge Replacement Project




Photo 7 –

Overview of bridge and surrounding habitat.

- Photo is taken from the northern end of the bridge looking south.



Photo 8 –

Overview of the bridge and surrounding habitat.

- Photo is taken from the southern end of the bridge looking north.

Site Photos – County Road 200A Bridge Replacement Project



Photo 9 –

Overview of the downstream side of the bridge and surrounding habitat.

- Photo taken from the east looking towards the west.



Photo 10 –

Overview of the upstream side of the bridge and surrounding habitat.

- Photo taken from the west looking east towards Black Butte Lake.