

# Appendix F

---

Site Photographs



**Photograph 1.** View of the Project site from the eastern corner of the Project Site. The 3017 El Camino Real building is visible.



**Photograph 2.** View of the 3001 El Camino Real building, facing north.



**Photograph 3.** View of the 3017 El Camino Real building, facing east.



**Photograph 4.** View of the area of two former underground storage tanks (USTs) on the northeastern side of the 3001 El Camino Real building, facing southwest.



**Photograph 5.** View of the area between the 3001 and 3017 El Camino Real buildings, facing southwest.



**Photograph 6.** View of cracked asphalt in the parking lot of the Project Site, facing west. Concrete patches are visible adjacent to the 3017 El Camino Real building.